

**Palm Beach County Fleet Management
Asset Maintenance History**

10181508 2010 ANDERSON EQ7207T Trailer, 14,000 Gvwr

Workorder: 1008268 **Meter:** 0 **In Date:** 08/03/2010 **Closed:** 08/04/2010
Problem: INSTALL REGISTRATION HOLDER

| | | |
|-------------------------------|------------------------------------|--------------|
| - install registration holder | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| | 97960 Document Holder (truck Lite) | 1.00 |
| Hours 1.00 | Labor: 60.00 | Parts: 10.58 |
| : | | Total: 70.58 |

Workorder: 1008350 **Meter:** 0 **In Date:** 08/04/2010 **Closed:** 08/16/2010
Problem: weld asset numbers

| | | |
|-----------------|-------------------|--------------|
| - Weld Asset#'s | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 1.50 | Labor: 90.00 | Parts: 2.00 |
| : | | Total: 92.00 |

Workorder: 1008568 **Meter:** 0 **In Date:** 08/09/2010 **Closed:** 08/09/2010
Problem: Pre Delivery Inspection

| | | | |
|---------------------------|---------------|-------------|---------------|
| - Pre Delivery Inspection | | | |
| Hours 2.00 | Labor: 120.00 | Parts: 0.00 | Total: 120.00 |
| : | | | |

Workorder: 1011697 **Meter:** 0 **In Date:** 10/19/2010 **Closed:** 10/28/2010
Problem: BRAKES LOCKING UP

| | | |
|---|-------------------|---------------|
| - C/s: Intermittent brake lock up. Perform pinpoint test, inspect brakes, test electrical system & found rust on Rr backing plate. Remove brake, clean & lube backing plate & test drive. | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 3.00 | Labor: 180.00 | Parts: 2.00 |
| : | | Total: 182.00 |

Workorder: 1107241 **Meter:** 0 **In Date:** 07/11/2011 **Closed:** 07/22/2011
Problem: P. M., Brake lights not working, wires are frayed.

| | | |
|---|-------------------------|---------------|
| - Peformed P.m. | Parts List | Qty |
| - Repaired wiring to lights & ordered assy. R&r assy. | Shop Supplies | 1.00 |
| - Repaired wiring to one axle. R&r breakaway also. | Tail Light Assy. | 2.00 |
| - R&r two tires. | St235/80r16-e Tires | 2.00 |
| - Shop Supplies | Waste Fee | 2.00 |
| | Tire Disposal Fee | 2.00 |
| | 004098 Breakaway Switch | 1.00 |
| Hours 8.75 | Labor: 525.00 | Parts: 356.58 |
| : | | Total: 881.58 |

Workorder: 1108336 **Meter:** 0 **In Date:** 08/08/2011 **Closed:** 08/12/2011
Problem: Right signal light not working

| | | |
|---|-------------------|---------------|
| - C/s: Right signal light not working. Perform pinpoint test & found damaged wire harness. Repair wire harness. | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 3.00 | Labor: 180.00 | Parts: 2.00 |
| : | | Total: 182.00 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1109317 **Meter:** 0 **In Date:** 08/31/2011 **Closed:** 08/31/2011
Problem: Left rear tail light not working

- Repaired wiring.

Hours 0.75 Labor: 45.00 Parts: 0.00 Total: 45.00
:

Workorder: 1111913 **Meter:** 0 **In Date:** 11/04/2011 **Closed:** 11/15/2011
Problem: Right brake light not working, wires frayed

- Replace both rear brake light assembly, & repair wire harness. **Parts List** **Qty**
Shop Supplies 1.00
- Shop Supplies Brake Light Assy. 2.00

Hours 2.50 Labor: 150.00 Parts: 13.43 Total: 163.43
:

Workorder: 1202903 **Meter:** 0 **In Date:** 03/26/2012 **Closed:** 03/28/2012
Problem: ROAD CALLED,FLAT TIRE AT 19110 SOUTH STATE ROAD 7.

- road called flat tire at 19110 s st rd 7 temporary plug tire and send trailer back to shop for proper repairs **Parts List** **Qty**
Shop Supplies 1.00

- repair right rear tire
- Shop Supplies

Hours 3.00 Labor: 180.00 Parts: 2.00 Total: 182.00
:

Workorder: 1205686 **Meter:** 0 **In Date:** 06/15/2012 **Closed:** 06/18/2012
Problem: needs tires

- ck needs tires, dismount mount four new tires **Parts List** **Qty**
- nitro fill four tires 80 psi Shop Supplies 1.00
- Shop Supplies Tire Disposal Fee 4.00
St235/80r16e-marathon G/y Tire 4.00
Waste Fee 4.00

Hours 2.50 Labor: 150.00 Parts: 635.56 Total: 785.56
:

Workorder: 1207424 **Meter:** 0 **In Date:** 08/08/2012 **Closed:** 08/17/2012
Problem: NEEDS SAFETY PIN AND CHECK LIGHTS

- replace both center park light bulbs **Parts List** **Qty**
- install pintle pin 18410 Pintle Pin 1.00

Hours 0.75 Labor: 45.00 Parts: 1.98 Total: 46.98
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1304537 **Meter:** 0 **In Date:** 05/07/2013 **Closed:** 05/20/2013

Problem: pm service, trailer jack and cracked welds

| | | |
|-----------------------------|----------------------------------|-----------------|
| - P.m. | Parts List | Qty |
| - Test and replace battery | 12v5amp/hour Battery | 1.00 |
| - Repair all lights | Led M C Lamp | 2.00 |
| - R&r jack rebuilt mount | License Bracket W/light | 1.00 |
| - R&r Brakes and hub assem. | Trailer Jack | 1.00 |
| - Shop Supplies | Trailer Conn Plug | 1.00 |
| | 93745 Adapter Plug Pl | 2.00 |
| | Break Away | 1.00 |
| | 60260r Tail Light Ova | 2.00 |
| | 94706 Adapter 3 Pron | 2.00 |
| | Lh Brake Assy | 2.00 |
| | Rh Brake Assy | 2.00 |
| | 7lug Hub Assembly | 4.00 |
| | Shop Supplies | 1.00 |
| | 2"x21 Black Pipe | 10.00 |
| | 2"x2"x24' Steel Tubing 1/4" Wall | 7.00 |
| Hours 17.00 | Labor: 1,020.0 | Parts: 1,369.54 |
| : | 0 | Total: 2,389.54 |

Workorder: 1305074 **Meter:** 0 **In Date:** 05/22/2013 **Closed:** 05/24/2013

Problem: boulevard 3 tires

| | | | | |
|---------------------------------|------------|-------------|-------------|-------------|
| - boulevard replace three tires | Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| | : | | | |

Workorder: 1310015 **Meter:** 0 **In Date:** 10/03/2013 **Closed:** 10/04/2013

Problem: trailer has no lights

| | | |
|--|-------------------|--------------|
| - repair trailer has no lights rr fuse | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 1.00 | Labor: 60.00 | Parts: 2.00 |
| : | | Total: 62.00 |

Workorder: 1405890 **Meter:** 0 **In Date:** 06/16/2014 **Closed:** 06/26/2014

Problem: pm

| | | |
|--|------------------------|-----------------|
| - pm | Parts List | Qty |
| - repaired tail and marker wiring | Slip Plate Spray 12oz | 1.00 |
| - removed fittings and cleaned galley and lubed | Mac Wite Lithium Gres | 1.00 |
| - installed new brake away switch and new trailer plug | Male Trailer Connector | 1.00 |
| repaired wiring into junction box | Breakaway Switch | 1.00 |
| - rr four tires | St235/80r16 Lr-e Mthn | 4.00 |
| - brake svc | Brake Cleaner | 1.00 |
| - Shop Supplies | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 4.00 |
| Hours 14.00 | Labor: 840.00 | Parts: 874.74 |
| : | | Total: 1,714.74 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1502416 **Meter:** 0 **In Date:** 03/06/2015 **Closed:** 03/20/2015

Problem: tires

| | | |
|--|-----------------------|---------------|
| - replace both rear tires and fill all tires with nitrogen | Parts List | Qty |
| - replace 2 damage grease cap on right side | St235/80r16 Lr-e Mthn | 2.00 |
| - Shop Supplies | Plug | 2.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 2.00 |
| Hours 2.00 | Labor: 120.00 | Parts: 426.69 |
| : | | Total: 546.69 |

Workorder: 1506272 **Meter:** 0 **In Date:** 06/23/2015 **Closed:** 07/14/2015

Problem: pm, brakes, jack handle shaft

| | | |
|---|------------------------|-----------------|
| - pm | Parts List | Qty |
| - clean and adj front and rear brakes remove 4 brake drums and clean and replace all 8 wheels bearing | Mac Wite Lithium Gres | 1.00 |
| - repalce trailer male end and wire harness to first junction box | Brake Cleaner | 2.00 |
| - install trailer break away battery and charger assembly | Male Trailer Connector | 1.00 |
| - repair tag and left front marker light | Break Away System | 1.00 |
| - travel to he shop for trailer jack handle repair | 4086 Switch Cable | 1.00 |
| - Shop Supplies | Vinyl Electrical Tape | 2.00 |
| | Shop Supplies | 1.00 |
| Hours 16.50 | Labor: 990.00 | Parts: 92.95 |
| : | | Total: 1,082.95 |

Workorder: 1506715 **Meter:** 0 **In Date:** 07/06/2015 **Closed:** 07/07/2015

Problem: repair handle

| | | |
|-----------------|-------------------|---------------|
| - Repair Handle | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 2.00 | Labor: 120.00 | Parts: 2.00 |
| : | | Total: 122.00 |

Workorder: 1510590 **Meter:** 0 **In Date:** 10/20/2015 **Closed:** 10/29/2015

Problem: TRAILER PLUG BROKEN

| | | |
|--|------------------------|---------------|
| - replace damage wire harness and male connector | Parts List | Qty |
| - Shop Supplies | Trailer Conn Plug | 1.00 |
| | Bulk Trailer Wire | 20.00 |
| | Vinyl Electrical Tape | 1.00 |
| | Butt Connector | 1.00 |
| | Male Trailer Connector | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 2.50 | Labor: 150.00 | Parts: 54.70 |
| : | | Total: 204.70 |

Workorder: 1513042 **Meter:** 0 **In Date:** 12/30/2015 **Closed:** 12/31/2015

Problem: NEEDS 2 TIRES

| | | |
|--------------------------------|-------------------|--------------|
| - rr two tires with used tires | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 1.50 | Labor: 90.00 | Parts: 2.00 |
| : | | Total: 92.00 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1600841 **Meter:** 0 **In Date:** 01/26/2016 **Closed:** 01/27/2016
Problem: flat right front tire on trailer (48.7 miles round trip)

| | | |
|--|-------------------|---------------|
| - travel to boca to install spare tire on trailerr transport to fleet for repair 48.7 miles round trip | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 3.00 | Labor: 180.00 | Parts: 2.00 |
| : | | Total: 182.00 |

Workorder: 1600846 **Meter:** 0 **In Date:** 01/26/2016 **Closed:** 01/27/2016
Problem: R/FRONT TIRE FLAT

| | | |
|----------------------------------|-----------------------|---------------|
| - replace both right side tires | Parts List | Qty |
| - fill all 4 tires with nitrogen | St235/80r16 Lr-e Mthn | 2.00 |
| - Shop Supplies | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 2.00 |
| Hours 2.00 | Labor: 120.00 | Parts: 424.95 |
| : | | Total: 544.95 |

Workorder: 1602742 **Meter:** 0 **In Date:** 03/15/2016 **Closed:** 03/17/2016
Problem: driver side back tire problem

| | | |
|--|-------------------|--------------|
| - ck flst left rear tire repair lr tire mount add n2 | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 1.00 | Labor: 60.00 | Parts: 2.00 |
| : | | Total: 62.00 |

Workorder: 1608440 **Meter:** 0 **In Date:** 08/16/2016 **Closed:** 08/24/2016
Problem: Check tires.

| | | |
|--|-----------------------|---------------|
| - C/c Tires. Replace 2 Driver Side Tires,mount,correct All N2. Level | Parts List | Qty |
| - Shop Supplies | St235/80r16 Lr-e Mthn | 2.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 2.00 |
| Hours 1.50 | Labor: 90.00 | Parts: 408.60 |
| : | | Total: 498.60 |

Workorder: 1612042 **Meter:** 0 **In Date:** 11/22/2016 **Closed:** 11/28/2016
Problem: FIRST TIRE IN THE PASSENGER SIDE IN FLAT

| | | |
|-----------------------|-------------------|--------------|
| - Repair R/front Tire | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 1.00 | Labor: 60.00 | Parts: 2.00 |
| : | | Total: 62.00 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1705648 **Meter:** 0 **In Date:** 06/07/2017 **Closed:** 06/30/2017
Problem: PM Service

| | | |
|--|-----------------------|-----------------|
| - Pm Service. | Parts List | Qty |
| - Replace 4 brake drum assembly.4 brake assembly all bearings,seals and rewire. | Rh Brake Assy | 2.00 |
| - Replace both rear tires and fill all tires with nitrogen. | Lh Brake Assy | 2.00 |
| - Replace breakaway switch and battery. | Non-chlor Brake Clnr | 2.00 |
| - Replace taglight assembly.replace reflective tape.repair corner rear marker light. | Cable Tie | 1.00 |
| - Shop Supplies | Vinyl Electrical Tape | 1.00 |
| | Wire Term 16-14 Blt | 15.00 |
| | St235/80r16 Gy Endur | 2.00 |
| | Breakaway Switch | 1.00 |
| | 12v5amp/hour Battery | 1.00 |
| | lic light w/bracket | 1.00 |
| | Bulb | 2.00 |
| | Reflective Tape | 4.00 |
| | H-d8- 6.50 7k Cupands | 4.00 |
| | Bearing Kit | 4.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 2.00 |
| Hours 20.00 | Labor: 1,200.00 | Parts: 1,920.71 |
| : | 0 | Total: 3,120.71 |

Workorder: 1805221 **Meter:** 0 **In Date:** 05/21/2018 **Closed:** 06/04/2018
Problem: pm/ weld on 4 new D rings on outside corners

| | | |
|--|------------------------|---------------|
| - pm service | Parts List | Qty |
| - replace trailer | Grease Cap W/plug | 4.00 |
| - weld on 4 new D rings and repair 1 hold down | Seal 2.250x3.371x.375 | 4.00 |
| - replace breakaway battery | Non-chlor Brake Clnr | 2.00 |
| - clean and adjust brakes | Male Trailer Connector | 1.00 |
| - Shop Supplies | Glos Blk | 2.00 |
| | D Ring | 4.00 |
| | 12v5amp/hour Battery | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 9.50 | Labor: 570.00 | Parts: 163.46 |
| : | | Total: 733.46 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1910551 **Meter:** 0 **In Date:** 10/11/2019 **Closed:** 10/28/2019
Problem: pm service

| | Parts List | Qty |
|--|------------------------|------------|
| - Pm Service | | |
| - Repl. 4 tires | Seal 2.250x3.371x.375 | 4.00 |
| - Repl. battery unit and switch | Tire | 4.00 |
| - Repl. trailer plug; repl. running light | Tr416 Valve Stem | 4.00 |
| - Repl. breakaway cable and service all brakes | Male Trailer Connector | 1.00 |
| - Repl. lunette eye (tow ring) | Led Chmsl Lamp | 2.00 |
| - Repl. ramp spring on both sides | Non-chlor Brake Clnr | 2.00 |
| - Shop Supplies | Break Away System | 1.00 |
| | Tow Ring | 1.00 |
| | Ramp Springs | 1.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 4.00 |
| | Freight Charge | 1.00 |

Hours 13.50 Labor: 985.50 Parts: 1,070.17 Total: 2,055.67
:

Workorder: 2012685 **Meter:** 0 **In Date:** 12/18/2020 **Closed:** 12/18/2020
Problem: Transition Prep Charge

| | | | |
|--------------------------|---------------|-------------|---------------|
| - Transition Prep Charge | | | |
| Hours 2.00 | Labor: 146.00 | Parts: 0.00 | Total: 146.00 |
| : | | | |