

1/30/2017
3:00:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169548 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

Workorder: 743326 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 08/29/2007	Hours	Description
Close Date: 08/29/2007	Quantity	
- Pre-Delivery Inspection	2.00	
Parts Charge: 0.00	Labor Charge: 110.00	

Workorder: 836184 **Problem:** P.M.SERVICE

Meter Reading: 3778	Labor	Parts
In Date: 03/28/2008	Hours	Description
Close Date: 03/31/2008	Quantity	
- Pm Service	2.75	05046 BATTERY PROTECTOR (CRC) 1.00
- Shop Supplies		NB-19 WIPER BLADES 19" ANCO 31-19 2.00
		WD40 SPRAY LUBE STOCK# 405540002 1.00
		SHOP SUPPLIES 1.00
		10W30 MOTOR OIL 6.00
		1372 OIL FILTER FRM PH2 WIX 51372 1.00
		10020 INJECTOR CLEANER DON'T REORDER 1.00
Parts Charge: 44.40	Labor Charge: 165.00	

Workorder: 840408 **Problem:** ROADSIDE ASSISTANCE, FLAT TIRE

Meter Reading: 7274	Labor	Parts
In Date: 06/23/2008	Hours	Description
Close Date: 06/24/2008	Quantity	
- Field Service Call	1.70	SHOP SUPPLIES 1.00
- Install Spare Tire		
- Shop Supplies		
Parts Charge: 2.00	Labor Charge: 42.00	

Workorder: 840435 **Problem:** L/Front TIRE FLAT.

Meter Reading: 7602	Labor	Parts
In Date: 06/24/2008	Hours	Description
Close Date: 06/30/2008	Quantity	
- C/S L/F Tire Flat; Verify Complaint; Remove Tire, Mount, Balance & Add Nitrogen; Remount Spare Tire	1.50	WASTE FEE 1.00
- Shop Supplies		SHOP SUPPLIES 1.00
		TIRE 235/75R17 1.00
		TIRE DISPOSAL FEE 1.00
Parts Charge: 162.87	Labor Charge: 90.00	

1/30/2017
3:00:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169548 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

Workorder: 842564

Problem: P.M.SERVICE.

Meter Reading: 9532		Labor		Parts	
In Date: 08/08/2008	Close Date: 08/14/2008	Hours	Description	Quantity	
- Pm Service		3.25	CA8039 AIR FILTER LBF AF1615 WIX 46418		1.00
- Test Drive			5W20 ENGINE OIL		6.00
- Shop Supplies			NB-19 WIPER BLADES 19" ANCO 31-19		2.00
			SHOP SUPPLIES		1.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
Parts Charge:		48.34	Labor Charge:	15.00	

Workorder: 932330

Problem: P.M.SERVICE

Meter Reading: 14732		Labor		Parts	
In Date: 01/06/2009	Close Date: 01/23/2009	Hours	Description	Quantity	
- Pm Service		7.75	1372 OIL FILTER FRM PH2 WIX 51372		1.00
- R&R Ft Tires & Balance			5W20 ENGINE OIL		6.00
- Disassemble Beacon Assy & Repair Socket			TIRES 235/75R17		2.00
- Road Test			WASTE FEES		2.00
- Transport & Pick Up At Alignment Shop			TIRE DISPOSAL FEE		2.00
- Shop Supplies			SHOP SUPPLIES		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
Parts Charge:		384.86	Labor Charge:	465.00	Commercial Charge: 68.40

Workorder: 935743

Problem: INSTALL CUSTOMERS COMP STAND

Meter Reading: 18669		Labor		Parts	
In Date: 03/27/2009	Close Date: 03/30/2009	Hours	Description	Quantity	
- Fabricate & Install Customers Computer Stand & Power Harness.		4.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	240.00	

1/30/2017
3:00:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169548 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

Workorder: 937511

Problem: P.M.SERVICE

Meter Reading: 19901	Labor	Parts	
In Date: 05/07/2009	Hours	Description	Quantity
- Pm Service	3.00	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Install New Decal		5W20 ENGINE OIL	6.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	33.85	Labor Charge:	180.00

Workorder: 938941

Problem: 001 WASH TICKET ISSUED OUT 06/12/09

Meter Reading: 0	Labor	Parts	
In Date: 06/12/2009	Hours	Description	Quantity
- 001 Wash Ticket Issued Out 06/12/09			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	7.20

Workorder: 945389

Problem: P.M. Service, plus pillar handle (driver's side) needs to be replaced.

Meter Reading: 23240	Labor	Parts	
In Date: 10/28/2009	Hours	Description	Quantity
- P.M.Service	6.75	SHOP SUPPLIES	1.00
- Repair Nail In L/Front Tire		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Transport&Pick Up Veh. At Dealer For Warranty		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
Repair(Defective D/S Pillar)		5W20 ENGINE OIL	7.00
- Shop Supplies			
Parts Charge:	55.80	Labor Charge:	315.00

Workorder: 1004971

Problem: P. M. SERVICE

Meter Reading: 29056	Labor	Parts	
In Date: 05/12/2010	Hours	Description	Quantity
- P. M. Service.	2.75	5W20 ENGINE OIL	7.00
- Shop Supplies		SHOP SUPPLIES	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
Parts Charge:	38.65	Labor Charge:	165.00

1/30/2017
3:00:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169548 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

Workorder: 1005361		Problem: Towed in, no start.			
Meter Reading: 29071		Labor		Parts	
In Date: 05/24/2010	Close Date: 05/25/2010	Hours	Description	Quantity	
- Test Starting & Charging System, Charge & Test Battery, Replace Failed Battery.		1.00	GROUP 59 BATTERY (MTC BXT 59)		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge:		114.92	Labor Charge:		60.00
Workorder: 1005401		Problem: electrical problem			
Meter Reading: 29071		Labor		Parts	
In Date: 05/22/2010	Close Date: 05/25/2010	Hours	Description	Quantity	
- From: Belvedere Club House Dr To: Lv					
Parts Charge:		0.00	Labor Charge:		0.00
			Commercial Charge:		78.00
Workorder: 1012397		Problem: P.M.SERVICE			
Meter Reading: 33959		Labor		Parts	
In Date: 11/04/2010	Close Date: 11/18/2010	Hours	Description	Quantity	
- P. M.		4.75	31-20 WIPER BLADES 20" BLADE		2.00
- Verify, Nail In Right Rear Tire. Remove, Dismount, Patch, Mount, Balance. Add N2. Dismount Spare, Mount F/R Tire, Swap, Add 35 Psi Of N2.			SHOP SUPPLIES		1.00
- Shop Supplies			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
			CA8039 AIR FILTER LBF AF1615 WIX 46418		1.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			5W20 ENGINE OIL		6.00
Parts Charge:		71.32	Labor Charge:		285.00
Workorder: 1013782		Problem: 1 - Wash ticket(s) issued			
Meter Reading: 35021		Labor		Parts	
In Date: 12/15/2010	Close Date: 12/15/2010	Hours	Description	Quantity	
- 1 - Wash Ticket(S) Issued					
Parts Charge:		0.00	Labor Charge:		0.00
			Commercial Charge:		7.20

1/30/2017
3:00:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169548 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

Workorder: 1105802

Problem: P. M. SERVICE

Meter Reading: 39393	Labor	Parts			
In Date: 06/01/2011	Hours	Description	Quantity		
- P. M. Service.	9.25	1372 OIL FILTER FRM PH2 WIX 51372	1.00		
- Verify, Needs 3 Tires. Dismount, Mount, Balance, & Add N2.		5W20 ENGINE OIL	6.00		
		FRONT CALIPER ASSY.	1.00		
- Verify, Needs Front Pads, Turn Rotors. Install New Calipers, Bleed System, & Test Drive.		SHOP SUPPLIES	1.00		
		FRONT CALIPER ASSY.	1.00		
- Shop Supplies		P235/75R17 WANGLER SILENT ARMOR 108T	3.00		
		TIRE DISPOSAL FEE	3.00		
		WASTE FEE	3.00		
		FRONT BRAKE PAD	1.00		
Parts Charge:	765.79	Labor Charge:	555.00		

Workorder: 1107603

Problem: STUCK IN A DITCH—Winch Out

Meter Reading: 39939	Labor	Parts			
In Date: 07/15/2011	Hours	Description	Quantity		
- From: 2030 S. Congress Ave-North Side Of Rd					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	96.00

Workorder: 1109409

Problem: 2 - Wash ticket(s) issued

Meter Reading: 41408	Labor	Parts			
In Date: 09/01/2011	Hours	Description	Quantity		
- 2 - Wash Ticket(S) Issued					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	14.40

1/30/2017
3:00:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169548 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

Workorder: 1112281 **Problem:** Towed-in, Smoking in rear of the vehicle, truck shaking. Also due for P.M. Service.

Meter Reading: 44427		Labor		Parts	
In Date: 11/17/2011	Close Date: 11/30/2011	Hours	Description	Quantity	
-	P. M. Service.	4.25	SHOP SUPPLIES		1.00
-	C/S: Smoking In Rear, Verify Concern & Found Parking		5W20 ENGINE OIL		1.00
	Brake Was On. Remove Caliper, Rotors, Clean & Adjust		1066 WHITE LITHIUM (CRC 05037)		1.00
	Parking Brake In Side Rotors.		09997 BRAKE CLEAN		1.00
-	Shop Supplies		G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
			5W20 ENGINE OIL		6.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
			CA8039 AIR FILTER LBF AF1615 WIX 46418		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
Parts Charge: 72.30		Labor Charge: 255.00			

Workorder: 1112378 **Problem:** Broke down for more info call 561-801-6257(Gloria)

Meter Reading: 44350		Labor		Parts	
In Date: 11/12/2011	Close Date: 11/21/2011	Hours	Description	Quantity	
-	From: Nb Jog Rd, South Of Clintmoore Rd, Boca Raton				
	To: 13026 Jog Rd				
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge:	104.15

Workorder: 1203766 **Problem:** pm service

Meter Reading: 49516		Labor		Parts	
In Date: 04/20/2012	Close Date: 04/26/2012	Hours	Description	Quantity	
-	Pm	3.75	5W20 ENGINE OIL		6.00
-	Verify Nail Damaged Patch Tire Mount Balance Add N2		SHOP SUPPLIES		1.00
-	Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372		1.00
Parts Charge: 26.62		Labor Charge: 225.00			

1/30/2017
3:00:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169548 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

Workorder: 1204107

Problem: vehicel will not start parked at lab loading zone

Meter Reading: 49574	Labor	Parts	Quantity
In Date: 05/01/2012	Hours	Description	Quantity
- Ck Vehicle Will Not Start Jump Start Vehicl From Wud	1.50	GROUP 59 BATTERY WARRANTY(MTC BXT 59)	1.00
Lab Parking Lot Recharge Battey Ck Charging System Ck		SHOP SUPPLIES	1.00
For Drain And Found Defective Battery Ace S Code			
H920P, Utc Code 602 Ran. Replace Battery			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	90.00

Workorder: 1206383

Problem: NEEDS STEP BAR.

Meter Reading: 52903	Labor	Parts	Quantity
In Date: 07/09/2012	Hours	Description	Quantity
- Install New Step Bar On Both Side Of Vehicle	1.50	SHOP SUPPLIES	1.00
- Shop Supplies		STEP BAR ASSY.	1.00
Parts Charge:	332.75	Labor Charge:	90.00

Workorder: 1206769

Problem: install side entry steps running board

Meter Reading: 52638	Labor	Parts	Quantity
In Date: 07/19/2012	Hours	Description	Quantity
-			
Parts Charge:	0.00	Labor Charge:	0.00

1/30/2017
3:00:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169548 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

Workorder: 1211435 **Problem:** pm, please ck air cond doesnot cool well stops cooling intermittently

Meter Reading: 58061	Labor	Parts		
In Date: 11/28/2012	Hours	Description	Quantity	
- Pm	7.00	758537188 235-75R17	2.00	
- Ck Intermittently Cooling Perform Leak Test Evacuate Add Leak Detection Dye Recharge Test Drive And Was Unable To Verify Intermittent Ac Problem At This Time		R134A REFRIGERANT	1.00	
		SHOP SUPPLIES	1.00	
		PH2 OIL FILTER LBF PH	1.00	
- Replace Both Rear Thres Fill With Nitrogen And Rotate To The Front		NAPA QUART 5W20	6.00	
		CA8039 AIR FILTER LBF	1.00	
- Install How Is My Driving Decal		FORD FUEL FILTER	1.00	
- Shop Supplies		31-20 WIPER BLADES 20	2.00	
		USED FIREX REFURBED F	1.00	
Parts Charge:	522.99	Labor Charge:	420.00	

Workorder: 1312135 **Problem:** pm

Meter Reading: 69812	Labor	Parts		
In Date: 12/04/2013	Hours	Description	Quantity	
- Pm Svc	3.25	NAPAGOLD FUEL FILTER	1.00	
- Replace Utility Bed Light		NAPAGOLD OIL FILTER	1.00	
- Shop Supplies		WIPER BLADE	2.00	
		WASHER FL	1.00	
		USED FIRE X REFURBISHED	1.00	
		SHOP SUPPLIES	1.00	
		NAPA QUART 5W20	7.00	
Parts Charge:	64.63	Labor Charge:	195.00	

Workorder: 1402749 **Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 73174	Labor	Parts		
In Date: 03/21/2014	Hours	Description	Quantity	
- 1 - Detail Vehicle Wash Ticket(S) Issued				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 97.92

1/30/2017
3:00:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169548 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

Workorder: 1405527

Problem: PM

Meter Reading: 76308	Labor	Parts	
In Date: 06/05/2014	Hours	Description	Quantity
- Pm	3.75	NAPAGOLD OIL FILTER	1.00
- Nail In Fr Tire Dismount Mount Patch Balance Add N2		NAPA QUART 5W20	7.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	32.39	Labor Charge:	225.00

Workorder: 1406709

Problem: dead battery

Meter Reading: 77299	Labor	Parts	
In Date: 07/08/2014	Hours	Description	Quantity
- Ck Dead Battery Test Battery Bad After Recharge	0.75	BATTERY	1.00
Replace Battery		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	121.61	Labor Charge:	45.00

Workorder: 1412688

Problem: P.M.SERVICE, CHECK TIRES

Meter Reading: 83107	Labor	Parts	
In Date: 12/19/2014	Hours	Description	Quantity
- Pm	4.75	NAPAGOLD AIR FILTER	1.00
- Ck Tires Replace 4 Tires		NAPAGOLD OIL FILTER	1.00
- Shop Supplies		NAPAGOLD FUEL FILTER	1.00
		WASHER FL	1.00
		235 75R17 ADVENTURE	4.00
		WIPER BLADE	2.00
		NAPA QUART 5W20	6.00
		SHOP SUPPLIES	1.00
		TIRE DISPOSAL FEE	4.00
Parts Charge:	1,022.70	Labor Charge:	285.00

1/30/2017
3:00:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169548 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

Workorder: 1505669

Problem: pm, going over a bump front end har knob sound

Meter Reading: 88917	Labor	Parts	
In Date: 06/05/2015	Hours	Description	
Close Date: 06/16/2015		Quantity	
- Pm	5.00	NAPAGOLD OIL FILTER	1.00
- Ck Knock In Front End Verify Sway Bar Link Bushings		SWAY BAR LINK	2.00
- Bad Replace Bushings Test Drive		NAPA QUART 5W20	7.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	124.49	Labor Charge:	300.00

Workorder: 1511982

Problem: P.M.SERVICE

Meter Reading: 94162	Labor	Parts	
In Date: 11/24/2015	Hours	Description	
Close Date: 12/09/2015		Quantity	
- Pm	3.75	NAPAGOLD FUEL FILTER	1.00
- Replace Bad Fuel Filter Retaining Clip		NAPAGOLD OIL FILTER	1.00
- Shop Supplies		NAPA QUART 5W20	7.00
		SHOP SUPPLIES	1.00
		CLIP KIT	1.00
		STEEL RETAINING CLIP	2.00
Parts Charge:	41.19	Labor Charge:	225.00

Workorder: 1600318

Problem: dead battery

Meter Reading: 95018	Labor	Parts	
In Date: 01/11/2016	Hours	Description	
Close Date: 01/15/2016		Quantity	
- Dead Battery Ck Charging Sys Test Battery Bad Replace Warranty By Napa	0.75	BATTERY	1.00
Parts Charge:	0.00	Labor Charge:	45.00

Workorder: 1601179

Problem: left rear tire

Meter Reading: 95413	Labor	Parts	
In Date: 02/03/2016	Hours	Description	
Close Date: 02/04/2016		Quantity	
- Ck Nail In Tire Repair Lr Tire	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

1/30/2017
3:00:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169548 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

Workorder: 1601381

Problem: low tire pressure indicator left rear

Meter Reading: 95540	Labor	Parts	
In Date: 02/09/2016	Hours	Description	Quantity
<hr/>			
- Nail Front Left Tier Repair Add N2 Reset Tpms	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1605520

Problem: Pm service.

Meter Reading: 98551	Labor	Parts	
In Date: 05/27/2016	Hours	Description	Quantity
<hr/>			
- Pm Service.	8.75	NAPA QUART 5W20	7.00
- Resurface Rear Brake Rotors.Service Calipers.Replace Brake Pads.		NAPAGOLD AIR FILTER	1.00
		NAPAGOLD OIL FILTER	1.00
- Rotate And Balance All Tires.		20" WIPER BLADE	2.00
- Install How Is My Driving Sticker.		B FLUID DOT 3-32OZ	1.00
- Shop Supplies		USED FIRE X REFURBISHED	1.00
		WASHER FLUID CONCENTR	1.00
		SHOP SUPPLIES	1.00
		DISC BRAKE PADS	1.00
		DISC BRAKE PADS	1.00
Parts Charge:	108.26	Labor Charge:	525.00

Workorder: 1610078

Problem: Left rear tire flat.

Meter Reading: 102571	Labor	Parts	
In Date: 09/26/2016	Hours	Description	Quantity
<hr/>			
- Repair And Balance Left Rear Tire.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

1/30/2017
3:00:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169548 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

Workorder: 1610425

Problem: dead battery in parking lot south of lab bldg.

Meter Reading: 102693	Labor	Parts	
In Date: 10/05/2016	Hours	Description	Quantity
- Jump Start Vehicle In Wud Parking Lot.Recharge Battery And Test Starting And Charging System.	1.50	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	90.00

Workorder: 1611026

Problem: Transition Prep Charge

Meter Reading: 102693	Labor	Parts	
In Date: 10/25/2016	Hours	Description	Quantity
- Transition Prep Charge	2.00		
Parts Charge:	0.00	Labor Charge:	0.00

Total Parts Charges: **4,204.73** Total Labor Charges: **5,882.00** Total Comm. Charges: **473.27**