

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10194192    2013 TORO GRNDSMSTR 4700D Mower, Fine Cut Rotary, 7 Gang, 150in Cut**

**Workorder:** 1312400    **Meter:** 1    **In Date:** 12/12/2013    **Closed:** 12/12/2013  
**Problem:** 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00    Labor: 120.00    Parts: 0.00    Total: 120.00

:

**Workorder:** 1403169    **Meter:** 48    **In Date:** 04/01/2014    **Closed:** 04/08/2014  
**Problem:** first service

- First Service

- Service Hydraulic w/filter

- Shop Supplies

**Parts List**

|                       |      |
|-----------------------|------|
| 15-40 Oil             | 6.00 |
| Napagold Oil Filter   | 1.00 |
| Napa Hydraulic Filtr  | 1.00 |
| Aw68 Hydro Fluid Hydr | 3.00 |
| Grease Nlgi 2         | 2.00 |
| Brake Cleaner         | 1.00 |
| Shop Supplies         | 1.00 |

Hours 3.00    Labor: 180.00    Parts: 82.30    Total: 262.30

:

**Workorder:** 1412322    **Meter:** 215    **In Date:** 12/09/2014    **Closed:** 12/19/2014  
**Problem:** pm service

- Pm

- Hyd Service

- Shop Supplies

**Parts List**

|                       |      |
|-----------------------|------|
| Napagold Air Filter   | 1.00 |
| Napagold Oil Filter   | 1.00 |
| 15-40 Oil             | 6.00 |
| Napa Hydraulic Filtr  | 1.00 |
| Aw68 Hydro Fluid Hydr | 2.00 |
| Fuel Filter           | 1.00 |
| Fuel Filter           | 1.00 |
| 1cart Palladium 2 Grs | 1.00 |
| Shop Supplies         | 1.00 |

Hours 5.00    Labor: 300.00    Parts: 226.46    Total: 526.46

:

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1512636      **Meter:** 478      **In Date:** 12/15/2015      **Closed:** 12/30/2015  
**Problem:** pm service

|                 | <b>Parts List</b>     | <b>Qty</b>    |
|-----------------|-----------------------|---------------|
| - Pm            | 15-40 Oil             | 6.00          |
| - Hyd Service   | Napa Hydraulic Filtr  | 1.00          |
| - Wash Eqpt     | Napagold Air Filter   | 1.00          |
| - Shop Supplies | Pm-22-a Additive Dies | 1.00          |
|                 | Fuel Filter           | 1.00          |
|                 | Brake Cleaner         | 1.00          |
|                 | Tran Flu Qt Dexron3i  | 2.00          |
|                 | Aw68 Hydro Fluid Hydr | 2.00          |
|                 | Napagold Oil Filter   | 1.00          |
|                 | Fuel Filter           | 2.00          |
|                 | Shop Supplies         | 1.00          |
| Hours 6.00      | Labor: 360.00         | Parts: 365.54 |
| :               |                       | Total: 725.54 |

**Workorder:** 1604968      **Meter:** 691      **In Date:** 05/12/2016      **Closed:** 06/13/2016  
**Problem:** pm/ hydraulic leak

|   | <b>Parts List</b>     | <b>Qty</b>    |
|---|-----------------------|---------------|
| - Pm  | 15-40 Oil             | 6.00          |
| - Ck hyd leak, reseal valve, fittings and hoses | Napagold Oil Filter   | 1.00          |
| - Replace fan belt                              | Fuel Filter           | 1.00          |
| - Wash Eqpt                                     | Fuel Filter           | 1.00          |
| - Shop Supplies                                 | Brake Cleaner         | 1.00          |
|   | Napagold Air Filter   | 1.00          |
|   | Aw68 Hydro Fluid Hydr | 4.00          |
|   | V-belt                | 1.00          |
|   | 1cart Palladium 2 Grs | 1.00          |
|   | O-ring                | 2.00          |
|   | O Ring                | 1.00          |
|   | Seal Kit              | 1.00          |
|   | Shop Supplies         | 1.00          |
| Hours 10.50                                     | Labor: 630.00         | Parts: 257.24 |
| :   |                       | Total: 887.24 |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1607902      **Meter:** 665      **In Date:** 08/02/2016      **Closed:** 08/11/2016

**Problem:** RIGHT WING PIVOT SHAFT BENT AND BOLT/ CHECK LEFT

|   |                     |               |
|---|---------------------|---------------|
| - Replace bent Pivot shaft and sleeves on right wing deck and inspect left deck | <b>Parts List</b>   | <b>Qty</b>    |
|   | Compression Spring  | 1.00          |
| - Shop Supplies   | Screw               | 1.00          |
|   | Bushing             | 3.00          |
|   | Carrier Pivot Shaft | 1.00          |
|   | thrust washer       | 1.00          |
|   | washer              | 1.00          |
|   | nut                 | 1.00          |
|   | Shop Supplies       | 1.00          |
|   | Freight Charge      | 1.00          |
| Hours 2.00  | Labor: 120.00       | Parts: 223.45 |
| :   |                     | Total: 343.45 |

**Workorder:** 1702000      **Meter:** 837      **In Date:** 02/27/2017      **Closed:** 03/15/2017

**Problem:** needs 4 tires

|                     |                        |                 |
|---------------------|------------------------|-----------------|
| - Replace all tires | <b>Parts List</b>      | <b>Qty</b>      |
| - Pm                | 29x14.00x15 Ultra Trac | 2.00            |
| - Hyd Service       | 20x10.00x10 Multi Trac | 2.00            |
| - Shop Supplies     | 15-40 Oil              | 6.00            |
|                     | Napagold Oil Filter    | 1.00            |
|                     | Fuel Filter            | 1.00            |
|                     | Fuel Filter            | 1.00            |
|                     | Napagold Air Filter    | 1.00            |
|                     | Aw68 Hydro Fluid Hydr  | 8.00            |
|                     | Napa Hydraulic Filtr   | 1.00            |
|                     | Shop Supplies          | 1.00            |
|                     | Tire Disposal Fee      | 4.00            |
| Hours 7.00          | Labor: 420.00          | Parts: 1,509.99 |
| :                   |                        | Total: 1,929.99 |

**Workorder:** 1705247      **Meter:** 895      **In Date:** 05/26/2017      **Closed:** 06/07/2017

**Problem:** hydraulic leak

|   |                   |               |
|---|-------------------|---------------|
| - Ck Hyd fluid leak. Reseal valve body and hose connections | <b>Parts List</b> | <b>Qty</b>    |
|   | Shop Supplies     | 1.00          |
| - Shop Supplies   |                   |               |
| Hours 4.00  | Labor: 240.00     | Parts: 2.00   |
| :   |                   | Total: 242.00 |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1705953      **Meter:** 912      **In Date:** 06/15/2017      **Closed:** 06/30/2017

**Problem:** hydraulic leak

|                                      |                       |               |
|--------------------------------------|-----------------------|---------------|
| - Ck hyd leak reseal valve and lines | <b>Parts List</b>     | <b>Qty</b>    |
| - Shop Supplies                      | Aw68 Hydro Fluid Hydr | 14.00         |
|                                      | Seal Kit              | 1.00          |
|                                      | O Ring                | 1.00          |
|                                      | O-ring                | 2.00          |
|                                      | Shop Supplies         | 1.00          |
|                                      | Freight Charge        | 1.00          |
| Hours 4.00                           | Labor: 240.00         | Parts: 84.07  |
| :                                    |                       | Total: 324.07 |

**Workorder:** 1803134      **Meter:** 1132      **In Date:** 03/26/2018      **Closed:** 03/30/2018

**Problem:** pm new blades

|                     |                       |               |
|---------------------|-----------------------|---------------|
| - pm service        | <b>Parts List</b>     | <b>Qty</b>    |
| - hydraulic service | 15-40 Oil             | 6.00          |
| - replace 7 blades  | Napagold Oil Filter   | 1.00          |
| - Shop Supplies     | Fuel Filter           | 1.00          |
|                     | Fuel Filter           | 1.00          |
|                     | Napagold Air Filter   | 1.00          |
|                     | Napagold Air Filter   | 1.00          |
|                     | Napa Hydraulic Filtr  | 1.00          |
|                     | Aw68 Hydro Fluid Hydr | 8.00          |
|                     | Blade Combo 27        | 7.00          |
|                     | Shop Supplies         | 1.00          |
| Hours 8.50          | Labor: 510.00         | Parts: 461.44 |
| :                   |                       | Total: 971.44 |

**Workorder:** 1905586      **Meter:** 1132      **In Date:** 05/28/2019      **Closed:** 06/07/2019

**Problem:** pm service, replace blades

|                  |                       |                 |
|------------------|-----------------------|-----------------|
| - Pm Service     | <b>Parts List</b>     | <b>Qty</b>      |
| - Hyd. Service   | Napagold Air Filter   | 1.00            |
| - Repl. 7 blades | Napagold Air Filter   | 1.00            |
| - Shop Supplies  | Napagold Oil Filter   | 1.00            |
|                  | Fuel Filter           | 1.00            |
|                  | Fuel Filter           | 1.00            |
|                  | 15-40 Oil             | 6.00            |
|                  | Napa Hydraulic Filtr  | 1.00            |
|                  | Aw68 Hydro Fluid Hydr | 2.00            |
|                  | Blade Combo 27        | 7.00            |
|                  | Shop Supplies         | 1.00            |
| Hours 8.50       | Labor: 569.50         | Parts: 469.74   |
| :                |                       | Total: 1,039.24 |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1908179      **Meter:** 1690      **In Date:** 08/06/2019      **Closed:** 08/09/2019

**Problem:** Hyd. oil

|                   | <b>Parts List</b>               | <b>Qty</b>    |
|-------------------|---------------------------------|---------------|
| - Fill hydraulics | Aw68 Serv Truck                 | 11.00         |
| - To Okeeheelee   | Shop Supplies                   | 1.00          |
| - Shop Supplies   |                                 |               |
| Hours 2.00        | Labor: 134.00      Parts: 32.70 | Total: 166.70 |
| :                 |                                 |               |

**Workorder:** 1909360      **Meter:** 1690      **In Date:** 09/11/2019      **Closed:** 10/25/2019

**Problem:** pm/ very slow in low range

|   | <b>Parts List</b>                  | <b>Qty</b>      |
|---|------------------------------------|-----------------|
| - Pm Service  | Napagold Air Filter                | 1.00            |
| - Hyd. service  | Napagold Oil Filter                | 1.00            |
| - Repl. L/f carrier shaft on L/f deck   | Napa Fuel Filter                   | 1.00            |
| - Won't regen; have dealer reprogram Ecu; replace wiring harness and display screen | Fuel Filter                        | 1.00            |
| - Repl. battery and test electrical system  | 15-40 Oil                          | 6.00            |
| - Shop Supplies   | Hydraulic Filter                   | 1.00            |
|   | Napa Hydraulic Filtr               | 1.00            |
|   | Aw68 Hydro Fluid Hydr              | 2.00            |
|   | Pivot Carrier Shaft                | 1.00            |
|   | Battery                            | 1.00            |
|   | Replace Wire Harness & Lcd Display | 1.00            |
|   | Shop Supplies                      | 1.00            |
|   | Freight Charge                     | 1.00            |
| Hours 8.00  | Labor: 584.00      Parts: 2,321.58 | Total: 2,905.58 |
| :   |                                    |                 |

**Workorder:** 1911779      **Meter:** 1738      **In Date:** 11/13/2019      **Closed:** 11/18/2019

**Problem:** hydraulic leak (hose)

|   | <b>Parts List</b>                | <b>Qty</b>    |
|---|----------------------------------|---------------|
| - Repl. hydraulic line; refill and test run | Aw68 Hydro Fluid Hydr            | 11.00         |
| - Shop Supplies                             | Hose & Fittings                  | 1.00          |
|   | Shop Supplies                    | 1.00          |
| Hours 2.00                                  | Labor: 146.00      Parts: 176.52 | Total: 322.52 |
| :   |                                  |               |

**Workorder:** 2000308      **Meter:** 1785      **In Date:** 01/10/2020      **Closed:** 01/27/2020

**Problem:** hydraulic hose leaking at yellow tape.

|   | <b>Parts List</b>                | <b>Qty</b>    |
|---|----------------------------------|---------------|
| - r/r line to replace O rings. replace 1 line. refill system and test run | Hose & Fittings (mako)           | 1.00          |
| - Shop Supplies   | Aw68 Hydro Fluid Hydr            | 6.00          |
|   | Shop Supplies                    | 1.00          |
| Hours 4.00  | Labor: 292.00      Parts: 170.76 | Total: 462.76 |
| :   |                                  |               |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 2004044      **Meter:** 1862      **In Date:** 04/22/2020      **Closed:** 05/06/2020

**Problem:** PTO will not engage / dull blades

|  |                   |               |
|--|-------------------|---------------|
| - run scanner check / preform manual regen cycle | <b>Parts List</b> | <b>Qty</b>    |
| - R&r seven blades / grase spindles              | Blade Combo 27    | 7.00          |
| - Shop Supplies                                  | Shop Supplies     | 1.00          |
| Hours 5.50                                       | Labor: 401.50     | Parts: 236.26 |
| :  |                   | Total: 637.76 |

**Workorder:** 2005256      **Meter:** 1878      **In Date:** 05/26/2020      **Closed:** 05/29/2020

**Problem:** eng stalls when PTO is on and mowing

|  |                       |               |
|--|-----------------------|---------------|
| - diagnose. perform manual regen. set for automatic regen.<br>clear codes. test run numerous times | <b>Parts List</b>     | <b>Qty</b>    |
| - top off hydraulic fluid  | Aw68 Hydro Fluid Hydr | 3.00          |
| - Shop Supplies  | Shop Supplies         | 1.00          |
| Hours 2.50   | Labor: 182.50         | Parts: 10.75  |
| :  |                       | Total: 193.25 |

**Workorder:** 2005387      **Meter:** 1878      **In Date:** 05/29/2020      **Closed:** 06/11/2020

**Problem:** parking brake problem

|                                  |                   |               |
|----------------------------------|-------------------|---------------|
| - replace damaged P brake levers | <b>Parts List</b> | <b>Qty</b>    |
| - Shop Supplies                  | Detent Br         | 1.00          |
|                                  | Pawl Brake        | 1.00          |
|                                  | Shop Supplies     | 1.00          |
|                                  | Freight Charge    | 1.00          |
| Hours 2.00                       | Labor: 146.00     | Parts: 88.22  |
| :                                |                   | Total: 234.22 |

**Workorder:** 2008233      **Meter:** 2000      **In Date:** 08/18/2020      **Closed:** 08/31/2020

**Problem:** pto/ left deck height bolt/ see notes

|  |                       |                 |
|--|-----------------------|-----------------|
| - remove hydraulic block to replace o rings and seal leak.<br>test | <b>Parts List</b>     | <b>Qty</b>      |
| - wash equipment   | O Ring                | 3.00            |
| - replace deck height bolts. order extra for dept                  | O-ring                | 3.00            |
| - diagnose pto. replace traction and pto switch. readjust          | Aw68 Hydro Fluid Hydr | 20.00           |
| - Shop Supplies  | O Ring                | 3.00            |
|  | O Ring                | 3.00            |
|  | Plate Asm Hoc         | 10.00           |
|  | Spcer Hoc             | 10.00           |
|  | Screw                 | 10.00           |
|  | Pto Switch            | 1.00            |
|  | Sensor Position       | 1.00            |
|  | Shop Supplies         | 1.00            |
|  | Freight Charge        | 1.00            |
|  | Freight Charge        | 1.00            |
| Hours 8.00   | Labor: 584.00         | Parts: 707.72   |
| :  |                       | Total: 1,291.72 |

**Palm Beach County Fleet Management  
Asset Maintenance History**

|  |                    |                            |                           |
|--|--------------------|----------------------------|---------------------------|
| <b>Workorder:</b> 2008800  | <b>Meter:</b> 2000 | <b>In Date:</b> 09/01/2020 | <b>Closed:</b> 09/03/2020 |
| <b>Problem:</b> needs AW68 fluid   |                    |                            |                           |
| - secure hydraulic oil for dept  |                    | <b>Parts List</b>          | <b>Qty</b>                |
| - Shop Supplies  |                    | Aw68 Hydro Fluid Hydr      | 8.00                      |
|  |                    | Shop Supplies              | 1.00                      |
| Hours 0.50   | Labor: 36.50       | Parts: 22.00               | Total: 58.50              |
| :  |                    |                            |                           |
| <b>Workorder:</b> 2008827  | <b>Meter:</b> 2000 | <b>In Date:</b> 09/01/2020 | <b>Closed:</b> 09/17/2020 |
| <b>Problem:</b> right wing goes up and down by itself                    |                    |                            |                           |
| - replace 3 switches and clean harness. test run                         |                    | <b>Parts List</b>          | <b>Qty</b>                |
| - Shop Supplies  |                    | Switch                     | 3.00                      |
|  |                    | Dielect Silicone Comp      | 1.00                      |
|  |                    | Qd Electronic Cleaner      | 1.00                      |
|  |                    | Shop Supplies              | 1.00                      |
| Hours 2.50   | Labor: 182.50      | Parts: 294.42              | Total: 476.92             |
| :  |                    |                            |                           |
| <b>Workorder:</b> 2009495  | <b>Meter:</b> 2021 | <b>In Date:</b> 09/21/2020 | <b>Closed:</b> 10/27/2020 |
| <b>Problem:</b> right wing lowers by itself/ sometimes starting problems |                    |                            |                           |
| - diagnose right wing. pinpoint test. replace faulty lift control module |                    | <b>Parts List</b>          | <b>Qty</b>                |
|  |                    | Electrical Tape            | 1.00                      |
| - remove lr carrier shaft, extract bolt and reinstall                    |                    | Controller Tec5001         | 1.00                      |
| - program new module   |                    | Programed Module           | 1.00                      |
| - Shop Supplies  |                    | Shop Supplies              | 1.00                      |
|  |                    | Freight Charge             | 1.00                      |
| Hours 11.00  | Labor: 803.00      | Parts: 1,788.59            | Total: 2,591.59           |
| :  |                    |                            |                           |
| <b>Workorder:</b> 2010177  | <b>Meter:</b> 2034 | <b>In Date:</b> 10/08/2020 | <b>Closed:</b> 10/22/2020 |
| <b>Problem:</b> hydraulic leak   |                    |                            |                           |
| - pm service   |                    | <b>Parts List</b>          | <b>Qty</b>                |
| - clean & degrease   |                    | Napagold Oil Filter        | 1.00                      |
| - remove traction block to replace orings on shut off valve              |                    | 15-40 Oil                  | 6.00                      |
| - service rear axle & outter axle carriers                               |                    | Napagold Air Filter        | 1.00                      |
| - drill & tap grease fitting   |                    | Fuel Filter                | 1.00                      |
| - Shop Supplies  |                    | Napa Fuel Filter           | 1.00                      |
|  |                    | Non-chlor Brake Clnr       | 2.00                      |
|  |                    | Gear Oil                   | 3.00                      |
|  |                    | Aw68 Hydro Fluid Hydr      | 2.00                      |
|  |                    | Shop Supplies              | 1.00                      |
| Hours 10.00  | Labor: 730.00      | Parts: 137.89              | Total: 867.89             |
| :  |                    |                            |                           |
| <b>Workorder:</b> 2101256  | <b>Meter:</b> 2034 | <b>In Date:</b> 02/02/2021 | <b>Closed:</b> 02/02/2021 |
| <b>Problem:</b> Transition Prep Charge                                   |                    |                            |                           |
| - Transition Prep Charge   |                    |                            |                           |
| Hours 2.00   | Labor: 146.00      | Parts: 0.00                | Total: 146.00             |
| :  |                    |                            |                           |