

**Palm Beach County Fleet Management
Asset Maintenance History**

10189842 2013 FORD F350 Utility Body, 1 Ton

Workorder: 1303283 **Meter:** 319 **In Date:** 04/04/2013 **Closed:** 04/04/2013
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 4.00 Labor: 240.00 Parts: 0.00 Total: 240.00
 :

Workorder: 1303959 **Meter:** 320 **In Date:** 04/23/2013 **Closed:** 04/23/2013
Problem: 1 - Key(s) issued

- 1 - Key(s) issued

Parts List
 Duplicate Vehicle Keys Qty 1.00

Hours 0.20 Labor: 12.00 Parts: 3.00 Total: 15.00
 :

Workorder: 1309803 **Meter:** 5987 **In Date:** 09/27/2013 **Closed:** 10/22/2013
Problem: Pm service

- P.m. Service.

- Rotate and balance all six tires.

- Shop Supplies

Parts List
 5w20 Engine Oil Qty 8.00
 Napagold Oil Filter 1.00
 Used Fire X Refurbished 1.00
 Floor Mat-2pc Rub Bk 1.00
 Shop Supplies 1.00

Hours 5.50 Labor: 330.00 Parts: 70.30 Total: 400.30
 :

Workorder: 1403323 **Meter:** 12389 **In Date:** 04/04/2014 **Closed:** 04/15/2014
Problem: Pm service.

- Perform pm service.

- Rotate and balance all six tires.

- Shop Supplies

Parts List
 5w20 Engine Oil Qty 7.00
 Napagold Oil Filter 1.00
 Wiper Blade 2.00
 Shop Supplies 1.00

Hours 5.50 Labor: 330.00 Parts: 32.27 Total: 362.27
 :

Workorder: 1408801 **Meter:** 17527 **In Date:** 09/02/2014 **Closed:** 09/18/2014
Problem: Pm service.Check over ac performance on max.setting.

- P.m. Service.

- A/c performance check,not cold.recover freon,system low.vacuum and recharge system to specs. and leak test.okay.

- Rotate and balance all six tires.

- Shop Supplies

Parts List
 5w20 Engine Oil Qty 7.00
 Napagold Oil Filter 1.00
 Wiper Blade 2.00
 Napagold Air Filter 1.00
 Used Fire X Refurbished 1.00
 R134a Lv Shop 1 1.00
 Shop Supplies 1.00

Hours 7.00 Labor: 420.00 Parts: 64.37 Total: 484.37
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1411373	Meter: 20148	In Date: 11/14/2014	Closed: 11/26/2014
Problem: Fuel cap broken			
- Replace broken gas cap.clear code with scan tool.		Parts List	Qty
- Shop Supplies		Gas Cap Non-locking	1.00
		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 15.61	Total: 75.61
:			

Workorder: 1501203	Meter: 23213	In Date: 02/02/2015	Closed: 02/19/2015
Problem: P.M. Service			
- Pm service.		Parts List	Qty
- Rotate and balance all six tires.		5w20 Engine Oil	7.00
- Replace missing gas cap.clear code with scan tool.		Napagold Oil Filter	1.00
- Shop Supplies		Wiper Blade	2.00
		Wd40 16oz	1.00
		Fuel Cap Diesel	1.00
		Gas Cap Non-locking	1.00
		Shop Supplies	1.00
Hours 6.50	Labor: 390.00	Parts: 82.79	Total: 472.79
:			

Workorder: 1506574	Meter: 27944	In Date: 06/30/2015	Closed: 07/15/2015
Problem: Pm service.			
- Pm service.		Parts List	Qty
- Replace and balance all six tires.		5w20 Engine Oil	7.00
- Complete front end alignment and test drive.		Napagold Oil Filter	1.00
- Shop Supplies		Wiper Blade	2.00
		Used Fire X Refurbished	1.00
		Stg Wheel Cov - Ford	1.00
		179636492 Lt245-75r17	6.00
		Shop Supplies	1.00
		Tire Disposal Fee	6.00
Hours 9.50	Labor: 570.00	Parts: 1,630.88	Total: 2,200.88
:			

Workorder: 1509538	Meter: 29819	In Date: 09/22/2015	Closed: 09/29/2015
Problem: Windshield wiper motor will not turn off.			
- Transport vehicle to and from dealer for defective wiper switch.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1600654 **Meter:** 33636 **In Date:** 01/20/2016 **Closed:** 01/28/2016
Problem: P.M. service.

- Pm service.	Parts List	Qty
- Replace leaking right rear axle seal.	5w20 Engine Oil	7.00
- Rotate and balance all six tires.	Napagold Oil Filter	1.00
- Shop Supplies	Napagold Air Filter	1.00
	22" Wiper Blade	2.00
	Napa Oil Seal	1.00
	Rear Axle Nut	1.00
	Shop Supplies	1.00
Hours 8.00	Labor: 480.00	Parts: 97.46
:		Total: 577.46

Workorder: 1605222 **Meter:** 38060 **In Date:** 05/19/2016 **Closed:** 05/27/2016
Problem: P.M. Service.Check battery.

- P.m. Service.	Parts List	Qty
- Recharge battery and test battery and charging system.battery failed load test.replace defective battery.	5w20 Engine Oil	8.00
- Rotate and balance six tires.	Napagold Oil Filter	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	Battery 65	1.00
	Shop Supplies	1.00
Hours 6.50	Labor: 390.00	Parts: 195.67
:		Total: 585.67

Workorder: 1610886 **Meter:** 44220 **In Date:** 10/21/2016 **Closed:** 10/31/2016
Problem: P.M. service

- P.m. Service.	Parts List	Qty
- Resurface front brake rotors,replace front pads.service and lube calipers.flush and bleed system.	5w20 Engine Oil	8.00
- Rotate and balance all six tires.	Napagold Oil Filter	1.00
- Shop Supplies	Napagold Air Filter	1.00
	22" Wiper Blade	2.00
	kit brake	1.00
	Shop Supplies	1.00
Hours 10.50	Labor: 630.00	Parts: 144.67
:		Total: 774.67

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1702247 **Meter:** 49575 **In Date:** 03/06/2017 **Closed:** 03/16/2017
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Flush and refill transmission.	5w20 Engine Oil	8.00
- Replace two tires.rotate and balance all six.	Napagold Oil Filter	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Syn-atf Trans Fluid S	18.00
	179636492 Lt245-75r17	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 7.50	Labor: 450.00	Parts: 623.49
:		Total: 1,073.49

Workorder: 1708160 **Meter:** 55277 **In Date:** 08/18/2017 **Closed:** 08/30/2017
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Perform rear differential service.	5w20 Engine Oil	7.00
- Pressure test and inspect cooling system.flush and refill coolant.	Napagold Oil Filter	1.00
- Replace four worn tires.rotate and balance all six tires.nitrofill.	22" Wiper Blade	2.00
- Shop Supplies	1qt Syngear Oil 75-90	4.00
	Friction Modifier	1.00
	Non-chlor Brake Clnr	1.00
	Anti Freeze Motorcraft	2.00
	179636492 Lt245-75r17	4.00
	Tr416 Valve Stem	4.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 10.00	Labor: 600.00	Parts: 1,204.45
:		Total: 1,804.45

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1801182 **Meter:** 60579 **In Date:** 01/31/2018 **Closed:** 02/08/2018
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Check and replace all six defective body mounts by cutting them out.	B Fluid Dot 3-32oz	1.00
- Check brakes.resurface both rear rotors, replace pads and calipers .flush and bleed brake system .road test.	Caliper Washer	4.00
- Balance and rotate all six tires.	Body Mount Kit	2.00
- Shop Supplies	5w20 Engine Oil	8.00
	Napagold Oil Filter	1.00
	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Body Mount Kit	4.00
	Brake Pad	1.00
	lube	1.00
	Brake Caliper	1.00
	Brake Caliper	1.00
	Caliper Plate Asy	1.00
	Real Brake Pad	1.00
	Shop Supplies	1.00
Hours 16.50	Labor: 990.00	Parts: 1,003.94
:		Total: 1,993.94

Workorder: 1808989 **Meter:** 67328 **In Date:** 08/30/2018 **Closed:** 09/06/2018
Problem: PM Service.

- P.m. service.	Parts List	Qty
- Test and replace right rear marker light .	5w20 Engine Oil	7.00
- Charge battery fully . Test battery and charging system . Battery failed load test . R&r defective battery.	Napagold Oil Filter	1.00
- Rotate and balance all six tires . Nitrofill tires.	Napagold Air Filter	1.00
- Shop Supplies	Used Fire X Refurbished	1.00
	22" Wiper Blade	2.00
	Led M C Lamp	1.00
	Battery	1.00
	Shop Supplies	1.00
Hours 6.80	Labor: 408.00	Parts: 188.63
:		Total: 596.63

Workorder: 1901343 **Meter:** 73191 **In Date:** 02/04/2019 **Closed:** 02/14/2019
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Rotate and balance all four tires . Nitrofill all.	Napagold Oil Filter	1.00
- Shop Supplies	5w20 Engine Oil	8.00
	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
	Shop Supplies	1.00
Hours 5.50	Labor: 368.50	Parts: 34.29
:		Total: 402.79

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1901869 **Meter:** 73313 **In Date:** 02/19/2019 **Closed:** 02/25/2019
Problem: A/C inop, Body damage right rear.

<ul style="list-style-type: none"> - A/c performance test .leak test . Recover freon . R&r defective evaporator and accumulator and evaporator temp sensor . Evucuate system and complete recharge to factory spec. Retest . - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> E8 A/c Oil Univ W Dye Freon Lv Shop 1 Evaporator Core accumulator sensor Kit O Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 2.00 1.00 1.00 1.00 1.00 1.00 	
Hours 11.80	Labor: 790.60	Parts: 501.05	Total: 1,291.65
:			

Workorder: 1903162 **Meter:** 73313 **In Date:** 02/26/2019 **Closed:** 03/22/2019
Problem: Damage to all right side of body & repair rust on left side of body in front & behind wheel well

<ul style="list-style-type: none"> - Damage to all right side of body & repair rust on left side of body in front & behind wheel well 	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:				

Workorder: 1908489 **Meter:** 78451 **In Date:** 08/14/2019 **Closed:** 08/28/2019
Problem: PM Service

<ul style="list-style-type: none"> - P.m. service. - A/c performance test . Leak test . Recover freon . Replace leaking condensor and seals . Evacuate system and complete recharge to factory spec. Retest . - Resurface both front brake rotors . Replace brake pads , calipers and brake hoses . Flush and bleed brake system . Road test . - Perform complete air intake decarb and cleaning . Flush injectors . - Perform tune up . Replace all sixteen spark plugs and wire set . - Test and replace defective trailer plug connector . Rewire as needed. - Rotate and balance all six tires . Nitrofill all. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> 5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Used Fire X Refurbished Oil Compressor Freon Lv Shop 2 Seal Kits Condenser B Fluid Dot 3-32oz Brake Caliper Brake Hose Brake Hose Brake Caliper Non-chlor Brake Clnr Brake Pad Motorcraft Motor Tune-up 16oz Intake Cleaner Kit Espak Plug Wire Espak Plug Wire Spark Plug trailer plug Injector Cleaner Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 8.00 1.00 2.00 1.00 1.00 2.00 2.00 1.00 2.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 4.00 4.00 16.00 1.00 1.00 1.00 	
Hours 21.10	Labor: 1,413.70	Parts: 1,101.00	Total: 2,514.70
:	0		

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1911498 **Meter:** 80689 **In Date:** 11/05/2019 **Closed:** 11/06/2019
Problem: Left front tire going flat .

- Repair left front tire and balance . Nitrofill all.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 73.00	Parts: 4.00
:		Total: 77.00

Workorder: 2001948 **Meter:** 83768 **In Date:** 02/26/2020 **Closed:** 03/05/2020
Problem: P.M. service and wipers will not shut off .

- P.m. service.	Parts List	Qty
- Replace four tires . Rotate and balance all six tires . Nitrofill all.	5w20 Engine Oil	8.00
	Napagold Oil Filter	1.00
- Computer diagnose wipers staying on . Monitor wiper pids . R&r defective wiper switch and retest .	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
- Remove and replace rusted out rear cable step . Drill and mount new step .	Lt245/75r17 Mich Defend Ltx	4.00
	Switch	1.00
- Perform complete front end alignment and road test .	Cable Step	1.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 12.30	Labor: 897.90	Parts: 1,307.10
:		Total: 2,205.00

Workorder: 2006811 **Meter:** 87500 **In Date:** 07/13/2020 **Closed:** 07/16/2020
Problem: A/c not cold at times , ABS light on at times and ignition sticking at times .

- Computer diagnose Abs light < code C1233 . Perform pinpoint test . R&r defective left front wheel speed sensor . Clear code and retest .	Parts List	Qty
	Abs Sensor	1.00
- A/c performance test . Recover , evacuate and recharge to factory spec . No leaks found . Operation normal .	Shop Supplies	1.00
- Shop Supplies		
Hours 4.00	Labor: 292.00	Parts: 98.25
:		Total: 390.25

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 2008539 **Meter:** 88630 **In Date:** 08/26/2020 **Closed:** 09/09/2020
Problem: PM Service, Check A/C.

<ul style="list-style-type: none"> - P.m. service. - Replace two tires . Rotate and balance all six tires . Nitrofill all. - Diagnose engine misfire . Perform tune up . Replace all sixteen spark plugs . Retread one plug hole due to carbon build up . Replace wires .retest and clear codes . Retest A/c working as designed . - Perform complete air intake decarb and cleaning . Flush injectors . - Perform complete front end alignment and road test . - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Napagold Oil Filter 5w20 Engine Oil Washer Fluid Concentr 22" Wiper Blade Used Fire X Refurbished Napagold Air Filter Lt245/75r17 Mich Defend Ltx Lubriguard - Anti-sei Dielect Silicone Comp Espak Plug Wire Espak Plug Wire Spark Plug Motor Tune-up 16oz Intake Cleaner Kit Shop Supplies Tire Disposal Fee 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 8.00 1.00 2.00 1.00 1.00 2.00 1.00 1.00 4.00 4.00 16.00 1.00 1.00 1.00 2.00 	
Hours 16.30 :	Labor: 1,189.90	Parts: 844.19	Total: 2,034.09

Workorder: 2102299 **Meter:** 93757 **In Date:** 03/01/2021 **Closed:** 03/01/2021
Problem: Transition Prep Charge

<ul style="list-style-type: none"> - Transition Prep Charge 	Hours 2.00 :	Labor: 146.00	Parts: 0.00	Total: 146.00
--	-----------------	---------------	-------------	---------------