

1/30/2017
3:58:36PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170973 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 745567

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	
In Date: 10/15/2007	Hours	Description	Quantity
- Pre-Delivery Inspection	2.00		
Parts Charge: 0.00	Labor Charge: 120.00		

Workorder: 835540

Problem: INSTALL LADDER RACK.P.M SERVICE

Meter Reading: 4245	Labor	Parts	
In Date: 03/14/2008	Hours	Description	Quantity
- Fabricate And Install Ladder Rack.	8.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Pm Service		5W20 ENGINE OIL	7.00
- Inspect/Test Trailer Hitch Assy.Scn Sys,Pin Point		5404 FEMALE CONNECTOR	1.00
Test.Repl Defective Trailer Plug Socket,Repair Wiring		SHOP SUPPLIES	1.00
Going To Socket.Retest Sys Ok		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
- Rotate & High Speed Balance All Four Tires.Nitro Fill All Tires.		LADDER RACK {WEATHERGUARD}	1.00
- Shop Supplies			
Parts Charge: 366.85	Labor Charge: 60.00		

Workorder: 843946

Problem: PM SERVICE

Meter Reading: 9875	Labor	Parts	
In Date: 09/09/2008	Hours	Description	Quantity
- Pm	3.75	SHOP SUPPLIES	1.00
- Rotate, Balance, Nitro Fill 4 Tires		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
- Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
		5W20 ENGINE OIL	7.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
Parts Charge: 75.85	Labor Charge: 60.00		

1/30/2017
3:58:36PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170973 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 934274

Problem: PM SERVICE ALSO SEE NOTES.

Meter Reading: 15017	Labor	Parts	
In Date: 02/20/2009	Hours	Description	Quantity
- Pm Service	2.75	05046 BATTERY PROTECTOR (CRC)	1.00
- Shop Supplies		5W20 ENGINE OIL	7.00
		31-20 WIPER BLADES 20" BLADE	2.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		1066 WHITE LITHIUM (CRC 05037)	1.00
		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	45.24	Labor Charge:	165.00

Workorder: 936273

Problem: NAIL IN R/R TIRE

Meter Reading: 16399	Labor	Parts	
In Date: 04/09/2009	Hours	Description	Quantity
- Repair R/R Tire.	1.00	TR416 VALVE STEM	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	3.19	Labor Charge:	60.00

Workorder: 940591

Problem: P.M service, check tires

Meter Reading: 20462	Labor	Parts	
In Date: 07/09/2009	Hours	Description	Quantity
- P.M Service.	7.25	5W20 ENGINE OIL	7.00
- Mount, Balance & Nirto Fill Four New Tires.		TR416 VALVE STEM	4.00
- Alignment.		179636492 LT245/75R17 WRANGLER SR-A E	4.00
- Shop Supplies		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
		TIRE DISPOSAL FEE	4.00
		SHOP SUPPLIES	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
Parts Charge:	777.78	Labor Charge:	435.00

1/30/2017
3:58:36PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170973 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 945866

Problem: P.M. Service.

Meter Reading: 25628	Labor	Parts	
In Date: 11/09/2009	Hours	Description	Quantity
- P.M Service.	3.75	SHOP SUPPLIES	1.00
- Rotate & Balance All Four Tires.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Shop Supplies		5W20 ENGINE OIL	7.00
		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
Parts Charge:	22.40	Labor Charge:	450.00

Workorder: 1003711

Problem: Pm service

Meter Reading: 30707	Labor	Parts	
In Date: 04/09/2010	Hours	Description	Quantity
- P.M Service.	6.75	SYN/ATF TRANS FLUID SYNTHETIC	12.00
- Test Starting & Charging System, Test & Replace Battery.		SHOP SUPPLIES	1.00
- Transmission Flush.		LEFT FRONT DOOR CHECK / F81Z2523552AA	1.00
- Replace Broken Door Check On Drivers Door.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Shop Supplies		GROUP 65 BATTERY (MTC BXT-65-850)	1.00
		5W20 ENGINE OIL	7.00
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
Parts Charge:	276.51	Labor Charge:	405.00

Workorder: 1009948

Problem: P.M. Service.Screw in r/r tire.

Meter Reading: 36113	Labor	Parts	
In Date: 09/10/2010	Hours	Description	Quantity
- Perform Pm Service.	4.75	5W20 ENGINE OIL	7.00
- Repair Flat Right Front Tire.Rotate And Balance All Four Tires.		09997 BRAKE CLEAN	1.00
- Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		SHOP SUPPLIES	1.00
		7090BLK FRT FLOOR MATS (RUBBER QUEEN)	1.00
		1401 BRAKE FLUID BRAKE FLUID	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
Parts Charge:	96.41	Labor Charge:	285.00

1/30/2017
3:58:36PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170973 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1102974

Problem: Pm service,also see notes on tires and wipers.

Meter Reading: 42119 In Date: 03/18/2011	Close Date: 03/24/2011	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		10.25	1372 OIL FILTER FRM PH2 WIX 51372		1.00
- Pressure Test And Inspect Cooling System.Reverse Flush And Renew Coolant			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
			CA10262 AIR FILTER MTC FA1883 WIX 49883		1.00
- Perform Rear Differential Service.			75W140 GEAR LUBE SYNTHETIC (MC XY75W140QL)		4.00
- Install Four New Tires .Nitrogen Fill And Balance All Four.			5W20 ENGINE OIL		7.00
- Perform Wheel Alignment Complete.			31-20 WIPER BLADES 20" BLADE		2.00
- Shop Supplies			82194 GRAY SILICONE (PERMATEX)		1.00
			TIRE DISPOSAL FEE		4.00
			ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)		1.00
			179636492 LT245/75R17 WRANGLER SR-A E		4.00
			SHOP SUPPLIES		1.00
			C8AZ19B546A ADDITIVE DIFFERENTIAL (MC XL-3)		1.00
	Parts Charge: 883.77	Labor Charge: 615.00			

Workorder: 1109920

Problem: P.M. service and screw in l/f and r/r tires see notes.

Meter Reading: 47692 In Date: 09/16/2011	Close Date: 09/26/2011	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		4.75	31-20 WIPER BLADES 20" BLADE		2.00
- Repair Two Flat Tires,Left Front And Right Rear.Nitrogen Fill And Balance All Four.			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			SHOP SUPPLIES		1.00
- Shop Supplies			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			5W20 ENGINE OIL		7.00
	Parts Charge: 45.18	Labor Charge: 285.00			

1/30/2017
3:58:36PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170973 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1203724

Problem: P.M. service and A/C not cold.

Meter Reading: 54584	Labor	Parts	
In Date: 04/19/2012	Hours	Description	Quantity
- P.M. Service.	6.25	5W20 ENGINE OIL	7.00
- Check A/C System,Low Freon.Recover Freon And		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
Replaceleaking Low Pressure Switch.Vacuum And		31-20 WIPER BLADES 20" BLADE	2.00
Recharge System.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Rotate And Balance All Tires.		A/C LOW PRESSURE SWITCH	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
Parts Charge:	70.09	Labor Charge:	375.00

Workorder: 1206047

Problem: Check engine light on and transmission harsh shift.

Meter Reading: 56215	Labor	Parts	
In Date: 06/27/2012	Hours	Description	Quantity
- Computer Diagnose For Check Engine Light On And	7.00	KA8A THROTTLE BODY/ UP ENGINE SERVICE KIT	1.00
Harsh Shift.Test And Replace Failed #8 Ignition Coil And		408 FUEL INJECTION CLEANER	1.00
All Eight Spark Plugs With New.Clear Codes With Scan		SHOP SUPPLIES	1.00
Tool And Road Test.		IGNITION COIL	1.00
- Perform Induction Service And Clean Trottle Body.Power		SPARK PLUG	8.00
Flush All Fuel Injectors And Relearn All Engine Controls			
With Scan Tool.			
- Shop Supplies			
Parts Charge:	252.06	Labor Charge:	420.00

Workorder: 1206562

Problem: 1 - Key(s) issued

Meter Reading: 56300	Labor	Parts	
In Date: 07/13/2012	Hours	Description	Quantity
- 1 - Key(S) Issued	0.20	DUPLICATE VEHICLE KEYS	1.00
Parts Charge:	3.00	Labor Charge:	18.00

1/30/2017
3:58:36PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170973 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1208140

Problem: Towed in for left rear tire flat.

Meter Reading: 58241	Labor	Parts	
In Date: 08/29/2012	Hours	Description	Quantity
<hr/>			
- Repair And Balance Left Rear Tire.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1208150

Problem: put spare on

Meter Reading: 58101	Labor	Parts	
In Date: 08/29/2012	Hours	Description	Quantity
<hr/>			
- Tow From: Croc 8100 Forrest Hill			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	104.15

Workorder: 1208726

Problem: service

Meter Reading: 58511	Labor	Parts	
In Date: 09/12/2012	Hours	Description	Quantity
<hr/>			
- Tire Service Schall Rd Off Military Trail North Of Okeechobee - Service			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	46.40

Workorder: 1208727

Problem: Tire

Meter Reading: 58511	Labor	Parts	
In Date: 09/12/2012	Hours	Description	Quantity
<hr/>			
- Tire Service Schall Rd Off Military North Of Okeechobee - Tire			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	211.99

1/30/2017
3:58:36PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170973 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1209604

Problem: Pm service and check over all tires.

Meter Reading: 59569	Labor	Parts	
In Date: 10/05/2012	Hours	Description	Quantity
- P.M. Service.	9.75	SHOP SUPPLIES	1.00
- Replace Two Tires,Repair Right Rear ,Balance All Four.		5W20 ENGINE OIL	7.00
- Replace Transmission Filter.Flush And Refill System.		31-20 WIPER BLADES 20	2.00
- Complete Wheel Alignment.Test Drive.		179636492 LT245-75R17	2.00
- Shop Supplies		SYN-ATF TRANS FLUID S	18.00
		PH2 OIL FILTER LBF PH	1.00
		TRANS FILTER	1.00
		TRANS PAN GASKET	1.00
		TR416 VALVE STEM	3.00
Parts Charge:	758.51	Labor Charge:	585.00

Workorder: 1304422

Problem: Pm service

Meter Reading: 65469	Labor	Parts	
In Date: 05/03/2013	Hours	Description	Quantity
- Perform Pm Service.	3.75	FORD FUEL FILTER	1.00
- Rotate And Balance All Four Tires.		USED FIRE X REFURBISHED	1.00
- Shop Supplies		5068 PENTRATING OIL	1.00
		SHOP SUPPLIES	1.00
		31-20 WIPER BLADES 20	2.00
		5W20 ENGINE OIL	7.00
		NAPAGOLD OIL FILTER	1.00
Parts Charge:	86.23	Labor Charge:	225.00

1/30/2017
3:58:36PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170973 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1310814

Problem: Pm service.

Meter Reading: 71584	Labor	Parts	
In Date: 10/29/2013	Hours	Description	
Close Date: 11/14/2013		Quantity	
- P.M. Service.	10.25	MAC WITE LITHIUM GRES	1.00
- Replace Both Headlamp,Dome Lamp And Brake Lamp Bulbs.		5W20 ENGINE OIL	7.00
		DISC BRAKE PADS	1.00
- Resurface Front Brake Rotors,Replaced Brake Pads.Service And Lube Calipers.Flush And Bleed System.		WIPER BLADE	2.00
		NAPAGOLD OIL FILTER	1.00
		BATTERY 65	1.00
- Test Battery And Charging System.Replace Bad Battery.		HALOGEN LAMP	2.00
- Rotate And Balance All Tires.		BULB	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	262.61	Labor Charge:	615.00

Workorder: 1312736

Problem: Left headlight inop.

Meter Reading: 72849	Labor	Parts	
In Date: 12/20/2013	Hours	Description	
Close Date: 12/30/2013		Quantity	
- Test And Replace Failed Left Headlamp Bulb With New.Part Warranty,No Charge For Part.	0.50	HALOGEN LAMP	1.00
Parts Charge:	0.00	Labor Charge:	30.00

Workorder: 1401680

Problem: Right rear signal lamp bulb inop.

Meter Reading: 75523	Labor	Parts	
In Date: 02/20/2014	Hours	Description	
Close Date: 02/27/2014		Quantity	
- Replace Right Rear Signal Light Bulb And Socket.	0.50	STP TRN TL LGT SOCKET	1.00
		SIGNAL STOP LAMP	1.00
Parts Charge:	9.21	Labor Charge:	30.00

Workorder: 1402436

Problem: RF tire flat

Meter Reading: 75721	Labor	Parts	
In Date: 03/12/2014	Hours	Description	
Close Date: 03/12/2014		Quantity	
- Tire Service N Of Forest Hill On Woodland Ave, E Of Jog - Rf Tire Flat			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	46.40

1/30/2017
3:58:36PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170973 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1402437

Problem: tire

Meter Reading: 75721	Labor	Parts
In Date: 03/12/2014	Hours	Description
Close Date: 03/12/2014	Quantity	
- Tire Service Woodland Ave North Of Forest Hill Blvd - Tire		
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 200.06

Workorder: 1403573

Problem: Pm service.

Meter Reading: 77545	Labor	Parts
In Date: 04/11/2014	Hours	Description
Close Date: 04/21/2014	Quantity	
- Perform Pm Service.	7.25	WIPER BLADE
- Install Four New Tires.Nitrogen Fill And Balance All Four.		179636492 LT245-75R17
- Perform Wheel Alignment Complete.		5W20 ENGINE OIL
- Shop Supplies		TIRE DISPOSAL FEE
		SHOP SUPPLIES
		NAPAGOLD FUEL FILTER
		NAPAGOLD AIR FILTER
		WD40 16OZ
		USED FIRE X REFURBISHED
		NAPAGOLD OIL FILTER
Parts Charge: 1,062.21	Labor Charge: 435.00	

Workorder: 1404831

Problem: Left head lamp inop.

Meter Reading: 78414	Labor	Parts
In Date: 05/16/2014	Hours	Description
Close Date: 05/20/2014	Quantity	
- Test And Replace Failed Left Headlamp Seal Beam With New.	0.50	HALOGEN LAMP
Parts Charge: 9.87	Labor Charge: 30.00	

1/30/2017
3:58:36PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170973 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1410423

Problem: Pm service

Meter Reading: 83310	Labor	Parts	
In Date: 10/17/2014	Hours	Description	Quantity
- Pm Service.	7.50	WIPER BLADE	2.00
- Replace Rear Brake Pads And Two Rear Brake Calipers.Resurface Both Rear Brake Rotors.Flush And Bleed System.Test Drive.		PEDAL PAD	1.00
		NAPAGOLD OIL FILTER	1.00
- Rotate And Balance All Four Tires.		REMAN BRAKE CALIPER	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		REAR PADS	1.00
		REMAN BRAKE CALIPER	1.00
		1401 BRAKE FLUID BRA	1.00
		5W20 ENGINE OIL	7.00
Parts Charge:	271.00	Labor Charge:	450.00

Workorder: 1503899

Problem: Right rear turnsignal lamp inop.

Meter Reading: 88007	Labor	Parts	
In Date: 04/15/2015	Hours	Description	Quantity
- Test And Replace Defective Right Rear Turnsignal Lamp Bulb.	0.50	4057 BULB	1.00
Parts Charge:	3.23	Labor Charge:	30.00

Workorder: 1505205

Problem: Pm service.

Meter Reading: 88733	Labor	Parts	
In Date: 05/22/2015	Hours	Description	Quantity
- P.M. Service.	6.25	NAPAGOLD OIL FILTER	1.00
- Trailer Plug Inop.Replace Defective Trailer Plug.Repair Wiring.		FEMALE CONN SOCKET	1.00
		5W20 ENGINE OIL	7.00
- A/C Blower Inop.Replace Bad Blower Resistor.		SHOP SUPPLIES	1.00
- Rotate And Balance Tires.		NAPAGOLD AIR FILTER	1.00
- Shop Supplies		BLOWER RESISTOR	1.00
		WIPER BLADE	2.00
Parts Charge:	86.38	Labor Charge:	375.00

1/30/2017
3:58:36PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170973 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1509207

Problem: Towed in for no start.

Meter Reading: 92701		Labor		Parts	
In Date: 09/14/2015	Close Date: 09/28/2015	Hours	Description	Quantity	
-	Test Battery And Charging System.Replace Defective Battery.	1.00	BATTERY		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
Parts Charge:		120.41	Labor Charge:		60.00

Workorder: 1509263

Problem: no start

Meter Reading: 92263		Labor		Parts	
In Date: 09/14/2015	Close Date: 09/15/2015	Hours	Description	Quantity	
-	Tow From: Belved And Marine Drive To: Lv Shop				
Parts Charge:		0.00	Labor Charge:		0.00
			Commercial Charge:		104.15

Workorder: 1512284

Problem: Pm service.

Meter Reading: 94148		Labor		Parts	
In Date: 12/04/2015	Close Date: 12/16/2015	Hours	Description	Quantity	
-	Pm Service.	16.25	22" WIPER BLADE		2.00
-	Replace Two Tires.Rotate And Balance All Four.		WASHER FLUID CONCENTR		1.00
-	Computer Diagnose Misfire And Check Engine Light Flashing.Code P0300 And P0301.Perform Major Tune Up.Replace One Ignition Coil And All Eight Spark Plugs.		NAPAGOLD OIL FILTER		1.00
-	Perform Engine Decarb,Injectors Cleaning And Trottle Body Cleaning.		USED FIRE X REFURBISHED		1.00
-	Check And Inspect Binding Ignition Lock Cylinder.Replace Defective Key Cylinder And Recode To Key.		TIRE DISPOSAL FEE		2.00
-	Perform Complete Front End Alignment.		INJECTOR CLEANER		1.00
-	Shop Supplies		INTAKE CLEANER KIT		1.00
			INGITION LOCK		1.00
			179636492 LT245-75R17		2.00
			5W20 ENGINE OIL		7.00
			NAPAGOLD FUEL FILTER		1.00
			SHOP SUPPLIES		1.00
			COIL ASSEMBLY		1.00
			THROTTLE BODY CLEANER		1.00
			SPARK PLUG		8.00
Parts Charge:		925.60	Labor Charge:		975.00

1/30/2017
3:58:36PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170973 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1605733

Problem: P.M. service and check engine light runs rough and right headlight inop.

Meter Reading: 98280		Labor		Parts	
In Date: 06/03/2016	Close Date: 06/21/2016	Hours	Description		Quantity
-	P.M. Service.	9.25	TIRE DISPOSAL FEE		1.00
-	Replace Right Headlamp.		NAPAGOLD OIL FILTER		1.00
-	Diagnose Check Engine Light.P0300,P0302.Perform		SHOP SUPPLIES		1.00
-	Pinpoint Test.Replace Defective #2 Coil.Clear Codes.		22" WIPER BLADE		2.00
-	Replace Front Shocks.		COIL ASSEMBLY		1.00
-	Replace Two Tires,Rotate And Balance All Four.		WASHER FLUID CONCENTR		1.00
-	Shop Supplies		GAS GRANDE FLEET SHOC		2.00
			179636492 LT245-75R17		1.00
			HALOGEN LAMP		1.00
			5W20 ENGINE OIL		7.00
Parts Charge: 478.47		Labor Charge: 555.00			

Workorder: 1610821

Problem: Transition Prep Charge

Meter Reading: 100428		Labor		Parts	
In Date: 10/20/2016	Close Date: 10/20/2016	Hours	Description		Quantity
-	Transition Prep Charge	2.00			
Parts Charge: 0.00		Labor Charge: 0.00			

Total Parts Charges:	6,994.06	Total Labor Charges:	8,208.00	Total Comm. Charges:	713.15
----------------------	-----------------	----------------------	-----------------	----------------------	---------------