

1/30/2017  
3:59:38PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174395 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

<b>Workorder:</b> 839206	<b>Problem:</b> PRE-DELIVERY INSPECTION				
<b>Meter Reading:</b> 0		<b>Labor</b>	<b>Parts</b>		
<b>In Date:</b> 05/30/2008	<b>Close Date:</b> 05/30/2008	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Pre-Delivery Inspection		<b>2.00</b>			
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b>	120.00		

<b>Workorder:</b> 841249	<b>Problem:</b> CANCEIVER PROBLEM				
<b>Meter Reading:</b> 1793		<b>Labor</b>	<b>Parts</b>		
<b>In Date:</b> 07/11/2008	<b>Close Date:</b> 07/14/2008	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Ck Canceiver Connection And Repair		<b>1.50</b>	SHOP SUPPLIES		1.00
- Test Fuel					
- Shop Supplies					
	<b>Parts Charge:</b> 2.00	<b>Labor Charge:</b>	30.00		

<b>Workorder:</b> 845232	<b>Problem:</b> P.M. SERVICE.CHECK TRAILER PLUG.INSTALL BACK UPALARM.				
<b>Meter Reading:</b> 4990		<b>Labor</b>	<b>Parts</b>		
<b>In Date:</b> 10/06/2008	<b>Close Date:</b> 10/15/2008	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Pm Service		<b>5.75</b>	1372 OIL FILTER FRM PH2 WIX 51372		1.00
- Installed Backup Alarm Sys.Diagnose Trailer.Plug			5404 FEMALE CONNECTOR		1.00
Concern,R&Rdefective Trailer Plug And Rewire.			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
- Shop Supplies			5W20 ENGINE OIL		7.00
			9-2951 BACKUP ALARM ECCO 575 GROTE 73120		1.00
			SHOP SUPPLIES		1.00
	<b>Parts Charge:</b> 84.00	<b>Labor Charge:</b>	180.00		

<b>Workorder:</b> 935120	<b>Problem:</b> P.M SERVICE				
<b>Meter Reading:</b> 10003		<b>Labor</b>	<b>Parts</b>		
<b>In Date:</b> 03/13/2009	<b>Close Date:</b> 03/19/2009	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Pm Service		<b>3.75</b>	1372 OIL FILTER FRM PH2 WIX 51372		1.00
- Rotate And Hi Speed Balance 4 Tires.Nitrofill Tires.			5W20 ENGINE OIL		7.00
- Shop Supplies			SHOP SUPPLIES		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
	<b>Parts Charge:</b> 45.87	<b>Labor Charge:</b>	225.00		

1/30/2017  
3:59:38PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174395 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 937955

**Problem:** L/F HEAD LIGHT NOT WORKING

Meter Reading: 12588	Labor	Parts	
In Date: 05/19/2009	Hours	Description	Quantity
- Test Front Head Light Curcuits,Replace Blown L/F Head Lamp And Retest.	0.50	H6054 SEALED BEAM	1.00
<b>Parts Charge:</b> 7.20	<b>Labor Charge:</b> 30.00		

**Workorder:** 941446

**Problem:** pm service

Meter Reading: 14940	Labor	Parts	
In Date: 07/31/2009	Hours	Description	Quantity
- P.M Service.	7.25	TIRE DISPOSAL FEE	2.00
- Mount Two New Tires, Rotate & Balance All Four Tires.		TR416 VALVE STEM	2.00
- Alignment.		31-20 WIPER BLADES 20" BLADE	2.00
- Shop Supplies		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		5W20 ENGINE OIL	7.00
		SHOP SUPPLIES	1.00
		179636492 LT245/75R17 WRANGLER SR-A E	2.00
<b>Parts Charge:</b> 414.40	<b>Labor Charge:</b> 435.00		

**Workorder:** 947278

**Problem:** P.M service, check tires.

Meter Reading: 20000	Labor	Parts	
In Date: 12/23/2009	Hours	Description	Quantity
- P.M Service.	4.75	5W20 ENGINE OIL	7.00
- Mount Two New Tires, Rotate & Balance All Four Tires.		TIRE DISPOSAL FEE	2.00
- Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		SHOP SUPPLIES	1.00
		179636492 LT245/75R17 WRANGLER SR-A E	2.00
		TR416 VALVE STEM	2.00
<b>Parts Charge:</b> 392.91	<b>Labor Charge:</b> 570.00		

1/30/2017  
3:59:38PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174395 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1005242

**Problem:** P.M service.

<b>Meter Reading: 25000</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 05/20/2010</b>	<b>Close Date: 05/26/2010</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	P.M Service.	<b>2.75</b>	SHOP SUPPLIES		1.00
-	Shop Supplies		5W20 ENGINE OIL		7.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
<b>Parts Charge:</b>		41.50	<b>Labor Charge:</b>	165.00	

**Workorder:** 1006941

**Problem:** Left rear drivier's turn bulb out

<b>Meter Reading: 26412</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 07/01/2010</b>	<b>Close Date: 07/08/2010</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	C/C: Tail Light Out. R/R Tail Light Bulb.	<b>0.50</b>	3157 TAIL LIGHT BULBS		1.00
<b>Parts Charge:</b>		1.11	<b>Labor Charge:</b>	30.00	

**Workorder:** 1011368

**Problem:** P.M. service and canceiver.

<b>Meter Reading: 30000</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 10/14/2010</b>	<b>Close Date: 10/25/2010</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Perform Pm Service.	<b>5.25</b>	CA10262 AIR FILTER MTC FA1883 WIX 49883		1.00
-	Perform Transmissiom Flush And Renew Fluid.		7090BLK FRT FLOOR MATS (RUBBER QUEEN)		1.00
-	Rotate And Balance All Four Tires.		1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Shop Supplies		5W20 ENGINE OIL		7.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			SHOP SUPPLIES		1.00
			XT6QSP TRANS FLUID MERCON SP		7.00
			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
<b>Parts Charge:</b>		140.58	<b>Labor Charge:</b>	315.00	

1/30/2017  
3:59:38PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174395 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1011861                      **Problem:** flash canceiver / spot # 219

Meter Reading: 30006	Labor	Parts	
In Date: 10/22/2010	Hours	Description	
Close Date: 10/26/2010		Quantity	
- Flash Canceiver	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 60.00	

**Workorder:** 1013700                      **Problem:** Right rear tire has nail.

Meter Reading: 31374	Labor	Parts	
In Date: 12/14/2010	Hours	Description	
Close Date: 12/14/2010		Quantity	
- Repair Left Rear Tire And Balance Same.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 60.00	

**Workorder:** 1103236                      **Problem:** Pm service.

Meter Reading: 34973	Labor	Parts	
In Date: 03/24/2011	Hours	Description	
Close Date: 03/29/2011		Quantity	
- Perform Pm Service.	5.75	31-20 WIPER BLADES 20" BLADE	2.00
- Test Starting And Charging System.Battery Failed Load		GROUP 65 BATTERY (MTC BXT-65-850)	1.00
- Test After Recharge.Replace Failed Battery With New.		TIRE DISPOSAL FEE	2.00
- Install Two New Tires To The Front Wheels And Balance		5W20 ENGINE OIL	7.00
- All Four.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Shop Supplies		179636492 LT245/75R17 WRANGLER SR-A E	2.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b> 529.45		<b>Labor Charge:</b> 345.00	

1/30/2017  
3:59:38PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174395 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1108490

**Problem:** Pm service and blower inop on lower speed see notes.

<b>Meter Reading: 40017</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 08/11/2011</b>	<b>Close Date: 08/22/2011</b>	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	P.M. Service.	<b>5.75</b>	SHOP SUPPLIES		1.00
-	Test And Replace Failed A/C Blower Resistor.		5W20 ENGINE OIL		7.00
-	Replace Two Tires,Rotate And Balance All Four.		G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
-	Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			D3TZ2457B BRAKE PEDAL PAD		1.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			YH1715 A/C BLOWER RESISTOR (MOTORCRAFT)		1.00
			179636492 LT245/75R17 WRANGLER SR-A E		2.00
			TIRE DISPOSAL FEE		2.00
<b>Parts Charge: 445.02</b>		<b>Labor Charge: 345.00</b>			

**Workorder:** 1112362

**Problem:** Replace wiper blades due to overspray.

<b>Meter Reading: 42925</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 11/21/2011</b>	<b>Close Date: 11/22/2011</b>	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Clean Off Paint Over Spray From Windshield And Replace Both Damage Wiper Blades With New.	<b>0.50</b>	31-20 WIPER BLADES 20" BLADE		2.00
<b>Parts Charge: 9.98</b>		<b>Labor Charge: 30.00</b>			

**Workorder:** 1200725

**Problem:** P.M. Service.

<b>Meter Reading: 44905</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 01/24/2012</b>	<b>Close Date: 01/31/2012</b>	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Perform Pm Service.	<b>3.75</b>	SHOP SUPPLIES		1.00
-	Rotate And Balance All Four Tires.		1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Shop Supplies		5W20 ENGINE OIL		7.00
<b>Parts Charge: 22.56</b>		<b>Labor Charge: 225.00</b>			

1/30/2017  
3:59:38PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174395 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1201333                      **Problem:** l/turn signal inop.

Meter Reading: 45249	Labor	Parts	
In Date: 02/09/2012	Hours	Description	Quantity
- C/C: L/R Tail Light Out. Verify Bad Bulb. R&R Bulb, & Reassemble.	0.50	3157 TAIL LIGHT BULBS	1.00
<b>Parts Charge:</b> 0.65	<b>Labor Charge:</b> 30.00		

**Workorder:** 1205911                      **Problem:** Pm service.

Meter Reading: 50016	Labor	Parts	
In Date: 06/22/2012	Hours	Description	Quantity
- Perform Pm Service.	3.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Rotate And Balance All Four Tires.		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
- Shop Supplies		5W20 ENGINE OIL	7.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
		SHOP SUPPLIES	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
<b>Parts Charge:</b> 55.87	<b>Labor Charge:</b> 225.00		

**Workorder:** 1212244                      **Problem:** P.M. service.

Meter Reading: 55005	Labor	Parts	
In Date: 12/20/2012	Hours	Description	Quantity
- P.M. Service.	7.75	5W20 ENGINE OIL	7.00
- Replace Back Up Light Bulbs.		USED FIREX REFURBED F	1.00
- Replace Two Tires,Rotate And Balance All Four.		SHOP SUPPLIES	1.00
- Complete Wheel Alignment.Test Drive.		179636492 LT245-75R17	2.00
- Shop Supplies		TIRE DISPOSAL FEE	2.00
		PH2 OIL FILTER LBF PH	1.00
		31-20 WIPER BLADES 20	2.00
<b>Parts Charge:</b> 545.79	<b>Labor Charge:</b> 465.00		

1/30/2017  
3:59:38PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174395 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1301569                      **Problem:** LEFT REAR SIGNAL LIGHT INOP.

Meter Reading: 56145	Labor	Parts
In Date: 02/13/2013	Hours	Description
Close Date: 02/21/2013		Quantity
- Repair L Rear Signal Light	<b>0.50</b>	MINIATURE BULB
		1.00
<b>Parts Charge:</b> 0.72	<b>Labor Charge:</b> 30.00	

**Workorder:** 1303443                      **Problem:** L/REAR SIGNAL LIGHT INOP.

Meter Reading: 57629	Labor	Parts
In Date: 04/09/2013	Hours	Description
Close Date: 04/10/2013		Quantity
- Rr Left Rear Signal Bulb	<b>0.50</b>	BULB
		1.00
<b>Parts Charge:</b> 0.99	<b>Labor Charge:</b> 30.00	

**Workorder:** 1306120                      **Problem:** Pm service

Meter Reading: 60000	Labor	Parts
In Date: 06/19/2013	Hours	Description
Close Date: 06/27/2013		Quantity
- Perform Pm Service.	<b>11.05</b>	5W20 ENGINE OIL
		7.00
- Inspect And Replace Failed Right Radiator Support To Frame Upper And Lower Mounts With New.		NAPAGOLD OIL FILTER
		1.00
		NAPAGOLD FUEL FILTER
		1.00
- Diagnose For Misfire.Test And Replace All Failed Eight Spark Plugs With New And Perform Tune Up.		KA8A THROTTLE BODY- U
		1.00
		408 FUEL INJECTION CL
		1.00
- Perform Induction Service.Power Flush All Fuel Injectors And Fuel Lines.Clean Trottle Body.Clear Codes With Scan Tool And Road Test.		INSULATOR
		1.00
		179636492 LT245-75R17
		2.00
		SHOP SUPPLIES
		1.00
- Install Two New Tires To The Front Wheels Nitrogen Fill And Balance All Four.		TIRE DISPOSAL FEE
		2.00
		SPARK PLUG
		8.00
- Shop Supplies		INSUALTOR
		1.00
<b>Parts Charge:</b> 768.72	<b>Labor Charge:</b> 663.00	

**Workorder:** 1307256                      **Problem:** damage to rgt rear fender, bumper & tail gate

Meter Reading: 60058	Labor	Parts
In Date: 06/26/2013	Hours	Description
Close Date: 07/22/2013		Quantity
- Damage To Rgt Rear Fender, Bumper & Tail Gate		
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 1,005.00

1/30/2017  
3:59:38PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174395 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1307531

**Problem:** wipers notd working

Meter Reading: 60347	Labor	Parts	Quantity
In Date: 07/29/2013	Hours	Description	Quantity
- Ck Wipers Not Working Verify Concern Perform Pinpoint Test Trace Wire Harness And Found Corrosion On Fuse Connetor Clean Corrosion And Replace Fuse	2.50	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	150.00

**Workorder:** 1400303

**Problem:** Pm service and has problem to refuel.Nozzle keeps tripping

Meter Reading: 65878	Labor	Parts	Quantity
In Date: 01/09/2014	Hours	Description	Quantity
- P.M. Service.	6.25	GAS CAP	1.00
- Check Hard To Fuel Complain.Replace Fuel Filler Tube Assemble And Charcoal Canister Per Tsb.Replace Fuel Cap.		SHOP SUPPLIES	1.00
		CH CANNISTER FILTER	1.00
		GAS CAP	1.00
- Rotate And Balance All Tires.		2015LPA STROBE ASSY A	1.00
- Shop Supplies		PIEPE	1.00
		USED FIRE X REFURBISHED	1.00
		WIPER BLADE	2.00
		NAPAGOLD OIL FILTER	1.00
		5W20 ENGINE OIL	7.00
<b>Parts Charge:</b>	462.65	<b>Labor Charge:</b>	375.00



1/30/2017  
3:59:38PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174395 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1409998

**Problem:** Pm service.

Meter Reading: 73247 In Date: 10/03/2014	Close Date: 10/17/2014	Labor Hours	Description	Parts	Quantity
- Pm Service.		<b>6.75</b>	NAPAGOLD AIR FILTER		1.00
- Check Battery And Charging System.Battery Failed			NAPAGOLD FUEL FILTER		1.00
- Loadtest.Replace Bad Battery.			USED FIRE X REFURBISHED		1.00
- Pressure Test And Inspect Cooling System.Flush And			NAPAGOLD OIL FILTER		1.00
- Refill Coolant.			MAC WITE LITHIUM GRES		1.00
- Rotate And Balance All Four Tires.			BATTERY		1.00
- Shop Supplies			PEAK GLOBAL		2.00
			WIPER BLADE		2.00
			WHL/COVR		1.00
			PEDAL PAD		1.00
			5W20 ENGINE OIL		7.00
			SHOP SUPPLIES		1.00
<b>Parts Charge:</b>		242.61	<b>Labor Charge:</b>		405.00

**Workorder:** 1412559

**Problem:** Towed in. Will not crank.No start.

Meter Reading: 74757 In Date: 12/16/2014	Close Date: 12/24/2014	Labor Hours	Description	Parts	Quantity
- Diagnose For No Crank.Test And Replace Defective		<b>1.25</b>	SHOP SUPPLIES		1.00
- Starter Motor Assembly.			STARTER		1.00
- Shop Supplies					
<b>Parts Charge:</b>		214.94	<b>Labor Charge:</b>		75.00

**Workorder:** 1412593

**Problem:** No start being towed to WPB Fleet

Meter Reading: 74596 In Date: 12/16/2014	Close Date: 12/17/2014	Labor Hours	Description	Parts	Quantity
- Tow From: 2100 Emerald Dunes Dr. To: Lv Shop					
<b>Parts Charge:</b>		0.00	<b>Labor Charge:</b>		0.00
			<b>Commercial Charge:</b>		104.15

1/30/2017  
3:59:38PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174395 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1505208

**Problem:** Pm service.

Meter Reading: 77680	Labor	Parts	
In Date: 05/22/2015	Hours	Description	Quantity
- Pm Service.	19.25	5W20 ENGINE OIL	7.00
- Replace Two Tires.Rotate And Balance All Four.		NAPAGOLD OIL FILTER	1.00
- Resurface Front And Rear Brake Rotors.Replace Both		WIPER BLADE	2.00
Front And Rear Brake Calipers And Pads.Flush And		179636492 LT245-75R17	2.00
Bleed System.		TR416 VALVE STEM	2.00
- Replace Four Failed Rear Body Mounts.		TIRE DISPOSAL FEE	2.00
- Complete Front Wheel Alignment.		Caliper w/ Hardware - Left Front (Eclips	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		BRAKE CLEANER	3.00
		Caliper w/ Hardware - Right Front (Eclip	1.00
		BODY MOUNT KIT	4.00
		PADS	1.00
		Caliper w/ Hardware - Right Rear (Eclips	1.00
		REAR PADS	1.00
		1401 BRAKE FLUID BRA	4.00
		Caliper w/ Hardware - Left Rear (Eclipse	1.00
<b>Parts Charge:</b>	1,415.26	<b>Labor Charge:</b>	1,155.00

**Workorder:** 1605766

**Problem:** P.M. service.

Meter Reading: 84480	Labor	Parts	
In Date: 06/03/2016	Hours	Description	Quantity
- P.M. Service.	6.25	PIGTAIL SOCKET	1.00
- Replace Two Tires,Rotate And Balance All Four.		20mr8 12 v fl23	1.00
- Replace Rear Bump Stoppers.		5W20 ENGINE OIL	7.00
- Replace Left Front Strobe Light.Fabricate And Rewire.		NAPAGOLD OIL FILTER	1.00
- Shop Supplies		20" WIPER BLADE	2.00
		NAPAGOLD AIR FILTER	1.00
		WASHER FLUID CONCENTR	1.00
		179636492 LT245-75R17	2.00
		USED FIRE X REFURBISHED	1.00
		TIRE DISPOSAL FEE	2.00
		NAPAGOLD FUEL FILTER	1.00
		SHOP SUPPLIES	1.00
		BUMPER	2.00
<b>Parts Charge:</b>	682.58	<b>Labor Charge:</b>	375.00

1/30/2017  
3:59:38PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174395 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1611059

**Problem:** Transition Prep Charge

**Meter Reading:** 86020

**Labor**

**Parts**

**In Date:** 10/26/2016

**Close Date:** 10/26/2016

**Hours**

**Description**

**Quantity**

---

- Transition Prep Charge

**2.00**

**Parts Charge:** 0.00

**Labor Charge:** 0.00

Total Parts Charges: **6,533.36**

Total Labor Charges: **7,143.00**

Total Comm. Charges: **1,109.15**