

1/30/2017  
4:03:32PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174399 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 838288                      **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 05/09/2008	Hours	Description
Close Date: 05/09/2008	Quantity	
- Pre-Delivery Inspection	<b>2.00</b>	
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 120.00	

**Workorder:** 840939                      **Problem:** INSTALL SPOT MIRRORS.

Meter Reading: 2209	Labor	Parts
In Date: 07/07/2008	Hours	Description
Close Date: 07/08/2008	Quantity	
- Install 2 New Spot Mirrors As Per Operator'S Request.	<b>0.50</b>	7039D SPOT MIRROR VELVAC 723060
<b>Parts Charge:</b> 3.66	<b>Labor Charge:</b> 30.00	2.00

**Workorder:** 843991                      **Problem:** RIGHT FRONT TIRE FLAT

Meter Reading: 4200	Labor	Parts
In Date: 09/10/2008	Hours	Description
Close Date: 09/12/2008	Quantity	
- Repair Rear Fron Tire. Patch And Balance	<b>1.00</b>	SHOP SUPPLIES
- Shop Supplies		1.00
<b>Parts Charge:</b> 2.00	<b>Labor Charge:</b> 60.00	

**Workorder:** 845925                      **Problem:** PM SERVICE

Meter Reading: 5558	Labor	Parts
In Date: 10/20/2008	Hours	Description
Close Date: 11/07/2008	Quantity	
- Pm Service	<b>8.25</b>	1372 OIL FILTER FRM PH2 WIX 51372
- Rotate & High Speed Balance All 4 Tires.Nitro Fill Tires.		G10166 FUEL FILTER MTC FG1083 WIX 33243
- Rtrain Pressure Sensors.		FLOOR MAT SET
- Hole In D/S Floor Mat.Remove Computer Stand & All		CA10262 AIR FILTER MTC FA1883 WIX 49883
- Accessories& Equipment To Get Ready To Send To		1066 WHITE LITHIUM (CRC 05037)
- Dealer,Reinstall After Repairs		SHOP SUPPLIES
- To/Fr Dealer For Warranty Floor Mat.		5W20 ENGINE OIL
- Shop Supplies		1.00
<b>Parts Charge:</b> 111.10	<b>Labor Charge:</b> 120.00	1.00

1/30/2017  
4:03:32PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174399 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 934646                      **Problem:** 002 KEYS ISSUED OUT                      03/02/09

Meter Reading: 0		Labor	Parts	
In Date: 03/02/2009	Close Date: 03/02/2009	Hours	Description	Quantity
- 002 Keys Issued Out	03/02/09	0.40	DUPLICATE VEHICLE KEYS	2.00
	<b>Parts Charge:</b> 6.00	<b>Labor Charge:</b> 24.00		

**Workorder:** 935505                      **Problem:** R/F TIRE FLAT

Meter Reading: 9362		Labor	Parts	
In Date: 03/24/2009	Close Date: 03/25/2009	Hours	Description	Quantity
- Dismount Spare Tire To Mount On R/F Wheel, Mount New Tire On Spare, Hi Speed Balance & Nitro Fill 2 Tires.		1.50	TR416 VALVE STEM	2.00
- Shop Supplies			SHOP SUPPLIES	1.00
			748636189 245/75R17 WRG SLT ARMOUR E	1.00
			TIRE DISPOSAL FEE	1.00
	<b>Parts Charge:</b> 205.88	<b>Labor Charge:</b> 90.00		

**Workorder:** 936723                      **Problem:** TIRESOLES OF BROWARD INC

Meter Reading: 0		Labor	Parts	
In Date: 03/23/2009	Close Date: 04/20/2009	Hours	Description	Quantity
- Tiresoles Of Broward Inc				
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 54.00	

**Workorder:** 937707                      **Problem:** P.M. SERVICE.

Meter Reading: 10890		Labor	Parts	
In Date: 05/13/2009	Close Date: 05/15/2009	Hours	Description	Quantity
- Pm Service		3.75	SHOP SUPPLIES	1.00
- Rotate & Hi Speed Balance All 4 Tires. Nitro Fill All Tires To Specs.			5W20 ENGINE OIL	7.00
- Shop Supplies			USED FIREX REFURBED FIRE EXTINGSHERS	1.00
			1372 OIL FILTER FRM PH2 WIX 51372	1.00
	<b>Parts Charge:</b> 35.00	<b>Labor Charge:</b> 225.00		

1/30/2017  
4:03:32PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174399 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 940061

**Problem:** install comp harness

<b>Meter Reading:</b> 12322	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 07/02/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Fabricate & Install Customers Computer Wire Harness	<b>1.50</b>	80865 FUSEHOLDER IMPERIAL 80865	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	8.98	<b>Labor Charge:</b>	90.00

**Workorder:** 941460

**Problem:** keys

<b>Meter Reading:</b> 13299	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 07/31/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Keys		5P8500 KEY	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	9.53	<b>Labor Charge:</b>	0.00

**Workorder:** 946073

**Problem:** P.M service, see notes.

<b>Meter Reading:</b> 16425	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 11/17/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- P.M Service.	<b>8.05</b>	3157 TAIL LIGHT BULBS	2.00
- Test & Replace Rear Turn Signal Bulbs.		TIRE DISPOSAL FEE	4.00
- Replace Missing Pintal Safety Pin.		18410 PINTLE PIN	1.00
- Mount, Balance & Nitro Fill Four New Tires.		179636492 LT245/75R17 WRANGLER SR-A E	4.00
- Alignment.		31-20 WIPER BLADES 20" BLADE	2.00
- Shop Supplies		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		5W20 ENGINE OIL	7.00
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
		TR416 VALVE STEM	4.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	803.01	<b>Labor Charge:</b>	966.00

1/30/2017  
4:03:32PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174399 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1006101

**Problem:** P.M. Service.

<b>Meter Reading:</b> 22176	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 06/09/2010	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Perform Pm Service.	<b>3.75</b>	5W20 ENGINE OIL	7.00
- Rotate And Balance All All Four Tires.		31-20 WIPER BLADES 20" BLADE	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
<b>Parts Charge:</b>	41.03	<b>Labor Charge:</b>	225.00

**Workorder:** 1011209

**Problem:** Check engine light on, also see notes on radio volume control.

<b>Meter Reading:</b> 26134	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 10/12/2010	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Transport Vehicle To Dealer For Battery And Radio Replacement Under Warranty.	<b>2.00</b>	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	60.00

**Workorder:** 1011876

**Problem:** flash canceiver spot # 175

<b>Meter Reading:</b> 26144	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 10/25/2010	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Flash Canceiver	<b>1.00</b>	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	60.00

1/30/2017  
4:03:32PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174399 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1100407

**Problem:** Pm service also see notes on trailer plug.

Meter Reading: 28449	Labor	Parts	
In Date: 01/11/2011	Hours	Description	Quantity
- Perform Pm Service.	7.25	5W20 ENGINE OIL	7.00
- Diagnose Trailer Plug Concern.Fabricate And Repaired		1372 OIL FILTER FRM PH2 WIX 51372	1.00
Damage Wiring Harness.Also Install New Plug		31-20 WIPER BLADES 20" BLADE	2.00
Receptacle.Fabricate And Install New Hitch Pindel Pin		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
And Secure.		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
- Inspect And Service Transmission.Flush And Renew		SYN/ATF TRANS FLUID SYNTHETIC	12.00
Fluid.		5404 FEMALE CONNECTOR	1.00
- Rotate And Balance All Four Tires.		SHOP SUPPLIES	1.00
- Shop Supplies		18410 PINTLE PIN	1.00
<b>Parts Charge:</b> 108.77		<b>Labor Charge:</b> 435.00	

**Workorder:** 1102530

**Problem:** Left rear brake light inop.

Meter Reading: 29920	Labor	Parts	
In Date: 03/07/2011	Hours	Description	Quantity
- Test And Replace Failed Left Rear Brake Lamp Bulb With	0.50	3157 TAIL LIGHT BULBS	1.00
New.			
<b>Parts Charge:</b> 1.19		<b>Labor Charge:</b> 30.00	

**Workorder:** 1105424

**Problem:** Left rear turn signal inop and left rear tire has a nail in it.

Meter Reading: 31820	Labor	Parts	
In Date: 05/23/2011	Hours	Description	Quantity
- Replace Left Rear Signal Light Bulb.	1.50	3157 TAIL LIGHT BULBS	1.00
- Repair And Balance Left Rear Tire.		SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 3.20		<b>Labor Charge:</b> 90.00	

1/30/2017  
4:03:32PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174399 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1106171                      **Problem:** Left rear tire flat.

Meter Reading: 32152	Labor	Parts	Quantity
In Date: 06/10/2011	Hours	Description	
- Repair Flat Left Rear Tire.Nitrogen Fill And Balance Same.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 60.00	

**Workorder:** 1108964                      **Problem:** flat tire put spare on or tow

Meter Reading: 34219	Labor	Parts	Quantity
In Date: 06/08/2011	Hours	Description	
- From: 8100 Forest Hill Croc			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00	
		<b>Commercial Charge:</b> 66.00	

**Workorder:** 1109941                      **Problem:** P.M. service and check tires.

Meter Reading: 34973	Labor	Parts	Quantity
In Date: 09/19/2011	Hours	Description	
- P.M. Service.	8.75	5W20 ENGINE OIL	7.00
- Replace And Balance All Four Tires.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Replace Extinguisher Bracket.		AMBER STROBE ASSY	1.00
- Replace Center Brake Light Bulb And Right Alley Light In		179636492 LT245/75R17 WRANGLER SR-A E	4.00
Light Bar.		TIRE DISPOSAL FEE	4.00
- Complete Wheel Alignment.		31-20 WIPER BLADES 20" BLADE	2.00
- Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		05023 BATTERY CLEANER	1.00
		SHOP SUPPLIES	1.00
		CUSTOM5LB BRACKET FIREX STOCK #340060300	1.00
<b>Parts Charge:</b> 899.94		<b>Labor Charge:</b> 525.00	

**Workorder:** 1113025                      **Problem:** Left brake lamp inop.

Meter Reading: 37819	Labor	Parts	Quantity
In Date: 12/09/2011	Hours	Description	
- Test And Replace Failed Left Brake Lamp Bulb With New.	0.50	3157 TAIL LIGHT BULBS	1.00
<b>Parts Charge:</b> 0.61		<b>Labor Charge:</b> 30.00	

1/30/2017  
4:03:32PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174399 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1200116

**Problem:** 1 - Key(s) issued

Meter Reading: 38797	Labor	Parts	
In Date: 01/04/2012	Hours	Description	Quantity
- 1 - Key(S) Issued	0.20	DUPLICATE VEHICLE KEYS	1.00
<b>Parts Charge:</b> 3.00	<b>Labor Charge:</b> 18.00		

**Workorder:** 1200366

**Problem:** P.M. service and check engine light on and blower speed control inop.

Meter Reading: 39053	Labor	Parts	
In Date: 01/11/2012	Hours	Description	Quantity
- P.M. Service.	8.75	FUEL PUMP ASSY	1.00
- Check A/C Blower Operation.Diagnose And Replaced Failed Blower Resistor.		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
		5W20 ENGINE OIL	7.00
- Diagnose Check Engine Light.Perform Fuel Pressure Test.Replace Fuel Pump And Refill Fuel Tank Clear Codes And Test Drive.		YH1715 A/C BLOWER RESISTOR (MOTORCRAFT)	1.00
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
- Rotate And Balance All Tires.		31-20 WIPER BLADES 20" BLADE	2.00
- Replace Missing Asset # On Front.		SHOP SUPPLIES	1.00
- Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372	1.00
<b>Parts Charge:</b> 484.23	<b>Labor Charge:</b> 525.00		

**Workorder:** 1206608

**Problem:** P.M. Service.

Meter Reading: 45014	Labor	Parts	
In Date: 07/16/2012	Hours	Description	Quantity
- P.M. Service.	3.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Rotate And Balance All Tires.		31-20 WIPER BLADES 20" BLADE	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
		5W20 ENGINE OIL	7.00
<b>Parts Charge:</b> 32.05	<b>Labor Charge:</b> 225.00		

1/30/2017  
4:03:32PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174399 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1301286

**Problem:** P.M. service and tire pressure light on.

Meter Reading: 52018	Labor	Parts	
In Date: 02/05/2013	Hours	Description	Quantity
- P.M. Service.	5.25	SHOP SUPPLIES	1.00
- Test Battery And Charging System.Replace Bad Battery.		1372 OIL FILTER	1.00
- Replace Left Headlamp.		NAPAGOLD FUEL FILTER	1.00
- Rotate And Balance All Tires.		BATTERY 65	1.00
- Shop Supplies		brake pedal pad	1.00
		HALOGEN LAMP	1.00
		USED FIREX REFURBED F	1.00
		5W20 ENGINE OIL	7.00
		31-20 WIPER BLADES 20	2.00
<b>Parts Charge:</b>	225.35	<b>Labor Charge:</b>	315.00

**Workorder:** 1306552

**Problem:** Right rear tire flat.

Meter Reading: 56006	Labor	Parts	
In Date: 07/01/2013	Hours	Description	Quantity
- Repair And Balance Right Rear Tire.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	60.00

**Workorder:** 1306701

**Problem:** Winch out

Meter Reading: 56006	Labor	Parts	
In Date: 06/29/2013	Hours	Description	Quantity
- Tow From: Southern Blvd West Of Palms West			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00



1/30/2017  
4:03:32PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174399 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1309349

**Problem:** P.M. service.

Meter Reading: 59673	Labor	Parts	Quantity
In Date: 09/16/2013	Hours	Description	Quantity
- P.M. Service.	<b>19.50</b>	5W20 ENGINE OIL	7.00
- Replace Belt Tensioner And Serpentine Belt.		HALOGEN LAMP	1.00
- Replace Leaking A/C High Pressure Hose.Vacuum And Recharge System Yo Specs.		31-20 WIPER BLADES 20	2.00
- Replace Right Head Lamp.		SHOP SUPPLIES	1.00
- Resurface Front And Rear Brakes Rotors,Replace Front And Rear Brake Pads.Service And Lube All Four Calipers,Flush And Bleed System And Test Drive.		NAPAGOLD OIL FILTER	1.00
- Replace And Balance Four New Tires.		BELT TENSIONER	1.00
- Complete Wheel Alignment.Test Drive.		TR416 VALVE STEM	4.00
- Shop Supplies		PADS	1.00
		LT245/75R17 HANKOOK TIRE	4.00
		TUBE ASY	1.00
		R134A LV SHOP 1	2.00
		REAR PADS	1.00
		PULLEY	1.00
		2232 BRAKE FLUID QUAR	2.00
		BELT	1.00
		BRAKE CLEANER	1.00
		TIRE DISPOSAL FEE	4.00
<b>Parts Charge:</b>	1,441.94	<b>Labor Charge:</b>	1,170.00

**Workorder:** 1403124

**Problem:** P.M. service.

Meter Reading: 65736	Labor	Parts	Quantity
In Date: 03/31/2014	Hours	Description	Quantity
- P.M. Service.	<b>5.00</b>	SEAT R AND R	1.00
- Replace Center Brake Light Bulb.		NAPAGOLD OIL FILTER	1.00
- R&R Front Seat For Repairs.		NAPAGOLD FUEL FILTER	1.00
- Rotate And Balance All Tires.		NAPAGOLD AIR FILTER	1.00
- Shop Supplies		BULB	1.00
		USED FIRE X REFURBISHED	1.00
		WIPER BLADE	2.00
		SHOP SUPPLIES	1.00
		5W20 ENGINE OIL	7.00
<b>Parts Charge:</b>	682.09	<b>Labor Charge:</b>	300.00

1/30/2017  
4:03:32PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174399 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1410052

**Problem:** P.M. service and check wiper blades.

Meter Reading: 72387	Labor	Parts	Quantity
In Date: 10/06/2014	Hours	Description	Quantity
- Pm Service.	<b>11.75</b>	NAPAGOLD OIL FILTER	1.00
- Perform Injectors Cleaning And Engine Decarb.Perform		SUPPORT	2.00
- Trottle Body Cleaning.		WIPER BLADE	2.00
- Computer Diagnose For Misfire.Fail Code P0300.Replace		SPARK PLUG	8.00
- Eight Sparkplugs.Clear Code And Road Test.		5W20 ENGINE OIL	7.00
- Replace Both Leaking Tool Box Struts/Shocks.		SPARK PLUG	8.00
- Rotate And Balance All Four Tires.		KA8A THROTTLE BODY- U	1.00
- Shop Supplies		408 FUEL INJECTION CL	1.00
		SHOP SUPPLIES	1.00
		WASHER FLUID CONCENTR	1.00
		SUPPORT	2.00
<b>Parts Charge:</b>	264.22	<b>Labor Charge:</b>	705.00

**Workorder:** 1505115

**Problem:** Pm service.Has to jump start.

Meter Reading: 74499	Labor	Parts	Quantity
In Date: 05/20/2015	Hours	Description	Quantity
- Pm Service.	<b>10.25</b>	PEAK GLOBAL	2.00
- Test And Replace Defective Battery.		5W20 ENGINE OIL	7.00
- Pressure Test And Inspect Cooling System.Flush And		USED FIRE X REFURBISHED	1.00
- Refill.		SHOP SUPPLIES	1.00
- Service Rear Differential.		WIPER BLADE	2.00
- Replace Two Front Body Mounts.		NAPAGOLD OIL FILTER	1.00
- Rotate And Balance All Four Tires.		FRICTION MODIFIER	1.00
- Shop Supplies		BODY MOUNT KIT	2.00
		75W140 FORD AXLE LUBE	4.00
		BATTERY	1.00
		NAPAGOLD FUEL FILTER	1.00
<b>Parts Charge:</b>	466.01	<b>Labor Charge:</b>	615.00

1/30/2017  
4:03:32PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174399 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1506684

**Problem:** Right rear tire has nail.

<b>Meter Reading:</b> 76227	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 07/06/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Repair And Balance Right Rear Tire.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	60.00

**Workorder:** 1511267

**Problem:** Pm service.

<b>Meter Reading:</b> 82625	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 11/03/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Pm Service.	9.25	179636492 LT245-75R17	4.00
- Replace And Balance All Four Tires.		bumper	2.00
- Replace Defective Trailer Harness Connector And Rewire.		22" WIPER BLADE	2.00
- Replace Both Defective Front Suspension Bump Stops.		REAL SUSPENSION BUMPSTOPS	2.00
- Replace Both Defective Rear Suspension Bump Stops.		TIRE DISPOSAL FEE	4.00
- Complete Front End Alignment And Road Test.		5W20 ENGINE OIL	7.00
- Shop Supplies		SHOP SUPPLIES	1.00
		FEMALE CONN SOCKET	1.00
		WASHER FLUID CONCENTR	1.00
		NAPAGOLD OIL FILTER	1.00
<b>Parts Charge:</b>	1,184.41	<b>Labor Charge:</b>	555.00

**Workorder:** 1512014

**Problem:** Left headlamp inop.

<b>Meter Reading:</b> 83172	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 11/30/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Replace Failed Left Headlamp Seal Beam.	0.50	HALOGEN LAMP	1.00
<b>Parts Charge:</b>	12.41	<b>Labor Charge:</b>	30.00

1/30/2017  
4:03:32PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174399 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

**Workorder:** 1607127

**Problem:** P.M. service.

<b>Meter Reading:</b> 88093		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 07/14/2016	<b>Close Date:</b> 07/26/2016	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	P.M. Service.	<b>4.25</b>	WD40 16OZ		1.00
-	Replace Both Washer Nozzles.		WASHER NOZZLE		2.00
-	Rotate And Balance All Tires.		22" WIPER BLADE		2.00
-	Shop Supplies		NAPAGOLD OIL FILTER		1.00
			USED FIRE X REFURBISHED		1.00
			5W20 ENGINE OIL		7.00
			NAPAGOLD AIR FILTER		1.00
			SHOP SUPPLIES		1.00
<b>Parts Charge:</b> 76.89		<b>Labor Charge:</b> 255.00			

**Workorder:** 1610988

**Problem:** Transition Prep Charge

<b>Meter Reading:</b> 88938		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 10/25/2016	<b>Close Date:</b> 10/25/2016	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Transition Prep Charge	<b>2.00</b>			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00			

Total Parts Charges:	<b>7,122.50</b>	Total Labor Charges:	<b>8,073.00</b>	Total Comm. Charges:	<b>120.00</b>
----------------------	-----------------	----------------------	-----------------	----------------------	---------------