Norkorder: 738616	Problem:	PRE-DE	LIVERY INSPECTIC	DN		
Meter Reading: 0			Labor		Parts	
In Date: 05/14/2007	Close Date: 05/14/	/2007	Hours	Description		Quantity
- Pre-Delivery Inspection			2.00			
	Parts Charge:	0.00	Labor Charge:	110.00		
Norkorder: 747768	Problem:	P.M SEF	RVICE			
Meter Reading: 1481			Labor		Parts	
In Date: 11/27/2007	Close Date: 11/28/	/2007	Hours	Description		Quantity
- Pm Service			<b>2.00</b> 1	10020 INJECTOR CLEANER [	DON'T REORDER	1.00
<ul> <li>Shop Supplies</li> </ul>				5W20 ENGINE OIL		5.00
			F	FL2017B OIL FILTER		1.00
			S	SHOP SUPPLIES		1.00
	Parts Charge:	25.87	Labor Charge:	120.00		
Norkorder: 839390	Problem:	P.M. SE	RVICE.			
Meter Reading: 2470			Labor		Parts	
In Date: 06/03/2008	Close Date: 06/05/	/2008	Hours	Description		Quantity
- Pm Service Complete			4.00	SHOP SUPPLIES		1.00
- Replaced Defective Valve	e Stems On All 4 Tires. Hi	iqh	3	3296 FUEL FILTER FRM G38	350	1.00
Speed Balance All Four 1		•	F	L-2017B OIL FILTER FORD	MOTORCRAFT ONLY	1.00
- Shop Supplies			5	5W20 ENGINE OIL		5.00
F F F		23.06		90.00		

orkorder: 847545 Meter Reading: 3153	Probl	em: P.IVI. SE	RVICE.REPAIR FI	LAT TIRE.	Parts	
In Date: 12/01/2008	Close Date: 12	2/09/2008	Hours	Description		Quantity
- Pm Service			4.00	CA10170 AIR FILTER LBF AF360	01 WIX 49187	1.00
- Mount 1 New Tire On Righ	t Rear.Rotate & Hig	h Speed		5W20 ENGINE OIL		5.00
Balance All 4 Tires.Nitro Fi	II All To Specs.			3296 FUEL FILTER FRM G3850	0	1.00
- Shop Supplies	I.			687492170 235/70R16 FORTER	RA USE 183407418	1.00
				SHOP SUPPLIES		1.00
				TIRE DISPOSAL FEE		1.00
				FL-2017B OIL FILTER FORD/MC	DTORCRAFT ONLY	1.00
	Parts Charge:	170.39	Labor Charge	<b>e:</b> 120.00		

Workorder: 938621	Proble	em: P.M SER	RVICE.		
Meter Reading: 3742			Labor	Parts	
In Date: 06/04/2009	Close Date: 06	/11/2009	Hours	Description	Quantity
- Pm Service			3.00	SHOP SUPPLIES	1.00
- Rotate And Hi Speed Bala	nce 4 Tires. Fill W/N	itrogen.		FL-2017B OIL FILTER FORD/MOTORCRAFT O	ONLY 1.00
<ul> <li>Shop Supplies</li> </ul>				5W20 ENGINE OIL	5.00
				WW-1202 WIPER BLADE (MOTORCRAFT)	1.00
				WW-2046 WIPER BLADE (MOTORCRAFT)	2.00
	Parts Charge:	68.80	Labor Charge	e: 180.00	

Norkorder: 1000127	Proble	em: P.M service	e.		
Meter Reading: 4132			Labor	Parts	
In Date: 01/05/2010	Close Date: 01	/12/2010	Hours	Description	Quantity
- P.M Service.			4.00	5W20 ENGINE OIL	5.00
- Mount Two New Tires, Rota	ate & Balance All Fo	our Tires.		SHOP SUPPLIES	1.00
- Shop Supplies				FL-2017B OIL FILTER FORD/MOTORCRAFT C	DNLY 1.00
				TIRE DISPOSAL FEE	2.00
				3296 FUEL FILTER FRM G3850	1.00
				WW-2046 WIPER BLADE (MOTORCRAFT)	2.00
				183407418 P235/70R16 WRANGLER SR-A 10	4S 2.00
	Parts Charge:	343.88	Labor Charg	<b>e:</b> 240.00	

#### Asset: K11807 2008 FORD ESCAPE Suv, Mid Size, Hybrid

Workorder: 1008745	Problem: Pm service. Also check engine light on and engine runs rough.						
Meter Reading: 4674			Labor	Par	rts		
In Date: 08/13/2010	Close Date: 08	/30/2010	Hours	Description	Quantity		
- P.M. Service.			4.00	5W20 ENGINE OIL	5.00		
- Transport Vehicle To Deal	er For Warranty Rep	airs(Failed		FL-2017B OIL FILTER FORD/MOTORCRAF			
Injectors.)				SHOP SUPPLIES	1.00		
<ul> <li>Shop Supplies</li> </ul>							
	Parts Charge:	18.91	Labor Charge	: 180.00			

#### Workorder: 1103460 Problem: Pm service.

Meter Reading: 5142		Labor	Parts	
In Date: 03/31/2011	Close Date: 04/07/2011	Hours	Description	Quantity
- Perform Pm Service.		3.00	SHOP SUPPLIES	1.00
<ul> <li>Rotate And Balance All For</li> </ul>	our Tires.		5W20 ENGINE OIL	5.00
<ul> <li>Shop Supplies</li> </ul>			WW-2046 WIPER BLADE (MOTORCRAFT)	2.00
			09997 BRAKE CLEAN	1.00
			DRIVER DOOR HANDLE ACCESS COVER	1.00
			WW-1202 WIPER BLADE (MOTORCRAFT)	1.00
			FL-2017B OIL FILTER FORD/MOTORCRAFT ONLY	1.00
	Parts Charge: 6.00	D Labor Charg	g <b>e:</b> 180.00	

Workorder: 1110399	Proble	em: P./M. Ser	vice.			
Meter Reading: 5588			Labor		Parts	
In Date: 09/29/2011	Close Date: 10	/06/2011	Hours	Description		Quantity
- P.M. Service.			3.00	FL-2017B OIL FILTER FORD/MO	OTORCRAFT ONLY	1.00
- Rotate And Balance All Tires	S.			WW-2046 WIPER BLADE (MOT	ORCRAFT)	2.00
<ul> <li>Shop Supplies</li> </ul>				SHOP SUPPLIES		1.00
				5W20 ENGINE OIL		5.00
F	Parts Charge:	62.56	Labor Charge	e: 180.00		

Workorder: 1112285	Proble	m: A/c blows	s warm.			
Meter Reading: 5749			Labor		Parts	
In Date: 11/17/2011	Close Date: 11/	29/2011	Hours	Description		Quantity
<ul> <li>A/C Performance Test,Ch</li> <li>To Duplicate Complaint.</li> <li>Shop Supplies</li> </ul>	eck Sytem For Codes	.Unable To	1.00	SHOP SUPPLIES		1.00
	Parts Charge:	2.00	Labor Charge	e: 60.00		

Workorder: 1206309	Problem:	P.M. Service.Check a/c.Water leak in trunk.
Motor Poading: 6378		Labor

Meter Reading: 6378			Labor	Parts	
In Date: 07/05/2012	Close Date: (	07/31/2012	Hours	Description	Quantity
- Perform Pm Service.			9.00	VALVE KIT (EXPANSION )	1.00
- Ac Performance And Leak Test	t.Recover Free	on.Test And		SHOP SUPPLIES	1.00
Replace Failed Ac Compressor	r.Expansion Va	alve And		ACCUMULATOR	1.00
Acumulator With New Flusf Ac	Lines For Deb	oris.Vacume		5W20 ENGINE OIL	5.00
And Recharge System To Spec	CS.			WW-2046 WIPER BLADE (MOTORCRAFT)	2.00
- Water Test Tail Gate For Leaks		nmets For		FL-2017B OIL FILTER FORD/MOTORCRAFT ONLY	1.00
Wiring Harness And Adjust Gat	te To Contact	Weather		3296 FUEL FILTER FRM G3850	1.00
Strip.Clean Water Stain Off He		round		COMPRESSOR CLUTCH	1.00
- Rotate And Balance All Four Ti				R134A REFRIGERANT	2.00
- Shop Supplies	103.			FP51 CAB FILTER FRM NONE WIX 24477	1.00
- Shop Supplies				A/C COMPRESSOR	1.00
				E8 A/C OIL R134A A/C OIL (TSI)	1.00
				COMPRESSOR COIL	1.00
				COMPRESSOR PULLEY	1.00
				O RING AND GASKET SEAL KIT	2.00
				EXPANSION VALVE	1.00
Part	ts Charge:	1,011.60	Labor Char	ge: 540.00	

Workorder: 1303490	Prob	em: Pm servi	се			
Meter Reading: 6998			Labor		Parts	
In Date: 04/10/2013	Close Date: 04	4/19/2013	Hours	Description		Quantity
- Perform Pm Service.			3.75	5W20 ENGINE OIL		5.00
<ul> <li>Inspect And Replace Both I</li> </ul>	ailed Hatch Struts	With New.		FILTER		1.00
- Rotate And Balance All Fou	ır Tires.			LIFT		1.00
<ul> <li>Shop Supplies</li> </ul>				SHOP SUPPLIES		1.00
				LIFT		1.00
	Parts Charge:	101.63	Labor Charg	e: 225.00		

Workorder: 1310594	Probl	em: Pm serv	ice			
Meter Reading: 7459			Labor		Parts	
In Date: 10/22/2013	Close Date: 10	)/29/2013	Hours	Description		Quantity
- P.M. Service.			4.00	SHOP SUPPLIES		1.00
- Test Battery And Charging	System.Replace Ba	ad Battery.		NAPAGOLD OIL FILTER		1.00
- Rotate And Balance All Fo	ur Tires.			FILTER		1.00
- Shop Supplies				BXT96R 59		1.00
				5W20 ENGINE OIL		5.00
	Parts Charge:	153.26	Labor Char	ge: 240.00		

Workorder: 1404709	Problem:	P.M. service.
--------------------	----------	---------------

Meter Reading: 7960			Labor		Parts	
In Date: 05/14/2014	Close Date: 05	/28/2014	Hours	Description		Quantity
- Perform Pm Service.			6.50	TIRE DISPOSAL FEE		2.00
<ul> <li>Install Two Tires To The Fr</li> </ul>	ont Wheels.Nitroger	n Fill And		5W20 ENGINE OIL		5.00
Balance All Four.				FILTER		1.00
- Perfrorm Wheel Alignment	Complete.			WW-1202 WIPER BLADE M		1.00
- Shop Supplies				WIPER BLADE		2.00
				NAPAGOLD FUEL FILTER		1.00
				183407418 P235-70R16		2.00
				SHOP SUPPLIES		1.00
	Parts Charge:	464.27	Labor Charge	: 390.00		

<ul> <li>Rotate And Balance All Four Tires.</li> <li>Transport Vehicle To And From Dealer For Safety Recalls</li> <li>Transport Vehicle To And From Dealer For Safety Recalls</li> <li>MAPAGOLD FUEL FILTER</li> <li>MAPAGOLD FU</li></ul>	Norkorder: 1502649	Problem:	Pm servic	e Safety recall #14S05				
<ul> <li>Pm Service.</li> <li>Rotate And Balance All Four Tires.</li> <li>Rotate And Balance All Four Tires.</li> <li>Transport Vehicle To And From Dealer For Safety Recalls</li> <li>MAPAGOLD FUEL FILTER</li> <li>MAPAGOLD FUEL FILTER</li> <li>MAPAGOLD FUEL FILTER</li> <li>Shop Supplies</li> <li>Shop Supplies</li> <li>Parts Charge:</li> <li>80.56</li> <li>Labor Charge:</li> <li>300.00</li> <li>Parts Charge:</li> <li>80.56</li> <li>Labor Charge:</li> <li>300.00</li> <li>Parts Charge:</li> <li>Cose Date: 07/09/2015</li> <li>House Soft Code Date: 07/09/2015</li> <li>Mort asm</li> <li>Computer Diagnose For No Start.</li> <li>Vehicle To Recharge Battery.</li> <li>Diagnose For Ticking Noise Under Dash. Test And Replace Defective Left Temperature Blend Door Actuator.</li> <li>Shop Supplies</li> <li>Parts Charge:</li> <li>Soft Close Date: 07/07/2015</li> <li>Labor Charge:</li> <li>210.00</li> </ul>	Meter Reading: 8777			Labor		Parts		
<ul> <li>Rotate And Balance All Four Tires.</li> <li>Rotate And Balance All Four Tires.</li> <li>Shi P SuPPLIES</li> <li>Transport Vehicle To And From Dealer For Safety Recalls</li> <li>NAPAGOLD FUEL FILTER</li> <li>100</li> <li>Shop Supplies</li> <li>WW-1202 WIPER BLADE M</li> <li>100</li> <li>BRAKE CLEANER</li> <li>SW20 ENGINE OIL</li> <li>Sw20 ENGINE OIL</li> <li>Sw20 ENGINE OIL</li> <li>Close Date: 07/09/2015</li> <li>Hours</li> <li>Description</li> <li>Outage Battery State Of Charge Low.Clear Code Then</li> <li>MOTOR ASY</li> <li>MOTOR ASY</li> <li>SHOP SUPPLIES</li> <li>SHOP SUPPLIES</li> <li>SHOP SUPPLIER</li> <li>SHOP SUPPLIER</li> <li>State And Hamma State And Balance All Ports</li> <li>Computer Diagnose For No Start.Code POATD High</li> <li>Outage Battery State Of Charge Low.Clear Code Then</li> <li>MOTOR ASY</li> <li>MOTOR ASY</li> <li>SHOP SUPPLIES</li> <li>SHOP SUPPLIES</li> <li>SHOP SUPPLIER LABER</li> <li>SHOP SUPPLIER LABER</li></ul>	In Date: 03/13/2015	Close Date: 03/31/	2015	Hours	Description			Quantity
<ul> <li>Transport Vehicle To And From Dealer For Safety Recalls</li> <li>Transport Vehicle To And From Dealer For Safety Recalls</li> <li>MAPAGOLD FÜEL FILTER</li> <li>MAC WITE 202 WIPER BLADE M</li> <li>Shop Supplies</li> <li>FILTER</li> <li>MAC WITE LITHIUM GRES</li> <li>MAC WITE Reading: 9180</li> <li>Labor MAC TOR ASY</li> <li>Mater Reading: 9035</li> <li>Labor Parts</li> <li>Mater Reading: 9035</li> <li>Mater Reading: 9035</li> <li>Labor Parts</li> <li>Mater Reading: 9035</li> <li>Mater Read</li></ul>	- Pm Service.			5.00 ACC	UFIT BEAM			2.00
#14S05 And 14S19       100         Shop Supplies       FILTER       1.00         MAC WITE LITHIUM GRES       1.00         BRAKE CLEANER       1.00         SW20 ENGINE OIL       5.00         Vorkorder: 1506737       Problem: Towed in for no start.       Parts Charge:       30.00         Meter Reading: 9180       Labor Charge:       300.00         In Date: 07/07/2015       Close Date: 07/09/2015       Hours       Description       Quantity         - Computer Diagnose For No Start. Code P0A7D.High       3.50       motor asm       1.00         Voltage Battery State Of Charge Low. Clear Code Then       MOTOR ASY       1.00         Notige Deference Left To Recharge High Voltage Battery.       SHOP SUPPLIES       1.00         Diagnose For Ticking Noise Under Dash. Test And Replace Defective Left Temperature Blend Door Actuator.       Shop Supplies       Parts Charge:       52.40         Vorkorder: 1506771       Problem: No start       Meter Reading: 9035       Labor       Parts         In Date: 07/06/2015       Close Date: 07/07/2015       Hours       Description       Quantity         - Tow From: Airport (Terminial Area) To: Lv Shop       State       Parts       Cuantity	- Rotate And Balance All F	Four Tires.		SHO	P SUPPLIES			1.00
#14S05 And 14S19       WW-1202 WIPER BLADE M       1.00         Shop Supplies       FILTER       1.00         MAC WITE LITHIUM GRES       1.00         BRAKE CLEANER       1.00         sW20 ENGINE OIL       5.00         Parts Charge:       80.56       Labor Charge:       300.00         Vorkorder: 1506737       Problem: Towed in for no start.       5.00         Meter Reading: 9180       Labor       Parts         In Date: 07/07/2015       Close Date: 07/09/2015       Hours       Description       Quantity         - Computer Diagnose For No Start.Code POA7D.High       3.50       motor asm       1.00         Voltage Battery State Of Charge Low Clear Code Then       MOTOR ASY       1.00         Vehicle To Recharge High Voltage Battery.       5HOP SUPPLIES       1.00         - Diagnose For Ticking Noise Under Dash.Test And Replace Defective Left Temperature Blend Door Actuator.       1.00         - Shop Supplies       Farts Charge:       52.40       Labor Parts         Vehicle To Recharge High Voltage Battery.       1.00       1.00         - Shop Supplies       Parts Charge:       52.40       Labor Charge:       210.00         Vehicle To Recharge High Voltage Battery.       5.00       10.00       20.00       20.00 <t< td=""><td>- Transport Vehicle To And</td><td>d From Dealer For Safety</td><td>Recalls</td><td>NAP</td><td>AGOLD FUEL FIL</td><td>TER</td><td></td><td>1.00</td></t<>	- Transport Vehicle To And	d From Dealer For Safety	Recalls	NAP	AGOLD FUEL FIL	TER		1.00
Only Deprinds       MAC WITE LITHIUM GRES       1.00         BRAKE CLEANER       1.00         SW20 ENGINE OIL       5.00         Vorkorder: 1506737       Problem: Towed in for no start.       5.00         Meter Reading: 9180       Labor       Parts         In Date: 07/07/2015       Close Date: 07/09/2015       Hours       Description       Quantity         - Computer Diagnose For No Start.Code POA7D.High       3.50       motor asm       1.00         Voltage Battery State Of Charge Low.Clear Code Then       MOTOR ASY       1.00         Voltage Battery State Of Charge Low.Clear Code Then       MOTOR ASY       1.00         Voltage Battery State Of Charge Iow.Clear Code Then       MOTOR ASY       1.00         Voltage Battery State Of Charge Low.Clear Code Then       MOTOR ASY       1.00         Vehicle To Recharge High Voltage Battery.       SHOP SUPPLIES       1.00         Diagnose For Ticking Noise Under Dash.Test And Replace Defective Left Temperature Blend Door Actuator.       Shop Supplies       1.00         Vorkorder: 1506771       Problem: No start       Meter Reading: 9035       Labor       Parts         Meter Reading: 9035       Labor       Parts       Quantity         - Tow From: Airport (Terminial Area) To; Lv Shop       Description       Quantity	•			WW-	1202 WIPER BLA	DE M		1.00
MAC WITE LITHIUM GRES 1.00 BRAKE CLEANER 1.00 SW20 ENGINE OIL 5.00 Parts Charge: 80.56 Labor Charge: 300.00 /orkorder: 1506737 Problem: Towed in for no start. Meter Reading: 9180 Labor Parts 0.00 In Date: 07/07/2015 Close Date: 07/09/2015 Hours Description Quantity - Computer Diagnose For No Start.Code P0A7D.High 3.50 motor asm 1.00 Voltage Battery State Of Charge Low.Clear Code Then MOTOR ASY 1.00 Reprogram Pom With Latest Calibration Update.Drive SHOP SUPPLIES 1.00 Vehicle To Recharge High Voltage Battery. - Diagnose For Ticking Noise Under Dash. Test And Replace Defective Left Temperature Blend Door Actuator. - Shop Supplies Parts Charge: 52.40 Labor Charge: 210.00 /orkorder: 1506771 Problem: No start Meter Reading: 9035 Labor Parts 100 /orkorder: 1506771 Problem: No start Meter Reading: 9035 Labor Parts 100 /or Form: Airport (Terminial Area) To: Lv Shop	- Shop Supplies			FILT	ER			1.00
W20 ENGINE OIL       5.00         Parts Charge:       80.56       Labor Charge:       300.00         /orkorder:       1506737       Problem:       Towed in for no start.       Parts         Meter Reading:       9180       Labor       Parts       Parts         In Date:       07/07/2015       Close Date:       07/09/2015       Hours       Parts         -       Computer Diagnose For No Start. Code POA7D. High       3.50       motor asm       1.00         Voltage Battery State Of Charge Low. Clear Code Then       MOTOR ASY       1.00         Voltage Battery State Of Charge Low. Clear Code Then       MOTOR ASY       1.00         Voltage Battery State Of Charge Low. Clear Code Then       MOTOR ASY       1.00         Voltice To Recharge High Voltage Battery.       SHOP SUPPLIES       1.00         -       Diagnose For Ticking Noise Under Dash. Test And Replace Defective Left Temperature Blend Door Actuator.       210.00         -       Shop Supplies       Parts Charge:       52.40       Labor Charge:       210.00         Meter Reading: 9035       Labor       Parts       Parts       Quantity         In Date:       07/07/2015       Hours       Description       Quantity         -       Tow From: Airport (Terminial Area) To: Lv Shop				MAC	WITE LITHIUM G	RES		1.00
Parts Charge:     80.56     Labor Charge:     300.00       forkorder: 1506737     Problem:     Towed in for no start.       Meter Reading: 9180     Labor     Parts       In Date: 07/07/2015     Close Date: 07/09/2015     Hours     Description       - Computer Diagnose For No Start. Code P0A7D. High     3.50     motor asm     1.00       - Computer Diagnose For No Start. Code P0A7D. High     3.50     motor asm     1.00       Voltage Battery State Of Charge Low. Clear Code Then     MOTOR ASY     1.00       Vehicle To Recharge High Voltage Battery.     SHOP SUPPLIES     1.00       - Diagnose For Ticking Noise Under Dash. Test And Replace Defective Left Temperature Blend Door Actuator.     SHOP SUPPLIES     1.00       - Shop Supplies     Parts Charge:     52.40     Labor Charge:     210.00       Vorkorder: 1506771     Problem: No start     210.00     Quantity       Meter Reading: 9035     Labor     Parts     Parts       In Date: 07/06/2015     Close Date: 07/07/2015     Hours     Description       - Tow From: Airport (Terminial Area). To: Lv Shop     -     Labor     Parts				BRA	KE CLEANER			1.00
Jorkorder:       1506737       Problem:       Towed in for no start.         Meter Reading:       9180       Labor       Parts         In Date:       07/2015       Close Date:       07/09/2015       Hours       Description       Quantity         -       Computer Diagnose For No Start.Code P0A7D.High       3.50       motor asm       1.00         Voltage Battery State Of Charge Low.Clear Code Then       MOTOR ASY       1.00         Voltage Dattery State Of Charge Low.Clear Code Then       MOTOR ASY       1.00         Vehicle To Recharge High Voltage Battery.       SHOP SUPPLIES       1.00         Vehicle To Recharge High Voltage Battery.       -       1.00         -       Diagnose For Ticking Noise Under Dash. Test And Replace Defective Left Temperature Blend Door Actuator.       -       -         -       Shop Supplies       -       -       210.00         /orkorder:       1506771       Problem:       No start       -         Meter Reading:       9035       Labor       Parts       -         In Date:       07/06/2015       Close Date:       07/07/2015       -       Quantity         -       Tow From: Airport (Terminial Area)       To: Lv Shop       -       -       -				5W2	0 ENGINE OIL			5.00
Meter Reading: 9180       Labor       Parts         In Date: 07/07/2015       Close Date: 07/09/2015       Hours       Description       Quantity         -       Computer Diagnose For No Start.Code P0A7D.High       3.50       motor asm       1.00         Voltage Battery State Of Charge Low.Clear Code Then       MOTOR ASY       1.00         Reprogram Pcm With Latest Calibration Update.Drive       SHOP SUPPLIES       1.00         Vehicle To Recharge High Voltage Battery.       5HOP SUPPLIES       1.00         -       Diagnose For Ticking Noise Under Dash.Test And Replace Defective Left Temperature Blend Door Actuator.       -       Shop Supplies         -       Parts Charge:       52.40       Labor Charge:       210.00         /orkorder: 1506771       Problem: No start         Meter Reading: 9035       Labor       Parts       Parts         In Date: 07/06/2015       Close Date: 07/07/2015       Hours       Description       Quantity         -       Tow From: Airport (Terminial Area) To: Lv Shop       -       -       -       -		Parts Charge:	80.56	Labor Charge:	300.00			
Meter Reading: 9180       Labor       Parts         In Date: 07/07/2015       Close Date: 07/09/2015       Hours       Description       Quantity         -       Computer Diagnose For No Start.Code P0A7D.High       3.50       motor asm       1.00         Voltage Battery State Of Charge Low.Clear Code Then       MOTOR ASY       1.00         Reprogram Pcm With Latest Calibration Update.Drive       SHOP SUPPLIES       1.00         Vehicle To Recharge High Voltage Battery.       SHOP SUPPLIES       1.00         -       Diagnose For Ticking Noise Under Dash.Test And Replace Defective Left Temperature Blend Door Actuator.       -         -       Shop Supplies       210.00         Parts Charge: 52.40       Labor Charge: 210.00         Vorkorder: 1506771         Problem:       No start         Meter Reading: 9035       Labor       Parts         In Date: 07/06/2015       Close Date: 07/07/2015       Hours       Description         -       Tow From: Airport (Terminial Area) To: Lv Shop       Vehicle Signation Signation       Quantity	Workorder: 1506737	Problem:	Towed in	for no start.				
In Date: 07/07/2015       Close Date: 07/09/2015       Hours       Description       Quantity         -       Computer Diagnose For No Start.Code POA7D.High Voltage Battery State Of Charge Low.Clear Code Then MOTOR ASY       3.50       motor asm       1.00         Voltage Battery State Of Charge Low.Clear Code Then Reprogram Pcm With Latest Calibration Update.Drive Vehicle To Recharge High Voltage Battery.       SHOP SUPPLIES       1.00         Diagnose For Ticking Noise Under Dash.Test And Replace Defective Left Temperature Blend Door Actuator.       Stop Supplies       210.00         /orkorder: 1506771       Problem: No start       210.00       Parts       Parts         /deter Reading: 9035       Close Date: 07/07/2015       Hours       Parts       Quantity         -       Tow From: Airport (Terminial Area) To: Ly Shop       To: Ly Shop       Description       Quantity				Labor		Parts		
Voltage Battery State Of Charge Low.Clear Code Then MOTOR ASY 1.00 Reprogram Pcm With Latest Calibration Update.Drive SHOP SUPPLIES 1.00 Vehicle To Recharge High Voltage Battery. - Diagnose For Ticking Noise Under Dash.Test And Replace Defective Left Temperature Blend Door Actuator. - Shop Supplies Parts Charge: 52.40 Labor Charge: 210.00 /orkorder: 1506771 Problem: No start Meter Reading: 9035 Labor Start In Date: 07/06/2015 Close Date: 07/07/2015 Hours Description Quantity - Tow From: Airport (Terminial Area) To: Lv Shop	_	Close Date: 07/09/	2015	Hours	Description			Quantity
Reprogram Pcm With Latest Calibration Update.Drive       SHOP SUPPLIES       1.00         Vehicle To Recharge High Voltage Battery.       Diagnose For Ticking Noise Under Dash.Test And Replace Defective Left Temperature Blend Door Actuator.       1.00         Shop Supplies       Parts Charge:       52.40       Labor Charge:       210.00         /orkorder: 1506771       Problem: No start       Parts       Parts         Meter Reading: 9035       Labor       Parts         In Date: 07/06/2015       Close Date: 07/07/2015       Hours       Description       Quantity         -       Tow From: Airport (Terminial Area) To: Lv Shop       To: Lv Shop       In Date: 07/06/2015       In Date: 07/07/2015       In Date:	- Computer Diagnose For	No Start.Code P0A7D.Hig	ıh	3.50 moto	or asm			1.00
Reprogram Pcm With Latest Calibration Update.Drive       SHOP SUPPLIES       1.00         Vehicle To Recharge High Voltage Battery.       Diagnose For Ticking Noise Under Dash.Test And Replace Defective Left Temperature Blend Door Actuator.       1.00         Shop Supplies       Parts Charge:       52.40       Labor Charge:       210.00         /orkorder: 1506771       Problem: No start       Parts       Parts         Meter Reading: 9035       Labor       Parts         In Date: 07/06/2015       Close Date: 07/07/2015       Hours       Description       Quantity         -       Tow From: Airport (Terminial Area) To: Lv Shop       To: Lv Shop       In Date: 07/06/2015       In Date: 07/07/2015       In Date:	Voltage Battery State Of	Charge Low.Clear Code	Гhen	МОТ	OR ASY			1.00
<ul> <li>Diagnose For Ticking Noise Under Dash.Test And Replace Defective Left Temperature Blend Door Actuator.</li> <li>Shop Supplies         <ul> <li>Parts Charge: 52.40</li> <li>Labor Charge: 210.00</li> </ul> </li> <li>/orkorder: 1506771         <ul> <li>Problem: No start</li> <li>Meter Reading: 9035</li> <li>Labor</li> <li>Parts</li> <li>Parts Charge: 07/07/2015</li> <li>Hours</li> <li>Description</li> </ul> </li> <li>Quantity</li> <li>Tow From: Airport (Terminial Area) To: Lv Shop</li> </ul>	Reprogram Pcm With Lat			SHOP SUPPLIES				1.00
<ul> <li>Diagnose For Ticking Noise Under Dash.Test And Replace Defective Left Temperature Blend Door Actuator.</li> <li>Shop Supplies         <ul> <li>Parts Charge: 52.40</li> <li>Labor Charge: 210.00</li> </ul> </li> <li>/orkorder: 1506771         <ul> <li>Problem: No start</li> <li>Meter Reading: 9035</li> <li>Labor</li> <li>Parts</li> <li>Parts Charge: 07/07/2015</li> <li>Hours</li> <li>Description</li> </ul> </li> <li>Quantity</li> <li>Tow From: Airport (Terminial Area) To: Lv Shop</li> </ul>								
Replace Defective Left Temperature Blend Door Actuator.         Shop Supplies         Parts Charge:       52.40         Labor Charge:       210.00         Vorkorder:       1506771         Problem:       No start         Meter Reading:       9035         Labor       Parts         In Date:       07/06/2015         Close Date:       07/07/2015         Hours       Description         Quantity								
<ul> <li>Shop Supplies</li> <li>Parts Charge: 52.40 Labor Charge: 210.00</li> <li>/orkorder: 1506771 Problem: No start</li> <li>Meter Reading: 9035 Labor Parts</li> <li>In Date: 07/06/2015 Close Date: 07/07/2015 Hours Description Quantity</li> <li>Tow From: Airport (Terminial Area) To: Lv Shop</li> </ul>			ctuator.					
Parts Charge:       52.40       Labor Charge:       210.00         /orkorder:       1506771       Problem:       No start         Meter Reading:       9035       Labor       Parts         In Date:       07/06/2015       Close Date:       07/07/2015       Hours       Description       Quantity         -       Tow From:       Airport (Terminial Area)       To:       Lv Shop       Lv Shop	•		otaaton					
Meter Reading: 9035     Labor     Parts       In Date: 07/06/2015     Close Date: 07/07/2015     Hours     Description     Quantity       - Tow From: Airport (Terminial Area) To: Lv Shop     To: Lv Shop     Vertice of the second seco		Parts Charge:	52.40	Labor Charge:	210.00			
Meter Reading: 9035     Labor     Parts       In Date: 07/06/2015     Close Date: 07/07/2015     Hours     Description     Quantity       - Tow From: Airport (Terminial Area) To: Lv Shop     To: Lv Shop     Vertice of the second seco			<b>.</b>					
In Date: 07/06/2015       Close Date: 07/07/2015       Hours       Description       Quantity         -       Tow From: Airport (Terminial Area) To: Lv Shop       Formation of the state of the		Problem:	No start					
- Tow From: Airport (Terminial Area) To: Lv Shop	_					Parts		
			2015	Hours	Description			Quantity
Parts Charge: 0.00 Labor Charge: 0.00 Commercial Charge: 128.65	- Tow From: Airport (Termi	inial Area) To: Lv Shop						
		Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	128.65	

#### Asset: K11807 2008 FORD ESCAPE Suv, Mid Size, Hybrid

Workorder: 1602463	Problem	: Pm servic	e.Headliner.			
Meter Reading: 10013			Labor		Parts	
In Date: 03/08/2016	Close Date: 03/23	/2016	Hours	Description		Quantity
- Pm Service.			5.00 HEA	DLINER R&R		1.00
- Rotate And Balance All Four Tires.			WW	-1202 WIPER BLAI	DE M	1.00
<ul> <li>Transport Vehicle To And From Central Trim Shop For Repairing Head Liner.</li> </ul>			FILT	1.00		
				OP SUPPLIES		1.00
<ul> <li>Shop Supplies</li> </ul>						2.00
		405 40		20 ENGINE OIL		5.00
	Parts Charge:	425.48	Labor Charge:	300.00		
Workorder: 1605632	Problem	: Towed in	for no start.			
Meter Reading: 10282			Labor		Parts	
In Date: 06/01/2016	Close Date:		Hours	Description		Quantity
-	Parts Charge:	0.00	Labor Charge:	0.00		
Workorder: 1605689	Problem	No start				
Meter Reading: 10282		-	Labor		Parts	
In Date: 06/01/2016	Close Date: 06/02	2/2016	Hours	Description		Quantity
- Tow From: Airports To: L	v Shop					

Total Parts Charges: 3

3,010.67

Total Labor Charges:

s: **3,665.00** 

Total Comm. Charges:

224.65