

**Palm Beach County Fleet Management
Asset Maintenance History**

10200920 2016 CLUB CAR CARRYALL 500 Utility Cart, Electric, Cargo

Workorder: 1603259 **Meter:** 0 **In Date:** 03/29/2016 **Closed:** 03/29/2016
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 1704188 **Meter:** 1 **In Date:** 04/26/2017 **Closed:** 05/11/2017
Problem: PM Service

- Pm service.

- Shop Supplies

Parts List

Shop Supplies

Qty

1.00

Hours 4.00 Labor: 240.00 Parts: 2.00 Total: 242.00
:

Workorder: 1803234 **Meter:** 448 **In Date:** 03/28/2018 **Closed:** 04/04/2018
Problem: Pm service.

- Pm service.

- Replace worn tires.

- Shop Supplies

Parts List

20x10.00x10 Multi Trac

Dust Cover

Shop Supplies

Tire Disposal Fee

Qty

4.00

1.00

1.00

4.00

Hours 6.00 Labor: 360.00 Parts: 557.05 Total: 917.05
:

Workorder: 1903142 **Meter:** 583 **In Date:** 03/21/2019 **Closed:** 03/27/2019
Problem: Pm service.

- Pm service.

- Replace worn front tires.

- Hesitating when accelerating. Found poor voltage to motor controller. Repaired poor connection at controller to correct.

- Shop Supplies

Parts List

20x10.00x10 Multi Trac

Shop Supplies

Tire Disposal Fee

Qty

2.00

1.00

2.00

Hours 6.00 Labor: 402.00 Parts: 298.66 Total: 700.66
:

Workorder: 2005280 **Meter:** 655 **In Date:** 05/27/2020 **Closed:** 07/02/2020
Problem: Pm service, check forward/reverse operation.

- Pm service.

- Diagnose forward reverse operation. Drive motor has internal damage causing overheating and shutting off. Installed new drive motor assy.

- Shop Supplies

Parts List

48v 3.7hp Motor

Shop Supplies

Qty

1.00

1.00

Hours 7.50 Labor: 547.50 Parts: 1,802.92 Total: 2,350.42
:

Workorder: 2104885 **Meter:** 655 **In Date:** 04/30/2021 **Closed:** 04/30/2021
Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00 Labor: 146.00 Parts: 0.00 Total: 146.00
: