

1/3/2022
11:44:49 AM

Palm Beach County Fleet Management Asset Maintenance History
10181159 2011 FORD F250 Pickup, 3/4 Ton, 4X4

Total Hours: 126.85 Labor: 8,287.05 Parts: 7,002.23 Comm: 748.25 Charged: 16037.53

Work Order: 1007977 **Meter:** 0 **In Date:** 07/27/2010 **Closed:** 07/27/2010
Problem: Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1008039 **Meter:** 300 **In Date:** 07/28/2010 **Closed:** 07/30/2010
Problem: 2 extra keys

Work Completed

- cut and program 2 extra keys
- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00
164-r8040 Ignition Key 2011- Newer (ford)	2.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 48.50 Total: 108.50

Work Order: 1102125 **Meter:** 2819 **In Date:** 02/24/2011 **Closed:** 03/03/2011
Problem: Pm service.

Work Completed

- Perform pm service.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	7.00
7090blk Frt Floor Mats (rubber Queen)	1.00
Used Firex Refurbed Fire Extingshers	1.00
31-22 Wiper Blades 22" Wiper Blade	2.00

Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 86.21 Total: 311.21

Work Order: 1109375 **Meter:** 4607 **In Date:** 09/01/2011 **Closed:** 09/09/2011
Problem: Pm service

Work Completed

- Perform pm service.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	7.00

Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 21.36 Total: 246.36

1/3/2022
11:44:49 AM

Palm Beach County Fleet Management Asset Maintenance History
10181159 2011 FORD F250 Pickup, 3/4 Ton, 4X4

Work Order: 1202580 **Meter:** 6045 **In Date:** 03/15/2012 **Closed:** 04/04/2012
Problem: P.M. service

Work Completed

- P.m. Service.
- Rotate and balance all tires.
- Transport vehicle for leaking steering gear assemble.
- Shop Supplies

Hours: 5.75

Comm: 0.00

Parts Issued

Parts Issued	Quantity
Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	7.00
1066 White Lithium (crc 05037)	1.00
31-22 Wiper Blades 22" Wiper Blade	2.00
Used Firex Refurbed Fire Extingshers	1.00

Labor: 345.00

Parts: 48.64

Total: 393.64

Work Order: 1300239 **Meter:** 9756 **In Date:** 01/07/2013 **Closed:** 01/24/2013
Problem: Pm service.

Work Completed

- Perform pm service.
- Rotate and balance all four tires.
- Shop Supplies

Hours: 3.75

Comm: 0.00

Parts Issued

Parts Issued	Quantity
5w20 Engine Oil	7.00
1372 Oil Filter	1.00
Used Firex Refurbed F	1.00
31-22 Wiper Blades 22	2.00
Shop Supplies	1.00

Labor: 225.00

Parts: 54.58

Total: 279.58

1/3/2022
11:44:49 AM

Palm Beach County Fleet Management Asset Maintenance History
10181159 2011 FORD F250 Pickup, 3/4 Ton, 4X4

Work Order: 1401312 **Meter:** 14763 **In Date:** 02/07/2014 **Closed:** 02/25/2014

Problem: P.M. service and request detail.

Work Completed

- P.m. Service.
- Replace two tires,rotate and balance all four.
- Install cambr/caster adjustment bushings.perform complete wheel alignment.test drive.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Mac Wite Lithium Gres	1.00
Wiper Blade	2.00
179636492 Lt245-75r17	2.00
Caster-camber Bushing	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 8.25

Comm: 0.00

Labor: 495.00 Parts: 596.78 Total: 1,091.78

Work Order: 1412204 **Meter:** 19084 **In Date:** 12/05/2014 **Closed:** 12/24/2014

Problem: Pm service and strobe lights inop.

Work Completed

- Pm service.
- Test starting and charging system .battery failed load test after recharge.replace defective battery.
- Replace two tires.rotate and balance all four.
- Diagnose strobe lights inop.test and replace defective inline fuse holder.repair loose Led Strobe lamp in left headlamp.replace defective third brake lamp bulb.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Wiper Blade	2.00
Stg Wheel Cov - Ford	1.00
Washer Fluid Concentr	1.00
Battery 65	1.00
179636492 Lt245-75r17	2.00
Fuse Holder	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 6.75

Comm: 0.00

Labor: 405.00 Parts: 751.16 Total: 1,156.16

1/3/2022
11:44:49 AM

Palm Beach County Fleet Management Asset Maintenance History
10181159 2011 FORD F250 Pickup, 3/4 Ton, 4X4

Work Order: 1510826 **Meter:** 23645 **In Date:** 10/26/2015 **Closed:** 11/05/2015

Problem: Pm service.Body damage.Report attached.Detail.

Work Completed

- Pm service.
- Replace defective fire extinguisher bracket.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Brake Cleaner	1.00
Custom Bracket Fire Ex	1.00
Shop Supplies	1.00

Hours: 4.25

Comm: 0.00

Labor: 255.00

Parts: 98.89

Total: 353.89

Work Order: 1512227 **Meter:** 23645 **In Date:** 11/10/2015 **Closed:** 12/03/2015

Problem: damage to lft rear fender

Work Completed

- damage to lft rear fender

Hours: 0.00

Comm: 582.00

Labor: 0.00

Parts: 0.00

Total: 582.00

Work Order: 1609197 **Meter:** 27862 **In Date:** 09/02/2016 **Closed:** 09/20/2016

Problem: P.M. service and install computer stand ans detail.

Work Completed

- P.m. Service.
- Replace six worn out body to chasis mount.replace both front suspension bump stops.
- Assemble and install computer stand.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

bumper	2.00
5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Wd40 Spr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Body Mount Kit	2.00
Body Mount Kit	4.00
Bumper	2.00
Shop Supplies	1.00

Hours: 12.25

Comm: 0.00

Labor: 735.00

Parts: 674.32

Total: 1,409.32

1/3/2022
11:44:49 AM

Palm Beach County Fleet Management Asset Maintenance History
10181159 2011 FORD F250 Pickup, 3/4 Ton, 4X4

Work Order: 1609402 **Meter:** 27736 **In Date:** 09/09/2016 **Closed:** 09/09/2016
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1703899 **Meter:** 30781 **In Date:** 04/18/2017 **Closed:** 04/28/2017
Problem: P.M. Service.

Work Completed

- P.m. service.
- Load test battery ,failed due to bad cell .replace battery with new.
- Inspect and service transfer case.
- Perform automatic transmission flush service.
- Replace right rear turnsignal bulb, blown filament.
- Rotate and balance four tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Battery	1.00
Ford Transfer Case Fluid	2.00
Syn-atf Trans Fluid S	18.00
Bulb	1.00
Shop Supplies	1.00

Hours: 7.75 Comm: 0.00 Labor: 465.00 Parts: 248.92 Total: 713.92

Work Order: 1800933 **Meter:** 34312 **In Date:** 01/25/2018 **Closed:** 02/01/2018
Problem: P.M. service and right front tire going flat.

Work Completed

- P.m. service.
- Replace both front tires.rotate and balance all four tires.nitrogen fill tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
179636492 Lt245-75r17	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 4.75 Comm: 0.00 Labor: 285.00 Parts: 494.99 Total: 779.99

1/3/2022
11:44:49 AM

Palm Beach County Fleet Management Asset Maintenance History
10181159 2011 FORD F250 Pickup, 3/4 Ton, 4X4

Work Order: 1803714 **Meter:** 35079 **In Date:** 04/05/2018 **Closed:** 04/09/2018
Problem: Right/Front has screw in tire

Work Completed

- Tire Service 8100 forest Hill blvd - Right/front has screw in tire

Hours: 0.00 Comm: 70.25 Labor: 0.00 Parts: 0.00 Total: 70.25

Work Order: 1810961 **Meter:** 37827 **In Date:** 10/24/2018 **Closed:** 10/24/2018
Problem: Right front tire going flat.

Work Completed

- Repair right front tire and balance . Nitrogen fill tires.

Parts Issued	Quantity
Shop Supplies	1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 3.00 Total: 70.00

1/3/2022
11:44:49 AM

Palm Beach County Fleet Management Asset Maintenance History
10181159 2011 FORD F250 Pickup, 3/4 Ton, 4X4

Work Order: 1811002 **Meter:** 37827 **In Date:** 10/25/2018 **Closed:** 11/01/2018
Problem: PM Service

Work Completed

- P.m. service.
- Replace two tires . Rotate and high speed balance all four tires. Nitrofill.
- Resurface front and rear rotors . Replace brake calipers and pads on front and rear . Flush and bleed brake system . Road test .
- Perform front end alignment .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
2pc Hd Mat Set Blk	1.00
Ford Triton Pvc Swc	1.00
179636492 Lt245-75r17	2.00
Pads	1.00
Caliper w/ Hardware - Right Front (eclip	1.00
Caliper w/ Hardware - Left Front (eclips	1.00
Rear Pads	1.00
Caliper w/ Hardware - Left Rear (eclipse	1.00
Caliper w/ Hardware - Right Rear (eclips	1.00
B Fluid Dot 3-32oz	2.00
Non-chlor Brake Clnr	3.00
Pedal Pad	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 15.25

Comm: 0.00

Labor: 1,021.75 Parts: 1,026.19 Total: 2,047.94

Work Order: 1812370 **Meter:** 38073 **In Date:** 12/05/2018 **Closed:** 12/10/2018
Problem: Rear directional light out, drivers side.

Work Completed

- Test and replace left rear turn signal bulb and socket .

Parts Issued

Quantity

Stp Trn TI Lgt Socket	1.00
Boxed Miniatures	1.00

Hours: 0.50

Comm: 0.00

Labor: 33.50 Parts: 10.80 Total: 44.30

1/3/2022
11:44:49 AM

Palm Beach County Fleet Management Asset Maintenance History
10181159 2011 FORD F250 Pickup, 3/4 Ton, 4X4

Work Order: 1813030 **Meter:** 38381 **In Date:** 12/27/2018 **Closed:** 12/31/2018
Problem: Passenger rear tail light out.

Work Completed

- Test and replace right brake light bulb and socket .

Hours: 0.50

Comm: 0.00

Parts Issued

Stp Trn TI Lgt Socket 1.00

Boxed Miniatures 1.00

Labor: 33.50 Parts: 10.80 Total: 44.30

Work Order: 1906009 **Meter:** 41282 **In Date:** 06/07/2019 **Closed:** 06/18/2019
Problem: P.M. service.

Work Completed

- P.m. service.

- Replace both rear defective bump stops .

- Repair right rear tire . Rotate and high speed balance all four tires . Nitrofill all.

- Shop Supplies

Hours: 5.25

Comm: 0.00

Parts Issued

Napagold Oil Filter 1.00

5w20 Engine Oil 7.00

22" Wiper Blade 2.00

Used Fire X Refurbished 1.00

Bumper 2.00

Shop Supplies 1.00

Labor: 351.75 Parts: 147.47 Total: 499.22

Work Order: 1908711 **Meter:** 43165 **In Date:** 08/20/2019 **Closed:** 08/26/2019
Problem: Had to jump start.

Work Completed

- Charge battery fully . Test battery and charging system . R&r defective battery .

- Shop Supplies

Hours: 1.00

Comm: 0.00

Parts Issued

Battery 1.00

Shop Supplies 1.00

Labor: 67.00 Parts: 141.90 Total: 208.90

Work Order: 1911889 **Meter:** 44911 **In Date:** 11/15/2019 **Closed:** 11/18/2019
Problem: Low tire.

Work Completed

- Computer diagnose tire pressure light . code B124d. Test and replace right rear Tpms sensor and retrain all Tpms .

- Shop Supplies

Hours: 1.00

Comm: 0.00

Parts Issued

Tpms12 Sensor Tire Pr 1.00

Shop Supplies 1.00

Labor: 73.00 Parts: 79.89 Total: 152.89

1/3/2022
11:44:49 AM

Palm Beach County Fleet Management Asset Maintenance History
10181159 2011 FORD F250 Pickup, 3/4 Ton, 4X4

Work Order: 2004707

Meter: 47510

In Date: 05/11/2020 **Closed:** 05/20/2020

Problem: P.M. service and noise from rear end .

Work Completed

- P.m. service.
- Computer diagnose airbag light , code b193c . Perform pinpoint test . R&r defective open clock spring . Clear code and retest .
- Diagnose noise from rear of vehicle . R&r both defective rear shocks .
- Perform complete air intake decarb and cleaning . Flush injectors .
- Diagnose engine misfire . Perform tune up . Replace all sixteen spark plugs and wire set . Replace number three and four coils . Clear codes and retest .
- Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Clock Spring	1.00
22" Wiper Blade	2.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Coil	2.00
Spark Plug	16.00
Espak Plug Wire	4.00
Espak Plug Wire	1.00
Ptp953 Throttle Body Cleaner4.5 Oz.	1.00
Gas Grande Shock	2.00
Housing Assy	1.00
Shop Supplies	1.00

Hours: 14.85

Comm: 0.00

Labor: 1,084.05

Parts: 1,189.23

Total: 2,273.28

1/3/2022
11:44:49 AM

Palm Beach County Fleet Management Asset Maintenance History
10181159 2011 FORD F250 Pickup, 3/4 Ton, 4X4

Work Order: 2102072 **Meter:** 55530 **In Date:** 02/24/2021 **Closed:** 03/08/2021

Problem: P.M. service , brakes noisy , a/c and radio inop at times and pops out of drive at times

Work Completed

- Preventive Maint. Service
- check , battery , charging system , after fully charge it fails load test , r@r defective battery
- check and replace defective trailer plug . Rewire as needed fabricated wires as needed
- replace two tires,balance and rotate all 4 Nitro fill all.
- check,verify ,resurfaced both front brakes rotors,replace calipers,pads,clean & lube rear pads ,rotors , flush and bleed brakes and road test
- pin point test , check over several times , road with assistant , Computer diagnose , scan for code , No codes , Check fluid level and color . ,no abnormal found at this time , for radio nor a/c system items operate as design
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	8.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Steering Wheel Cover Large	1.00
Used Fire X Refurbished	1.00
Battery	1.00
trailer plug	1.00
Lt245/75r17 Mich Defend Ltx	2.00
Brk Fluid Dot 4-32oz	1.00
Brake Pad	1.00
Caliper w/ Hardware - Right Front (eclip	1.00
Caliper w/ Hardware - Left Front (eclips	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 11.75

Comm: 0.00

Labor: 857.75

Parts: 1,137.89

Total: 1,995.64

Work Order: 2105220 **Meter:** 56263 **In Date:** 05/10/2021 **Closed:** 05/13/2021

Problem: A/C INOP

Work Completed

- Service Ac system, evacuate and recharge Ac, inspect for leaks, Performance tests good
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 4.00

Total: 150.00

1/3/2022
11:44:49 AM

Palm Beach County Fleet Management Asset Maintenance History
10181159 2011 FORD F250 Pickup, 3/4 Ton, 4X4

Work Order: 2109907 **Meter:** 57638 **In Date:** 09/14/2021 **Closed:** 09/23/2021

Problem: PM Service , A/C warm ,tire light on , check lights and steering wheel cover

Work Completed

- Preventive Maint. Service
- Performance Check A/c System And For Leaks. R&r Failed High And Low Service Valve Cores Leaking Freon. Vacuum Leak Test Passed And Recharge A/c System.
- R&r Faulty Left Rear Tire Sensor , Rotate And Balance Four Tires.
- R&r Failed Right Front Turn Signal Bulb.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Steering Wheel Cover Large	1.00
Freon Lv Shop 2	1.00
Valve Core	1.00
Valve Core	1.00
Tpms Kit	1.00
Turn Signal Bulb	1.00
Valve Assy	1.00
Shop Supplies	1.00

Hours: 7.75 Comm: 0.00

Labor: 565.75 Parts: 126.76 Total: 692.51

Work Order: 2111494 **Meter:** 58224 **In Date:** 10/25/2021 **Closed:** 10/25/2021

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 126.85

Total Labor: 8,287.05

Total Comm: 748.25

Total Parts: 7,002.23