Palm Beach County Fleet Management Asset Maintenance History 10198048 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Charged: 15702.02 Total Hours: 72.60 Labor: 4,874.00 Parts: 9,294.91 Comm: 1,533.11 Work Order: 1503072 **Meter:** 116 03/25/2015 **Closed:** 03/25/2015 In Date: Problem: 1061 - Pre Delivery Inspection **Work Completed** - Pre Delivery Inspection Comm: 0.00 Hours: 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00 Work Order: 1508836 09/02/2015 **Closed**: 09/02/2015 **Meter:** 3431 In Date: Problem: 1 - Wash ticket(s) issued **Work Completed** - 1 - Wash ticket(s) issued Hours: 0.00 Comm: 8.34 Labor: 0.00 Parts: 0.00 Total: 8.34 Work Order: 1509577 **Meter:** 4118 In Date: 09/22/2015 **Closed**: 09/23/2015 Problem: Pm service. **Work Completed Parts Issued** Quantity Syn0w20 5.00 - P/m service. Napagold Oil Filter 1.00 - Rotate and balance tires. Accufit Hybrid 1.00 - Test drive. Accufit Hybrid 1.00 - Shop Supplies 2.00 **Brake Cleaner** Accufit Rear 1.00 **Shop Supplies** 1.00 Hours: 3.50 Comm: 0.00 Labor: 210.00 Parts: 76.78 Total: 286.78 Work Order: 1511948 **Meter:** 4800 In Date: 11/23/2015 Closed: 11/23/2015 Problem: 10 - Wash ticket(s) issued **Work Completed** - 10 - Wash ticket(s) issued Hours: 0.00 Comm: 83.40 Labor: 0.00 Parts: 0.00 Total: 83.40

Palm Beach County Fleet Management Asset Maintenance History 10198048 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1603822 Meter: 7940 In Date: 04/12/2016 Closed: 04/22/2016

Problem: P.M. service and detail.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Napagold Oil Filte	r	1.00
- Rotate and balance all tire.		Syn0w20		5.00
- Shop Supplies		Washer Fluid Cond	centr	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 32.93	Total: 212.93

Work Order: 1604110 Meter: 7825 In Date: 04/19/2016 Closed: 04/19/2016

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.00 Labor: 0.00 Parts: 0.00 Total: 90.00

Work Order: 1610987 Meter: 16297 In Date: 10/25/2016 Closed: 10/31/2016

Problem: Pm service.

Work Completed		Parts Issued		Quantity
- Pm service.		Syn0w20		5.00
- Rotate and balance tires.		Napagold Oil Filte	r	1.00
- Test drive.		Washer Fluid Cond	centr	1.00
- Shop Supplies		Wiper Blade Anco		1.00
		Wiper Bleade Ance	0	1.00
		Shop Supplies		1.00
Hours: 3.50	Comm: 0.00	Labor: 210.00	Parts: 39.83	Total: 249.83

Palm Beach County Fleet Management Asset Maintenance History 10198048 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: Problem:	1704952 Pm service.	Meter:	13858		In Date:	05/18/2017	Closed:	05/22/201
Work Com	pleted			Parts Issued			Qı	uantity
- Pm servic	ce.			Syn0w20				5.00
- Rotate ar	nd balance tires.			Napagold Oil Filter				1.00
- Test drive	e.			Wiper Blade Anco				1.00
- Shop Sup	pplies			Wiper Bleade Anco				1.00
				Washer Fluid Concer	ntr			1.00
				Shop Supplies				1.00
	Hours: 3.50		Comm: 0.00	Labor: 210.00	Parts: 40.	58	Total:	250.58
Nork Order: Problem:	1707480 Check front end noise.	Meter:	14040		In Date:	07/31/2017	Closed:	08/02/201
Work Com	pleted			Parts Issued			Qı	uantity
- Brake and	d suspension inspection per co	omplaint. No pro	blem found.	Shop Supplies				1.00
	e to verify complaint. No probl							
- Shop Sup								
5op 5ap	Hours: 1.50		Comm: 0.00	Labor: 90.00	Parts: 2.0	0	Total:	92.00
Work Order: Problem:	1800316 Pm service.	Meter:	17236		In Date:	01/09/2018	Closed:	01/11/201
Work Com	pleted			Parts Issued			Qı	uantity
- Pm servic	ce.			Syn0w20				5.00
- Rotate ar	nd balance tires.			Napagold Oil Filter				1.00
- Test drive	2.			Washer Fluid Concer	ntr			1.00
- Shop Sup	oplies			Wiper Blade Anco				1.00
	•			Wiper Bleade Anco				1.00
				Shop Supplies				1.00
	Hours: 3.50		Comm: 0.00	Labor: 210.00	Parts: 40.	94	Total:	250.94

Palm Beach County Fleet Management Asset Maintenance History 10198048 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1807150 Meter: 22451 In Date: 07/13/2018 Closed: 07/19/2018

Problem: PM Service

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Replace all four tires .balance and nitrogen fill tires.		Syn0w20		5.00
- Check battery and charging system . Charge battery fully	After charge	14in Exactfit-rear		1.00
battery failed load test . R&r defective battery.		Wiper Blade Anco		1.00
- Complete four wheel alignment. Road test.		Wiper Bleade Anco)	1.00
- Shop Supplies		Cabin Air Filter		1.00
		Air Filter (gold)		1.00
		Lithium Coin Cell		1.00
		Battery		1.00
		738274571 195-65r15 A		4.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 7.50 Co	omm: 0.00	Labor: 450.00	Parts: 835.89	Total: 1,285.8

Work Order: 1810332 Meter: 26422 In Date: 10/04/2018 Closed: 10/22/2018

Problem: Noise from left front tire area.

Work Completed		Parts Issued		Quantity
- Test drive to locate noise . Reinstall lower splash	shield and retest.	Lithium Coin Cell		1.00
- Test and replace key fob battery.		Shop Supplies		1.00
- Shop Supplies				
Hours: 0.80	Comm: 0.00	Labor: 53.60	Parts: 8.42	Total: 62.02

Work Completed

- Tow From: 2650 Military Trail (cresthaven and Military) To: Lv shop

Hours: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10198048 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1811485 Meter: 27609 11/07/2018 **Closed:** 11/15/2018 In Date: Problem: P.M. service. **Work Completed Parts Issued** Quantity Napagold Oil Filter 1.00 - P.m. service . Syn0w20 5.00 - Rotate and high speed balance all four tires. 14in Exactfit-rear 1.00 - Shop Supplies 19in Exactfit-hbrd 1.00 26in Exactfit-hbrd 1.00 **Shop Supplies** 1.00 Hours: 3.00 Comm: 0.00 Labor: 201.00 Parts: 76.67 Total: 277.67 Work Order: 1813063 Meter: 29549 In Date: 12/27/2018 **Closed**: 12/31/2018 Problem: Spare on right rear. Quantity **Work Completed Parts Issued** 738274571 195-65r15 A 1.00 - Replace right rear tire and balance . Nitrogen fill all tires and remount spare. **Shop Supplies** 1.00 - Shop Supplies Tire Disposal Fee 1.00 Hours: 0.50 Comm: 0.00 Labor: 33.50 Parts: 125.38 Total: 158.88 Work Order: 1813108 Meter: 29481 **In Date:** 12/26/2018 **Closed:** 12/31/2018 Problem: Flat tire on R/P

Comm: 0.00

Labor: 0.00

Parts: 0.00

Total: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10198048 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1902438 Meter: 32617 In Date: 03/05/2019 Closed: 03/13/2019

Problem: P.M. service.

Work Completed		Parts Issued		Quantity	
- P.m. service.	Napagold Oil Filte	er	1.00		
- Rotate and high speed balance all four tires . Nitro	ofill all.	Syn0w20 Wiper Blade Anco Wiper Bleade Anco 14in Exactfit-rear Washer Fluid Concentr		5.00	
- Shop Supplies				1.00	
				1.00	
				1.00	
				1.00	
		Shop Supplies		1.00	
Hours: 3.00	Comm: 0.00	Labor: 201.00	Parts: 53.39	Total: 254.39	

Work Order: 1906297 Meter: 37578 In Date: 06/14/2019 Closed: 06/24/2019

Problem: PM Service

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Rotate and balance all four tires . Nitrofill all .		Syn0w20		5.00
- Shop Supplies		Washer Fluid Concentr		1.00
		14in Exactfit-rear		1.00
		Wiper Blade Anco Wiper Bleade Anco		1.00
				1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 201.00	Parts: 53.37	Total: 254.37

Work Order: 1907155 Meter: 38183 In Date: 07/11/2019 Closed: 07/11/2019

Problem: 3 - Wash ticket(s) issued

Work Completed

- 3 - Wash ticket(s) issued

Hours: 0.00 Comm: 25.02 Labor: 0.00 Parts: 0.00 Total: 25.02

Palm Beach County Fleet Management Asset Maintenance History 10198048 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1910436 Meter: 43212 In Date: 10/08/2019 Closed: 10/24/2019

Problem: PM Service

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filter	•	1.00
- Rotate and balance all four tires . Nitrofill all.		Syn0w20		5.00
- Shop Supplies		Washer Fluid Concentr		1.00
		14in Exactfit-rear Wiper Blade Anco Wiper Bleade Anco Mac Wite Lithium Gres		1.00
				1.00
				1.00
				1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 219.00	Parts: 60.24	Total: 279.24

Work Order: 2003345 Meter: 48225 In Date: 04/02/2020 Closed: 04/09/2020

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	er	1.00
- Replace cabin air filter and clean fresh air intake .		Syn0w20		5.00
- Rotate and balance all four tires . Nitrofill all.		14in Exactfit-rear		1.00
- Shop Supplies		Wiper Bleade And	0	1.00
		Wiper Blade Anco		1.00
		Washer Fluid Con-	centr	1.00
		Non-chlor Brake C	Clnr	1.00
		Cabin Filter		1.00
		Shop Supplies		1.00
Hours: 3.50	Comm: 0.00	Labor: 255.50	Parts: 68.52	Total: 324.02

Work Order: 2005290 Meter: 48891 In Date: 05/26/2020 Closed: 05/27/2020

Problem: No start

Work Completed

- Tow From: 345 S Congress Ave Delray Beach To: Lv shop

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Palm Beach County Fleet Management Asset Maintenance History 10198048 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2005302 Meter: 49051 In Date: 05/27/2020 Closed: 05/29/2020

Problem: Towed in for no start.

Work Completed

- Charge battery fully . Test battery and charging system . Perform draw test

. Right front Map light switch left on .

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 0.00 Total: 36.50

Work Order: 2007720 Meter: 50833 In Date: 08/05/2020 Closed: 08/25/2020

Problem: Towed in for not going in gear .

Work Completed	Parts Issued	Quantity
- Transport vehicle from dealer for stolen hybrid battery and component	Battery Replacement	1.00
replacement and reprogramming.	Shop Supplies	1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 6,711.95 Total: 6,784.95

Work Order: 2007930 Meter: 50833 In Date: 08/04/2020 Closed: 08/11/2020

Problem: Not shifing into Gear

Work Completed

- Tow From: 345 S Congress, Delay-se Parking Lot To: Lv Shop-2601 Vista

Parkway

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2008148 Meter: 50833 In Date: 08/13/2020 Closed: 08/14/2020

Problem: Transport to PB Toyota Scion for Battery replacement

Work Completed

- Tow From: Fleet Lv shop To: Palm Beach Toyota @ Southern and

Congress ave

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Palm Beach County Fleet Management Asset Maintenance History 10198048 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2010537 Meter: 52751 In Date: 10/20/2020 Closed: 11/02/2020

Problem: P.M. service and detail.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filter	ſ	1.00
- replace 4 tires	Syn0w20		5.00	
- Preform 4 wheel alignment using alignment machine. Adjust front toe,		Wiper Blade Anco		1.00
camber, and caster. Center steering wheel. Test drive.		Wiper Bleade Anco		1.00
- Shop Supplies		Tire Mic 195/65/15 Shop Supplies		4.00
				1.00
		Tire Disposal Fee		4.00
Hours: 6.50	Comm: 0.00	Labor: 474.50	Parts: 546.78	Total: 1,021.28

Work Order: 2010760 Meter: 52751 In Date: 10/22/2020 Closed: 10/26/2020

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.00 Labor: 0.00 Parts: 0.00 Total: 90.00

Work Order: 2103386 Meter: 57883 In Date: 03/25/2021 Closed: 04/08/2021

Problem: P.M. service, check tires, recall 20V-369 and detail.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Syn0w20		5.00
- Replaced cabin filter. Cleaned debris from fresh air	Napagold Oil Filter 14in Exactfit-rear 19in Exactfit-hbrd		1.00	
- Rotated and balanced all 4 tire. Nitrogen filled all ti			1.00	
All tires Michelin with 9/32 tread or more. No problem			1.00	
- Transport to and from dealer for recall 20v-369.	- Transport to and from dealer for recall 20v-369.			1.00
- Shop Supplies		Cabin Air Filter		1.00
		Shop Supplies		1.00
Hours: 5.50	Comm: 0.00	Labor: 401.50	Parts: 86.04	Total: 487.54

Palm Beach County Fleet Management Asset Maintenance History 10198048 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2103982 Meter: 57883 In Date: 04/08/2021 Closed: 04/08/2021

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.00 Labor: 0.00 Parts: 0.00 Total: 90.00

Work Order: 2106460 Meter: 60584 In Date: 06/15/2021 Closed: 06/17/2021

Problem: broken windshield

Work Completed Parts Issued Quantity

- set up repairs & reasset Shop Supplies 1.00

- Shop Supplies

Hours: 1.00 Comm: 858.35 Labor: 73.00 Parts: 4.00 Total: 935.35

Work Order: 2108637 Meter: 63110 In Date: 08/10/2021 Closed: 08/17/2021

Problem: PM Service.

Work Completed		Parts Issued		Quantity
 - Preventive Maint. Service - Rotate and speed balance, nitro fill - Check all brakes, R & I new front brakes, Resurface both front rotors, Service caliper sliding bolts, bleed brakes, road test 		Napagold Oil Filter		1.00
		Syn0w20		5.00
		Washer Fluid Concentr		1.00
		14in Exactfit-rear		1.00
- Shop Supplies		19in Exactfit-hbrd		1.00
		26in Exactfit-hbrd		1.00
		Brk Fluid Dot 4-12oz		1.00
		Non-chlor Brake Clnr		1.00
		Brake Pad		1.00
		Shop Supplies		1.00
Hours: 6.00	Comm: 0.00	Labor: 438.00	Parts: 123.75	Total: 561.75

Palm Beach County Fleet Management Asset Maintenance History 10198048 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2112503 Meter: 68213 In Date: 11/23/2021 Closed: 12/02/2021

Problem: PM Service. Squeak from left front wheel area.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service	entive Maint. Service		14in Exactfit-rear	
- Rotated and balanced all 4 tires. Nitrogen filled all tires.		19in Exactfit-hbrd		1.00
- Battery tested bad. Charged battery	26in Exactfit-hbrd		1.00	
battery.		Napagold Oil Filter		1.00
- Diagnose key fob inop. Replaced ke	Syn0w20		5.00	
- Test drive for noise. Inspect front bra	Lithium Coin Cell		1.00	
calipers slides. Test drove and noise is gone Shop Supplies		Battery		1.00
		Shop Supplies		1.00
Hours: 5.30	Comm: 0.00	Labor: 386.90	Parts: 307.49	Total: 694.39

Work Order: 2200128 Meter: 69052 In Date: 01/05/2022 Closed: 01/05/2022

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 72.60 Total Labor: 4,874.00 Total Comm: 1,533.11 Total Parts: 9,294.91