

10/17/2016
2:45:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155214 2004 GMC 2500 HD Utility Truck, W/Strobe System

Workorder: 441361 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 04/14/2004	Hours	Description
Close Date: 04/14/2004	Quantity	
- Pre-Delivery Inspection	2.00	
Parts Charge: 0.00	Labor Charge: 100.00	

Workorder: 443113 **Problem:** TAG CHARGE

Meter Reading: 18	Labor	Parts
In Date: 04/30/2004	Hours	Description
Close Date: 04/30/2004	Quantity	
- Tag Charge		TAG CHARGE 1.00
Parts Charge: 51.85	Labor Charge: 0.00	

Workorder: 459938 **Problem:** P.M SERVICE,WASHER BOTTLE LEAKING

Meter Reading: 5008	Labor	Parts
In Date: 10/25/2004	Hours	Description
Close Date: 11/03/2004	Quantity	
- Pm	4.40	10W30 MOTOR OIL 6.00
- Fm Sr To Maroone Chev For Warrenty Repair To Washer		1522 OIL FILTER FRM PH3675/9837 WIX 51522 1.00
Bottle Pu When Done		SHOP SUPPLIES 1.00
- Shop Supplies		
Parts Charge: 11.02	Labor Charge: 220.00	

Workorder: 465655 **Problem:** SLOW LEAK L/FRONT TIRE

Meter Reading: 6368	Labor	Parts
In Date: 12/29/2004	Hours	Description
Close Date: 12/30/2004	Quantity	
- Repair 2 Tires	1.40	SHOP SUPPLIES 1.00
- Shop Supplies		
Parts Charge: 2.00	Labor Charge: 70.00	

10/17/2016
2:45:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155214 2004 GMC 2500 HD Utility Truck, W/Strobe System

Workorder: 543401

Problem: PM SERVICE

Meter Reading: 10161		Labor		Parts	
In Date: 04/29/2005	Close Date: 05/10/2005	Hours	Description	Quantity	
- Pm		4.40	AF1519 AIR FILTER USE LAF1520 FRM CA8755A		1.00
- Transprot To Rayside For Tail Gate Strap Recall			15/40 OIL		7.00
- Shop Supplies			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			10020 INJECTOR CLEANER DON'T REORDER		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			SHOP SUPPLIES		1.00
Parts Charge: 36.52		Labor Charge: 220.00			

Workorder: 548589

Problem: LANGUAGE ON GAUGES NEEDS RESET,DRIVERS SEAT,RECALL

Meter Reading: 11575		Labor		Parts	
In Date: 06/24/2005	Close Date: 07/05/2005	Hours	Description	Quantity	
- Sr Fleet To Maroone For Chevy For Warranty Work		2.90	SHOP SUPPLIES		1.00
- Check Instrument Cluster , Sent To Dealer					
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 145.00			

Workorder: 560171

Problem: FLAT TIRE

Meter Reading: 13222		Labor		Parts	
In Date: 12/30/2005	Close Date: 01/10/2006	Hours	Description	Quantity	
- Replace Tire		1.00	744395900 245/75R16 245/75R16 WRANGLER HT		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge: 144.67		Labor Charge: 50.00			

10/17/2016
2:45:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155214 2004 GMC 2500 HD Utility Truck, W/Strobe System

Workorder: 634481

Problem: P.M SERVICE

Meter Reading: 14745		Labor		Parts	
In Date: 02/14/2006	Close Date: 02/15/2006	Hours	Description	Quantity	
- Pm Service		4.00	6678 AIR FILTER FRM CA8755A WIX 46678		1.00
- Rotate Tires And Replace L/F			10W30 MOTOR OIL		7.00
- Shop Supplies			SHOP SUPPLIES		1.00
			744395900 245/75R16 245/75R16 WRANGLER HT		1.00
			10020 INJECTOR CLEANER DON'T REORDER		1.00
			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
Parts Charge: 185.92		Labor Charge: 50.00			

Workorder: 637739

Problem: NAILS IN BOTH REAR TIRES

Meter Reading: 17401		Labor		Parts	
In Date: 04/20/2006	Close Date: 04/24/2006	Hours	Description	Quantity	
- Repaired Flats		2.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 100.00			

Workorder: 642023

Problem: P.M SERVICE

Meter Reading: 20030		Labor		Parts	
In Date: 07/07/2006	Close Date: 07/11/2006	Hours	Description	Quantity	
- Pm Service		4.50	SHOP SUPPLIES		1.00
- Mount And Balance 2 Front Tires			TIRE DISPOSAL FEE		2.00
- Shop Supplies			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			744395900 245/75R16 245/75R16 WRANGLER HT		2.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			6678 AIR FILTER FRM CA8755A WIX 46678		1.00
			31-22 WIPER BLADES 22" WIPER BLADE		2.00
			10020 INJECTOR CLEANER DON'T REORDER		1.00
			10W30 MOTOR OIL		7.00
Parts Charge: 362.78		Labor Charge: 75.00			

10/17/2016
2:45:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155214 2004 GMC 2500 HD Utility Truck, W/Strobe System

Workorder: 732744

Problem: P.M.SERVICE,NAILS IN R/FRONT TIRE

Meter Reading: 25697		Labor		Parts	
In Date: 01/12/2007	Close Date: 01/16/2007	Hours	Description	Quantity	
- Pm Service		7.50	31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Fill Tires W/Nitrogen			SHOP SUPPLIES		1.00
- Service Differential			10020 INJECTOR CLEANER DON'T REORDER		1.00
- Flush Transmission			10W30 MOTOR OIL		7.00
- Flat Repair			SYN/ATF TRANS FLUID SYNTHETIC		16.00
- Road Test			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
- Shop Supplies			85/140 GEAR OIL GEAR LUBE		3.00
Parts Charge:		112.43	Labor Charge:		27.50

Workorder: 736721

Problem: WILL NOT START (VEH. AT METER SHOP)

Meter Reading: 27657		Labor		Parts	
In Date: 04/05/2007	Close Date: 04/05/2007	Hours	Description	Quantity	
- Complaint - Will Not Start (At Meter Shop); Jump Start; Recharge & Test Batt Sys; Code 4L1S6-Rub8; R&R Defective Battery		1.00	SHOP SUPPLIES		1.00
- Shop Supplies			GROUP 78 BATTERY (ACD 78PS)		1.00
Parts Charge:		92.98	Labor Charge:		55.00

Workorder: 737417

Problem: SISTERS TOWING & TRANSPORTATON TOW FROM WHISPER WA

Meter Reading: 0		Labor		Parts	
In Date: 04/19/2007	Close Date: 04/19/2007	Hours	Description	Quantity	
- Sisters Towing & Transportaton Tow From Whisper Walk Development - Tow To Sr Fleet					
Parts Charge:		0.00	Labor Charge:		0.00
				Commercial Charge:	78.00

10/17/2016
2:45:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155214 2004 GMC 2500 HD Utility Truck, W/Strobe System

Workorder: 737420

Problem: R/REAR TIRE FLAT

Meter Reading: 28055	Labor	Parts	
In Date: 04/19/2007	Hours	Description	Quantity
- R&R Rear Tires	2.00	744395900 245/75R16 245/75R16 WRANGLER HT	2.00
- Rotate Tires & Test Drive		TIRE DISPOSAL FEE	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	305.19	Labor Charge:	41.25

Workorder: 742626

Problem: P.M.SERVICE

Meter Reading: 28987	Labor	Parts	
In Date: 08/07/2007	Hours	Description	Quantity
- Pm Service	2.75	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Shop Supplies		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		USED FIREX REFURBED FIRE EXTINGUISHERS	1.00
		SHOP SUPPLIES	1.00
		10W30 MOTOR OIL	7.00
		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
Parts Charge:	55.82	Labor Charge:	151.25

Workorder: 832838

Problem: SKIPPING

Meter Reading: 30106	Labor	Parts	
In Date: 01/16/2008	Hours	Description	Quantity
- Diagnose Fuel Pump As Faulty; Remove Tank Conn, Lines&Shielddrop Tank & Remove Pump & Sender; Repl Oring; Reinstall Tank; Test Drive	7.00	FUEL PUMP W/SENDER	1.00
		SPARK PLUGS	8.00
		SHOP SUPPLIES	1.00
- Test Ignition Coils; Replace Bad Plug Wires & Fouled Spark Plugs		IGNITION WIRES	1.00
- Shop Supplies			
Parts Charge:	526.35	Labor Charge:	195.00

10/17/2016
2:45:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155214 2004 GMC 2500 HD Utility Truck, W/Strobe System

Workorder: 834625

Problem: P.M.SERVICE

Meter Reading: 30592	Labor	Parts	Quantity
In Date: 02/26/2008	Hours	Description	Quantity
- Pm Service	6.00	31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Replace R/F Center Cap & All Lug Nut Caps		LUG NUT CAPS	5.00
- Replace Leaking Brake Booster; Bleed P/S System		LUG NUT CAPS	19.00
- Shop Supplies		10W30 MOTOR OIL	7.00
		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
		SHOP SUPPLIES	1.00
		BRAKE BOOSTER	1.00
		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
		CENTER CAP	1.00
Parts Charge:	601.88	Labor Charge:	180.00

Workorder: 844246

Problem: PM SERVICE

Meter Reading: 33059	Labor	Parts	Quantity
In Date: 09/16/2008	Hours	Description	Quantity
- Pm Service	5.75	744395900 245/75R16 245/75R16 WRANGLER HT	2.00
- Replace Both Left & Right Led Tail Lamps		SHOP SUPPLIES	1.00
- R&R 2 Tires & Balance		44202R TAIL LIGHT 4" RED 42 LED	2.00
- Test Drive		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Shop Supplies		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
		TIRE DISPOSAL FEE	2.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		10W30 MOTOR OIL	7.00
Parts Charge:	459.75	Labor Charge:	15.00

10/17/2016
2:45:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155214 2004 GMC 2500 HD Utility Truck, W/Strobe System

Workorder: 935693

Problem: PM SERVICE

Meter Reading: 34120		Labor	Parts	
In Date: 03/26/2009	Close Date: 03/31/2009	Hours	Description	Quantity
- Pm Service		7.25	1066 WHITE LITHIUM (CRC 05037)	1.00
- R&R Both Engine Mounts & Test Drive; Remove & Retap Strippedmotor Mount Bolts On R/S			SHOP SUPPLIES MOUNTS	1.00 2.00
- Install New Decal			1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Shop Supplies			10W30 MOTOR OIL	7.00
			6678 AIR FILTER FRM CA8755A WIX 46678	1.00
Parts Charge: 231.22		Labor Charge:	435.00	

Workorder: 937165

Problem: LEAKING FUEL.

Meter Reading: 34467		Labor	Parts	
In Date: 04/28/2009	Close Date: 05/07/2009	Hours	Description	Quantity
- C/S Leaking Fuel; R&R Fuel Hose		2.00	SHOP SUPPLIES	1.00
- Shop Supplies			FUEL HOSE	4.00
Parts Charge: 57.14		Labor Charge:	120.00	

Workorder: 943594

Problem: P.M.SERVICE/SEE NOTE

Meter Reading: 35237		Labor	Parts	
In Date: 09/23/2009	Close Date: 10/02/2009	Hours	Description	Quantity
- P.M.Service		7.25	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- R/R Pintal Pin			10W30 MOTOR OIL	7.00
- Unsieze And Lube Vise			31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Repair Connector At Power Pack To Light			USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Tighten Body Bolts			1401 BRAKE FLUID BRAKE FLUID	1.00
- Install Scan/Test For Codes(P0135,P0141,P0155,P0161,H02S;Heater Code.Perform Heater Current Test;Found No Problem At This Time;Test Drive			2560 HITCH PIN/CLIP SHOP SUPPLIES	1.00 1.00
- Shop Supplies				
Parts Charge: 55.26		Labor Charge:	435.00	

10/17/2016
2:45:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155214 2004 GMC 2500 HD Utility Truck, W/Strobe System

Workorder: 944468

Problem: BRAKE LIGHT DOESN'T WORK WHEN TRUCK IN GEAR. CHECK ENGINE LIGHT STAYS ON.

Meter Reading: 35411	Labor	Parts	
In Date: 10/13/2009	Hours	Description	Quantity
- Ck Engine Light On;Verified;Scan For	9.00	WIRE CONNECTOR	1.00
Codes#Po332;Pinpoint Test,Found Bad Knock		KNOCK SENSOR	1.00
Sensore;R/R Both Sensors&Intake Gaskets,Clear		INTAKE GASKET	1.00
Codes.Test Drive		KNOCK SENSOR	1.00
- Brake Light Inop. When Truck In Gear.Perform Pinpoint		09997 BRAKE CLEAN	1.00
Test For Intermittent Short,Tracing&Repair Short In Brake		SHOP SUPPLIES	1.00
Wiring Circuit.			
- Shop Supplies			
Parts Charge: 267.26		Labor Charge: 540.00	

Workorder: 1002658

Problem: P. M. SERVICE

Meter Reading: 38216	Labor	Parts	
In Date: 03/16/2010	Hours	Description	Quantity
- P. M. Service.	6.75	31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Lube Steering Shaft, Reinstall.		SHOP SUPPLIES	1.00
- Verify 2 Tires Punctures With Nails. Remove 2 Nails,		10W30 MOTOR OIL	7.00
Dismount Tires, Patch, Mount, Balance, Add Nitrogen.		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Remove Vice From Higtch Mount, Lube, Tighten & Test,			
Reinstall.			
- Clean Bumper, Install New Driving Sticker.			
- Shop Supplies			
Parts Charge: 34.05		Labor Charge: 405.00	

10/17/2016
2:45:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155214 2004 GMC 2500 HD Utility Truck, W/Strobe System

Workorder: 1010741

Problem: P. M. SERVICE

Meter Reading: 41399	Labor	Parts	
In Date: 09/30/2010	Hours	Description	Quantity
- P. M.	13.00	10W30 MOTOR OIL	7.00
- Installed Laptop. Checked For Codes P0135 Bank 1		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Sensor 1. Followed Diagnostic Chart. R&R Sensor & Road Tested.		TIRE DISPOSAL FEE	1.00
- Repaired Wiring To Lights In Rear.		744395900 245/75R16 245/75R16 WRANGLER HT	1.00
- Repaired Connection From Pach Assembly.		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Freed & Lubed Vise.		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
- Retightened Body Bolts.		O2 SENSOR,BANK 1 SENSOR 1	1.00
- R&R Tire & Balanced.		SHOP SUPPLIES	1.00
- Repaired Tire.			
- Repaired Leak @ Power Steering. Removed Line & Regulator, Installed New Orings.			
- Shop Supplies			
Parts Charge: 401.33	Labor Charge: 780.00		

Workorder: 1103685

Problem: P. M. SERVICE

Meter Reading: 44789	Labor	Parts	
In Date: 04/05/2011	Hours	Description	Quantity
- P. M. Service.	4.25	SHOP SUPPLIES	1.00
- Replace Both Rear Tires & Rotate To The Front.		744395900 245/75R16 245/75R16 WRANGLER HT	2.00
- Shop Supplies		10W30 MOTOR OIL	7.00
		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
		1066 WHITE LITHIUM (CRC 05037)	1.00
		TIRE DISPOSAL FEE	2.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
Parts Charge: 270.20	Labor Charge: 255.00		

10/17/2016
2:45:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155214 2004 GMC 2500 HD Utility Truck, W/Strobe System

Workorder: 1104865

Problem: Battery won't start

Meter Reading: 44794	Labor	Parts	
In Date: 05/06/2011	Hours	Description	Quantity
- Jump Start Vehicle From Parking Lot, Recharge, Check Battery, Check For Draw & Found Bad Battery. Replace Battery.	1.00	GROUP 78 BATTERY (ACD 78PS)	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	91.37	Labor Charge:	60.00

Workorder: 1111783

Problem: P.M.SERVICE

Meter Reading: 47190	Labor	Parts	
In Date: 11/02/2011	Hours	Description	Quantity
- P. M. Service.	4.75	10W30 MOTOR OIL	7.00
- Tighten & Adjust Tailgate.		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Remove Lube Steering Shaft.		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	46.83	Labor Charge:	285.00

Workorder: 1204918

Problem: P.M.SERVICE

Meter Reading: 52331	Labor	Parts	
In Date: 05/29/2012	Hours	Description	Quantity
- Pm	12.25	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Verify Needs Two Rear Tires Mount Balance Rotate To Front Add N2		10W30 MOTOR OIL	7.00
- Verify Needs Rrer Pads Replace Rear Pads Turn Rotors Reassemble Test Drive		744395900 245/75R16 245/75R16 WRANGLER HT	2.00
- Verify Ck Engine Light On Scan Found Code Po442 Small Leak In Evap System Inspect Evap Sys Tighten Gas Cap Clear Code Test Drive		TIRE DISPOSAL FEE	2.00
- Ck Chains On Bin Doors Repair Multiple Chains Install Rope		REAR BRAKE PAD	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	464.28	Labor Charge:	735.00

10/17/2016
2:45:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155214 2004 GMC 2500 HD Utility Truck, W/Strobe System

Workorder: 1207745 **Problem:** engine temp. light coolant come on and air dont get cold

Meter Reading: 53761	Labor	Parts	
In Date: 08/15/2012	Hours	Description	Quantity
- Ck Engine Temp Light Is On Verify Concern Perform	8.75	WATER PUMP	1.00
P[Inpoint Test And Found Leaking Water Pump Replace		THERMOSTAT GASKET	1.00
Water Pump Thermostat And Flush Cooling Sye		THERMOSTAT	1.00
- Replace Alternator And Ac Belt		ALT.BELT	1.00
- Ck Ac Not Cold Verfiy Concern Perform Perssure Test		A/C BELT	1.00
And Found Low Freon Evacuate Add Dye Recharge Ok		SHOP SUPPLIES	1.00
For Leaks And Ws Unable To Fint Leaks At This Time		R134A REFRIGERANT	1.00
- Shop Supplies		ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)	1.00
		09997 BRAKE CLEAN	1.00
Parts Charge:	215.46	Labor Charge:	525.00

Workorder: 1301641 **Problem:** pm

Meter Reading: 57327	Labor	Parts	
In Date: 02/15/2013	Hours	Description	Quantity
- Pm	7.50	NAPAGOLD OIL FILTER	1.00
- Replace Both Rear Tires And Rotate To The Front		744395900 245-75R16	2.00
- Ck Engine Light Was On Scan And Found Code Po155		TIRE DISPOSAL FEE	2.00
Perform Pinpoint Teat And Found Bad O2 Sensor Bank 2		10W30 BULK SR	7.00
Sensor 1, Replace Sensor Clear Code And Test Drive		USED FIREX REFURBED F	1.00
- Fill Al Tires With Nitrogen		SHOP SUPPLIES	1.00
- Remove Lube And Reinstall Steering Shaft		OXYGEN SENSOR	1.00
- Shop Supplies			
Parts Charge:	614.07	Labor Charge:	450.00

10/17/2016
2:45:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155214 2004 GMC 2500 HD Utility Truck, W/Strobe System

Workorder: 1309815

Problem: P.M.SERVICE

Meter Reading: 62248	Labor	Parts	
In Date: 09/27/2013	Hours	Description	Quantity
- Pm	6.25	NAPAGOLD OIL FILTER	1.00
- Verify Needs Two Tires Dismount Mount Balance Add N2		744395900 245-75R16	2.00
- Verify Vice On Hitch Not Working		10W30 BULK SR	7.00
- Remove Steering Shaft Lubricate Shaft And Reinstall		WD40 16OZ	1.00
- Shop Supplies		TIRE DISPOSAL FEE	2.00
		WIPER BLADE	2.00
		SHOP SUPPLIES	1.00
Parts Charge:	521.10	Labor Charge:	375.00

Workorder: 1401460

Problem: BATTERY?

Meter Reading: 65250	Labor	Parts	
In Date: 02/13/2014	Hours	Description	Quantity
- Recharge And Ck Battery Replace Bad Battery	0.75	SHOP SUPPLIES	1.00
- Shop Supplies		GROUP 78 BATTERY	1.00
Parts Charge:	97.60	Labor Charge:	45.00

Workorder: 1403397

Problem: flat tire in front of meter shop

Meter Reading: 67347	Labor	Parts	
In Date: 04/08/2014	Hours	Description	Quantity
- Ck Flat Tire Replace 4 Rear Tire Rr Valve Stem Add N2	1.00	SHOP SUPPLIES	1.00
- Shop Supplies		744395900 245-75R16	1.00
		TIRE DISPOSAL FEE	1.00
Parts Charge:	244.33	Labor Charge:	60.00

10/17/2016
2:45:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155214 2004 GMC 2500 HD Utility Truck, W/Strobe System

Workorder: 1403941

Problem: P.M.SERVICE

Meter Reading: 67856		Labor	Parts	
In Date: 04/23/2014	Close Date: 05/28/2014	Hours	Description	Quantity
- Pm		12.25	USED FIRE X REFURBISHED	1.00
- Replace Left Rear Brake Light Assembly			NAPAGOLD AIR FILTER	1.00
- Replace Leaking Left Rear Axle Seal			PTEX ULTRA BLACK 30Z	1.00
- Resurface Front Rotors Svc Calipers Replace Pads And Test Drive			NAPA OIL SEAL	1.00
			BRAKE PAD	1.00
- Remove Steering Shaft Lube And Adj Shaft			1401 BRAKE FLUID BRA	2.00
- Shop Supplies			SEAL	1.00
			SHOP SUPPLIES	1.00
			WD40 16OZ	1.00
			LED SUP MDL 44 42 DIO	1.00
			10W30 BULK SR	7.00
			NAPAGOLD OIL FILTER	1.00
			WIPER BLADE	2.00
Parts Charge:		373.51	Labor Charge:	735.00

Workorder: 1409973

Problem: p/s leaking

Meter Reading: 69689		Labor	Parts	
In Date: 10/03/2014	Close Date: 10/21/2014	Hours	Description	Quantity
- Replace Leaking Power Steering Cooler And Flush Power Steering System		7.00	SHOP SUPPLIES	1.00
			P/S COOLER ASSY	1.00
- Install Brake Pedal Cover			BRAKE CLEANER	1.00
- Replace Right Front Running Light Bulb, Repair Both Front Turn Signal And Left Marker Light			BULB	1.00
			PEDAL PAD	1.00
- Shop Supplies			BULB	2.00
			PWR STEERING FL-QUART	1.00
Parts Charge:		127.46	Labor Charge:	420.00

10/17/2016
2:45:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155214 2004 GMC 2500 HD Utility Truck, W/Strobe System

Workorder: 1410448

Problem: CHECK ENGINE LIGHT ON

Meter Reading: 69689	Labor	Parts	
In Date: 10/20/2014	Hours	Description	Quantity
- Ck Engine Light Is On Scan And Found Code Po442 Fer	4.75	FUEL LINE HOSE	10.00
Form Pinpoint Teste On Evap Sys And Foiund Leaking		SHOP SUPPLIES	1.00
Vent Hose Replace Hose And Clear Code		HOSE CLAMP	4.00
- Test Drive Before And After Repair			
- Shop Supplies			
Parts Charge:	14.06	Labor Charge:	285.00

Workorder: 1412878

Problem: P.M.SERVICE,CHECK ENGINE LIGHT ON

Meter Reading: 71292	Labor	Parts	
In Date: 12/30/2014	Hours	Description	Quantity
- Pm	8.25	ATM-15 FUSE	1.00
- Replace 3 Times Both Rear And Right Front Use Right		GAS CAP NON-LOCKING	1.00
Front To Replace Spare		GAS CAP NON-LOCKING	1.00
- Ck And Replace Blown Fuse For Dlc And Cig Lighter		TIRE DISPOSAL FEE	3.00
- Ck Engoine Light Is On Scan Foiund Po442, Perform		SHOP SUPPLIES	1.00
Pinpoint Test On Evap System And Found Bad Gas Cap		NAPAGOLD OIL FILTER	1.00
Replace Gas Cap And Clear Codes		WASHER FL	1.00
- Fill All Tires With Nitrogen		10W30 BULK SR	7.00
- Shop Supplies		744395900 245-75R16	3.00
Parts Charge:	774.44	Labor Charge:	495.00

10/17/2016
2:45:43PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155214 2004 GMC 2500 HD Utility Truck, W/Strobe System

Workorder: 1501940

Problem: Driver seat cushion damage.Ticking noise under dash.Power outlet inop.

Meter Reading: 72519 In Date: 02/24/2015	Close Date: 03/18/2015	Labor Hours	Description	Parts	Quantity
- Diagnose For Noise Under Dash.Replace Defective Left Side Temperature Blend Door Actuator And Calibrate With Scan Tool.		3.75	SHOP SUPPLIES		1.00
			INTER STEERING SHAFT		1.00
			SEAT R AND R		1.00
- Inspect For Clunking Noise In Steering.Replace Worn Intermediate Sector Shaft.			AIR DOOR ACTUATOR		1.00
- Remove Damage Driver Seat For Repairs And Reinstall After Repaired.					
- Shop Supplies					
Parts Charge:		513.41	Labor Charge:		225.00

Workorder: 1506194

Problem: noise from rear of vehicle

Meter Reading: 73990 In Date: 06/19/2015	Close Date: 06/30/2015	Labor Hours	Description	Parts	Quantity
- Pm		7.50	10W30 BULK SR		7.00
- Ck Nosit From Rear Of Vehicle Test Drive Inspect And Found Broken Drive Shaft Center Support Bearing Remove Shaft Press Near Bearing On And Test Drive			BEARING		1.00
			WASHER FLUID CONCENTR		1.00
			USED FIRE X REFURBISHED		1.00
- Install Brake Pedal Cover			BOOT KIT		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			WIPER BLADE		2.00
			NAPAGOLD OIL FILTER		1.00
			BRAKE PAD PEDAL		1.00
Parts Charge:		297.58	Labor Charge:		450.00

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155214 2004 GMC 2500 HD Utility Truck, W/Strobe System

Workorder: 1601047

Problem: P.M.SERVICE

Meter Reading: 78208		Labor		Parts	
In Date: 01/29/2016	Close Date: 02/08/2016	Hours	Description		Quantity
- Pm		3.50	SHOP SUPPLIES		1.00
- Ck Charging Sys And Replace Bad Battery			USED FIRE X REFURBISHED		1.00
- Shop Supplies			NAPAGOLD OIL FILTER		1.00
			10W30 BULK SR		7.00
			WASHER FLUID CONCENTR		1.00
			BATTERY		1.00
Parts Charge: 152.36		Labor Charge: 210.00			

Workorder: 1604442

Problem: Gas cap missing.

Meter Reading: 78894		Labor		Parts	
In Date: 04/27/2016	Close Date: 04/29/2016	Hours	Description		Quantity
- Replace Missing Gas Cap And Secure With New Strap.		0.25	FUEL CAP		1.00
Parts Charge: 29.94		Labor Charge: 15.00			

Workorder: 1607960

Problem: Power outlets inop.

Meter Reading: 81585		Labor		Parts	
In Date: 08/03/2016	Close Date: 08/04/2016	Hours	Description		Quantity
- Test And Replace Open Fuse For Power Outlets.		0.50			
Parts Charge: 0.00		Labor Charge: 30.00			

Workorder: 1609096

Problem: Transition Prep Charge

Meter Reading: 82100		Labor		Parts	
In Date: 08/31/2016	Close Date: 08/31/2016	Hours	Description		Quantity
- Transition Prep Charge		2.00			
Parts Charge: 0.00		Labor Charge: 0.00			

Total Parts Charges:	8,847.42	Total Labor Charges:	10,065.00	Total Comm. Charges:	78.00
----------------------	-----------------	----------------------	------------------	----------------------	--------------