### Palm Beach County Fleet Management Asset Maintenance History 10169418 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/Extended Cab

Total Hours: 133.30 Labor: 8,341.60 Parts: 5,814.57 Comm: 1,374.40 Charged: 15530.57

Work Order: 739107 Meter: 0 In Date: 05/24/2007 Closed: 05/24/2007

Problem: PRE-DELIVERY INSPECTION

**Work Completed** 

- Pre-delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 110.00 Parts: 0.00 Total: 110.00

Work Order: 748589 Meter: 1403 In Date: 12/13/2007 Closed: 12/14/2007

Problem: P.M. SERVICE.

Work Completed		Parts Issued		Quantity
- Pm Service		Shop Supplies	1.00	
- Rotate And High Speed Balance All 4 Tires.nitro Fill Tires - Shop Supplies		1372 Oil Filter Fr	1372 Oil Filter Frm Ph2 Wix 51372	
		5w20 Engine Oil		6.00
		10020 Injector Cle	aner Don't Reorder	1.00
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 23.03	Total: 248.03

Work Order: 840321 Meter: 2757 In Date: 06/20/2008 Closed: 06/23/2008

Problem: P.M SERVICE

Work Completed			Parts Issued		Quantity
- Pm Service			Shop Supplies		1.00
- Shop Supplies			Ca8039 Air Filter L	bf Af1615 Wix 46418	1.00
			1372 Oil Filter Frr	m Ph2 Wix 51372	1.00
			G10166 Fuel Filter	Mtc Fg1083 Wix 33243	1.00
			5w20 Engine Oil		6.00
			31-20 Wiper Blade	es 20" Blade	2.00
			Used Firex Refurbe	ed Fire Extingshers	1.00
	Hours: 2.75	Comm: 0.00	Labor: 165.00	Parts: 62.23	Total: 227.23

Hours: 2.75

#### Palm Beach County Fleet Management Asset Maintenance History 10169418 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/Extended Cab

Work Order: 932641 **Meter:** 4453 01/12/2009 **Closed:** 01/17/2009 In Date: Problem: P.M. SERVICE. **Parts Issued** Quantity **Work Completed Shop Supplies** 1.00 - Pm Service 1372 Oil Filter Frm Ph2 Wix 51372 1.00 - Shop Supplies G10166 Fuel Filter Mtc Fq1083 Wix 33243 1.00 5w20 Engine Oil 7.00 31-20 Wiper Blades 20" Blade 2.00 Hours: 2.75 Comm: 0.00 Labor: 165.00 Parts: 51.58 Total: 216.58 Work Order: 941841 Meter: 5832 08/07/2009 Closed: In Date: 08/20/2009 **Problem:** pm service also see notes on valve stems campaign 09l03 **Parts Issued** Quantity **Work Completed Shop Supplies** 1.00 - P.m service. 1372 Oil Filter Frm Ph2 Wix 51372 1.00 - Rotate & balance all four tires, inspect valve stems Per 09103 campaign. 5w20 Engine Oil 7.00 - Shop Supplies 5lb Firex Abc Stock# 340280001 1.00 Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 83.34 Total: 308.34 Work Order: 1002187 Meter: 7958 In Date: 03/02/2010 **Closed**: 03/09/2010 Problem: P.M service. Quantity **Work Completed Parts Issued Shop Supplies** 1.00 - P.m service. 1372 Oil Filter Frm Ph2 Wix 51372 1.00 - Shop Supplies G10166 Fuel Filter Mtc Fq1083 Wix 33243 1.00 5w20 Engine Oil 7.00

Comm: 0.00

Used Firex Refurbed Fire Extingshers

Parts: 48.20

Labor: 165.00

1.00

Total: 213.20

# Palm Beach County Fleet Management Asset Maintenance History 10169418 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/Extended Cab

Work Order: 1010592 Problem: P.M. Service.	Meter:	9920		In Date:	09/27/2010	Closed:	09/30/2010
Work Completed			Parts Issued			Qı	uantity
- P.m. Service.			Shop Supplies				1.00
- Rotate and balance all tires.			1372 Oil Filter Fri	m Ph2 Wix 51	372		1.00
- Shop Supplies			5w20 Engine Oil				7.00
			31-20 Wiper Blade	es 20" Blade			2.00
Hours: 3.75		Comm: 0.00	Labor: 225.00	Parts: 27.	29	Total:	252.29
Work Order: 1103705 Problem: Pm service.	Meter:	11431		In Date:	04/05/2011	Closed:	04/14/2011
Work Completed			Parts Issued			Qı	uantity
- Perform pm service.			Shop Supplies				1.00
- Rotate and balance all four tires.			Fuel Filter (use Frn	n G10166)			1.00
- Shop Supplies			1372 Oil Filter Fr	m Ph2 Wix 51	372		1.00
			Ca8039 Air Filter L	.bf Af1615 Wix	46418		1.00
			5w20 Engine Oil				7.00
			Used Firex Refurbe	ed Fire Extings	hers		1.00
			05046 Battery Pro	tector (crc)			1.00
Hours: 3.75		Comm: 0.00	Labor: 225.00	Parts: 53.	65	Total:	278.65
Work Order: 1111458 Problem: Pm service	Meter:	13814		In Date:	10/28/2011	Closed:	11/07/2011
Work Completed			Parts Issued			Qı	uantity
- P.m. Service.			Shop Supplies				1.00
- Rotate and balance all tires.			1372 Oil Filter Fri	m Ph2 Wix 51	372		1.00
- Shop Supplies			5w20 Engine Oil				7.00
			31-20 Wiper Blade	es 20" Blade			2.00
			Used Firex Refurbe	ed Fire Extings	hers		1.00
Hours: 3.75		Comm: 0.00	Labor: 225.00	Parts: 45.	92	Total:	270.92

## Palm Beach County Fleet Management Asset Maintenance History 10169418 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/Extended Cab

Work Order: 1113445 Meter: 14534 In Date: 12/27/2011 Closed: 01/04/2012

**Problem:** Left front seat back has hole in cover.

Work CompletedParts IssuedQuantity- R&r driver seat and send to upholstery shop for repair.Shop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 166.56 Labor: 60.00 Parts: 2.00 Total: 228.56

Work Order: 1204175 Meter: 15506 In Date: 05/02/2012 Closed: 05/10/2012

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Shop Supplies		1.00
- Rotate and balance all tires.		1372 Oil Filter Fr	m Ph2 Wix 51372	1.00
- Shop Supplies		G10166 Fuel Filter	Mtc Fg1083 Wix 33243	1.00
		5w20 Engine Oil		7.00
		31-20 Wiper Blade	es 20" Blade	2.00
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 37.71	Total: 262.71

Work Order: 1211541 Meter: 16964 In Date: 11/30/2012 Closed: 12/13/2012

Problem: Pm service.

Work Completed		Parts Issued		Quantity
- Perform pm service.		5w20 Engine Oil		7.00
- Test starting and charging system.battery failed loadte	est after	Ph2 Oil Filter Lbf Pl	า	1.00
recharge.replace failed battery with new.		Used Firex Refurbe	d F	1.00
- Remove and replace all four dry rotted valve stems wit	th new.nitrogen fill	Group 59 Battery N	<b>1</b> tc	1.00
and balance all four tires.		Shop Supplies		1.00
- Shop Supplies				
Hours: 5.75	Comm: 0.00	Labor: 345.00	Parts: 176.99	Total: 521.99

Hours: 4.75

#### Palm Beach County Fleet Management Asset Maintenance History 10169418 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/Extended Cab

Work Order: 1306189 Meter: 18585 06/20/2013 **Closed:** 06/28/2013 In Date: Problem: Pm service **Parts Issued** Quantity **Work Completed** 5w20 Engine Oil 7.00 - P.m. Service. 1.00 Napagold Oil Filter - Rotate and balance all tires. 31-20 Wiper Blades 20 2.00 - Shop Supplies Napagold Fuel Filter 1.00 Floor Mat-2pc Rub Bk 1.00 **Shop Supplies** 1.00 Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 70.64 Total: 295.64 Work Order: 1400079 Meter: 20200 In Date: 01/03/2014 **Closed**: 01/24/2014 Problem: P.M. service. **Work Completed Parts Issued** Quantity 5w20 Engine Oil 7.00 - P.m. Service. Napagold Oil Filter 1.00 - Replace and balance four new tires. Used Fire X Refurbished 1.00 - Complete wheel alignment.test drive. Wiper Blade 2.00 - Shop Supplies 235 75r17 Adventure 4.00 **Shop Supplies** 1.00 Tire Disposal Fee 4.00 Hours: 7.25 Comm: 0.00 Labor: 435.00 Parts: 990.40 Total: 1.425.40 Work Order: 1408266 Meter: 21788 In Date: 08/20/2014 **Closed:** 08/28/2014 Problem: Pm service. **Parts Issued** Quantity **Work Completed** 5w20 Engine Oil 7.00 - Pm service. Napagold Oil Filter 1.00 - Replace battery due to bad cell with warranty part. Napagold Fuel Filter 1.00 - Rotate and balance all four tires. Wiper Blade 2.00 - Shop Supplies **Shop Supplies** 1.00

Comm: 0.00

Labor: 285.00

Parts: 38.86

Total: 323.86

## Palm Beach County Fleet Management Asset Maintenance History 10169418 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/Extended Cab

Work Order: 1502241 Meter: 23014 In Date: 03/03/2015 Closed: 03/18/2015

Problem: Pm service.

Work Completed		Parts Issued		Quantity
- Pm service.		5w20 Engine Oil		7.00
- Flush and refill transmission fluid.		Napagold Oil Filte	r	1.00
- Rotate and balance all four tires.		Wiper Blade		2.00
- Shop Supplies		Used Fire X Refurb	oished	1.00
		Syn-atf Trans Fluid	S E	12.00
		Shop Supplies		1.00
Hours: 5.25	Comm: 0.00	Labor: 315.00	Parts: 104.23	Total: 419.23

Work Order: 1509728 Meter: 24809 In Date: 09/25/2015 Closed: 10/13/2015

Problem: Pm service.

Work Completed		Parts Issued		Quantity
- Pm service		5w20 Engine Oil		7.00
- Inspect and replace both defective front sway bar l	links.	Napagold Oil Filte	r	1.00
- Rotate and balance all four tires.		Wiper Blade		2.00
- Shop Supplies		Washer Fluid Cond	centr	1.00
		Napagold Fuel Filt	ter	1.00
		Sway Bar Link		2.00
		Shop Supplies		1.00
Hours: 4.75	Comm: 0.00	Labor: 285.00	Parts: 136.76	Total: 421.76

### Palm Beach County Fleet Management Asset Maintenance History 10169418 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/Extended Cab

Work Order: 1603710 Meter: 25963 In Date: 04/08/2016 Closed: 04/20/2016

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		7.00
- Pressure test and inspect cooling system.flush and re	efill system.	Napagold Oil Filter		1.00
- Test battery and charging system.replace bad battery	y.	Used Fire X Refurb	ished	1.00
- Replace front brake rotors, calipers and pads. flush an	d bleed system.	Mac Wite Lithium (	Gres	1.00
- Rotate and balance all tires.		20" Wiper Blade		2.00
- Shop Supplies		Napagold Air Filte	r	1.00
		Peak Global		2.00
		Battery		1.00
		Caliper w/ Hardwa	re - Right Front (eclip	1.00
		Caliper w/ Hardwa	re - Left Front (eclips	1.00
		B Fluid Dot 3-32oz		1.00
		Brake Rotor Only		2.00
		Disc Brake Pads		1.00
		Front Caliper		1.00
		Shop Supplies		1.00
Hours: 10.75	Comm: 0.00	Labor: 645.00	Parts: 561.49	Total: 1,206.49

Work Order: 1608489 Meter: 26960 In Date: 08/16/2016 Closed: 08/29/2016

Problem: Rear tail light lens cracked and missing and wiper blades and right rear door inop

Work Completed		Parts Issued		Quantity
- Diagnose and replace defective right rear door	latch assemble.	Door Latch		1.00
- Replace both tail light lenses.fabricate and inst	all strobe lights.	lamp assy		1.00
- Shop Supplies	-	Tail Lamp Assemb	ly	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 352.10	Total: 532.10

## Palm Beach County Fleet Management Asset Maintenance History 10169418 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/Extended Cab

Work Order: 1610599 Meter: 27396 In Date: 10/13/2016 Closed: 10/26/2016

**Problem:** P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		6.00
- Inspect and service transfer case.		Napagold Oil Filte	r	1.00
- Rotate and balance tires.		20" Wiper Blade		2.00
- Shop Supplies		Washer Fluid Cond	centr	1.00
		Stg Wheel Cov - Fe	ord	1.00
		Tran Flu Qt Dexron3i Napagold Fuel Filter		2.00
				1.00
		Shop Supplies		1.00
Hours: 4.75	Comm: 0.00	Labor: 285.00	Parts: 58.22	Total: 343.22

Work Order: 1704511 Meter: 28838 In Date: 05/04/2017 Closed: 05/11/2017

**Problem:** P.M. Service. Driver side rear door does not open.

Work Completed		Parts Issued	Quantity
- P.m. service.		5w20 Engine Oil	6.00
- R&r drivers front seat for repair.		Napagold Oil Filter	1.00
- R&r door latch assembly.driver side rear door.retest		20" Wiper Blade	2.00
- Shop Supplies		Used Fire X Refurbished	1.00
		Washer Fluid Concentr	1.00
		Door Latch	1.00
		Seat R And R	1.00
		Stg Wheel Cov - Ford	1.00
		Shop Supplies	1.00
Hours: 4.75	Comm: 0.00	Labor: 285.00 Parts: 593.93	Total: 878.93

## Palm Beach County Fleet Management Asset Maintenance History 10169418 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/Extended Cab

Work Order: 1711662 Meter: 29955 In Date: 11/29/2017 Closed: 12/07/2017

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		6.00
- Rotate and balance four tires.		Napagold Oil Filte	r	1.00
- Shop Supplies		Washer Fluid Con-	centr	1.00
		20" Wiper Blade		2.00
		Napagold Fuel Fil	ter	1.00
		Shop Supplies		1.00
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 33.62	Total: 258.62

Work Order: 1806924 Meter: 30612 In Date: 07/06/2018 Closed: 07/16/2018

Problem: PM Service

Work Completed		Parts Issued	Quantity		
<ul><li>P.m. service.</li><li>Replace all four tires and balance .nitrogen fill tires.</li><li>Complete front end alignment and road test.</li></ul>		Napagold Oil Filter	1.00		
		5w20 Engine Oil	6.00 2.00		
		20" Wiper Blade			
- Shop Supplies		Washer Fluid Conc	1.00		
		Used Fire X Refurbished		1.00	
		235 75r17 Adventure		4.00	
		Shop Supplies		1.00	
		Tire Disposal Fee		4.00	
Hours: 7.25	Comm: 0.00	Labor: 435.00	Parts: 875.65	Total: 1,310.65	

## Palm Beach County Fleet Management Asset Maintenance History 10169418 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/Extended Cab

Work Order: 1813089 Meter: 31378 In Date: 12/28/2018 Closed: 01/07/2019

Problem: P.M. service.

Work Completed		Parts Issued	Quantity		
- P.m. service.	Napa Quart 5w20	6.00			
- Check battery and charging system . After fully recharging battery ,battery failed load test . R&r defective battery.		Napagold Oil Filter	1.00		
		Napagold Air Filte	1.00		
- Diagnose noise from belt area. R&r defective belt and	Napagold Fuel Filte	1.00			
- Balance and rotate all four tire. Nitrofill all.	22" Wiper Blade	2.00			
- Shop Supplies		Battery	1.00		
	Belt		1.00		
		Ford Triton Pvc Swc		1.00	
		Shop Supplies		1.00	
Hours: 5.55	Comm: 0.00	Labor: 371.85	Parts: 243.95	Total: 615.80	

Work Order: 1907035 Meter: 32916 In Date: 07/08/2019 Closed: 07/18/2019

Problem: P.M. service, washers inop and ABS light on .

Work Completed		Parts Issued		Quantity	
- P.m. service.	ı. service.		Napagold Oil Filter		
<ul> <li>Test and replaxee defective washer pump . Clean tank and refill .</li> <li>Computer diagnose Abs light , code C1300 . Perform pin point test . R&amp;r defective Abs module and perform Pmi on module . Flush and bleed brake system . Retest and clear codes . Road test .</li> <li>Balance and rotate all four tires . Nitrofill all.</li> </ul>		5w20 Engine Oil	6.00		
		Washer Fluid Cond	1.00		
		22" Wiper Blade		2.00	
		Washer Pump	1.00		
		Ford Triton Pvc Sw	1.00		
- Shop Supplies		Used Fire X Refurb	1.00		
		Non-chlor Brake Clnr		1.00	
		B Fluid Dot 3-32oz		2.00	
		Brake Module		1.00	
		Shop Supplies		1.00	
Hours: 8.75 Com	m: 0.00	Labor: 586.25	Parts: 938.69	Total: 1,524.94	

#### **Palm Beach County Fleet Management Asset Maintenance History** 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/Extended Cab 10169418

Work Order: 1912177 Meter: 33441 11/25/2019 **Closed:** 11/25/2019 In Date:

Problem: Transition Prep Charge

**Work Completed** 

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Work Order: 1912195 Meter: 33572 In Date: 11/26/2019 Closed: 12/06/2019

**Problem:** get ready for loaners, clean head lights

**Parts Issued** Quantity **Work Completed** Hdlght Clr Coat 1.00 - prep vehicle to add to loaner line. apply new asset numbers 3m Tm Headlight Lens 1.00 - perform headlight restoration

- top off loaner

Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 30.81 Total: 322.81

In Date:

In Date:

03/10/2020 **Closed:** 

03/31/2020

Work Order: 1912344 Meter: 33441 In Date: 12/02/2019 Closed: 12/02/2019

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

**Work Completed** 

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Total: 96.00 Parts: 0.00 Work Order: 1913083 Meter: 33576 12/26/2019 **Closed:** 01/06/2020

Problem: pm service

**Work Completed Parts Issued** Quantity Napagold Oil Filter 1.00 - pm service 6.00 Napa Quart 5w20 2.00 20" Wiper Blade

Hours: 2.75 Comm: 0.00 Labor: 200.75 Parts: 36.68 Total: 237.43

Meter: 33830

**Problem:** damage to tail gate

**Work Completed** 

Work Order: 2003233

- damage to tail gate

Hours: 0.00 Comm: 1,021.44 Labor: 0.00 Parts: 0.00 Total: 1,021.44

# Palm Beach County Fleet Management Asset Maintenance History 10169418 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/Extended Cab

Work Order: Problem:	2006529 pm service	Meter:	35613		In Date:	07/01/2020	Closed:	07/10/2020
Work Completed			Parts Issued			Quantity		
- pm service				Napagold Oil Filter				1.00
•				Napa Quart 5w20				6.00
				Washer Fluid Concer	ntr			1.00
				20" Wiper Blade				2.00
	Hours: 2.75		Comm: 0.00	Labor: 200.75	Parts: 38.	51	Total:	239.26
Work Order: Problem:	2101504 PM SERVICE	Meter:	42018		In Date:	02/09/2021	Closed:	02/22/2021
Work Completed				Parts Issued			Qı	uantity
- Preventive Maint. Service				Napa Quart 5w20				6.00
				Napagold Oil Filter				1.00
				Washer Fluid Concer	ntr			1.00
				22" Wiper Blade				2.00
	Hours: 2.75		Comm: 0.00	Labor: 200.75	Parts: 38.	.63	Total:	239.38
Work Order: Problem:	2110445 needs hitch lockout / pm	Meter:	42238		In Date:	09/28/2021	Closed:	10/19/2021
Work Com	pleted			Parts Issued			Qı	uantity
- lock out h	nitch			Hitch Pin Lock				1.00
- pm servic	ce			Napa Quart 5w20				6.00
•				Napagold Oil Filter				1.00
				Napagold Air Filter				1.00
				Washer Fluid Concentr			1.00	
				22" Wiper Blade				2.00
				Used Fire X Refurbis	pished			1.00
	Hours: 3.25		Comm: 0.00	Labor: 237.25	Parts: 59.	.50	Total:	296.75

Palm Beach County Fleet Management Asset Maintenance History 10169418 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/Extended Cab

Work Order: 2111245 Meter: 42235 In Date: 10/19/2021 Closed: 10/19/2021

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

**Work Completed** 

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2203094 Meter: 43325 In Date: 03/22/2022 Closed:

Problem: pm/ radio volume not working

**Work Completed** 

- Preventive Maint. Service

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 2203177 Meter: 43325 In Date: 03/24/2022 Closed: 03/24/2022

**Problem:** Transition Prep Charge

**Work Completed** 

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 133.30 Total Labor: 8,341.60 Total Comm: 1,374.40 Total Parts: 5,814.57