

4/4/2022
10:43:30 AM

Palm Beach County Fleet Management Asset Maintenance History
10199063 2016 FORD F150 Pickup, 1/2 Ton

Total Hours: 142.30 Labor: 9,678.80 Parts: 7,900.01 Comm: 7,615.58 Charged: 25194.39

Work Order: 1601073 **Meter:** 324 **In Date:** 02/01/2016 **Closed:** 02/01/2016
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1605567 **Meter:** 6016 **In Date:** 05/31/2016 **Closed:** 06/13/2016
Problem: P.M. service and install 4 corner strobes.

Work Completed

- P.m. Service.
- Install four corner sytrobe lights.fabricate and install wiring and switch.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Vtx609a Led Strobe Am	2.00
Vtx609c Led Strobe Cl	2.00
Fuse Holder	1.00
Ds-364 Rocker Switch	1.00
Clr Rtv Silcn Sealant	1.00
Fab Loom-split Poly	12.00
Shop Supplies	1.00

Hours: 11.00 Comm: 0.00 Labor: 660.00 Parts: 508.06 Total: 1,168.06

Work Order: 1609042 **Meter:** 12047 **In Date:** 08/31/2016 **Closed:** 09/21/2016
Problem: P.M. service and check tires leaking air.

Work Completed

- P.m. Service.
- Repair two tires,rotate and balance all four.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 45.44 Total: 285.44

4/4/2022
10:43:30 AM

Palm Beach County Fleet Management Asset Maintenance History
10199063 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1610740 **Meter:** 13486 **In Date:** 10/18/2016 **Closed:** 10/18/2016

Problem: 3 - Wash ticket(s) issued

Work Completed

- 3 - Wash ticket(s) issued

Hours: 0.00 Comm: 28.62 Labor: 0.00 Parts: 0.00 Total: 28.62

Work Order: 1611436 **Meter:** 15222 **In Date:** 11/04/2016 **Closed:** 11/21/2016

Problem: Had to jump start.

Work Completed

- Recharge battery and test battery and charging system.battery fail load test.replace defective battery.

- Shop Supplies

Parts Issued

Quantity

Battry Motorcraft 1.00

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 166.67 Total: 226.67

Work Order: 1613157 **Meter:** 17713 **In Date:** 12/29/2016 **Closed:** 01/25/2017

Problem: P.M. Service.Recall.

Work Completed

- P.m. Service.

- Rotate and balance tires.

- Transport vehicle to dealer for recall #16b32.

- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil 6.00

Napagold Oil Filter 1.00

Used Fire X Refurbished 1.00

Stg Wheel Cov - Ford 1.00

Floor Mat-2pc Rub Bk 1.00

Shop Supplies 1.00

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 78.38 Total: 378.38

Work Order: 1701974 **Meter:** 20106 **In Date:** 02/27/2017 **Closed:** 03/07/2017

Problem: Right rear tire going flat.

Work Completed

- Repair and balance right rear tire.

- Shop Supplies

Parts Issued

Quantity

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

4/4/2022
10:43:30 AM

Palm Beach County Fleet Management Asset Maintenance History
10199063 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1809734 **Meter:** 47114 **In Date:** 09/20/2018 **Closed:** 09/20/2018
Problem: 3 - Wash ticket(s) issued

Work Completed

- 3 - Wash ticket(s) issued

Hours: 0.00 Comm: 28.62 Labor: 0.00 Parts: 0.00 Total: 28.62

Work Order: 1810549 **Meter:** 48761 **In Date:** 10/15/2018 **Closed:** 10/18/2018
Problem: P.M. service and left rear tire going flat.

Work Completed

- P.m. service.

- Resurface rear brake rotors . Replace rear brake pads and service calipers .
flush and bleed brake system .road test.

- Repair left rear tire . Rotate and high speed balance all four wheels .
Nitrofill all.

- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter 1.00

5w20 Engine Oil 6.00

22" Wiper Blade 2.00

Washer Fluid Concentr 1.00

Brake Pad 1.00

brake fluid 1.00

Non-chlor Brake Clnr 1.00

Shop Supplies 1.00

Hours: 7.50 Comm: 0.00 Labor: 502.50 Parts: 116.82 Total: 619.32

Work Order: 1813072 **Meter:** 52070 **In Date:** 12/28/2018 **Closed:** 12/31/2018
Problem: Right front tire going flat.

Work Completed

- Repair right front tire and balance . Nitrogen fill all tires.

- Shop Supplies

Parts Issued

Quantity

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 3.00 Total: 70.00

4/4/2022
10:43:30 AM

Palm Beach County Fleet Management Asset Maintenance History
10199063 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1901055 **Meter:** 53706 **In Date:** 01/29/2019 **Closed:** 02/07/2019

Problem: P.M. service.

Work Completed

- P.m. service.
- Check battery and charging system after fully recharging . Battery failed load test. R&r defective battery .
- Balance and rotate all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Battry Motorcraft	1.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 268.00 Parts: 220.01 Total: 488.01

Work Order: 1905823 **Meter:** 59257 **In Date:** 06/03/2019 **Closed:** 06/18/2019

Problem: P.M. Service.Front bumper rusting.Check inverter.

Work Completed

- P.m. service.
- Diagnose power inverter and test . R&r defective inverter . Test operation .
- Pressure test and inspect cooling system . Leak test . Replace leaking water pump , thermostat , A/c belt and drive belt . Flush and refill cooling system . Test drive.
- Rotate and balance all four tires . Nitrofill all.
- Transport to and from dealer for recalls 17s33 and 18s27 .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
400w Inverter Cobra	1.00
Gasket	1.00
Anti Freeze Motorcraft	1.00
V Belt	1.00
V Belt	1.00
Tmermostat Housing	1.00
Water Pump	1.00
Shop Supplies	1.00

Hours: 12.60

Comm: 0.00

Labor: 844.20 Parts: 490.82 Total: 1,335.02

4/4/2022
10:43:30 AM

Palm Beach County Fleet Management Asset Maintenance History
10199063 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1906947 **Meter:** 59257 **In Date:** 06/17/2019 **Closed:** 07/03/2019
Problem: repaint front bumper

Work Completed

- repaint front bumper

Hours: 0.00 Comm: 297.24 Labor: 0.00 Parts: 0.00 Total: 297.24

Work Order: 1908739 **Meter:** 62602 **In Date:** 08/21/2019 **Closed:** 08/26/2019
Problem: Right rear tire flat spare on vehicle .

Work Completed

- Replace both rear tires due to large hole . Balance both . Nitrofill all tires .
Remount spare .
- Shop Supplies

Parts Issued

Quantity

183114470 P245-70r17 2.00
Shop Supplies 1.00
Tire Disposal Fee 2.00

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 427.96 Total: 494.96

Work Order: 1910357 **Meter:** 65137 **In Date:** 10/07/2019 **Closed:** 10/21/2019
Problem: P.M. service and missing jack .

Work Completed

- P.m. service.
- Replace two tires . Rotate and high speed balance all four tires . Nitrofill all.
- Install jack . Mount fire extinguisher bracket .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter 1.00
5w20 Engine Oil 6.00
22" Wiper Blade 2.00
Washer Fluid Concentr 1.00
245/70/17 Tire Mich 2.00
Shop Supplies 1.00
Tire Disposal Fee 2.00

Hours: 4.50 Comm: 0.00 Labor: 328.50 Parts: 503.44 Total: 831.94

Work Order: 1911404 **Meter:** 65882 **In Date:** 11/01/2019 **Closed:** 11/04/2019
Problem: towing for accident

Work Completed

- Towed for accident - dispatched by Sheriff's office
- Shop Supplies

Parts Issued

Quantity

Commercial Towing 1.00
Shop Supplies 1.00

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 378.50 Total: 378.50

4/4/2022
10:43:30 AM

Palm Beach County Fleet Management Asset Maintenance History
10199063 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2000477 **Meter:** 65882 **In Date:** 11/05/2019 **Closed:** 01/15/2020
Problem: : Damage to left mirror, left door glass, left front fender, left front wheel, hood, grille, bumper & poss strg

Work Completed

- : Damage to left mirror, left door glass, left front fender, left front wheel, hood, grille, bumper & poss strg

Hours: 0.00 Comm: 5,581.82 Labor: 0.00 Parts: 0.00 Total: 5,581.82

Work Order: 2002307 **Meter:** 66374 **In Date:** 03/05/2020 **Closed:** 03/26/2020
Problem: ABS light and traction control light on .

Work Completed

- Computer diagnose Abs light ,code C003a. Perform pinpoint test . Replace broken left rear Abs wheel speed sensor .
- Replace bent rear axle housing and broken left rear axle . Replace pinon seal and bearing and crush sleeve . Fill fluid and road test .
- Replace bent left front lower control arm and steering knuckle and adjusting bolts .
- Perform complete alignment and road test .
- Shop Supplies

Parts Issued

Quantity

Abs Sensor	1.00
Spacer	1.00
Seal	1.00
Cup	1.00
Bearing	1.00
Cone And	1.00
Cup	1.00
Nut Lock	1.00
Flange	1.00
Px Grey Rtv Silicone	1.00
Non-chlor Brake Clnr	2.00
75w140 Ford Axle Lube	3.00
Pinion	1.00
Washer	1.00
Shaft Asy	1.00
Housing Asy	1.00
Knuckle	1.00
Cam	1.00
Arm Asy	1.00
Shop Supplies	1.00

Hours: 16.20 Comm: 0.00 Labor: 1,182.60 Parts: 1,719.60 Total: 2,902.20

4/4/2022
10:43:31 AM

Palm Beach County Fleet Management Asset Maintenance History
10199063 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2003295 **Meter:** 66782 **In Date:** 03/31/2020 **Closed:** 04/06/2020
Problem: P.M. service.

Work Completed

- P.m. service.
- Replace cabin air filter and clean fresh air intake .
- Replace both front brake rotors and pads . Service calipers . Flush and bleed brake system . Road test .
- Diagnose engine misfire . Perform tune up . Replace all six spark plugs and intake gasket . Clear codes and retest .
- Perform complete airintake decarb and cleaning . Flush injectors .
- Balance and rotate all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Ford Triton Pvc Swc	1.00
Cabin Air Filter	1.00
Brake Pad	1.00
Brake Rotor	2.00
Gasket	1.00
Spark Plugs	6.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Shop Supplies	1.00

Hours: 12.00

Comm: 0.00

Labor: 876.00

Parts: 400.92

Total: 1,276.92

Work Order: 2007517 **Meter:** 72270 **In Date:** 07/30/2020 **Closed:** 08/06/2020
Problem: P.M. service , trailer warning on dash and wires hanging down under dash .

Work Completed

- P.m. service.
- Resecure wires under dash .test and replace defective trailer plug connector and rewire as needed . Test and replace defective power inverter on center floor board . Retest .
- Replace damaged left rear tail light lens and mount strobe bulb in lens .
- Repair right front tire .rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
trailer plug	1.00
400w Inverter Cobra	1.00
Lamp Assy	1.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 511.00

Parts: 203.76

Total: 714.76

4/4/2022
10:43:31 AM

Palm Beach County Fleet Management Asset Maintenance History
10199063 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2008988 **Meter:** 72379 **In Date:** 09/08/2020 **Closed:** 09/10/2020
Problem: Hard start, ABS light, Power steering inop.

Work Completed

- Computer diagnose Abs light and power steering ., codes U0420 ,u3003 and U3000 .all codes caused by low voltage . Charge and test battery and charging system . R&r defective battery . Clear codes and retest .

Parts Issued

Quantity

Battry Motorcraft	1.00
Shop Supplies	1.00

- Shop Supplies

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 192.82 Total: 338.82

Work Order: 2012881 **Meter:** 77444 **In Date:** 12/29/2020 **Closed:** 01/06/2021
Problem: P.M. Service and detail .

Work Completed

- Preventive Maint. Service
- Perform speed balance all four, nitro fill
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Shop Supplies	1.00

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 34.84 Total: 253.84

Work Order: 2100079 **Meter:** 77332 **In Date:** 01/05/2021 **Closed:** 01/05/2021
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2102324 **Meter:** 80243 **In Date:** 03/01/2021 **Closed:** 03/02/2021
Problem: Left front tire flat.

Work Completed

- Repair and balance right front tire.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 4.00 Total: 77.00

4/4/2022
10:43:31 AM

Palm Beach County Fleet Management Asset Maintenance History
10199063 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2113225 **Meter:** 93804 **In Date:** 12/15/2021 **Closed:** 12/20/2021
Problem: PM Service. right front tire has plug in it .

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- mount 2 rotate and balance all 4 tires nitro fill all
- R&i new rear brake pads along with rotors , service calipers . flush and bleed braking system test drive after completion
- Shop Supplies

5w20 Engine Oil	6.00
Filter	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
245/70/17 Tire Mich	2.00
Brake Rotor	2.00
Brake Pad	1.00
Brk Fluid Dot 4-32oz	1.00
Non-chlor Brake Clnr	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 7.50 Comm: 0.00

Labor: 547.50 Parts: 649.56 Total: 1,197.06

Work Order: 2202551 **Meter:** 96833 **In Date:** 03/08/2022 **Closed:** 03/08/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 142.30

Total Labor: 9,678.80

Total Comm: 7,615.58

Total Parts: 7,900.01