

5/2/2022
10:48:27 AM

Palm Beach County Fleet Management Asset Maintenance History
10199066 2016 FORD F150 Pickup, 1/2 Ton

Total Hours: 97.55 Labor: 6,582.60 Parts: 4,197.86 Comm: 186.40 Charged: 10966.86

Work Order: 1601093 **Meter:** 331 **In Date:** 02/01/2016 **Closed:** 02/01/2016
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1606807 **Meter:** 6064 **In Date:** 07/06/2016 **Closed:** 07/18/2016
Problem: P.M. service and trailer fault warning on dash.

Work Completed

- P.m. Service.
- Diagnose trailer warning message.replace corroded trailer plug.rewire.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wd40 16oz	1.00
Floor Mat	1.00
trailer plug	1.00
Clr Rtv Silcn Sealant	1.00
Shop Supplies	1.00

Hours: 4.25 Comm: 0.00 Labor: 255.00 Parts: 74.65 Total: 329.65

Work Order: 1612756 **Meter:** 12777 **In Date:** 12/13/2016 **Closed:** 12/30/2016
Problem: P.M. service and recall 16b32.

Work Completed

- P.m. Service.
- Rotate and balance tires.
- Transport vehicle to dealer for recall #16b32(throttle body).
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Stg Wheel Cov - Ford	1.00
Shop Supplies	1.00

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 34.97 Total: 334.97

5/2/2022
10:48:27 AM

Palm Beach County Fleet Management Asset Maintenance History
10199066 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1702176 **Meter:** 15523 **In Date:** 03/02/2017 **Closed:** 03/09/2017
Problem: Left front tire going flat.

Work Completed

Parts Issued

Quantity

- Repair and balance left front tire.
- Shop Supplies

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1704759 **Meter:** 18532 **In Date:** 05/12/2017 **Closed:** 05/18/2017
Problem: P.M. service and pulls to the left.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Perform complete front wheel alignment.road test.
- Rotate and high speed balance all four wheels.nitro fill all.
- Shop Supplies

5w20 Engine Oil 6.00

Napagold Oil Filter 1.00

22" Wiper Blade 2.00

Used Fire X Refurbished 1.00

Washer Fluid Concentr 1.00

Shop Supplies 1.00

Hours: 5.50 Comm: 0.00 Labor: 330.00 Parts: 40.34 Total: 370.34

Work Order: 1705054 **Meter:** 18690 **In Date:** 05/22/2017 **Closed:** 05/25/2017
Problem: Towed in for no start.

Work Completed

Parts Issued

Quantity

- Test battery and starting system.perform pinpoint test on starter circuit.r&r& defective starter.retest.
- Shop Supplies

Starter 1.00

Shop Supplies 1.00

Hours: 1.50 Comm: 0.00 Labor: 90.00 Parts: 111.11 Total: 201.11

Work Order: 1705314 **Meter:** 18966 **In Date:** 05/22/2017 **Closed:** 05/30/2017
Problem: wont start

Work Completed

- Tow From: 2090 elison wilson/ juno park To: 2601 vista parkway

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

5/2/2022
10:48:27 AM

Palm Beach County Fleet Management Asset Maintenance History
10199066 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1712093 **Meter:** 25990 **In Date:** 12/11/2017 **Closed:** 12/19/2017
Problem: P.M. service.

Work Completed

- P.m. service.
- Upon inspection load test battery,battery failed .charge battery .repeat procedure.battery failed test.remove and replace battery then check charging system,checks ,ok.
- Mount and balance four tires .nitrofill
- Performed four wheel alignment.
- Shop Supplies

Parts Issued

	Quantity
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Mac Wite Lithium Gres	1.00
22" Wiper Blade	2.00
183114470 P245-70r17	4.00
Battry Motorcraft	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 7.50

Comm: 0.00

Labor: 450.00 Parts: 1,028.82 Total: 1,478.82

Work Order: 1805064 **Meter:** 31854 **In Date:** 05/16/2018 **Closed:** 05/24/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

	Quantity
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 180.00 Parts: 41.36 Total: 221.36

Work Order: 1810173 **Meter:** 36752 **In Date:** 10/01/2018 **Closed:** 10/02/2018
Problem: Left front tire going flat .

Work Completed

- Repair left front tire and balance . Nitrogen fill tires.
- Shop Supplies

Parts Issued

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 67.00 Parts: 3.00 Total: 70.00

5/2/2022
10:48:27 AM

Palm Beach County Fleet Management Asset Maintenance History
10199066 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1810474 **Meter:** 37252 **In Date:** 10/11/2018 **Closed:** 10/18/2018

Problem: P.M. service and pulls to the right and tool box strut broken .

Work Completed

- P.m. service.
- Replace broken tool box strut on right side.
- Test drive . Perform alignment and road test.
- Rotate and balance all four wheels .nitrofill and reset Tpms.
- Perform cooling system service . Pressure test and flush coolant and refill.
- Shop Supplies

Hours: 7.80

Comm: 0.00

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Support	1.00
Anti Freeze Motorcraft	2.00
Shop Supplies	1.00

Labor: 522.60

Parts: 97.23

Total: 619.83

Work Order: 1901546 **Meter:** 42001 **In Date:** 02/08/2019 **Closed:** 02/20/2019

Problem: PM Service,

Work Completed

- P.m. service.
- Computer diagnose check engine light , code P1450 . Perform evap test .
Replace defective purge valve . Clear codes and retest .
- Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Hours: 5.00

Comm: 0.00

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Valva Asy	1.00
Shop Supplies	1.00

Labor: 335.00

Parts: 75.36

Total: 410.36

Work Order: 1904052 **Meter:** 44190 **In Date:** 04/15/2019 **Closed:** 04/16/2019

Problem: Left rear tire going flat.

Work Completed

- Repair left rear tire and balance . Nitrogen fill tires .
- Shop Supplies

Hours: 1.00

Comm: 0.00

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Labor: 67.00

Parts: 3.00

Total: 70.00

5/2/2022
10:48:27 AM

Palm Beach County Fleet Management Asset Maintenance History
10199066 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1906309 **Meter:** 47574 **In Date:** 06/14/2019 **Closed:** 06/27/2019
Problem: PM Service, Ignition or starter issue, no crank, no click?

Work Completed

Parts Issued

Quantity

- P.m. service.
- Test and replace defective trailer connector and fabricate wire as needed.
- Replace and balance all four tires . Nitrofill all.
- Test drive and measure all four rotor run out . Resurface both front rotors and service calipers . Road test .
- Complete front end alignment and road test .
- Computer diagnose no start . Scan for codes no codes present . Could not duplicate at this time . Swap rear defrost relay with starter relay .
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
trailer plug	1.00
245/70/17 Tire Mich	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 10.50 Comm: 0.00 Labor: 703.50 Parts: 992.90 Total: 1,696.40

Work Order: 1911724 **Meter:** 53380 **In Date:** 11/12/2019 **Closed:** 12/04/2019
Problem: P.M . service and trailer warning on dash .

Work Completed

Parts Issued

Quantity

- P.m. Service.
- Diagnose trailer warning loght.replace and rewire corroded trailer plug.perform module update.
- Replace cabin filter.clean debri from duct.
- Replace missing pintle pin
- Replace broken driver door panel.diagnose and replace door lock actuator and lock cable.
- Rotate and balance tires.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
trailer plug	1.00
Cabin Air Filter	1.00
Pintle Pin W/clip	1.00
Panel Asy	1.00
Cable	1.00
Latch	1.00
Shop Supplies	1.00

Hours: 9.75 Comm: 0.00 Labor: 711.75 Parts: 487.53 Total: 1,199.28

5/2/2022
10:48:27 AM

Palm Beach County Fleet Management Asset Maintenance History
10199066 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2004889 **Meter:** 58962 **In Date:** 05/14/2020 **Closed:** 05/20/2020
Problem: P.M. service and recalls 17S33 and 18S27 .

Work Completed

- P.m. service.
- Rotate and balance all four tires . Nitrofill all.
- Transport to and from dealer for recalls 17s33 and 18s27 .
- Shop Supplies

Hours: 5.00

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Labor: 365.00 Parts: 46.30 Total: 411.30

Work Order: 2012599 **Meter:** 63042 **In Date:** 12/17/2020 **Closed:** 12/28/2020
Problem: P.M. service.

Work Completed

- Preventive Maint. Service
- clean a/c air intake and install cabin filter
- Rotate and hi speed balance all four tires . nitro fill all.
- Shop Supplies

Hours: 3.50

Comm: 0.00

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Cabin Filter	1.00
Shop Supplies	1.00

Labor: 255.50 Parts: 61.71 Total: 317.21

5/2/2022
10:48:27 AM

Palm Beach County Fleet Management Asset Maintenance History
10199066 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2106568 **Meter:** 67797 **In Date:** 06/16/2021 **Closed:** 06/23/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Battery tested bad. Charged battery fully and retested bad. R and R bad battery. Use scan tool to reset Bms
- Replaced 2 tires. Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Diagnose engine misfire . Performed tune-up replace all six spark plugs . Retest .
- Performed fuel flush and decarbon service.
- Shop Supplies

Parts Issued

	Quantity
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Steering Wheel Cover Large	1.00
245/70/17 Tire Mich	2.00
Gasket	1.00
Spark Plugs	6.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Battry Motorcraft	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 11.50

Comm: 0.00

Labor: 839.50

Parts: 932.95

Total: 1,772.45

Work Order: 2110870 **Meter:** 70269 **In Date:** 10/06/2021 **Closed:** 10/06/2021
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Work Order: 2110917 **Meter:** 70269 **In Date:** 10/07/2021 **Closed:** 10/08/2021
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

5/2/2022
10:48:27 AM

Palm Beach County Fleet Management Asset Maintenance History
10199066 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2112929 **Meter:** 71259 **In Date:** 12/07/2021 **Closed:** 12/16/2021
Problem: PM Service.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- rotate/balanced 4 tires
- replace 3rd stop /cargo lamps
- wash vehicle and debris from clean air cowl system and replaced cabin air filter
- update cal-start decal
- check eng. light on. scanned and cleared p0302 misfire code replaced cly#2 coil and intake plenum gasket. Test drive. No misfire detected.

Napa Quart 5w20	6.00
Filter	1.00
Napagold Air Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Boxed Miniatures	3.00
Cabin Filter	1.00
Gasket	1.00
Ign Coil	1.00

Hours: 7.25

Comm: 0.00

Labor: 529.25

Parts: 164.66

Total: 693.91

Work Order: 2201290 **Meter:** 71997 **In Date:** 02/03/2022 **Closed:** 02/17/2022
Problem: Engine misfire under load.

Work Completed

- Engine misfiring. Diagnose with ford Ids and reprogram Pcm with latest software update. Test drive to verify fix.

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 0.00

Total: 109.50

Work Order: 2204302 **Meter:** 72225 **In Date:** 04/22/2022 **Closed:** 04/22/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 97.55

Total Labor: 6,582.60

Total Comm: 186.40

Total Parts: 4,197.86