

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156344 2004 HUDSON BROTHERS HSE16 Trailer, 4 Ton Low Boy

Workorder: 538883

Problem: TAG CHARGE

Meter Reading: 0	Labor	Parts		
In Date: 03/14/2005	Hours	Description	Quantity	
- Tag Charge		TAG CHARGE	1.00	
Parts Charge:	22.10	Labor Charge:	0.00	

Workorder: 1105939

Problem: P. M. SERVICE

Meter Reading: 0	Labor	Parts		
In Date: 06/06/2011	Hours	Description	Quantity	
- P. M. Service.	7.00	1066 WHITE LITHIUM (CRC 05037)	1.00	
- Service Electronic Trailer Brakes. Repack Wheel Bearings & Reinstall Drum.		SHOP SUPPLIES	1.00	
- Verify, Trailer Deck Dirty & Slippery When Wet. Pressure Clean All Boards. Clean Trailer.		6Y648 GRAPHITE LUBE (IMPERIAL 6590)	1.00	
- Shop Supplies				
Parts Charge:	24.82	Labor Charge:	420.00	

Workorder: 1603436

Problem: trailer pin

Meter Reading: 0	Labor	Parts		
In Date: 04/01/2016	Hours	Description	Quantity	
- Replace Pintle Pin.	0.25	PINTLE PIN W/CHAIN	1.00	
Parts Charge:	2.61	Labor Charge:	15.00	

Workorder: 1612865

Problem: Transition Prep Charge

Meter Reading: 0	Labor	Parts		
In Date: 12/15/2016	Hours	Description	Quantity	
- Transition Prep Charge	2.00			
Parts Charge:	0.00	Labor Charge:	0.00	

Total Parts Charges:	49.53	Total Labor Charges:	435.00	Total Comm. Charges:	0.00
----------------------	--------------	----------------------	---------------	----------------------	-------------