

1/9/2023
4:40:00 PM

Palm Beach County Fleet Management Asset Maintenance History
10162883 2006 TOYOTA PRIUS Car, Mid-Size, Hybrid

Total Hours: 183.70 Labor: 11,562.65 Parts: 8,668.81 Comm: 1,381.19 Charged: 21612.65

Work Order: 636150 **Meter:** 0 **In Date:** 03/22/2006 **Closed:** 03/22/2006
Problem: WASH VEHICLE

Work Completed

- Wash Vehicle
- Pre-delivery Inspection

Hours: 2.50 Comm: 0.00 Labor: 125.00 Parts: 0.00 Total: 125.00

Work Order: 637353 **Meter:** 0 **In Date:** 03/29/2006 **Closed:** 05/03/2006
Problem: 001 DETAIL VEHICLE 03/29/06

Work Completed

- 001 Detail Vehicle 03/29/06

Hours: 0.00 Comm: 5.94 Labor: 0.00 Parts: 0.00 Total: 5.94

Work Order: 639547 **Meter:** 0 **In Date:** 05/15/2006 **Closed:** 05/18/2006
Problem: 001 WASH TICKET ISSUED OUT 05/15/06

Work Completed

- 001 Wash Ticket Issued Out 05/15/06

Hours: 0.00 Comm: 5.94 Labor: 0.00 Parts: 0.00 Total: 5.94

Work Order: 646105 **Meter:** 0 **In Date:** 09/12/2006 **Closed:** 09/25/2006
Problem: 001 WASH TICKET ISSUED OUT 09/12/06

Work Completed

- 001 Wash Ticket Issued Out 09/12/06

Hours: 0.00 Comm: 5.94 Labor: 0.00 Parts: 0.00 Total: 5.94

Work Order: 646108 **Meter:** 0 **In Date:** 09/14/2006 **Closed:** 09/25/2006
Problem: 002 WASH TICKETS ISSUED OUT 09/14/06

Work Completed

- 002 Wash Tickets Issued Out 09/14/06

Hours: 0.00 Comm: 11.88 Labor: 0.00 Parts: 0.00 Total: 11.88

1/9/2023
4:40:01 PM

Palm Beach County Fleet Management Asset Maintenance History
10162883 2006 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1100905 **Meter:** 33501 **In Date:** 01/24/2011 **Closed:** 02/03/2011

Problem: P.M. service and hybrid recall.

Work Completed

- P.m. Service.
- Replace two tires,rotate and balance all.
- Complete wheel alignment.
- Service and adjust rear brakes.
- Transport vehicle to dealer for recall,waterpump.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Big G Degreaser Stock# 485180002	1.00
Ph4967 Oil Filter Lbf Ph2840 Wix 51394	1.00
09997 Brake Clean	1.00
5w30 Oil	4.00
Nb-18 Wiper Blades 18" Anco 31-18	1.00
31-24 Wiper Blades 24" Blade	1.00
738523571 P185/65r15 Assurance Fuel Max 88h	2.00
Tire Disposal Fee	2.00

Hours: 9.50

Comm: 0.00

Labor: 570.00

Parts: 218.77

Total: 788.77

Work Order: 1107621 **Meter:** 35814 **In Date:** 07/20/2011 **Closed:** 07/27/2011

Problem: Pm service and smells moldy

Work Completed

- Perform pm service.
- Remove cabin air filter.clean ac housing and vent ducts.deodorized evaporator housing and heater box.
- Rotate and balance all four tires.
- Perform rear drum brakes service and adjust brake shoes.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Ph4967 Oil Filter Lbf Ph2840 Wix 51394	1.00
Cf9846a Cab Filter Wix 24875	1.00
5w30 Oil	4.00
Nb-18 Wiper Blades 18" Anco 31-18	1.00
31-24 Wiper Blades 24" Blade	1.00
6984 Evapor Cleaner Evaporator Cleaner	1.00

Hours: 5.00

Comm: 0.00

Labor: 300.00

Parts: 45.74

Total: 345.74

Work Order: 1107888 **Meter:** 35814 **In Date:** 07/27/2011 **Closed:** 07/27/2011

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00

Comm: 91.80

Labor: 0.00

Parts: 0.00

Total: 91.80

1/9/2023
4:40:01 PM

Palm Beach County Fleet Management Asset Maintenance History
10162883 2006 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1111897 **Meter:** 37054 **In Date:** 11/04/2011 **Closed:** 11/04/2011
Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 17.02 Labor: 0.00 Parts: 0.00 Total: 17.02

Work Order: 1200626 **Meter:** 37836 **In Date:** 01/19/2012 **Closed:** 01/30/2012
Problem: Pm service.

Work Completed

- P.m. Service.
- Test battery and charging system.replace bad battery.
- Rotate and balance all tires.
- Service and adjust rear brakes.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Ph4967 Oil Filter Lbf Ph2840 Wix 51394	1.00
5w30 Oil	4.00
00544-21171-325 Battery (toyota)	1.00

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 235.84 Total: 535.84

Work Order: 1206690 **Meter:** 39740 **In Date:** 07/18/2012 **Closed:** 08/07/2012
Problem: Pm service and low washer fluid.

Work Completed

- Perform pm service.
- Rotate and balance all four tires.
- Perform rear drum brake service and adjust brake shoes.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Ph4967 Oil Filter Lbf Ph2840 Wix 51394	1.00
09997 Brake Clean	1.00
Wd40 Spray Lube Stock# 405540002	1.00
5w30 Oil	4.00
31-24 Wiper Blades 24" Blade	1.00
Nb-18 Wiper Blades 18" Anco 31-18	1.00

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 35.84 Total: 275.84

Work Order: 1209812 **Meter:** 40303 **In Date:** 10/12/2012 **Closed:** 10/12/2012
Problem: 4 - Wash ticket(s) issued

Work Completed

- 4 - Wash ticket(s) issued

Hours: 0.00 Comm: 34.03 Labor: 0.00 Parts: 0.00 Total: 34.03

1/9/2023
4:40:01 PM

Palm Beach County Fleet Management Asset Maintenance History
10162883 2006 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1603826 **Meter:** 64838 **In Date:** 04/12/2016 **Closed:** 04/26/2016
Problem: Pm service.

Work Completed

- Pm service.
- Service rear brake.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	4.00
Wiper Blades 24"	1.00
18" wiper blades	1.00
Washer Fluid Concentr	1.00
Brake Cleaner	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 180.00

Parts: 31.39

Total: 211.39

Work Order: 1611075 **Meter:** 67783 **In Date:** 10/26/2016 **Closed:** 11/14/2016
Problem: Pm service.TPMS warning light on.

Work Completed

- Pm service.
- Verify dead battery.jump start.recharge and test battery.good.verify headlights left on.
- C/c Tpms light on.repair left rear tire and reset Tpms.
- Service rear drum brakes.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	4.00
Shop Supplies	1.00

Hours: 5.75

Comm: 0.00

Labor: 345.00

Parts: 19.63

Total: 364.63

1/9/2023
4:40:01 PM

Palm Beach County Fleet Management Asset Maintenance History
10162883 2006 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1704532 **Meter:** 70026 **In Date:** 05/04/2017 **Closed:** 05/15/2017
Problem: PM Service

Work Completed

- Pm Service.
- Service rear brakes.
- Replace both front marker light and both tag light bulbs.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

Drain Plug	1.00
Napagold Oil Filter	1.00
Napa Quart 5w30	4.00
Washer Fluid Concentr	1.00
Wiper Blades 24"	1.00
18" wiper blades	1.00
Air Filter (gold)	1.00
Non-chlor Brake Clnr	1.00
Bulb	4.00
Accufit Rear	1.00
Shop Supplies	1.00

Hours: 4.75

Comm: 0.00

Labor: 285.00 Parts: 51.37 Total: 336.37

Work Order: 1711296 **Meter:** 72543 **In Date:** 11/15/2017 **Closed:** 12/11/2017
Problem: PM Service

Work Completed

- Pm Service.
- Clean and adjust rear brakes.
- Replace both rear tires and rotate to the front.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	4.00
Washer Fluid Concentr	1.00
Wiper Blades 24"	1.00
18" wiper blades	1.00
Non-chlor Brake Clnr	1.00
738523571 P185-65r15	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 4.50

Comm: 0.00

Labor: 270.00 Parts: 249.72 Total: 519.72

1/9/2023
4:40:01 PM

Palm Beach County Fleet Management Asset Maintenance History
10162883 2006 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1807050 **Meter:** 74984 **In Date:** 07/11/2018 **Closed:** 07/23/2018
Problem: PM Service.

Work Completed

- Pm Service.
- Service rear brakes.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

Napa Quart 5w30	4.00
Napagold Oil Filter	1.00
18" wiper blades	1.00
Wiper Blades 24"	1.00
Washer Fluid Concentr	1.00
Non-chlor Brake Clnr	1.00
Shop Supplies	1.00

Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 32.65 Total: 257.65

Work Order: 1810447 **Meter:** 76448 **In Date:** 10/10/2018 **Closed:** 10/18/2018
Problem: TIRES LIGHT ON

Work Completed

- Repair tire.fill all with nitrogen and reset Tpms.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 3.00 Total: 70.00

1/9/2023
4:40:01 PM

Palm Beach County Fleet Management Asset Maintenance History
10162883 2006 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1900964 **Meter:** 77582 **In Date:** 01/25/2019 **Closed:** 02/11/2019
Problem: PM Service

Work Completed

- Pm Service.
- Service rear brakes.
- Replace leaking water pump,belt and flush cooling system.
- Restore both head lamps.
- Test drive before and and after repairs.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	4.00
Wiper Blades 24"	1.00
18" wiper blades	1.00
Washer Fluid Concentr	1.00
Non-chlor Brake Clnr	2.00
Drive Belt	1.00
Toyota Coolant	1.00
Water Pump	1.00
Hdlght Clr Coat	1.00
3m Tm Headlight Lens	1.00
Shop Supplies	1.00
Labor: 770.50	Parts: 231.60
Hours: 11.50	Comm: 0.00
Total: 1,002.10	

Work Order: 1907735 **Meter:** 78911 **In Date:** 07/25/2019 **Closed:** 08/12/2019
Problem: PM Service

Work Completed

- Pm Service.
- Service rear brakes.
- Shop Supplies

Parts Issued

Quantity

Napa Quart 5w30	4.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
18" wiper blades	1.00
Wiper Blades 24"	1.00
Non-chlor Brake Clnr	1.00
Shop Supplies	1.00
Labor: 184.25	Parts: 34.82
Hours: 2.75	Comm: 0.00
Total: 219.07	

1/9/2023
4:40:01 PM

Palm Beach County Fleet Management Asset Maintenance History
10162883 2006 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1909856 **Meter:** 78957 **In Date:** 09/24/2019 **Closed:** 09/30/2019
Problem: Towed in No start dead battery.

Work Completed

- Recharge and check batteryreplace bad battery.
- Shop Supplies

Parts Issued

Quantity

Battery	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 281.99 Total: 348.99

Work Order: 1910123 **Meter:** 78957 **In Date:** 09/24/2019 **Closed:** 10/01/2019
Problem: Towed dead battery wont start.

Work Completed

- Tow From: 345 South Congress Ave Delray To: 13026 Jog Road Delray

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2002183 **Meter:** 79235 **In Date:** 03/02/2020 **Closed:** 03/17/2020
Problem: PM Service and damage tire.Towed in.

Work Completed

- Pm Service.
- Replace cabin air filter.
- Service rear brakes.
- Replace four tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	4.00
Wiper Blades 24"	1.00
18" wiper blades	1.00
Washer Fluid Concentr	1.00
Napagold Air Filter	1.00
Napa Cabin Air Filter	1.00
Non-chlor Brake Clnr	1.00
738523571 P185-65r15	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 5.50 Comm: 0.00 Labor: 401.50 Parts: 639.09 Total: 1,040.59

1/9/2023
4:40:01 PM

Palm Beach County Fleet Management Asset Maintenance History
10162883 2006 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 2002272 **Meter:** 79174 **In Date:** 03/02/2020 **Closed:** 03/04/2020
Problem: Towed for damage tire and PM Service..

Work Completed

- Tow From: 345 Congress Ave Delray To: 13026 Jod Road Delray

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2008430 **Meter:** 80893 **In Date:** 08/24/2020 **Closed:** 08/31/2020
Problem: P.M. service

Work Completed

- P.m. service.
- Diagnose engine misfire . Perform tune up . Replace all four spark plugs .
- Perform complete air intake decarb and cleaning .
- Resurface both front brake rotors and service calipers . Replace brake pads
- . Flush and bleed system . Inspect and service rear brakes . Road test .
- Balance and rotate all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	4.00
16in Exactfit-rear	1.00
18" wiper blades	1.00
Wiper Blades 24"	1.00
Spark Plug	4.00
Intake Cleaner Kit	1.00
Brake Pads	1.00
Shop Supplies	1.00

Hours: 10.30 Comm: 0.00 Labor: 751.90 Parts: 209.61 Total: 961.51

Work Order: 2009138 **Meter:** 81277 **In Date:** 09/11/2020 **Closed:** 11/03/2020
Problem: Dash won't light up at times .

Work Completed

- Diagnose inop combination meter display. Transport vehicle to dealer for replacement and reprogram.
- Shop Supplies

Parts Issued

Quantity

Replace/program Combo Meter	1.00
Shop Supplies	1.00

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 2,464.29 Total: 2,500.79

1/9/2023
4:40:01 PM

Palm Beach County Fleet Management Asset Maintenance History
10162883 2006 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 2010831 **Meter:** 81277 **In Date:** 10/28/2020 **Closed:** 11/24/2020
Problem: Replace broken a/c vents and trim.

Work Completed

- Instruments & Gauges, Install vents.
- Shop Supplies

Parts Issued

Quantity

Left Center A /c Vent	1.00
Register Assembly	1.00
Register Assy	1.00
Shop Supplies	1.00

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 559.44 Total: 559.44

Work Order: 2012014 **Meter:** 81277 **In Date:** 12/01/2020 **Closed:** 12/02/2020
Problem: dash will not light up, lacandice 561-274-3187 whitney 561-722-8751 call when there to bring keys down

Work Completed

- Tow From: 345 s congress, annex building To: vista

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2012740 **Meter:** 81278 **In Date:** 12/21/2020 **Closed:** 12/28/2020
Problem: Cluster display black

Work Completed

- Drive To Dealer For replacement and proگرامing of combination meter .
- Shop Supplies

Parts Issued

Quantity

Repacement And Prog Meter	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 1,176.90 Total: 1,249.90

1/9/2023
4:40:01 PM

Palm Beach County Fleet Management Asset Maintenance History
10162883 2006 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 2102890 **Meter:** 82667 **In Date:** 03/15/2021 **Closed:** 03/26/2021
Problem: PM Service

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Rotate Balanced 4 Tires, nitrogen filled and reinstalled on vehicle.
- Clean And Adjust Rear Brakes, Lube
- Clean Engine Debris
- replaced worn decal
- Tire pressure sensor not reading on Rr. Remove tire and replace Tpm sensor. Use Ids and Tpm3 to reprogram Tpm system.
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w30	4.00
Wiper Blades 24"	1.00
18" wiper blades	1.00
Sensor	1.00
Shop Supplies	1.00

Hours: 6.00 Comm: 0.00 Labor: 438.00 Parts: 154.39 Total: 592.39

Work Order: 2105535 **Meter:** 82860 **In Date:** 05/17/2021 **Closed:** 06/25/2021
Problem: Towed in wont start.

Work Completed

- Check starting & charging system found battery need to be recharge, recharge & test, battery is ok at this time.

Hours: 0.50 Comm: 96.00 Labor: 36.50 Parts: 0.00 Total: 132.50

Work Order: 2106718 **Meter:** 82978 **In Date:** 05/17/2021 **Closed:**
Problem: Wont Start.

Work Completed

- .

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

1/9/2023
4:40:01 PM

Palm Beach County Fleet Management Asset Maintenance History
10162883 2006 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 2211153 **Meter:** 85235 **In Date:** 10/28/2022 **Closed:** 10/28/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 183.70

Total Labor: 11,562.65

Total Comm: 1,381.19

Total Parts: 8,668.81