Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1007590 Meter: 0 In Date: 07/19/2010 Closed: 07/19/2010

Problem: Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1013621 Meter: 4850 In Date: 12/10/2010 Closed: 12/27/2010

Problem: Pm service.

Quantity **Work Completed Parts Issued Shop Supplies** 1.00 - Perform pm service. Ch10358 Oil Filter Lbf P980 Wix 57064 1.00 - Rotate and balance all four tires. 75-540 0w/20 Motor Oil 5.00 - Shop Supplies Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 42.17 Total: 222.17

Work Order: 1106659 Meter: 10110 In Date: 06/24/2011 Closed: 07/05/2011

Problem: Pm service and wiper blades.

Work Completed		Parts Issued	Quantity
- Perform pm service.		Shop Supplies	1.00
- Rotate and balance all four tires.		Ch10358 Oil Filter Lbf P980 Wix 57064	1.00
- Shop Supplies		75-540 0w/20 Motor Oil	5.00
		Nb-18 Wiper Blades 18" Anco 31-18	1.00
		31-24 Wiper Blades 24" Blade	1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00 Parts: 52.24	Total: 232.24

Work Order: 1108766 Meter: 11119 In Date: 08/18/2011 Closed: 08/18/2011

Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 17.02 Labor: 0.00 Parts: 0.00 Total: 17.02

Hours: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order:			Meter:			In Date:	09/07/2011	Closed:	09/09/2011
Problem:	Towed in	battery discharge.Drive	r side map la	amp was left on.					
Work Com	pleted				Parts Issued			Qı	uantity
•	_	ed battery.test starting lamp was left on	and chargin	g system.test for	Shop Supplies				1.00
- Shop Sup	plies								
	ŀ	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Work Order: Problem:			Meter:	11433		In Date:	09/07/2011	Closed:	09/08/2011
Work Com	pleted								
- From: 50	s military	To: lv shop							
	ŀ	Hours: 0.00		Comm: 104.15	Labor: 0.00	Parts: 0.0	0	Total:	104.15
Work Order: Problem:		ice and check wipers.	Meter:	15049		In Date:	12/29/2011	Closed:	01/09/2012
Work Com	pleted				Parts Issued			Qı	uantity
- Perform _I	om service				Shop Supplies				1.00
- Rotate ar	nd balance	all four tires.			Ch10358 Oil Filter	Lbf P980 Wix	57064		1.00
- Shop Sup	plies				75-540 0w/20 Mo	tor Oil			5.00
					31-24 Wiper Blade	es 24" Blade			1.00
					Nb-18 Wiper Blad	es 18" Anco 3	31-18		1.00
					8524247030 Rear \	Wiper Blade (2	2010 Prius)		1.00
	ŀ	Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 56.	54	Total:	236.54
Work Order: Problem:		ticket(s) issued	Meter:	14928		In Date:	12/29/2011	Closed:	12/29/2011
Work Com	pleted								
2 14/ 1	ticket(s) is	auad							

Comm: 19.46

Labor: 0.00

Parts: 0.00

Total: 19.46

Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1203468 Meter: 18243 In Date: 04/12/2012 Closed: 04/12/2012

Problem: FLAT TIRE/ DRIVER WILL COME WITH VEHICLE

Work Completed

- Tow From: 50 S. Military To: Lv Shop

Hours: 0.00 Comm: 104.15 Labor: 0.00 Parts: 0.00 Total: 104.15

Work Order: 1203497 Meter: 18444 In Date: 04/12/2012 Closed: 04/16/2012

Problem: Towed in left rear tire flat.

Work Completed Parts Issued Quantity

- Repair and balance left rear tire. Shop Supplies 1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Labor: 240.00

Parts: 41.51

Total: 281.51

Work Order: 1204675 Meter: 20143 In Date: 05/17/2012 Closed: 05/24/2012

Problem: Pm service

Work CompletedParts IssuedQuantity- Perform pm service.Shop Supplies1.00- Repair flat right rear tire.nitrogen fill and balance all four.Ch10358 Oil Filter Lbf P980 Wix 570641.00- Shop SuppliesCf10285 Cab Filter Wix 244831.0075-540 0w/20 Motor Oil5.00

Work Order: 1209596 Meter: 25513 In Date: 10/05/2012 Closed: 11/20/2012

Comm: 0.00

Problem: Pm service.

Hours: 4.00

Work Completed		Parts Issued		Quantity
- P.m. Service		0w-20 Motor Oil		5.00
- Replace two tires,rotate and balance all four.		Ch10358 Oil Filter	Lb	1.00
- Complete wheel alignment test drive.		Wd40 Spray Lube	Stock	1.00
- Transport vehicle to dealer for oil pan leak and leaking a	ıxle boot.	Tire P195/65r15		2.00
- Shop Supplies		Shop Supplies		1.00
	Camma, 0.00	Lahar: 540.00	Domes 270.40	Total: 700.40

Hours: 8.50 Comm: 0.00 Labor: 510.00 Parts: 279.16 Total: 789.16

Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1209818 Meter: 25021 In Date: 10/12/2012 Closed: 10/12/2012

Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 17.02 Labor: 0.00 Parts: 0.00 Total: 17.02

Work Order: 1304758 Meter: 30150 In Date: 05/13/2013 Closed: 05/23/2013

Problem: P.M. service.

Work Completed	Parts Issued		Quantity
- Perform pm service.	Syn0w20		4.00
- Install two new tires to the front wheels.nitrogen fill and balance all four	Napagold Oil Filte	er	1.00
- Shop Supplies	Wiper Blade		1.00
	31-24 Wiper Blad	31-24 Wiper Blades 2	
	8524247010 Blade	e Rear	1.00
	738274571 195-65	5r15 A	2.00
	Shop Supplies		1.00
	Tire Disposal Fee		2.00
Hours: 4.00 Comm: 0.00	Labor: 240.00	Parts: 250.50	Total: 490.50

Work Order: 1305560 Meter: 30635 In Date: 06/05/2013 Closed: 06/05/2013

Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 17.02 Labor: 0.00 Parts: 0.00 Total: 17.02

Hours: 3.00

Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: Problem:	1310315 P.M. service.	Meter:	35124		In Date:	10/11/2013	Closed:	10/31/2013
Work Com	pleted			Parts Issued			Qı	ıantity
- Perform	om service.			Syn0w20				5.00
	nd balance all four tires.			Napagold Oil Filter				1.00
- Shop Sup	pplies			Wiper Blade				1.00
				31-24 Wiper Blades 2	2			1.00
				Air Filter (gold)				1.00
				Washer Fluid Concen	tr			1.00
				Shop Supplies				1.00
	Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 57.	55	Total:	237.55
Work Order: Problem:	1310357 2 - Wash ticket(s) issued	Meter:	34998		In Date:	10/15/2013	Closed:	10/15/2013
Work Com	pleted							
- 2 - Wash	ticket(s) issued							
	Hours: 0.00		Comm: 17.02	Labor: 0.00	Parts: 0.0	0	Total:	17.02
Work Order: Problem:	1402450 Remote will not open door.	Meter:	38665		In Date:	03/13/2014	Closed:	03/20/2014
Work Com	pleted			Parts Issued			Qı	ıantity
- Test and	replace failed door lock remote I	pattery with n	ew.	Lithium Coin Cell				1.00
	Hours: 0.50	,	Comm: 0.00	Labor: 30.00	Parts: 5.5	5	Total:	35.55
Work Order: Problem:	1404064 P.M. Service.	Meter:	39968		In Date:	04/28/2014	Closed:	05/06/2014
Work Com	pleted			Parts Issued			Qı	ıantity
- Perform	om service.			Syn0w20				5.00
- Rotate ar	nd balance all four tires.			Napagold Oil Filter				1.00
- Shop Sup	pplies			31-24 Wiper Blades 2	2			1.00
				Wiper Blade				1.00

Comm: 0.00

Labor: 180.00

Parts: 46.04

Total: 226.04

Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1405103 Meter: 40900 In Date: 05/27/2014 Closed: 05/29/2014

Problem: Remote inop.

Work Completed Parts Issued Quantity

- Test and replace key fob battery.

Lithium Coin Cell 1.00

Hours: 0.25 Comm: 0.00 Labor: 15.00 Parts: 5.55 Total: 20.55

Work Order: 1406556 Meter: 41223 In Date: 07/02/2014 Closed: 07/02/2014

Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 17.02 Labor: 0.00 Parts: 0.00 Total: 17.02

Work Order: 1406724 Meter: 41261 In Date: 07/08/2014 Closed: 07/08/2014

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1410515 Meter: 42943 In Date: 10/21/2014 Closed: 10/28/2014

Problem: pm service/change tag

Work Completed Parts Issued Quantity

Syn0w20 5.00

- Pm Syn0w20 5.00
- Remove aging asset numbers, remake decals and reapply, swap plates Napagold Oil Filter 1.00

 31-24 Wiper Blades 2
 1.00

 Wiper Blade
 1.00

Rear Blade Toyota 1.00
Washer Fluid Concentr 1.00

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 75.00 Total: 255.00

Work Order: 1410701 Meter: 42941 In Date: 10/27/2014 Closed: 10/27/2014

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 91.80 Labor: 0.00 Parts: 0.00 Total: 91.80

Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1412446 Meter: 43190 In Date: 12/12/2014 Closed: 12/31/2014

Problem: towed in/ will not start

Work Completed Parts Issued Quantity

- Test and repalce remote battery

Lithium Coin Cell

1.00

- Scan for codes send to dealer for hybrid battery and inverter warranty

- Wash Vehicle

Hours: 4.50 Comm: 0.00 Labor: 270.00 Parts: 5.43 Total: 275.43

Work Order: 1412532 Meter: 43190 In Date: 12/12/2014 Closed: 12/15/2014

Problem: NO START

Work Completed

- Tow From: 8100 Forest Hill Blvd To: Lv Shop

Hours: 0.00 Comm: 104.15 Labor: 0.00 Parts: 0.00 Total: 104.15

Work Order: 1412592 Meter: 43190 In Date: 12/16/2014 Closed: 12/17/2014

Problem: to dealer for no start/ hybrid light on

Work Completed

- Tow From: vista To: palm beach toyota

Hours: 0.00 Comm: 104.15 Labor: 0.00 Parts: 0.00 Total: 104.15

Work Order: 1500042 Meter: 43200 In Date: 01/02/2015 Closed: 01/02/2015

Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.73 Labor: 0.00 Parts: 0.00 Total: 9.73

Work Order: 1500295 Meter: 43200 In Date: 01/08/2015 Closed: 01/08/2015

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.00 Labor: 0.00 Parts: 0.00 Total: 90.00

Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1502895 Meter: 44131 In Date: 03/19/2015 Closed: 03/27/2015

Problem: pm service

 Work Completed
 Parts Issued
 Quantity

 - Pm
 Napagold Oil Filter
 1.00

 - Wash
 Syn0w20
 5.00

 Air Filter (gold)
 1.00

 Labor: 180.00
 Porto: 30.60
 Total: 310.60

Meter: 44131

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 39.69 Total: 219.69

In Date:

04/13/2015 **Closed:** 04/13/2015

Problem: 1 - Wash ticket(s) issued

Work Completed

Work Order: 1503752

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.54 Labor: 0.00 Parts: 0.00 Total: 9.54

Work Order: 1504501 Meter: 44231 In Date: 05/01/2015 Closed: 05/01/2015

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.00 Labor: 0.00 Parts: 0.00 Total: 90.00

Work Order: 1509645 Meter: 45422 In Date: 09/24/2015 Closed: 09/25/2015

Problem: pm service

 Work Completed
 Parts Issued
 Quantity

 - Pm Service
 Napagold Oil Filter
 1.00

 Syn0w20
 5.00

 Exact Fit Blade
 1.00

 Wiper Blade
 1.00

 Wiper Blade - Accufit - Rear - Oe Style
 1.00

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 54.45 Total: 174.45

Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1602469 Meter: 47638 In Date: 03/08/2016 Closed: 03/15/2016

Problem: pm serice

 Work Completed
 Parts Issued
 Quantity

 - Pm
 Napagold Oil Filter
 1.00

 - Carwash
 Syn0w20
 5.00

 Cabin Air Filter
 1.00

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 36.09 Total: 216.09

Work Order: 1602828 Meter: 47638 In Date: 03/17/2016 Closed: 03/17/2016

Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 8.34 Labor: 0.00 Parts: 0.00 Total: 8.34

Work Order: 1605838 Meter: 51946 In Date: 06/07/2016 Closed: 06/15/2016

Problem: pm service

Work Completed		Parts Issued		Quantity
- Pm		Napagold Oil Filter	•	1.00
- R/r w/ tires due to dryrott		Syn0w20		5.00
		Wiper Blades 24"		1.00
		18" wiper blades		1.00
		Wiper Blade - Accufit - Rear - Oe Style 738274571 195-65r15 A Washer Fluid Concentr		1.00 4.00
				1.00
		Tire Disposal Fee		4.00
Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 508.66	Total: 748.66

Work Order: 1609068 Meter: 52995 In Date: 08/31/2016 Closed: 08/31/2016

Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 8.34 Labor: 0.00 Parts: 0.00 Total: 8.34

Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1612565 Meter: 54293 12/07/2016 **Closed**: 12/20/2016 In Date: Problem: pm service **Work Completed Parts Issued** Quantity Syn0w20 5.00 - Pm Service Napagold Oil Filter 1.00 Wiper Blades 24" 1.00 18" wiper blades 1.00 Total: 155.99 Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 35.99 Work Order: 1700996 Meter: 54917 01/31/2017 **Closed**: 02/06/2017 In Date: Problem: Won't start **Work Completed**

- Fm to 25r00 Main St. Bg.

- Jumpstart vehicle.

Hours: 1.50 Comm: 0.00 Labor: 90.00 Parts: 0.00 Total: 90.00

Work Order: 1701362 Meter: 55301 In Date: 02/09/2017 Closed: 02/09/2017

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

 Hours: 0.00
 Comm: 90.00
 Labor: 0.00
 Parts: 0.00
 Total: 90.00

 Work Order:
 1702652
 Meter: 55342
 In Date: 03/15/2017
 03/15/2017
 Closed: 03/21/2017

Problem: to dealer for recall 16V-487

Work Completed

- To and from Dealer for recall 16v-487

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1704814 Problem: pm service	Meter:	55470		In Date:	05/15/2017	Closed:	05/22/201
·							
Work Completed			Parts Issued			Qı	uantity
- pm service			Syn0w20				5.00
			Napagold Oil Filter				1.00
			Wiper Blades 24"				1.00
			18" wiper blades				1.00
Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 36.	74	Total:	156.74
Work Order: 1709973 Problem: no start	Meter:	56145		In Date:	10/12/2017	Closed:	10/16/201
Work Completed			Parts Issued			Qı	uantity
- Check battery, r/r Weak battery			Agm Battery				1.00
Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 21	1.07	Total:	271.07
Work Order: 1710948	Meter:	56298		In Date:	11/03/2017	Closed:	
Problem: pm service							
Work Completed							
-							
Hours: 0.00		Comm: 0.00	Labor: 0.00	Parts: 0.0	0	Total:	0.00
Work Order: 1711783 Problem: pm service	Meter:	56299		In Date:	12/01/2017	Closed:	12/04/201
Work Completed			Parts Issued			Qı	uantity
- pm service			Syn0w20				5.00
·			Napagold Oil Filter				1.00
			Wiper Blades 24"				1.00
			18" wiper blades				1.00
			Non-chlor Brake Cln	r			1.00
			Washer Fluid Conce	ntr			1.00
Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 42.	36	Total:	162.36

Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1802813 Meter: 57512 In Date: 03/15/2018 Closed: 03/28/2018

Problem: vehicle stumbled and stalled out when first picked up

Work Completed

- check vehicle. out of fuel. refuel and test drive

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 0.00 Total: 60.00

Work Order: 1805292 Meter: 57630 In Date: 05/23/2018 Closed: 05/30/2018

Problem: pm service

Work Completed		Parts Issued		Quantity
- pm service		Napagold Oil Filter		1.00
- replace key fob battery		Syn0w20		5.00
		16in Exactfit-rear 18" wiper blades		1.00
				1.00
		Wiper Blades 24"		1.00
		Air Filter (gold) Cabin Air Filter		1.00
				1.00
		Lithium Coin Cell		1.00
Hours: 2.50	Comm: 0.00	Labor: 150.00	Parts: 69.38	Total: 219.38

Work Order: 1808160 Meter: 58496 In Date: 08/08/2018 Closed: 08/09/2018

Problem: ac doesnt stay cool

Work Completed

- check for ac operation and leaks. normal at this time

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 0.00 Total: 60.00

Work Order: 1810369 Meter: 58702 In Date: 10/09/2018 Closed: 10/09/2018

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.00 Labor: 0.00 Parts: 0.00 Total: 90.00

Hours: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1811563 Meter: 58702 11/09/2018 **Closed:** 11/21/2018 In Date: Problem: pm service **Parts Issued** Quantity **Work Completed** 5.00 Syn0w20 - pm service Napagold Oil Filter 1.00 Wiper Blades 24" 1.00 1.00 18" wiper blades 16in Exactfit-rear 1.00 Hours: 2.00 Comm: 0.00 Labor: 134.00 Parts: 48.56 Total: 182.56 Work Order: 1903967 Meter: 59886 04/11/2019 Closed: 04/15/2019 In Date: Problem: pm service **Parts Issued** Quantity **Work Completed** Napagold Oil Filter 1.00 - Pm Service Syn0w20 5.00 - Replace asset #s 195/65r15 Mich Premier 2.00 - Replace 2 dry rotted tires; nitro filled & installed on front of vehicle 18" wiper blades 1.00 - Top off loaner Wiper Blades 24" 1.00 Tire Disposal Fee 2.00 Comm: 0.00 Hours: 5.00 Labor: 335.00 Parts: 330.97 Total: 665.97 Work Order: 1904580 Meter: 59896 04/26/2019 **Closed:** 04/26/2019 In Date: Problem: 1 - Wash ticket(s) issued **Work Completed** - 1 - Wash ticket(s) issued Hours: 0.00 Comm: 8.34 Labor: 0.00 Parts: 0.00 Total: 8.34 Work Order: 1909675 Meter: 59936 **In Date:** 09/19/2019 **Closed:** 09/19/2019 Problem: 1 - Wash ticket(s) issued **Work Completed** - 1 - Wash ticket(s) issued

Comm: 90.00

Labor: 0.00

Parts: 0.00

Total: 90.00

Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

 Work Order:
 1909791
 Meter:
 59948
 In Date:
 09/24/2019
 Closed:
 09/30/2019

Problem: pm service

Work Completed		Parts Issued		Quantity
- pm service	Napagold Oil Filter		1.00	
·		Syn0w20		5.00
		Wiper Blades 24"		1.00
		18" wiper blades		1.00
Hours: 2.00	Comm: 0.00	Labor: 134.00	Parts: 41.16	Total: 175.16

Work Order: 2002466 Meter: 62012 In Date: 03/10/2020 Closed: 03/23/2020

Problem: pm service

Work Completed		Parts Issued		Quantity
- pm service	Napagold Oil Filte	r	1.00	
- replace front pads, resurface rotors and service	e calipers	Syn0w20		5.00
		Washer Fluid Concentr Wiper Blades 24" 18" wiper blades lube		1.00
				1.00
				1.00
				1.00
		Front Brake Pad		1.00
Hours: 5.50	Comm: 0.00	Labor: 401.50	Parts: 132.14	Total: 533.64

Work Order: 2009145 Meter: 64701 In Date: 09/11/2020 Closed: 10/09/2020

Problem: pm service

Work Completed		Parts Issued		Quantity
- pm service		Napagold Oil Filter	r	1.00
		Syn0w20		5.00
		18" wiper blades		1.00
		Wiper Blades 24"		1.00
Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 40.26	Total: 186.26

Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 2011842 Meter: 64773 In Date: 11/30/2020 Closed: 12/14/2020

Problem: slow starting

Work Completed

- Check and charge 12v battery, hybrid batteries low test drive to charge

hybrid batteries and charging system

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 0.00 Total: 73.00

Work Order: 2104000 Meter: 65876 In Date: 04/09/2021 Closed: 04/12/2021

Problem: pm service

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Syn0w20		5.00
		Napagold Oil Filter Wiper Blades 24" 18" wiper blades		1.00
				1.00
				1.00
		16in Exactfit-rear		1.00
Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 51.81	Total: 197.81

Work Order: 2108178 Meter: 66921 In Date: 07/29/2021 Closed: 07/30/2021

Problem: low tire light

Work Completed	Parts Issued	Quantity
- Replace right front tpms sensor and program	Sensor	1.00

- Check hybrid system light on,hybrid battery low test drive to charge hybrid battery and check charging system,clear code

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 84.69 Total: 230.69

Work Order: 2109501 Meter: 67350 In Date: 08/30/2021 Closed: 09/03/2021

Problem: tire light on

Work Completed			Parts Issued		Quantity			
- Check Tire Light On, Tire Light Is Flashing, test And Replaced 1 Faulty Tire			Sensor	1.00				
Pressure Sensor In Rr Tire.								
Hours:	1.00	Comm: 0.00	Labor: 73.00	Parts: 83.92	Total: 156.92			

Hours: 2.00

Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: Problem:	2110223 pm service	Meter:	67446		In Date:	09/21/2021	Closed:	10/20/2021
Work Com	pleted			Parts Issued			Qı	uantity
- Preventive Maint. Service				Syn0w20				5.00
				Napagold Oil Filter				1.00
				Air Filter (gold)				1.00
				Wiper Blades 24"				1.00
				18" wiper blades				1.00
				16in Exactfit-rear				1.00
				Washer Fluid Conce	ntr			1.00
	Hours: 2.00		Comm: 0.00	Labor: 146.00	Parts: 49.	32	Total:	195.32
Work Order: Problem:	2111327 1 - Detail Vehicle Wash Ticket(s) I	Meter: ssued	67446		In Date:	10/20/2021	Closed:	10/20/2021
Work Com	pleted							
- 1 - Detai	Vehicle Wash Ticket(s) Issued							
	Hours: 0.00		Comm: 84.75	Labor: 0.00	Parts: 0.0	0	Total:	84.75
Work Order: Problem:	2202141 1 - Detail Vehicle Wash Ticket(s) I	Meter: ssued	68522		In Date:	02/24/2022	Closed:	02/24/2022
Work Com	pleted							
- 1 - Detai	l Vehicle Wash Ticket(s) Issued							
	Hours: 0.00		Comm: 84.75	Labor: 0.00	Parts: 0.0	0	Total:	84.75
Work Order: Problem:	2203572 pm service	Meter:	68543		In Date:	03/31/2022	Closed:	04/19/2022
Work Com	pleted			Parts Issued			Qı	uantity
- Preventive Maint. Service	ve Maint. Service			Syn0w20				5.00
				Napagold Oil Filter				1.00
				18in Exactfitblade				1.00
			16in Exactfit-rear				1.00	
				Wiper Blades 24"				1.00

Comm: 0.00

Labor: 146.00

Parts: 45.38

Total: 191.38

Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 2209571 Meter: 68689 In Date: 09/14/2022 Closed: 09/15/2022

Problem: NO START

Work Completed	Parts Issued	Quantity
 - Ck Dead Battery. Test Electrical System, Replace Vehicle 12v Battery And Key Fob Battery - Replace Rear Hatch Lift Support Struts 	Agm Battery	1.00
	Lithium Coin Cell	1.00
	Lift Support	2.00

- add fuel

Hours: 2.50 Comm: 0.00 Labor: 182.50 Parts: 258.75 Total: 441.25

Work Order: 2209663 Meter: 68695 In Date: 09/13/2022 Closed: 09/16/2022

Problem: NO START

Work Completed

- Tow From: 2520 Lake Worth Rd, Lw Rd (rangers Bldg) To: Lv Shop

Hours: 0.00 Comm: 113.00 Labor: 0.00 Parts: 0.00 Total: 113.00

Work Order: 2209664 Meter: 68695 In Date: 09/16/2022 Closed: 09/16/2022

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued to: TODD MOORE

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued to: Todd Moore

Hours: 0.00 Comm: 84.75 Labor: 0.00 Parts: 0.00 Total: 84.75

Work Order: 2210080 Meter: 68736 In Date: 09/30/2022 Closed:

Problem: pm service

Work Completed

- Preventive Maint. Service

- Check Engine Light Is On, Code P0afc Stored,

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 2210775 Meter: 68736 In Date: 10/21/2022 Closed: 10/21/2022

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Palm Beach County Fleet Management Asset Maintenance History 10180941 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 103.75 Total Labor: 6,574.00 Total Comm: 1,474.48 Total Parts: 3,122.58