- 002 Wash Tickets Issued Out 07/01/08

Hours: 0.00

Comm: 16.68

# Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Total Hours:	185.30	Labor: 11,917.	50 Parts: 8,251.53	Comm: 658.01		Charged	: 20827.04	
Work Order: Problem:		N ELIVERY INSPEC	Meter: 0 CTION		In Date:	05/14/2008	Closed:	05/14/2008
Work Com	pleted							
- Pre-deliv	ery Inspe	ection						
		Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: Problem:		L COMPUTER S	<b>leter:</b> 325 TAND.		In Date:	05/19/2008	Closed:	05/22/2008
Work Com	pleted			Parts Issued			Qı	uantity
- Installed	Compute	er Stand.		Shop Supplies				1.00
- Shop Sup	pplies			425-5426 Comp St	and F-150 (jo	tto Desk)		1.00
		Hours: 1.50	Comm: 0.00	Labor: 90.00	Parts: 284	1.00	Total:	374.00
Work Order: Problem:		N SH TICKET ISSI	<b>leter:</b> 0 JED OUT 05/21/08		In Date:	05/21/2008	Closed:	05/27/2008
Work Com	pleted							
- 001 Wasl	h Ticket I	ssued Out 05/2	1/08					
		Hours: 0.00	Comm: 7.14	Labor: 0.00	Parts: 0.0	0	Total:	7.14
Work Order: Problem:			<b>Neter:</b> 0 SUED OUT 07/01/08		In Date:	07/01/2008	Closed:	07/02/2008
Work Com	pleted							

Labor: 0.00

Parts: 0.00

Total: 16.68

# Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 847288 Meter: 4196 In Date: 11/19/2008 Closed: 11/22/2008

Problem: P.M SERVICE

Work Completed		Parts Issued		Quantity
- Pm Service - Rotate And High Speed Balance All 4 Tires.		Shop Supplies Ca8039 Air Filter Lbf Af1615 Wix 46418		1.00
				1.00
- Shop Supplies		1372 Oil Filter Frm Ph2 Wix 51372		1.00
		G10166 Fuel Filter	Mtc Fg1083 Wix 33243	1.00
		5w20 Engine Oil		7.00
		Used Firex Refurbed Fire Extingshers		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 58.17	Total: 238.17

Work Order: 934789 Meter: 0 In Date: 03/04/2009 Closed: 03/05/2009

**Problem:** 002 WASH TICKETS ISSUED OUT 03/04/09

#### **Work Completed**

- 002 Wash Tickets Issued Out 03/04/09

Hours: 0.00 Comm: 16.68 Labor: 0.00 Parts: 0.00 Total: 16.68

Work Order: 938745 Meter: 8640 In Date: 06/08/2009 Closed: 06/15/2009

Problem: P.M SERVICE.

Work Completed		<b>Parts Issued</b>		Quantity
- Pm Service	Shop Supplies		1.00	
- Rotate And Hi Speed Balance 4 Tires. Nitro Fill Tires.		1372 Oil Filter Frm Ph2 Wix 51372		1.00
- Shop Supplies		5w20 Engine Oil		7.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 19.11	Total: 199.11

Work Order: 946130 Meter: 12051 In Date: 11/17/2009 Closed: 11/17/2009

Problem: 2 - Wash ticket(s) issued

# **Work Completed**

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 16.68 Labor: 0.00 Parts: 0.00 Total: 16.68

Hours: 2.00

# Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1000403 Problem: P.M service.	Meter:	13192		In Date:	01/11/2010	Closed:	01/22/2010
Work Completed			Parts Issued			Q	uantity
- P.m service.			Big G Degreaser St	tock# 485180	002		1.00
- Rotate & balance all four tires.			Shop Supplies				1.00
- Shop Supplies			1372 Oil Filter Frr	m Ph2 Wix 51	372		1.00
			Ca8039 Air Filter L	bf Af1615 Wix	46418		1.00
			G10166 Fuel Filter	Mtc Fg1083 V	Wix 33243		1.00
			5w20 Engine Oil				7.00
			31-20 Wiper Blade	es 20" Blade			2.00
			Used Firex Refurbe	ed Fire Extings	shers		1.00
Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 70.	.93	Total:	250.93
Work Order: 1007420 Problem: P.M. Service.Boby damage.	Meter:	16895		In Date:	07/14/2010	Closed:	07/19/2010
Work Completed			Parts Issued			Q	uantity
- Perform pm service.			Shop Supplies				1.00
- Rotate and balance all four wheels.			1372 Oil Filter Frr	m Ph2 Wix 51	372		1.00
- Shop Supplies			5w20 Engine Oil				7.00
Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 18.	.61	Total:	198.61
Work Order: 1007612 Problem: REFLASH CANCEIVERLEAV	<b>Meter:</b> E FOR HANI		\GE	In Date:	07/19/2010	Closed:	07/22/2010
Work Completed			Parts Issued			Q	uantity
- flash Canceiver			Shop Supplies				1.00
- Install Blown fuse and new plug screws							
- Shop Supplies							

Comm: 0.00

Labor: 120.00

Parts: 2.00

Total: 122.00

# Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1008776 Meter: 16896 In Date: 07/21/2010 Closed: 08/16/2010

Problem: damage to tail gate

**Work Completed** 

- damage to tail gate

Hours: 0.00 Comm: 252.00 Labor: 0.00 Parts: 0.00 Total: 252.00

Work Order: 1013431 Meter: 19490 In Date: 12/07/2010 Closed: 12/08/2010

**Problem:** Has to keep jump starting battery.

Work CompletedParts IssuedQuantity- Test battery and charging system.recharge and retest battery,fail load<br/>test.replace defective battery.Shop Supplies1.00Group 59 Battery (mtc Bxt 59)1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 120.19 Total: 180.19

Work Order: 1101236 Meter: 20458 In Date: 02/01/2011 Closed: 02/09/2011

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
<ul> <li>Perform pm service.</li> <li>Install four new tires.nitrogen fill and balance all four.</li> <li>Inspect and replace failed high pressure power steering hose between pump and rack with new.flush system and renew fluid.</li> </ul>		Shop Supplies	Shop Supplies	
		1372 Oil Filter Frr	1372 Oil Filter Frm Ph2 Wix 51372 G10166 Fuel Filter Mtc Fg1083 Wix 33243	
		G10166 Fuel Filter		
		5w20 Engine Oil		7.00
- Shop Supplies		Syn/atf Trans Fluid Synthetic		2.00
		Used Firex Refurbed Fire Extingshers 31-20 Wiper Blades 20" Blade Power Steering Hose 183783418 P235/70r17 Wrangler Sr-a Xl Tire Disposal Fee		1.00
				2.00
				1.00
				4.00
				4.00
Hours: 6.00 Co	omm: 0.00	Labor: 360.00	Parts: 789.20	Total: 1,149.20

# Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1105774 Meter: 22657 In Date: 06/01/2011 Closed: 06/01/2011

Problem: 1 - Wash ticket(s) issued

# **Work Completed**

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.73 Labor: 0.00 Parts: 0.00 Total: 9.73

Work Order: 1108649 Meter: 23945 In Date: 08/16/2011 Closed: 08/25/2011

**Problem:** P.M. service.

Work Completed		Parts Issued	Quantity	
- Perform pm service.	Shop Supplies	1.00		
- Rotate and balance all four tires.	1372 Oil Filter Frm Ph2 Wix 51372		1.00	
- Shop Supplies		Ca8039 Air Filter Lbf Af1615 Wix 46418		1.00
		5w20 Engine Oil		7.00
		31-20 Wiper Blade	es 20" Blade	2.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 37.45	Total: 217.45

Work Order: 1200942 Meter: 26430 In Date: 01/30/2012 Closed: 02/09/2012

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Shop Supplies		1.00
- A/c blower operates on high only.test and replace defective	e blower	1372 Oil Filter Fri	m Ph2 Wix 51372	1.00
resistor.		G10166 Fuel Filter Mtc Fg1083 Wix 33243		1.00
- Rotate and balance all tires.		5w20 Engine Oil		7.00
- Shop Supplies		1066 White Lithium (crc 05037)		1.00
		7090blk Frt Floor Mats (rubber Queen) Used Firex Refurbed Fire Extingshers 31-20 Wiper Blades 20" Blade Yh1715 A/c Blower Resistor (motorcraft)		1.00
				1.00
				2.00
				1.00
Hours: 4.00 Co	mm: 0.00	Labor: 240.00	Parts: 108.66	Total: 348.66

#### Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1201380 Meter: 26433 In Date: 02/09/2012 Closed: 02/09/2012

Problem: 2 - Wash ticket(s) issued

**Work Completed** 

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.46 Labor: 0.00 Parts: 0.00 Total: 19.46

Work Order: 1208322 Meter: 30528 In Date: 09/04/2012 Closed: 09/17/2012

**Problem:** P.M. service and had to jump start in AM.

Work Completed		Parts Issued		Quantity
- P.m. Service.	Shop Supplies	1.00		
- Rotate and balance all tires.	1372 Oil Filter Frm Ph2 Wix 51372		1.00	
- Shop Supplies		5w20 Engine Oil		7.00
		31-20 Wiper Blade	es 20" Blade	2.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 32.26	Total: 212.26

Work Order: 1209142 Meter: 30840 In Date: 09/25/2012 Closed: 09/27/2012

**Problem:** Left front tire flat.

Work Completed	Parts Issued	Quantity
- Repair and balance left front tire.	Shop Supplies	1.00
Chara Comalia		

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

**In Date:** 11/16/2012 **Closed:** 11/16/2012

**Work Order:** 1211174 **Meter:** 32021

Problem: 2 - Wash ticket(s) issued

**Work Completed** 

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.46 Labor: 0.00 Parts: 0.00 Total: 19.46

# Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1302883 Meter: 34852 In Date: 03/25/2013 Closed: 04/03/2013

Problem: P.M. service and tool box loose.

Work Completed		Parts Issued		Quantity	
- Perform pm service.		5w20 Engine Oil 1372 Oil Filter Napagold Fuel Filter		7.00	
- Drill and secure tool box to bed with thru bolts a	1.00				
- Rotate and balance all four tires.	1.00				
- Shop Supplies		31-20 Wiper Blades 20		2.00	
		Floor Mat-2pc Rub Bk		1.00	
		Used Firex Refurbed F Shop Supplies		1.00	
				1.00	
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 89.87	Total: 314.87	

Work Order: 1307826 Meter: 38070 In Date: 08/06/2013 Closed: 08/06/2013

Problem: 2 - Wash ticket(s) issued

### **Work Completed**

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.46 Labor: 0.00 Parts: 0.00 Total: 19.46

Work Order: 1309185 Meter: 38933 In Date: 09/10/2013 Closed: 09/19/2013

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.	5w20 Engine Oil		7.00	
- Test battery and charging system.replace bad battery.	Napagold Oil Filter Napagold Air Filter 31-20 Wiper Blades 20		1.00	
- Replace two tires,rotate and balance all four.			1.00 2.00	
- Complete wheel alignment.test drive.				
- Shop Supplies		Battery		1.00
		183783418 P235-70r17		2.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 7.50 Co	omm: 0.00	Labor: 450.00	Parts: 592.20	Total: 1,042.2

# Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Problem: Pm service.

Work Completed		Parts Issued		Quantity
- P.m. Service.	5w20 Engine Oil		7.00	
- Resurface front brake rotors.replace front pads.service	Napagold Oil Filter  Napagold Fuel Filter		1.00	
calipers.flush and bleed system.			1.00	
- Rotate and balance all tires.		Used Fire X Refurbished Front Pads		1.00
- Shop Supplies				1.00
		Shop Supplies		1.00
Hours: 6.50	Comm: 0.00	Labor: 390.00	Parts: 111.52	Total: 501.52

Work Order: 1405877 Meter: 44630 In Date: 06/16/2014 Closed: 06/16/2014

Problem: 3 - Wash ticket(s) issued

#### **Work Completed**

- 3 - Wash ticket(s) issued

Hours: 0.00 Comm: 29.20 Labor: 0.00 Parts: 0.00 Total: 29.20

Work Order: 1408672 Meter: 47029 In Date: 08/28/2014 Closed: 08/29/2014

**Problem:** Multiple screws thru both rear tires.

Work Completed		Parts Issued		Quantity
- Replace two tires and balance both.		183783418 P235-70r17		2.00
- Shop Supplies		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 440.52	Total: 500.52

# Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1410093 Meter: 48135 In Date: 10/07/2014 Closed: 10/17/2014

Problem: Pm service.

Work Completed		Parts Issued		Quantity
- Pm service.		5w20 Engine Oil		7.00
- Rotate and balance all four tires.		Napagold Oil Filte	r	1.00
- Shop Supplies		Wiper Blade		2.00
		Stg Wheel Cov - Ford		1.00
		<b>Shop Supplies</b>		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 51.53	Total: 231.53

Work Order: 1503583 Meter: 53951 In Date: 04/07/2015 Closed: 04/28/2015

Problem: Pm service.

Work Completed		Parts Issued		Quantity
- Pm service.	Pm service.			7.00
- Service transmission.replace filter.flush and refill tr	Napagold Oil Filte	r	1.00	
- Pressure test and inspect cooling system.flush and	Wiper Blade		2.00	
- Inspect front suspension and replace both defective	ve worn sway bar links.	Napagold Fuel Filt	er	1.00
- Rotate and balance all four tires.		Syn-atf Trans Fluid S		16.00
- Shop Supplies		Ft1167 Trans Filter L		1.00
		Peak Global		2.00
		Sway Bar Link - Fro	ont Susp	2.00
		Shop Supplies		1.00
Hours: 8.50	Comm: 0.00	Labor: 510.00	Parts: 266.71	Total: 776.71

Hours: 0.00

# Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: Problem:	1509775 Pm service.	Meter:	58283		In Date:	09/28/2015	Closed:	10/13/2015
Work Com	pleted			Parts Issued			Qı	ıantity
- Pm servic	ce.			5w20 Engine Oil				7.00
- Inspect a	nd service rear differential.			Napagold Oil Filter				1.00
•	or clunking noise.remove drive sh	aft.clean and	lube binding slip	Used Fire X Refurbis	hed			1.00
joint.	3		3 1	Wiper Blade				2.00
- Rotate ar	nd balance all four tires.			75w140 Ford Axle Lu	ube			3.00
- Shop Sup	pplies			Repair Kit				1.00
				Friction Modifier				1.00
				Air Freshener				1.00
				Shop Supplies				1.00
	Hours: 5.25		Comm: 0.00	Labor: 315.00	Parts: 164	1.57	Total:	479.57
Work Order: Problem:	1509809 1 - Wash ticket(s) issued	Meter:	58279		In Date:	09/28/2015	Closed:	09/28/2015
Work Com	pleted							
- 1 - Wash	ticket(s) issued							
	Hours: 0.00		Comm: 9.54	Labor: 0.00	Parts: 0.0	0	Total:	9.54
Work Order: Problem:	1511156 1 - Wash ticket(s) issued	Meter:	58670		In Date:	10/30/2015	Closed:	10/30/2015
Work Com	pleted							
- 1 - Wash	ticket(s) issued							
	Hours: 0.00		Comm: 9.54	Labor: 0.00	Parts: 0.0	0	Total:	9.54
Work Order: Problem:	1513144 2 - Wash ticket(s) issued	Meter:	60455		In Date:	12/31/2015	Closed:	12/31/2015
Work Com	pleted							
- 2 - Wash	ticket(s) issued							

Comm: 19.08

Labor: 0.00

Parts: 0.00

Total: 19.08

# Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1601240 Meter: 61342 In Date: 02/04/2016 Closed: 02/10/2016

Problem: remove canceiver

Work Completed Parts Issued Quantity
- Remove Canceiver Shop Supplies 1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1601804 Meter: 61813 In Date: 02/22/2016 Closed: 02/22/2016

Problem: 1 - Key(s) issued

 Work Completed
 Parts Issued
 Quantity

 - 1 - Key(s) issued
 Duplicate Vehicle Keys
 1.00

 Hours: 0.30
 Comm: 0.00
 Labor: 18.00
 Parts: 3.00
 Total: 21.00

Problem: 2 - Wash ticket(s) issued

#### **Work Completed**

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.08 Labor: 0.00 Parts: 0.00 Total: 19.08

Work Order: 1602674 Meter: 62374 In Date: 03/14/2016 Closed: 03/17/2016

**Problem:** P.M. service and right rear tire flat.

Work Completed		Parts Issued		Quantity
- Pm service.		5w20 Engine Oil		7.00
Repair right rear tire.rotate and balance all four.		Napagold Oil Filter		1.00
- Shop Supplies			20" Wiper Blade	
a all a all h		Washer Fluid Concentr Napagold Fuel Filter		1.00
				1.00
		Fuel Retaining Clip	DS .	1.00
		Shop Supplies		1.00
Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 38.72	Total: 278.72

# Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1602688 Meter: 62278 In Date: 03/14/2016 Closed: 03/14/2016

Problem: Flat tire on r/r

### **Work Completed**

- Tire Service 310 Lakeshore Dr, Lake Park fl - Flat tire on r/r

Hours: 0.00 Comm: 70.25 Labor: 0.00 Parts: 0.00 Total: 70.25

Work Order: 1609504 Meter: 67160 In Date: 09/13/2016 Closed: 09/27/2016

Problem: P.M. Service

Work Completed	Parts Issued	Quantity
- P.m. Service.	5w20 Engine Oil	7.00
- Tune-up.replace spark plugs	Napagold Oil Filter	1.00
- Service and clean throttle body and induction system.flush injec tors.	20" Wiper Blade	2.00
- Replace twlo tires,rotate and balance all four.	Washer Fluid Concentr	1.00
- Resurface rear brake rotors, replace rear pads. service and lube rear	Used Fire X Refurbished	1.00
calipers.flush and bleed system.	Spark Plug	8.00
- Replace serpentine belt.	Injector Cleaner	1.00
- Replace worn out sway bar links and bushings.	Intake Cleaner Kit	1.00
- Completre wheel alignment.test drive.	Throttle Body Cleaner	1.00
- Shop Supplies	183783418 P235-70r17	2.00
	Disc Brake Pads	1.00
	Serpentine Belt	1.00
	front sway bar link	2.00
	Nut	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 17.50 Comm: 0.00	Labor: 1,050.00 Parts: 828.41	Total: 1,878.41

Work Order: 1609779 Meter: 66943 In Date: 09/19/2016 Closed: 09/19/2016

Problem: 2 - Wash ticket(s) issued

#### **Work Completed**

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.08 Labor: 0.00 Parts: 0.00 Total: 19.08

#### Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1610417 Meter: 67704 In Date: 10/04/2016 Closed: 10/14/2016

**Problem:** Had to jump start.

 Work Completed
 Parts Issued
 Quantity

 - Test battery and charging system.replace bad battery.
 Battery
 1.00

 - Shop Supplies
 Shop Supplies
 1.00

 Hours: 1.00
 Comm: 0.00
 Labor: 60.00
 Parts: 126.43
 Total: 186.43

Work Order: 1612851 Meter: 68460 In Date: 12/15/2016 Closed: 12/15/2016

Problem: 1 - Wash ticket(s) issued

#### **Work Completed**

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.54 Labor: 0.00 Parts: 0.00 Total: 9.54

Work Order: 1702611 Meter: 73117 In Date: 03/14/2017 Closed: 03/28/2017

**Problem:** P.M. service and shimmy at 55mph.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		7.00
- Replace worn out front sway bar links.		Napagold Oil Filter	r	1.00
- Replace broken washer pump.		Napagold Fuel Filt	er	1.00
- Replace two tires,rotate and balance all four.	·		20" Wiper Blade	
- Shop Supplies		Washer Fluid Concentr		1.00
		Pedal Pad		1.00
		183783418 P235-7	70r17	2.00
		Steel Retaining Clip Nut		1.00
				2.00
		Washer Pump		1.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 5.50	Comm: 0.00	Labor: 330.00	Parts: 532.22	Total: 862.22

#### Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1702772 Meter: 72789 In Date: 03/20/2017 Closed: 03/20/2017

Problem: 6 - Wash ticket(s) issued

### **Work Completed**

- 6 - Wash ticket(s) issued

Hours: 0.00 Comm: 57.24 Labor: 0.00 Parts: 0.00 Total: 57.24

Work Order: 1706920 Meter: 78026 In Date: 07/14/2017 Closed: 07/31/2017

Problem: P.M. service.

Work Completed		Parts Issued		Quantity	
- P.m. service.		Nut		2.00	
- Swaybar upper link bushing failed .remove and re	aybar upper link bushing failed .remove and replace with new.		5w20 Engine Oil		
- Rotate and high speed balance all four tires.	Napagold Oil Filter		1.00		
- Shop Supplies		20" Wiper Blade		2.00	
		Washer Fluid Concentr		1.00	
		Used Fire X Refurbished Shop Supplies		1.00	
				1.00	
Hours: 3.50	Comm: 0.00	Labor: 210.00	Parts: 71.44	Total: 281.44	

Work Order: 1707115 Meter: 78021 In Date: 07/20/2017 Closed: 07/20/2017

Problem: 2 - Wash ticket(s) issued

# **Work Completed**

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.08 Labor: 0.00 Parts: 0.00 Total: 19.08

Work Order: 1707955 Meter: 78599 In Date: 08/14/2017 Closed: 08/14/2017

Problem: 2 - Wash ticket(s) issued

# **Work Completed**

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.08 Labor: 0.00 Parts: 0.00 Total: 19.08

#### Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Problem: Transition Prep Charge

**Work Completed** 

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1802049 Meter: 81341 In Date: 02/23/2018 Closed: 02/26/2018

**Problem:** get ready to transfer & repair driver seat

Work CompletedParts IssuedQuantity- Get ready for transfer and repair driver seatSeat Repair1.00

Hours: 1.50 Comm: 0.00 Labor: 90.00 Parts: 288.75 Total: 378.75

Work Order: 1802522 Meter: 81341 In Date: 03/07/2018 Closed: 03/12/2018

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Pm Service		Napa Quart 5w20	Napa Quart 5w20	
- Rotate and balance tires.		Napagold Oil Filter		1.00
		20" Wiper Blade Washer Fluid Concentr Napagold Fuel Filter		2.00
				1.00
				1.00
		Napagold Air Filte	er	1.00
Hours: 2.75	Comm: 0.00	Labor: 165.00	Parts: 55.74	Total: 220.74

Work Order: 1804468 Meter: 82364 In Date: 04/30/2018 Closed: 05/14/2018

**Problem:** Right rear tire flat.

**Work Completed** 

- Repair and balance right rear tire.

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 0.00 Total: 60.00

# Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1808388 Meter: 84660 In Date: 08/15/2018 Closed: 08/27/2018

Problem: DEAD BATTERY

Work Completed		Parts Issued		Quantity	
- Test charging system and replace bad battery.		Battery		1.00	
		Bat Term Protecto	or	1.00	
Hours: 0.75	Comm: 0.00	Labor: 45.00	Parts: 134.31	Total: 179.31	

Work Order: 1901207 Meter: 87850 In Date: 01/31/2019 Closed: 02/19/2019

Problem: P.M.SERVICE

Work Completed	Parts Issued	Quantity
- Pm Service.	Fuel Line Clip	2.00
- Service rear differential.	Napagold Fuel Filter	1.00
- Repair right rear tire.mount and balance.rotate and balance all.co	rrect N2 Napa Quart 5w20	7.00
and relearn Tpms.	Napagold Oil Filter	1.00
- Vacume debris from under hooh.clean/wash exterior.	Washer Fluid Concentr	1.00
- Replace broken fuel line retaining clip for fuel filter.	20" Wiper Blade	2.00
	Ptex Ultra Grey 3oz	1.00
	Friction Modifier	1.00
	75w140 Ford Axle Lube	4.00
Hours: 8.00 Comm: 0	.00 Labor: 536.00 Parts: 212.72	Total: 748.72

Work Order: 1904212 Meter: 88890 In Date: 04/18/2019 Closed: 04/30/2019

**Problem:** Loose front bumper.

Work Completed		Parts Issued		Quantity
- Replace front bumper and perform adjustr	ments to fit properly.	Bumper Assy		1.00
- Drill right side headlamp assembly to drain	n water in headlight.			
Hours: 5.00	Comm: 0.00	Labor: 335.00	Parts: 225.98	Total: 560.98

# Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1908371 Meter: 90451 In Date: 08/12/2019 Closed: 08/19/2019

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Pm Service.	Napagold Oil Filte	r	1.00	
- Replace both front hubs bearing with brake rotors.replace front brake		Napa Quart 5w20		7.00
pads, service calipers and slides. bleed system.		Washer Fluid Concentr		1.00
- Replace both rear door latches and cable assemblies to open and close		20" Wiper Blade		2.00
properly.		Non-chlor Brake Clnr		1.00
- Rotate and balance four tires.program and reset tire monitor with scan tool.		Disc Brake Pads		1.00
- Replace how is my driving sticker.		Disc Brk Rotor Drum		2.00
- Replace flow is my unving sticker.		Door Latch		1.00
		Door Latch		1.00
Hours: 13.00	Comm: 0.00	Labor: 871.00	Parts: 686.22	Total: 1,557.22

Work Order: 2001169 Meter: 92390 In Date: 02/03/2020 Closed: 02/18/2020

**Problem:** PM Service. Right rear tire flat.

Work Completed		Parts Issued		Quantity
<ul><li>- Pm Service.</li><li>- Replace four tires.mount,balance and add N2</li></ul>		Napagold Air Filter		1.00
		Napagold Fuel Filter Napa Quart 5w20		1.00
- Drain coolant.flush reservoir.refill,purge air and te	7.00			
- Wash interior and exterior.		Napagold Oil Filter		1.00
		20" Wiper Blade 235/70/17 Tire Goodyear Peak Global Antifrz		2.00
				4.00
				2.00
		Tire Disposal Fee		4.00
Hours: 7.50	Comm: 0.00	Labor: 547.50	Parts: 941.39	Total: 1,488.89

Work Order: 2003932 Meter: 92907 In Date: 04/21/2020 Closed: 04/27/2020

**Problem:** Right front tire flat.

# **Work Completed**

- Repair right front tire.

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 0.00 Total: 73.00

# Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 2005075 Meter: 93027 In Date: 05/20/2020 Closed: 07/17/2020

**Problem:** Two flat tires.

# **Work Completed**

- Repaired right front and right rear tires.

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Work Order: 2007403 Meter: 93061 In Date: 07/28/2020 Closed: 07/31/2020

Problem: PM Service

Work Completed Parts Issued			Quantity	
- Pm Service Rotate and balance four tires.		Napagold Oil Filte	er	1.00
		Napa Quart 5w20		7.00
- Service tool box adjust latches to close properly.		Washer Fluid Con-	centr	1.00
- Repair running lamp wiring.		20" Wiper Blade		2.00
- Vacume interior and wash truck.				
Hours: 6.00	Comm: 0.00	Labor: 438.00	Parts: 42.75	Total: 480.75

Work Order: 2100698 Meter: 94687 In Date: 01/20/2021 Closed: 01/25/2021

Problem: PM Service.

- Rotate and balance all tires, correct Nitrogen pressures.  - Wash interior and exterior  Napagold Oil Filter  Used Fire X Refurbished  Washer Fluid Concentr  1.0  20" Wiper Blade	Work Completed	Parts Issued		Quantity	
- Wash interior and exterior  Napagold Oil Filter  Used Fire X Refurbished  Washer Fluid Concentr  1.0  20" Wiper Blade  2.0	- Preventive Maint. Service		Napagold Fuel Filter		1.00
Used Fire X Refurbished 1.0 Washer Fluid Concentr 1.0 20" Wiper Blade 2.0	- Rotate and balance all tires, correct Nitrogen	Napa Quart 5w20		7.00	
Washer Fluid Concentr 1.0 20" Wiper Blade 2.0	- Wash interior and exterior				1.00
20" Wiper Blade 2.0					1.00
			Washer Fluid Con	centr	1.00
Hours: 4.50 Comm: 0.00 Labor: 328.50 Parts: 63.93 Total: 392			20" Wiper Blade		2.00
	Hours: 4.50	Comm: 0.00	Labor: 328.50	Parts: 63.93	Total: 392.43

Work Order: 2102002 Meter: 95333 In Date: 02/23/2021 Closed: 02/24/2021

**Problem:** Two flat tires.

# **Work Completed**

- repair and balance 2 flat tires.

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

# Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 2105731 Meter: 96556 In Date: 05/24/2021 Closed: 05/27/2021

**Problem:** Left taillamp lens separated and fell off.

 Work Completed
 Parts Issued
 Quantity

 - Replace left tail light lens.
 lamp assy
 1.00

 Hours: 1.00
 Comm: 0.00
 Labor: 73.00
 Parts: 66.06
 Total: 139.06

Work Order: 2107262 Meter: 96986 In Date: 07/06/2021 Closed: 07/13/2021

Problem: PM Service

Work Completed		Parts Issued		Quantity
- Pm Service		Napa Quart 5w20		7.00
- Rotate And Balanced 4 Tires	Napagold Oil Filter		1.00	
- Service Tool Box Adjust Latches To Close Properly		Washer Fluid Concentr		1.00
		20" Wiper Blade		2.00
Hours: 3.50	Comm: 0.00	Labor: 255.50	Parts: 33.79	Total: 289.29

Work Order: 2110102 Meter: 97886 In Date: 09/17/2021 Closed: 09/24/2021

Problem: Engine shakes and check engine light on

Work Completed		Parts Issued		Quantity
- scan po304 misfire code replaced coil #4 cly .replaced pcm 20a fuse to communicate w/scanner cleared codes		Fmx-20 Fuse		1.00
		Ignition Coil		1.00
Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 51.05	Total: 197.05

Work Order: 2112685 Meter: 98158 In Date: 11/30/2021 Closed: 12/21/2021

Problem: Tail Gate

Work Completed		Parts Issued		Quantity	
- Replace damage rear bumper cover & tail gate.		Tail Lamp Assemb	ly	1.00	
- Check engine light is on, engine is misfiring, scan & found # P0305, perform pinpoint test & found ignition coli #5 is bad, replace # 5 coil & clear			Tag Lamp		2.00
			Cover Bumber		1.00
- Test drive after repair to verify all repairs are complete		Ignition Coil		1.00	
		Steering Wheel Cover Large		1.00	
	Hours: 4.50	Comm: 0.00	Labor: 328.50	Parts: 267.33	Total: 595.83

# Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Problem: PM Service. pm Pass. rear taillight, Head light resurface

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napa Quart 5w20	7.00
- restore front head lamps	Napagold Oil Filter	1.00
- right rear tail lamp lens cracked. replace assy and replaced bul	os on both Washer Fluid Concentr	1.00
sides	20" Wiper Blade	2.00
- replaced driver's door check	Used Fire X Refurbished	2.00
- rotate balanced 4 tires	3m Tm Headlight Lens	1.00
	Tail Lamp Assembly	1.00
	Boxed Miniatures	2.00
	Boxed Miniatures	2.00
	Check Asy	1.00
Hours: 6.50 Comm	0.00 Labor: 474.50 Parts: 143.53	Total: 618.03

Work Order: 2208429 Meter: 101525 In Date: 08/15/2022 Closed: 08/22/2022

Problem: PM Service

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filter		1.00
- Rotate and balance tires, correct Nitrogen levels to 38 Psi.		Napa Quart 5w20		7.00
		Napagold Air Filter		1.00
		20" Wiper Blade		2.00
Hours: 3.00	Comm: 0.00	Labor: 219.00	Parts: 48.93	Total: 267.93

Work Order: 2210219 Meter: 102173 In Date: 10/05/2022 Closed: 10/07/2022

**Problem:** Dead battery. Had to travel to 200 West atlantic to jump start vehicle as er Jaimie Bostrom

Work Completed	Parts Issued	Quantity
- Test starting and charging system.battery failed load test after	Battery	1.00
recharge.replace battery.		
T 1: 000 W Ad at 6 at 1 at 1 at 1 at 1 at 1		

- Travel to 200 W Atlantic ave. Court House to jump start vehicle and brought back to Sr Shop for repairs.

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 127.36 Total: 273.36

# Palm Beach County Fleet Management Asset Maintenance History 10174481 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 2300954 Meter: 1034979 In Date: 01/30/2023 Closed: 01/30/2023

Problem: Transition Prep Charge

**Work Completed** 

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 185.30 Total Labor: 11,917.50 Total Comm: 658.01 Total Parts: 8,251.53