

3/6/2023
11:33:59 AM

Palm Beach County Fleet Management Asset Maintenance History
10192660 2013 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Total Hours: 154.90 Labor: 10,295.85 Parts: 8,256.25 Comm: 3,818.95 Charged: 22371.04

Work Order: 1304845 **Meter:** 329 **In Date:** 05/15/2013 **Closed:** 05/15/2013
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1304898 **Meter:** 342 **In Date:** 05/16/2013 **Closed:** 05/30/2013
Problem: Install DMI UNIT.

Work Completed

- Install Dmi unit.fabricate and install wiring.

- Shop Supplies

Parts Issued

Quantity

Rac 1-obd-k Distance 1.00

Shop Supplies 1.00

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 1,433.86 Total: 1,673.86

Work Order: 1306199 **Meter:** 1146 **In Date:** 06/20/2013 **Closed:** 06/24/2013
Problem: Left front tire flat.

Work Completed

- Repair flat left front tire.nitrogen fill and balance same.

- Shop Supplies

Parts Issued

Quantity

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1308331 **Meter:** 3527 **In Date:** 08/19/2013 **Closed:** 08/19/2013
Problem: Can't get Key into Ignition

Work Completed

- Tow From: Jpp To: Lv Shop

Hours: 0.00 Comm: 55.14 Labor: 0.00 Parts: 0.00 Total: 55.14

3/6/2023
11:33:59 AM

Palm Beach County Fleet Management Asset Maintenance History
10192660 2013 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1308418 **Meter:** 3771 **In Date:** 08/20/2013 **Closed:** 08/27/2013
Problem: Key will not go in ignition cylinder.

Work Completed

Parts Issued

Quantity

- Transport vehicle to and from dealer for replacing failed ignition switch cylinder with new and recode to original keys under factory warranty.
- Shop Supplies

| | |
|---------------|------|
| Shop Supplies | 1.00 |
|---------------|------|

| | | | | |
|-------------|------------|---------------|-------------|---------------|
| Hours: 2.00 | Comm: 0.00 | Labor: 120.00 | Parts: 2.00 | Total: 122.00 |
|-------------|------------|---------------|-------------|---------------|

Work Order: 1310717 **Meter:** 6572 **In Date:** 10/25/2013 **Closed:** 11/08/2013
Problem: Pm service.

Work Completed

Parts Issued

Quantity

- P.m. Service.
- Rotate and balance all tires.
- Shop Supplies

| | |
|---------------------|------|
| 5w20 Engine Oil | 6.00 |
| Napagold Oil Filter | 1.00 |
| Washer Fl | 1.00 |
| Shop Supplies | 1.00 |

| | | | | |
|-------------|------------|---------------|--------------|---------------|
| Hours: 3.75 | Comm: 0.00 | Labor: 225.00 | Parts: 24.22 | Total: 249.22 |
|-------------|------------|---------------|--------------|---------------|

Work Order: 1402160 **Meter:** 11652 **In Date:** 02/24/2014 **Closed:** 03/05/2014
Problem: put spare on left rear

Work Completed

- Tow From: jpp maint comp

| | | | | |
|-------------|-------------|-------------|-------------|--------------|
| Hours: 0.00 | Comm: 67.39 | Labor: 0.00 | Parts: 0.00 | Total: 67.39 |
|-------------|-------------|-------------|-------------|--------------|

Work Order: 1402347 **Meter:** 12022 **In Date:** 03/10/2014 **Closed:** 03/20/2014
Problem: Pm service.Left rear tire flat.

Work Completed

Parts Issued

Quantity

- P.m. Service.
- Rotate and balance all tires.
- Shop Supplies

| | |
|-------------------------|------|
| 5w20 Engine Oil | 6.00 |
| Napagold Oil Filter | 1.00 |
| Washer Fl | 1.00 |
| Used Fire X Refurbished | 1.00 |
| Wiper Blade | 2.00 |
| Shop Supplies | 1.00 |

| | | | | |
|-------------|------------|---------------|--------------|---------------|
| Hours: 3.75 | Comm: 0.00 | Labor: 225.00 | Parts: 47.14 | Total: 272.14 |
|-------------|------------|---------------|--------------|---------------|

3/6/2023
11:33:59 AM

Palm Beach County Fleet Management Asset Maintenance History
10192660 2013 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1409378 **Meter:** 17442 **In Date:** 09/18/2014 **Closed:** 09/30/2014
Problem: Pm service.

Work Completed

- Pm service.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

| | |
|---------------------|------|
| 5w20 Engine Oil | 6.00 |
| Napagold Oil Filter | 1.00 |
| Brake Cleaner | 1.00 |
| Napagold Air Filter | 1.00 |
| Shop Supplies | 1.00 |

Hours: 3.75

Comm: 0.00

Labor: 225.00 Parts: 33.80 Total: 258.80

Work Order: 1503035 **Meter:** 20633 **In Date:** 03/24/2015 **Closed:** 03/31/2015
Problem: Pm service.

Work Completed

- Pm service.
- Repair flat right front tire.rotate and balance all four.
- Shop Supplies

Parts Issued

Quantity

| | |
|----------------------|------|
| 5w20 Engine Oil | 6.00 |
| Napagold Oil Filter | 1.00 |
| Stg Wheel Cov - Ford | 1.00 |
| Shop Supplies | 1.00 |

Hours: 4.75

Comm: 0.00

Labor: 285.00 Parts: 39.94 Total: 324.94

Work Order: 1510429 **Meter:** 26258 **In Date:** 10/15/2015 **Closed:** 10/28/2015
Problem: Pm service.

Work Completed

- Pm service.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

| | |
|---------------------|------|
| 5w20 Engine Oil | 6.00 |
| Napagold Oil Filter | 1.00 |
| 22" Wiper Blade | 2.00 |
| Shop Supplies | 1.00 |

Hours: 3.75

Comm: 0.00

Labor: 225.00 Parts: 27.79 Total: 252.79

3/6/2023
11:33:59 AM

Palm Beach County Fleet Management Asset Maintenance History
10192660 2013 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1603994 **Meter:** 30596 **In Date:** 04/15/2016 **Closed:** 04/22/2016

Problem: P.M. service and left wiper blade broken .

Work Completed

- P.m. Service.
- Test battery and charging system.recharge and retest battery,failed load test.replace defective battery.
- Resurface front brake rotors,replace front pads.service and lube calipers.flush and bleed system.
- Replace and rewire corroded trailer plug.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

| | |
|-------------------------|------|
| 5w20 Engine Oil | 6.00 |
| Napagold Oil Filter | 1.00 |
| Used Fire X Refurbished | 1.00 |
| 22" Wiper Blade | 2.00 |
| Napagold Air Filter | 1.00 |
| Battery 65 | 1.00 |
| Brake Pad | 1.00 |
| trailer plug | 1.00 |
| Shop Supplies | 1.00 |

Hours: 10.00

Comm: 0.00

Labor: 600.00 Parts: 276.17 Total: 876.17

Work Order: 1610693 **Meter:** 35049 **In Date:** 10/17/2016 **Closed:** 11/14/2016

Problem: P.M. service.

Work Completed

- P.m. Service.
- Replace and balance four new tires.
- Complete wheel alignment.test drive.
- Transport vehicle to dezaler for air bag light.
- Shop Supplies

Parts Issued

Quantity

| | |
|-----------------------------|------|
| 5w20 Engine Oil | 6.00 |
| Napagold Oil Filter | 1.00 |
| 22" Wiper Blade | 2.00 |
| Washer Fluid Concentr | 1.00 |
| 265 / 70 / 17 Sl / Tire Gdy | 4.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 4.00 |

Hours: 9.25

Comm: 0.00

Labor: 555.00 Parts: 979.50 Total: 1,534.50

3/6/2023
11:33:59 AM

Palm Beach County Fleet Management Asset Maintenance History
10192660 2013 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1705137 **Meter:** 39254 **In Date:** 05/24/2017 **Closed:** 05/31/2017
Problem: P.M. service and towed in left rear tire flat.

Work Completed

- P.m. service.
- Replace blown tag light bulb.replace corroded tag light bulb socket.
- Completed transfer case service.
- Pressure test and inspect cooling system.flush and refill.
- Repair one tire .high speed balanced all four tires.nitrofilled.
- Shop Supplies

Parts Issued

Quantity

| | | |
|--------------------------|---------------|---------------|
| Napagold Oil Filter | 1.00 | |
| 5w20 Engine Oil | 6.00 | |
| 22" Wiper Blade | 2.00 | |
| Washer Fluid Concentr | 1.00 | |
| Used Fire X Refurbished | 1.00 | |
| Big G Degreaser 1 Gal | 1.00 | |
| Bulb | 1.00 | |
| Non-chlor Brake Clnr | 1.00 | |
| Ford Transfer Case Fluid | 2.00 | |
| Anti Freeze Motorcraft | 2.00 | |
| Tag Lamp Socket | 1.00 | |
| Shop Supplies | 1.00 | |
| Labor: 495.00 | Parts: 138.59 | Total: 633.59 |

Hours: 8.25

Comm: 0.00

Work Order: 1705525 **Meter:** 39254 **In Date:** 05/24/2017 **Closed:** 06/02/2017
Problem: put on spare tire

Work Completed

- Tow From: john Pp/ maint compound

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

3/6/2023
11:33:59 AM

Palm Beach County Fleet Management Asset Maintenance History
10192660 2013 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1711078 **Meter:** 44654 **In Date:** 11/08/2017 **Closed:** 11/21/2017
Problem: P.M. service.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Resurface both rear brake rotors.service parking brakes and brake calipers.replace brake pads with new.flush and bleed brake system.road test.
- Rotate and balance high speed balance all four tires.
- Shop Supplies

| | |
|-------------------------|------|
| 5w20 Engine Oil | 6.00 |
| Napagold Oil Filter | 1.00 |
| 22" Wiper Blade | 2.00 |
| Used Fire X Refurbished | 1.00 |
| Brake Pad | 1.00 |
| B Fluid Dot 3-32oz | 1.00 |
| Non-chlor Brake Clnr | 1.00 |
| Brake Pad | 1.00 |
| Shop Supplies | 1.00 |

Hours: 7.75 Comm: 0.00 Labor: 465.00 Parts: 185.17 Total: 650.17

Work Order: 1800122 **Meter:** 45657 **In Date:** 01/03/2018 **Closed:** 01/19/2018
Problem: Squeaking noise from front brake when braking.

Work Completed

Parts Issued

Quantity

- Test drive for brake noise.resurface front brake rotors.service and lube calipers.
- Shop Supplies

| | |
|---------------|------|
| Shop Supplies | 1.00 |
|---------------|------|

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 2.00 Total: 122.00

Work Order: 1802369 **Meter:** 47493 **In Date:** 03/02/2018 **Closed:** 03/06/2018
Problem: Wipers stay on.

Work Completed

Parts Issued

Quantity

- Diagnose wipers staying on .r&r defective wiper switch per Tsb 15-0061. Retest.
- Shop Supplies

| | |
|---------------|------|
| Switch | 1.00 |
| Shop Supplies | 1.00 |

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 43.31 Total: 103.31

3/6/2023
11:33:59 AM

Palm Beach County Fleet Management Asset Maintenance History
10192660 2013 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1805026 **Meter:** 49630 **In Date:** 05/15/2018 **Closed:** 05/24/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Perform automatic transmission flush service.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

| | |
|-----------------------|-------|
| 5w20 Engine Oil | 6.00 |
| Napagold Oil Filter | 1.00 |
| Washer Fluid Concentr | 1.00 |
| 22" Wiper Blade | 2.00 |
| Syn-atf Trans Fluid S | 13.00 |
| Shop Supplies | 1.00 |

Hours: 5.25 Comm: 0.00 Labor: 315.00 Parts: 79.30 Total: 394.30

Work Order: 1806056 **Meter:** 50127 **In Date:** 06/11/2018 **Closed:** 06/13/2018
Problem: screw in the tire on the passenger rear side

Work Completed

- Tire Service Jpp next to Ice Machine - screw in the tire on the passenger rear side

Hours: 0.00 Comm: 70.25 Labor: 0.00 Parts: 0.00 Total: 70.25

Work Order: 1808499 **Meter:** 52193 **In Date:** 08/07/2018 **Closed:** 08/17/2018
Problem: Flat tire on F/L

Work Completed

- Tire Service Jpp Maint Compound - Flat tire on F/l

Hours: 0.00 Comm: 70.25 Labor: 0.00 Parts: 0.00 Total: 70.25

3/6/2023
11:33:59 AM

Palm Beach County Fleet Management Asset Maintenance History
10192660 2013 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1811670 **Meter:** 54258 **In Date:** 11/14/2018 **Closed:** 11/26/2018
Problem: P.M. service and check tire vibration .

Work Completed

- P.m. service.
- Load test battery and recharge . Battery failed load test. R&r defective battery .retest.
- R&r corroded right rear taglamp socket and bulb.
- Replace two worn tires . Rotate and high speed balance all four . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

| | |
|-------------------------|------|
| Napagold Oil Filter | 1.00 |
| Napa Quart 5w20 | 6.00 |
| Washer Fluid Concentr | 1.00 |
| 22" Wiper Blade | 2.00 |
| Used Fire X Refurbished | 1.00 |
| Battery 65 | 1.00 |
| Boxed Miniatures | 1.00 |
| Tag Lamp | 1.00 |
| 265 70 R17 Tire | 2.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 2.00 |

Hours: 6.05

Comm: 0.00

Labor: 405.35 Parts: 705.09 Total: 1,110.44

Work Order: 1904182 **Meter:** 55411 **In Date:** 04/17/2019 **Closed:** 04/18/2019
Problem: Replace steering wheel cover .

Work Completed

- Install new steering wheel cover .

Hours: 0.20

Comm: 0.00

Parts Issued

Quantity

| | | |
|---------------------|--------------|--------------|
| Ford Triton Pvc Swc | 1.00 | |
| Labor: 13.40 | Parts: 18.47 | Total: 31.87 |

3/6/2023
11:33:59 AM

Palm Beach County Fleet Management Asset Maintenance History
10192660 2013 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1905348 **Meter:** 56078 **In Date:** 05/16/2019 **Closed:** 05/31/2019

Problem: P.M. service ,remove aftermarket blue tooth .missing l/f seat trim r/f door weather strip ,mirror.

Work Completed

- P.m. service.
- R&r damaged right front door weatherstrips and left front seat side trim panel .
- Remove after market blue tooth harness and speaker from dash . Replace inline fuse holder for radio .
- R&r peeling rear view mirror assembly .
- Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

| | |
|-----------------------|------|
| Napagold Oil Filter | 1.00 |
| 5w20 Engine Oil | 7.00 |
| 22" Wiper Blade | 2.00 |
| Washer Fluid Concentr | 1.00 |
| 2pc Hd Mat Set Blk | 1.00 |
| Housing | 1.00 |
| Weatherstr | 1.00 |
| Weatherstr | 1.00 |
| Mini Add-a-circuit | 1.00 |
| Shop Supplies | 1.00 |

Hours: 5.85

Comm: 0.00

Labor: 391.95

Parts: 513.11

Total: 905.06

3/6/2023
11:33:59 AM

Palm Beach County Fleet Management Asset Maintenance History
10192660 2013 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1912165 **Meter:** 60410 **In Date:** 11/25/2019 **Closed:** 12/10/2019

Problem: P.M. Service.Check engine light intermitten.Rear bumper damage.

Work Completed

- P.m. service.
- Computer diagnose check engine light , code P2196 and P2198 . Peerform pinpoint test . R&r defective purge valve . Retest evap system and clear codes .
- Replace both front brake rotors and calipers and brake pads . Resurface both rear brake rotors for noise . Flush and bleed brake system .road test .
- Replace two tires .balance and rotate all four tires . Nitrofill all.
- Peform complete front end alignment and road test .
- Shop Supplies

Parts Issued

Quantity

| | |
|-------------------------|------|
| Napagold Oil Filter | 1.00 |
| 5w20 Engine Oil | 6.00 |
| Used Fire X Refurbished | 1.00 |
| 22" Wiper Blade | 2.00 |
| Purge Valve | 1.00 |
| Caliper Washer | 4.00 |
| lube | 1.00 |
| Brk Fluid Dot 4-32oz | 1.00 |
| Non-chlor Brake Clnr | 1.00 |
| Caliper | 1.00 |
| Caliper | 1.00 |
| Front Rotor | 2.00 |
| Lt265/70/17 Tire Nit | 2.00 |
| Brake Pad | 1.00 |
| 265 70 R17 Tire | 2.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 2.00 |

Hours: 14.25

Comm: 0.00

Labor: 1,040.25

Parts: 1,750.90

Total: 2,791.15

Work Order: 2000354

Meter: 60410

In Date: 12/12/2019 **Closed:** 01/10/2020

Problem: damage to rear bumper

Work Completed

- damage to rear bumper

Hours: 0.00

Comm: 827.64

Labor: 0.00

Parts: 0.00

Total: 827.64

3/6/2023
11:33:59 AM

Palm Beach County Fleet Management Asset Maintenance History
10192660 2013 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 2005470 **Meter:** 63614 **In Date:** 06/01/2020 **Closed:** 06/15/2020
Problem: P.M. service ,A/C inop on low ,left radio speaker inop at times, check brake noise and recall 19S07.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Diagnose A/c low speed inop. R&r defective blower resistor . Perform A/c performance test. Recover and vacuum system and complete recharge to factory spec . All good at this time .
- Diagnose left front speaker inop . Remove left front door panel to replace open wire harness in door . Retest .
- Diagnose test drive for brake noise . Replace both rear brake rotors , calipers and pads . Flush and bleed brake system . Road test .
- Rotate and balance all folur tires . Nitrofill all.
- Transport to and from dealer for recall 19s07 .
- Shop Supplies

| | |
|----------------------|------|
| Napagold Oil Filter | 1.00 |
| 5w20 Engine Oil | 6.00 |
| resistor | 1.00 |
| Wire Asy | 1.00 |
| Non-chlor Brake Clnr | 2.00 |
| Brk Fluid Dot 4-32oz | 1.00 |
| Housing | 1.00 |
| Housing | 1.00 |
| Rotor Assy | 2.00 |
| Brake Pad | 1.00 |
| 22" Wiper Blade | 2.00 |
| Shop Supplies | 1.00 |

Hours: 13.75 Comm: 0.00 Labor: 1,003.75 Parts: 667.54 Total: 1,671.29

Work Order: 2012808 **Meter:** 69027 **In Date:** 12/23/2020 **Closed:** 01/06/2021
Problem: P.M. service.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Rotated and balanced all 4 tires. Nitrogen filled all tires
- Shop Supplies

| | |
|-------------------------|------|
| Napagold Oil Filter | 1.00 |
| 5w20 Engine Oil | 6.00 |
| Napagold Air Filter | 1.00 |
| Used Fire X Refurbished | 1.00 |
| Washer Fluid Concentr | 1.00 |
| 22" Wiper Blade | 2.00 |
| Shop Supplies | 1.00 |

Hours: 3.75 Comm: 0.00 Labor: 273.75 Parts: 58.75 Total: 332.50

3/6/2023
11:33:59 AM

Palm Beach County Fleet Management Asset Maintenance History
10192660 2013 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 2100583 **Meter:** 69170 **In Date:** 01/14/2021 **Closed:** 01/15/2021
Problem: Front in collision damage

Work Completed

- Tow From: jpp maint compound To: accident line

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2102054 **Meter:** 69170 **In Date:** 01/19/2021 **Closed:** 02/23/2021
Problem: : Damage to front bumper, grille, right head light & possible under hood

Work Completed

- : Damage to front bumper, grille, right head light & possible under hood

Hours: 0.00 Comm: 2,355.48 Labor: 0.00 Parts: 0.00 Total: 2,355.48

Work Order: 2108787 **Meter:** 73633 **In Date:** 08/12/2021 **Closed:** 08/26/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service

- Perform Charging And Load Test Battery Failed Load Test Replace Battery And Retest

- Balance And Rotate All Tires With Nitro Fill

- Front Assest Number Missing Back Assest Number Peeling Replace Both Sides

- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter 1.00

5w20 Engine Oil 6.00

22" Wiper Blade 1.00

Battery 1.00

22" Wiper Blade 1.00

Shop Supplies 1.00

Hours: 5.55 Comm: 0.00 Labor: 405.15 Parts: 164.20 Total: 569.35

Work Order: 2113461 **Meter:** 77155 **In Date:** 12/20/2021 **Closed:** 12/23/2021
Problem: Towed in for crank but no start .Intermittent battery light coming on/off. P.M. service

Work Completed

- Computer diagnose crank but on start . Perform pinpoint test . Perform Tsb 15-0137 , fuse relocation kit for fuse 27 . Clear codes and retest .test for battery light on ok

- P.m. service.

- Rotate And Balance Four Tires. Nitro Fill All .

- Shop Supplies

Parts Issued

Quantity

Fuse Relocate Kit 1.00

5w20 Engine Oil 6.00

Filter 1.00

22" Wiper Blade 2.00

Used Fire X Refurbished 1.00

Shop Supplies 1.00

Hours: 5.75 Comm: 0.00 Labor: 419.75 Parts: 60.91 Total: 480.66

3/6/2023
11:33:59 AM

Palm Beach County Fleet Management Asset Maintenance History
10192660 2013 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 2200023 **Meter:** 77249 **In Date:** 12/20/2021 **Closed:** 01/03/2022
Problem: NO Start

Work Completed

- Tow From: Jpp maint in Nursery next to restroom To: Lv shop

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2203822 **Meter:** 82550 **In Date:** 04/08/2022 **Closed:** 04/13/2022
Problem: PM Service. Brakes pulsate and wiper blades

Work Completed

- Performed P.m. Service & Inspection
- Mount 2 Tires Then Balance And Rotate All 4 Wheels, Reset Tpms.
- Performed Front Wheel Alignment & Test Drove Vehicle.
- Removed All 4 Brake Pads & Rotors, Resurface All 4 Brake Rotors, Replaced Brake Pads, Then Bleed And Flush The Entire Brake System, Test Drove And Burnish Brakes.
- Shop Supplies

Parts Issued

Quantity

| | |
|--|------|
| Napagold Oil Filter | 1.00 |
| 5w20 Engine Oil | 6.00 |
| Washer Fluid Concentr | 1.00 |
| 22" Wiper Blade | 2.00 |
| Brake Pad | 1.00 |
| Brake Pads | 1.00 |
| Brk Fluid Dot 4-32oz | 1.00 |
| Non-chlor Brake Clnr | 1.00 |
| 265/70/17tirebfg | 2.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 2.00 |
| Labor: 1,040.25 Parts: 532.98 Total: 1,573.23 | |

Hours: 14.25 Comm: 0.00

3/6/2023
11:33:59 AM

Palm Beach County Fleet Management Asset Maintenance History
10192660 2013 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 2209033 **Meter:** 88314 **In Date:** 08/29/2022 **Closed:** 09/01/2022
Problem: PM Service and knocking noise from right rear while driving . Detail

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Diagnose right tag light inop. Replaced blown bulb.
- Diagnose noise while driving. Found to have bad Rf strut. Replaced both front strut assemblies. Test drove.
- Performed full front end alignment. Road test .
- Shop Supplies

| | |
|-----------------------|------|
| Washer Fluid Concentr | 1.00 |
| 22" Wiper Blade | 2.00 |
| Napagold Oil Filter | 1.00 |
| 5w20 Engine Oil | 6.00 |
| Strut Assy | 2.00 |
| Shop Supplies | 1.00 |

Hours: 9.75 Comm: 0.00 Labor: 711.75 Parts: 466.93 Total: 1,178.68

Work Order: 2209237 **Meter:** 88314 **In Date:** 09/01/2022 **Closed:** 09/02/2022
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2209033 for: Jonathan Chin Lee

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2209033 for: Jonathan Chin Lee

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2209913 **Meter:** 89026 **In Date:** 09/23/2022 **Closed:** 09/26/2022
Problem: Left front tire has a slow leak

Work Completed

Parts Issued

Quantity

- Repair left front tire, balance and nitro service
- Shop Supplies

| | |
|---------------|------|
| Shop Supplies | 1.00 |
|---------------|------|

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Work Order: 2300997 **Meter:** 93270 **In Date:** 01/30/2023 **Closed:** 01/30/2023
Problem: remove DMI to have installed on new asset.

Work Completed

- Remove instrument cover, uninstall Dmi wiring and Aldl box.

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 0.00 Total: 36.50

3/6/2023
11:33:59 AM

Palm Beach County Fleet Management Asset Maintenance History
10192660 2013 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 2301291 **Meter:** 93270 **In Date:** 02/08/2023 **Closed:** 02/08/2023
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 154.90

Total Labor: 10,295.85

Total Comm: 3,818.95

Total Parts: 8,256.25