

3/6/2023
4:06:04 PM

Palm Beach County Fleet Management Asset Maintenance History
10203223 2017 CLUB CAR CARRYALL 500 Utility Cart, Electric, Cargo

Total Hours: 61.50 Labor: 4,277.75 Parts: 4,979.13 Comm: 1,463.40 Charged: 10720.28

Work Order: 1701692 **Meter:** 0 **In Date:** 02/16/2017 **Closed:** 02/16/2017
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1701840 **Meter:** 0 **In Date:** 02/22/2017 **Closed:** 03/24/2017
Problem: install solar charger

Work Completed

- Supply and install solar charger
- Shop Supplies

Parts Issued

Quantity

Sevroof23548v Solar Roof 1.00
Shop Supplies 1.00

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 2,114.00 Total: 2,114.00

Work Order: 1702879 **Meter:** 0 **In Date:** 03/20/2017 **Closed:** 03/22/2017
Problem: Transport New cart to Hagen Ranch water plant

Work Completed

- Tow From: fleet To: 12751 Hagen Ranch Rd, Boynton

Hours: 0.00 Comm: 60.00 Labor: 0.00 Parts: 0.00 Total: 60.00

Work Order: 1802704 **Meter:** 236 **In Date:** 03/12/2018 **Closed:** 03/29/2018
Problem: PM Service.

Work Completed

- Pm Service.
- Verify that 12 volts functions inop.trouble shoot,found fuse pulled out of Dc to Dc converter.reinstall 15 amps fuse and secure.
- Wash equipment.
- Clean batteries.test and refill all cells.
- Service front and rear drum brakes.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies 1.00

Hours: 8.50 Comm: 0.00 Labor: 510.00 Parts: 2.00 Total: 512.00

3/6/2023
4:06:04 PM

Palm Beach County Fleet Management Asset Maintenance History
10203223 2017 CLUB CAR CARRYALL 500 Utility Cart, Electric, Cargo

Work Order: 1802765 **Meter:** 0 **In Date:** 03/12/2018 **Closed:** 03/13/2018
Problem: Towed in for Pm Service.

Work Completed

- Tow From: 12751 Hagen Ranch Road Boynton Beach. To: 13026 Jog Road Delray.

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1803035 **Meter:** 0 **In Date:** 03/20/2018 **Closed:** 03/22/2018
Problem: Towed back after PM Service.

Work Completed

- Tow From: 13026 Jog Road Delray To: 12751 Hagen Ranch Road Boynton

Hours: 0.00 Comm: 60.00 Labor: 0.00 Parts: 0.00 Total: 60.00

Work Order: 1809712 **Meter:** 397 **In Date:** 09/20/2018 **Closed:** 09/27/2018
Problem: Worn out tires.

Work Completed

- C/c worn tires.replace 2 front tires.add N2
- Shop Supplies

Parts Issued

Quantity

Tire 20x10-10 6 Ply 2.00
Shop Supplies 1.00

Hours: 1.75 Comm: 0.00 Labor: 105.00 Parts: 245.42 Total: 350.42

Work Order: 1809856 **Meter:** 236 **In Date:** 09/20/2018 **Closed:** 09/25/2018
Problem: Tow in for worn out tires.

Work Completed

- Tow From: 12751 Hagen Ranch Road Boynton To: 13026 Jog Road Delray.

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1810001 **Meter:** 236 **In Date:** 09/25/2018 **Closed:** 09/27/2018
Problem: Tow back after service

Work Completed

- Tow From: 13026 Jog Road delray To: 12751 Hagen Ranch Road Boynton

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

3/6/2023
4:06:04 PM

Palm Beach County Fleet Management Asset Maintenance History
10203223 2017 CLUB CAR CARRYALL 500 Utility Cart, Electric, Cargo

Work Order: 1900195 **Meter:** 397 **In Date:** 12/31/2018 **Closed:** 01/04/2019

Problem: Towed in for repairs.

Work Completed

- Tow From: 12751 Hagen Ranch Road Boynton To: 13026 Jog Road Delray

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1900534 **Meter:** 482 **In Date:** 01/14/2019 **Closed:** 01/22/2019

Problem: Flat tire.Pulling to one side and front end problem.

Work Completed

- Repair F/I tire.repair and correct all N2 levels.
- Hector turf provide hardware to resecure front leafsprings after it came loose.
- Shop Supplies

Parts Issued

Parts Issued	Quantity
Shop Supplies	1.00

Hours: 2.50 Comm: 0.00 Labor: 167.50 Parts: 3.00 Total: 170.50

Work Order: 1900661 **Meter:** 397 **In Date:** 01/15/2019 **Closed:** 01/16/2019

Problem: Towed back after repairs.

Work Completed

- Tow From: 13026 Jog Road Delray To: 12751 Hagen Ranch Road Boynton

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1903454 **Meter:** 550 **In Date:** 03/29/2019 **Closed:** 04/15/2019

Problem: PM Service

Work Completed

- Pm Service.
- Wash all batteries.clean connections.test and refill all cells.
- Service rear brakes drums.
- Wash equipment.
- Shop Supplies

Parts Issued

Parts Issued	Quantity
Shop Supplies	1.00

Hours: 6.25 Comm: 0.00 Labor: 418.75 Parts: 3.00 Total: 421.75

3/6/2023
4:06:04 PM

Palm Beach County Fleet Management Asset Maintenance History
10203223 2017 CLUB CAR CARRYALL 500 Utility Cart, Electric, Cargo

Work Order: 1903536 **Meter:** 482 **In Date:** 03/29/2019 **Closed:** 04/02/2019
Problem: Towed in for PM Service.

Work Completed

- Tow From: 12751 Hagen Ranch Road Boynton To: 13026 Jog Road Delray.

Hours: 0.00 Comm: 60.00 Labor: 0.00 Parts: 0.00 Total: 60.00

Work Order: 1903936 **Meter:** 482 **In Date:** 04/08/2019 **Closed:** 04/11/2019
Problem: Towed Back After Pm Service.

Work Completed

- Tow From: 13026 Jog Road Delray To: 12751 Hagen Ranch Road

Hours: 0.00 Comm: 60.00 Labor: 0.00 Parts: 0.00 Total: 60.00

Work Order: 2000577 **Meter:** 550 **In Date:** 01/16/2020 **Closed:** 01/27/2020
Problem: Flat tire.Had to drive to Hagen Ranch Road to R/R tire.

Work Completed

- Repair left rear tire.correct all N2.

- Travel to Hagen Ranch Road to repair tire.

- Shop Supplies

Hours: 1.50 Comm: 0.00 Labor: 109.50 Parts: 4.00 Total: 113.50

Parts Issued	Quantity
Shop Supplies	1.00

Work Order: 2000899 **Meter:** 770 **In Date:** 01/28/2020 **Closed:** 01/31/2020
Problem: FLAT TIRE

Work Completed

- C/c Flat tire.replace two rear tires.mount and add N2

- Travel to Hagen Ranch Road.bring wheels to Sr Shop to R/r tires.return to Hagen Ranch road to install.

- Shop Supplies

Hours: 2.75 Comm: 0.00 Labor: 200.75 Parts: 272.71 Total: 473.46

Parts Issued	Quantity
Tire 20x10-10 6 Ply	2.00
Shop Supplies	1.00

3/6/2023
4:06:04 PM

Palm Beach County Fleet Management Asset Maintenance History
10203223 2017 CLUB CAR CARRYALL 500 Utility Cart, Electric, Cargo

Work Order: 2003344 **Meter:** 770 **In Date:** 04/02/2020 **Closed:** 04/20/2020
Problem: PM Service.Check battery cables.

Work Completed

Parts Issued

Quantity

- Pm Service.
- Replace two front tires.correct all N2.
- Install new glove box door with latch.roof broken.send to Vista to be welded.
- C/c wont move.replace multiple battery cables.test and refill all cells.recharge to full.
- Wash equipment.
- Shop Supplies

Tire 20x10-10 6 Ply Kenda	2.00
Bulk Battery Cable	5.00
Bulk Battery Cable	10.00
Cabl/lug	10.00
Door-glove Box	1.00
Latch	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 10.25 Comm: 0.00 Labor: 748.25 Parts: 336.49 Total: 1,084.74

Work Order: 2003401 **Meter:** 770 **In Date:** 04/01/2020 **Closed:** 04/03/2020
Problem: Towed In for PM Service and battery cables .

Work Completed

- Tow From: 12751 Hagen Ranch Road Boynton To: 13026 Jog Road Delray

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2003904 **Meter:** 796 **In Date:** 04/20/2020 **Closed:** 04/22/2020
Problem: repair cracked solar panel

Work Completed

Parts Issued

Quantity

- repair cracks in solar panel
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 4.00 Total: 150.00

Work Order: 2003967 **Meter:** 770 **In Date:** 04/20/2020 **Closed:** 04/21/2020
Problem: need brackets welded

Work Completed

- Tow From: south shop To: 2601 vista

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

3/6/2023
4:06:04 PM

Palm Beach County Fleet Management Asset Maintenance History
10203223 2017 CLUB CAR CARRYALL 500 Utility Cart, Electric, Cargo

Work Order: 2004020 **Meter:** 770 **In Date:** 04/21/2020 **Closed:** 04/22/2020
Problem: Transport repaired cart back to shop

Work Completed

- Tow From: Fleet Se shop To: 12751 Hagen Ranch Rd, Boynton Beach Fl

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2008536 **Meter:** 796 **In Date:** 08/26/2020 **Closed:** 10/27/2020
Problem: Noise in rear end or drums

Work Completed

- Verify noise coming from front. Replace all lower suspension bushings, reassemble and adjust steering linkage.
- Customers complaint, noise coming from rear. Verify complaint, remove and disassemble rear differential and found cracked housing lost all fluid. Replace rear differential assembly.
- Remove axle shafts from housings to swap rear drum brake plates and components to the new rear diff assembly.
- Wash equipment for repairs
- Shop Supplies

Parts Issued

Quantity

Spring Bushing	4.00
Sleeve	2.00
Screw 3/8-16x3.375	2.00
Electric Transaxle Asm	1.00
1qt Syngear Oil 75-90	1.00
Shop Supplies	1.00

Hours: 11.00 Comm: 0.00 Labor: 803.00 Parts: 1,705.20 Total: 2,508.20

Work Order: 2008671 **Meter:** 796 **In Date:** 08/26/2020 **Closed:** 08/28/2020
Problem: Towed in for noise in rear end or wheels

Work Completed

- Tow From: 2751 Hagen Ranch Road Boynton To: 13026 Jog Road Delray

Hours: 0.00 Comm: 60.00 Labor: 0.00 Parts: 0.00 Total: 60.00

Work Order: 2011693 **Meter:** 796 **In Date:** 11/19/2020 **Closed:** 11/23/2020
Problem: Towed back after service.

Work Completed

- Tow From: 13026 Jog Road Delray To: 12751 Hagen Ranch Road Boynton.

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

3/6/2023
4:06:04 PM

Palm Beach County Fleet Management Asset Maintenance History
10203223 2017 CLUB CAR CARRYALL 500 Utility Cart, Electric, Cargo

Work Order: 2104363 **Meter:** 957 **In Date:** 04/19/2021 **Closed:** 12/16/2021

Problem: Towed in for PM Service.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Remove hood assm. replace driver side headlight bulb. reassemble.
- Service front and rear drum brakes. Clean and adjust.
- Wash equipment. Wash roof to ensure welds. Wash batteries for service. Wash seats and leaves from bed.
- Customers complaint repair roof. Remove, fabricate and repair solar roof and brackets. Weld new Brackets to aluminum roof. Drill new mounting holes. Clean and paint roof brackets black to match roof. Reinstall roof on cart.
- Shop Supplies

Blister Pack Capsules	1.00
1.5" Alum U Channel	1.00
1.25" U Channel	1.00
24x24x0.25 Alum Plate	1.00
Shop Supplies	1.00

Hours: 11.00 Comm: 0.00 Labor: 803.00 Parts: 289.32 Total: 1,092.32

Work Order: 2104750 **Meter:** 796 **In Date:** 04/19/2021 **Closed:** 04/28/2021

Problem: Towed in for PM Service.

Work Completed

- Tow From: 12751 Hagen Ranch Road Boynton To: 13026 Jog Road Delray

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2113403 **Meter:** 957 **In Date:** 12/17/2021 **Closed:** 12/20/2021

Problem: Towed back after service and repair complete.

Work Completed

- Tow From: 13026 Jog Road Delray To: 12751 Hagen Ranch Road Boynton

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2212871 **Meter:** 957 **In Date:** 12/12/2022 **Closed:** 12/23/2022

Problem: Swap Out from Southern Region Water Reclamation Facility 12751 Hagen Ranch Rd. Boynton Beach Fl. 33437 to fleet wpb

Work Completed

- Tow From: 12751 Hagen Ranch Rd. Boynton Beach Fl. 33437 To: 2601 Vista Pkwy, West Palm Beach 33411

Hours: 0.00 Comm: 113.00 Labor: 0.00 Parts: 0.00 Total: 113.00

3/6/2023
4:06:04 PM

Palm Beach County Fleet Management Asset Maintenance History
10203223 2017 CLUB CAR CARRYALL 500 Utility Cart, Electric, Cargo

Work Order: 2301489 **Meter:** 957 **In Date:** 02/14/2023 **Closed:** 02/14/2023
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 61.50

Total Labor: 4,277.75

Total Comm: 1,463.40

Total Parts: 4,979.13