

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 836914 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	Quantity
In Date: 04/14/2008	Hours	Description	
- Pre-Delivery Inspection	2.00		
Parts Charge:	0.00	Labor Charge:	120.00

Workorder: 843015 **Problem:** CANCEIVER NOT WORKING

Meter Reading: 900	Labor	Parts	Quantity
In Date: 08/20/2008	Hours	Description	
- Canceiver Not Reading Found Loose Wire Tightened And Tie Rap Reprogram And Filled	0.50		
Parts Charge:	0.00	Labor Charge:	30.00

Workorder: 844163 **Problem:** 005 WASH TICKETS ISSUED OUT 09/11/08

Meter Reading: 0	Labor	Parts	Quantity
In Date: 09/11/2008	Hours	Description	
- 005 Wash Tickets Issued Out 09/11/08			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	41.70

Workorder: 846013 **Problem:** P.M SERVICE

Meter Reading: 1236	Labor	Parts	Quantity
In Date: 10/21/2008	Hours	Description	
- Pm Service	3.30	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Rotate & High Speed Balance All 4 Tires.Nitro Fill All Tires To Spec.		5W20 ENGINE OIL	7.00
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	38.50	Labor Charge:	48.00

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 937635

Problem: P.M SERVICE

Meter Reading: 2197		Labor		Parts	
In Date: 05/11/2009	Close Date: 05/14/2009	Hours	Description	Quantity	
- Pm Service		2.75	SHOP SUPPLIES		1.00
- Shop Supplies			31-20 WIPER BLADES 20" BLADE		2.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			5W20 ENGINE OIL		7.00
Parts Charge:		31.04	Labor Charge:	165.00	

Workorder: 1000374

Problem: P.M service.

Meter Reading: 3439		Labor		Parts	
In Date: 01/11/2010	Close Date: 01/12/2010	Hours	Description	Quantity	
- P.M Service.		2.75	5W20 ENGINE OIL		7.00
- Shop Supplies			SHOP SUPPLIES		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
Parts Charge:		44.79	Labor Charge:	165.00	

Workorder: 1007049

Problem: Pm service

Meter Reading: 4147		Labor		Parts	
In Date: 07/06/2010	Close Date: 07/07/2010	Hours	Description	Quantity	
- P.M. Service.		2.75	5W20 ENGINE OIL		7.00
- Shop Supplies			SHOP SUPPLIES		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
Parts Charge:		31.51	Labor Charge:	165.00	

Workorder: 1007074

Problem: REFLASH CANCEIVER

Meter Reading: 4136		Labor		Parts	
In Date: 07/06/2010	Close Date: 07/08/2010	Hours	Description	Quantity	
- Reflash Canceiver And Reprogram		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	60.00	

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 1100013

Problem: P.M. Service.

Meter Reading: 5442		Labor		Parts	
In Date: 01/03/2011	Close Date: 01/05/2011	Hours	Description	Quantity	
-	Perform Pm Service.	3.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00	
-	Rotate And Balance All Four Tires.		31-20 WIPER BLADES 20" BLADE	2.00	
-	Shop Supplies		5W20 ENGINE OIL	7.00	
			CA8039 AIR FILTER LBF AF1615 WIX 46418	1.00	
			WD40 SPRAY LUBE STOCK# 405540002	1.00	
			SHOP SUPPLIES	1.00	
			G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00	
Parts Charge: 45.53		Labor Charge: 225.00			

Workorder: 1104922

Problem: wont fuel

Meter Reading: 6050		Labor		Parts	
In Date: 05/10/2011	Close Date: 05/10/2011	Hours	Description	Quantity	
-	Install Fuse And Install New Canceiver Screws	1.00	SHOP SUPPLIES	1.00	
-	Shop Supplies				
Parts Charge: 2.00		Labor Charge: 60.00			

Workorder: 1106776

Problem: P.M. Service.Radio inop.

Meter Reading: 6372		Labor		Parts	
In Date: 06/27/2011	Close Date: 06/29/2011	Hours	Description	Quantity	
-	Perform Pm Service.	4.75	5W20 ENGINE OIL	7.00	
-	Remove Radio And Unplug Wiring Harness To Power Down,Reset And Relearn.		1372 OIL FILTER FRM PH2 WIX 51372	1.00	
-	Rotate And Balance All Four Tires.		SHOP SUPPLIES	1.00	
-	Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS	1.00	
Parts Charge: 35.40		Labor Charge: 285.00			

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 1107010 **Problem:** Right rear tire flat.

Meter Reading: 6473	Labor	Parts		
In Date: 07/01/2011	Hours	Description	Quantity	
- Repair Flat Right Rear Tire.Nitrogen Fill And Balance Same.	1.00	SHOP SUPPLIES	1.00	
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	60.00	

Workorder: 1109513 **Problem:** P.M. service and rattle from under truck at certain RPMs and rattle from center console.

Meter Reading: 11203	Labor	Parts		
In Date: 09/06/2011	Hours	Description	Quantity	
- Perform Pm Service.	7.25	5W20 ENGINE OIL	7.00	
- Install Four Tires.Nitrogen Fill And Balance All Four.		1372 OIL FILTER FRM PH2 WIX 51372	1.00	
- Perform Wheel Alignment Complete.		31-20 WIPER BLADES 20" BLADE	2.00	
- Shop Supplies		TIRE DISPOSAL FEE	4.00	
		758536189 255/70R17 WRG SILENT ARMOR 110T	4.00	
		SHOP SUPPLIES	1.00	
Parts Charge:	776.62	Labor Charge:	435.00	

Workorder: 1110025 **Problem:** 20 - Wash ticket(s) issued

Meter Reading: 11467	Labor	Parts		
In Date: 09/20/2011	Hours	Description	Quantity	
- 20 - Wash Ticket(S) Issued				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 194.64

Workorder: 1112662 **Problem:** P.M. service and rattle under truck at stops.

Meter Reading: 17581	Labor	Parts		
In Date: 11/30/2011	Hours	Description	Quantity	
- Perform Pm Service.	4.25	5W20 ENGINE OIL	7.00	
- Rotate And Balance All Four Tires.		31-20 WIPER BLADES 20" BLADE	2.00	
- Diagnose For Rattling Noise.Remove And Straighten Bent Skid Plate And Reposition Same.		1372 OIL FILTER FRM PH2 WIX 51372	1.00	
- Shop Supplies		BIG G DEGREASER STOCK# 485180002	1.00	
		SHOP SUPPLIES	1.00	
Parts Charge:	39.82	Labor Charge:	255.00	

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 1200917

Problem: P.M. service.

Meter Reading: 22273		Labor		Parts	
In Date: 01/30/2012	Close Date: 02/09/2012	Hours	Description	Quantity	
-	P.M. Service.	9.25	1372 OIL FILTER FRM PH2 WIX 51372	1.00	
-	Replace And Balance Four Tires.		SHOP SUPPLIES	1.00	
-	Complete Wheel Alignment.Test Drive.		31-20 WIPER BLADES 20" BLADE	2.00	
-	Transport Vehicle To Dealer For Leaking P[Inion Seal.		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00	
-	Shop Supplies		758536189 255/70R17 WRG SILENT ARMOR 110T	4.00	
			5W20 ENGINE OIL	7.00	
			TIRE DISPOSAL FEE	4.00	
Parts Charge: 783.77		Labor Charge: 555.00			

Workorder: 1203500

Problem: P.M. service

Meter Reading: 29280		Labor		Parts	
In Date: 04/12/2012	Close Date: 04/19/2012	Hours	Description	Quantity	
-	P.M. Service.	4.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00	
-	Repair Right Rear Tire,Rotate And Balance All Four.		CA8039 AIR FILTER LBF AF1615 WIX 46418	1.00	
-	Shop Supplies		D3TZ2457B BRAKE PEDAL PAD	1.00	
			SYN/ATF TRANS FLUID SYNTHETIC	1.00	
			SHOP SUPPLIES	1.00	
			5W20 ENGINE OIL	7.00	
Parts Charge: 43.32		Labor Charge: 285.00			

Workorder: 1204211

Problem: Right side headlamp inop.

Meter Reading: 31023		Labor		Parts	
In Date: 05/03/2012	Close Date: 05/07/2012	Hours	Description	Quantity	
-	Test And Replace Failed Right Front Head Lamp Bulb With New.	0.50	9008 BULB	1.00	
Parts Charge: 13.89		Labor Charge: 30.00			

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 1204690 **Problem:** Wiper blades not clearing windshield.

Meter Reading: 32275	Labor	Parts	
In Date: 05/17/2012	Hours	Description	Quantity
- Clean Bugs From Windshield And Replace Wiper Blades.	0.50	31-20 WIPER BLADES 20" BLADE	2.00
Parts Charge: 9.98	Labor Charge: 30.00		

Workorder: 1205004 **Problem:** P.M. service and hazard lights inop and replace tires.

Meter Reading: 34743	Labor	Parts	
In Date: 05/30/2012	Hours	Description	Quantity
- P.M. Service.	10.25	5W20 ENGINE OIL	7.00
- Check Inop Four Way Flashers.Replace Defective Multifunction Switch.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Replace And Balance Four Tires		TIRE DISPOSAL FEE	4.00
- Replace And Resurface Front Rotors.Replace Brake Pads.Service And Lube Calipers,Flush And Bleed System.		MULTIFUNCTIONAL SWITCH	1.00
- Shop Supplies		2232 BRAKE FLUID QUART	1.00
		SHOP SUPPLIES	1.00
		FRONT ROTORS	2.00
		758536189 255/70R17 WRG SILENT ARMOR 110T	4.00
		MX1083 BRAKE PADS	1.00
		05046 BATTERY PROTECTOR (CRC)	1.00
Parts Charge: 1,119.72	Labor Charge: 615.00		

Workorder: 1206629 **Problem:** Front tires flat spots and noisy.

Meter Reading: 38373	Labor	Parts	
In Date: 07/17/2012	Hours	Description	Quantity
- Rotate And Balance All Four Tires.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 60.00		

Workorder: 1207796 **Problem:** 10 - Wash ticket(s) issued

Meter Reading: 40902	Labor	Parts	
In Date: 08/16/2012	Hours	Description	Quantity
- 10 - Wash Ticket(S) Issued			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 97.32	

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 1208725

Problem: Pm service and check tires.

Meter Reading: 43813		Labor		Parts	
In Date: 09/13/2012	Close Date: 09/26/2012	Hours	Description		Quantity
-	P.M. Service.	8.25	SHOP SUPPLIES		1.00
-	Test Battery And Charging System.Replace Bad Battery.		179469492 LT245/70R17 WRANGLER SR-A E		4.00
-	Replace And Balance Four Tires.		TIRE DISPOSAL FEE		4.00
-	Complete Wheel Alignment.Test Drive.		CA8039 AIR FILTER LBF AF1615 WIX 46418		1.00
-	Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			GROUP 65 BATTERY (MTC BXT-65-850)		1.00
			5W20 ENGINE OIL		7.00
Parts Charge:		953.61	Labor Charge:	495.00	

Workorder: 1209427

Problem: Replace wiper blades.

Meter Reading: 45054		Labor		Parts	
In Date: 10/02/2012	Close Date: 10/10/2012	Hours	Description		Quantity
-	Replace Wiper Blades.	0.25	31-20 WIPER BLADES 20		2.00
Parts Charge:		11.10	Labor Charge:	15.00	

Workorder: 1300477

Problem: Pm service.

Meter Reading: 53428		Labor		Parts	
In Date: 01/14/2013	Close Date: 01/24/2013	Hours	Description		Quantity
-	Perform Pm Service.	6.25	5W20 ENGINE OIL		7.00
-	Install Two New Tires To The Front Wheels.Nitrogen Fill		31-20 WIPER BLADES 20		2.00
-	And Balance All Four.		FORD FUEL FILTER		1.00
-	Inspect And Service Transmission..Flush And Renew		CA8039 AIR FILTER LBF		1.00
-	Transmission Fluid.		1372 OIL FILTER		1.00
-	Shop Supplies		SYN-ATF TRANS FLUID S		16.00
			TIRE DISPOSAL FEE		2.00
			SHOP SUPPLIES		1.00
			179469492 LT245-70R17		2.00
Parts Charge:		660.99	Labor Charge:	375.00	

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 1302607

Problem: P.M. service and tires worn.

Meter Reading: 58876		Labor		Parts	
In Date: 03/15/2013	Close Date: 03/21/2013	Hours	Description		Quantity
-	P.M. Service.	8.75	TIRE DISPOSAL FEE		2.00
-	Replace Two Tires,Rotate And Balance All Four.		179469492 LT245-70R17		2.00
-	Resurface Rear Brake Rotors,Replace Rear Pads.Service		1401 BRAKE FLUID BRA		1.00
	And Lube Calipers,Flush And Bleed System And Test		WD40 SPRAY LUBE STOCK		1.00
	Drive.		BRAKE PADS		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
			5W20 ENGINE OIL		7.00
			1372 OIL FILTER		1.00
Parts Charge: 536.77		Labor Charge: 525.00			

Workorder: 1305318

Problem: Pm service.

Meter Reading: 66512		Labor		Parts	
In Date: 05/30/2013	Close Date: 06/11/2013	Hours	Description		Quantity
-	P.M. Service.	6.75	TIRE DISPOSAL FEE		4.00
-	Replace And Balance Four New Tires.		31-20 WIPER BLADES 20		2.00
-	Pressure Test And Inspect Cooling System.Flush And		NAPAGOLD AIR FILTER		1.00
	Refill System.		SHOP SUPPLIES		1.00
-	Shop Supplies		MAC WITE LITHIUM GRES		1.00
			NAPAGOLD FUEL FILTER		1.00
			179469492 LT245-70R17		4.00
			PEAK GLOBAL		2.00
			NAPAGOLD OIL FILTER		1.00
			5W20 ENGINE OIL		7.00
Parts Charge: 982.34		Labor Charge: 405.00			

Workorder: 1305887

Problem: Has to jump start in A/m.

Meter Reading: 67827		Labor		Parts	
In Date: 06/13/2013	Close Date: 06/24/2013	Hours	Description		Quantity
-	Test Battery And Charging System.Replace Bad Battery.	1.00	BATTERY 65		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
Parts Charge: 2.00		Labor Charge: 60.00			

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 1306811

Problem: Struck by lightening.

Meter Reading: 69069	Labor	Parts	
In Date: 07/09/2013	Hours	Description	Quantity
- Computer Diagnose For Damage By Lightening.Replace	20.00	MODULE	1.00
Damage Pcm,Gem,Abs.Rcm,Vsm And Reprogram Each		SENSOR	1.00
Module With Ids.Remove Fuel Tank,Replace Damage Fuel		RECEIVER	1.00
Lines,Sensors,Radio And Fan Clutch With New.		CAPACITOR	1.00
- Shop Supplies		SENSOR	1.00
		SENSOR	1.00
		TUBE ASY	1.00
		R134A REFRIGERANT	2.00
		AERIAL ASY	1.00
		CLUTCH ASY	1.00
		BOX ASY	1.00
		ANTENNA	1.00
		NEW STARTER	1.00
		SHOP SUPPLIES	1.00
		CONTROL	1.00
		RADIO	1.00
Parts Charge:	3,911.35	Labor Charge:	1,200.00

Workorder: 1307575

Problem: remove canceiver

Meter Reading: 69069	Labor	Parts	
In Date: 07/30/2013	Hours	Description	Quantity
- Remove Canceiver Due To Lightening Strike	0.50		
Parts Charge:	0.00	Labor Charge:	30.00

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 1307701

Problem: Check engine light on.

Meter Reading: 70542	Labor	Parts		
In Date: 08/01/2013	Hours	Description	Quantity	
- Computer Diagnose For Check Engine Light On.Test And	5.25	SHOP SUPPLIES	1.00	
Replace Failed Egr Valve Assembly And Mass Air Flow		MASS AIR FLOW SENSOR	1.00	
Sensor With New Due To Lightening Damage.Clear Codes		EGR VALVE	1.00	
With Scan Tool And Roadtest.		SWITCH	1.00	
- Diagnose For Instrument Cluster Illumination Inop.Test And		SENSOR	1.00	
Replace Failed Headlamp Switch Assembly And Sun				
Load Sensor With New Due To Lightening Damage.				
- Shop Supplies				
Parts Charge:	498.82	Labor Charge:	315.00	

Workorder: 1308960

Problem: no start

Meter Reading: 71417	Labor	Parts		
In Date: 08/07/2013	Hours	Description	Quantity	
- Tow From: Pbia To: Vista				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 104.15

Workorder: 1309854

Problem: Pm service.

Meter Reading: 74014	Labor	Parts		
In Date: 09/30/2013	Hours	Description	Quantity	
- P.M. Service.	9.00	5W20 ENGINE OIL	7.00	
- Replace Left Spot Light Bulb In Light Bar.		PEDAL PAD	1.00	
- Inspect And Service Transfer Case.		USED FIRE X REFURBISHED	1.00	
- Replace Two Tires,Rotate And Balance All Four.		FORD TRANSFER CASE FLUID	3.00	
- Complete Wheel Alignment.Test Drive.		179469492 LT245-70R17	2.00	
- Shop Supplies		17189E BULB MR11-12V	1.00	
		NAPAGOLD OIL FILTER	1.00	
		SHOP SUPPLIES	1.00	
		TIRE DISPOSAL FEE	2.00	
		31-20 WIPER BLADES 20	2.00	
Parts Charge:	538.71	Labor Charge:	540.00	

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 1312043

Problem: Check for vibration at 35mph and over 55mph

Meter Reading: 77180	Labor	Parts	
In Date: 12/03/2013	Hours	Description	Quantity
- Clean Off Mud From Inside Corner Of All Wheels.Rotate And Balance All Four Wheels.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 60.00		

Workorder: 1400800

Problem: Pm service

Meter Reading: 80870	Labor	Parts	
In Date: 01/24/2014	Hours	Description	Quantity
- P.M. Service.	4.75	5W20 ENGINE OIL	7.00
- Replace Two Tires,Rotate And Balance All Four.		NAPAGOLD OIL FILTER	1.00
- Shop Supplies		NAPAGOLD AIR FILTER	1.00
		NAPAGOLD FUEL FILTER	1.00
		WASHER FLUID CONCENTR	1.00
		MAC WITE LITHIUM GRES	1.00
		179469492 LT245-70R17	2.00
		WIPER BLADE	2.00
		TIRE DISPOSAL FEE	2.00
		SHOP SUPPLIES	1.00
Parts Charge: 514.17	Labor Charge: 285.00		

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 1403566

Problem: Pm service.Left rear tire flat.Light bar alley lamp inop.

Meter Reading: 85210		Labor		Parts	
In Date: 04/11/2014	Close Date: 04/22/2014	Hours	Description		Quantity
-	Perform Pm Service.	12.75	FRICTION MODIFIER		1.00
-	Inspect And Replace Failed Serpentine Belt With New.		SERPENTINE BELT		1.00
-	Dismantle Light Bar And Replace Failed Alley Lamp Bulb With New.		179469492 LT245-70R17		2.00
-	Inspect Rear End For Noise And Replace Failed Differential Side Bearings,Abs Tone Wheel And Housing With New. Flush Debris From Tube And Perform Differential Service.Also Service Front Differential.		SHOP SUPPLIES		1.00
-	Install Two New Tires To The Front Wheels.Nitrogen Fill And Balance All Four.		bearingas		2.00
-	Shop Supplies		TIRE DISPOSAL FEE		2.00
			ring		1.00
			cup		2.00
			5W20 ENGINE OIL		7.00
			NAPAGOLD OIL FILTER		1.00
			17189E BULB MR11-12V		1.00
			differenti		1.00
			75W140 FORD AXLE LUBE		5.00
Parts Charge: 1,161.89		Labor Charge: 765.00			

Workorder: 1404004

Problem: Left head lamp inop.

Meter Reading: 85485		Labor		Parts	
In Date: 04/24/2014	Close Date: 04/29/2014	Hours	Description		Quantity
-	Test And Replace Failed Left Headlamp Bulb With New.	0.50	HALOGEN CAPSULE		1.00
Parts Charge: 12.81		Labor Charge: 30.00			

Workorder: 1404334

Problem: 1 - Wash ticket(s) issued

Meter Reading: 85720		Labor		Parts	
In Date: 05/02/2014	Close Date: 05/02/2014	Hours	Description		Quantity
-	1 - Wash Ticket(S) Issued				
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 9.73	

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 1405317

Problem: Engine runs rough.

Meter Reading: 87720	Labor	Parts	
In Date: 06/02/2014	Hours	Description	Quantity
- Diagnose Check Engine Light.P115E.Perform Pin Point Test.Replace Defective Throttle Body.Clear Code And Test Drive.	2.25	THROTTLE	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge: 266.00		Labor Charge: 135.00	

Workorder: 1408859

Problem: Pm service.

Meter Reading: 93943	Labor	Parts	
In Date: 09/03/2014	Hours	Description	Quantity
- Pm Service.	11.25	NAPAGOLD OIL FILTER	1.00
- Replace And Balance Four Tires.		USED FIRE X REFURBISHED	1.00
- Complete Front End Alignment And Test Drive.		WIPER BLADE	2.00
- Replace Rear Brake Pads And Two Rear Brake Rotors		REAR ROTOR	2.00
Due To Under Specs.Service Calipers And Bleed Brake System.Test Drive.		5W20 ENGINE OIL	7.00
- Shop Supplies		TIRE DISPOSAL FEE	4.00
		245 70R17 AT ADVENTURE	4.00
		BRAKE CLEANER	1.00
		DISC BRAKE PADS	1.00
		SHOP SUPPLIES	1.00
Parts Charge: 1,496.04		Labor Charge: 675.00	

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 1410752

Problem: Pm service and left front tire worn.

Meter Reading: 98282	Labor	Parts	
In Date: 10/28/2014	Hours	Description	Quantity
- Pm Service.	7.25	5W20 ENGINE OIL	7.00
- Replace Two Tires.Rotate And Balance All Four.		NAPAGOLD OIL FILTER	1.00
- Perform Front End Alignment And Test Drive.		NAPAGOLD AIR FILTER	1.00
- Shop Supplies		NAPAGOLD FUEL FILTER	1.00
		183114470 P245-70R17	2.00
		245 70R17 AT ADVENTURE	2.00
		FLOOR MAT-2PC RUB BK	1.00
		WIPER BLADE	2.00
		SHOP SUPPLIES	1.00
		TIRE DISPOSAL FEE	2.00
Parts Charge:	643.00	Labor Charge:	435.00

Workorder: 1411720

Problem: Left rear tire flat.

Meter Reading: 99533	Labor	Parts	
In Date: 11/19/2014	Hours	Description	Quantity
- Repair And Balance Left Rear Tire.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1412806

Problem: Right rear tire flat.

Meter Reading: 102431	Labor	Parts	
In Date: 12/24/2014	Hours	Description	Quantity
- Repair Flat And Balance Right Rear Tire.	1.50	HALOGEN CAPSULE	1.00
- Test And Replace Defective Right Headlamp Bulb.		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	20.67	Labor Charge:	90.00

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 1501463

Problem: Pm service and left headlamp highbeam inop.

Meter Reading: 105277		Labor		Parts	
In Date: 02/09/2015	Close Date: 02/19/2015	Hours	Description	Quantity	
- Pm Service.		9.25	Caliper w/ Hardware - Right Front (Eclip		1.00
- Replace And Balance All Four Tires,			HALOGEN CAPSULE		1.00
- Replace Front Brake Pads And Both Front Brake			NAPAGOLD OIL FILTER		1.00
Calipers.Resurface Both Front Brake Rotors.Bleed And			DISC BRAKE PADS		1.00
Flush Brake System.Road Test.			Caliper w/ Hardware - Left Front (Eclips		1.00
- Test And Replace Defective Left Headlamp High Beam			MIRROR		1.00
Bulb.			5W20 ENGINE OIL		7.00
- Shop Supplies			WIPER BLADE		2.00
			SHOP SUPPLIES		1.00
			1401 BRAKE FLUID BRA		2.00
			TIRE DISPOSAL FEE		4.00
			255 70R17 ADVENTURE WRL		4.00
			WASHER FLUID CONCENTR		1.00
			BRAKE CLEANER		1.00
	Parts Charge: 1,388.49		Labor Charge: 555.00		

Workorder: 1504069

Problem: left headlight inop.

Meter Reading: 109234		Labor		Parts	
In Date: 04/20/2015	Close Date: 04/28/2015	Hours	Description	Quantity	
- Replace Left Headlight Bulb.		0.50	HALOGEN CAPSULE		1.00
	Parts Charge: 18.67		Labor Charge: 30.00		

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 1505583

Problem: P.M. service .ops

Meter Reading: 111667		Labor		Parts	
In Date: 06/03/2015	Close Date: 06/09/2015	Hours	Description		Quantity
- Pm Service.		12.75	5W20 ENGINE OIL		7.00
- Inspect And Replace Serpentine Belt (Worn) And Two Idler Pulleys (Noisy)			WIPER BLADE		2.00
			WASHER FLUID CONCENTR		1.00
- Inspect And Replace Worn Left Side Sway Bar Link.			NAPAGOLD OIL FILTER		1.00
- Replace And Balance Four Tires.			NAPAGOLD FUEL FILTER		1.00
- Perform Engine Tune Up. Replace Eight Plugs.			SWAY BAR LINK		1.00
- Perform Injection Service And Flush Induction Service And Decarbing.			255 70R17 ADVENTURE WRL		4.00
			THROTTLE BODY CLEANER		1.00
- Diagnose Licence Plate Light And Left Front Marker Light Inop. Replace Three Bulbs-Burnt.			TIRE DISPOSAL FEE		4.00
			BULB		3.00
- Shop Supplies			SHOP SUPPLIES		1.00
			SPARK PLUG		8.00
			SPARK PLUG		8.00
			BELT		1.00
			GROOVER PULLEY		2.00
			SPARK PLUG		8.00
			KA8A THROTTLE BODY- U		1.00
			INJECTOR CLEANER		1.00
	Parts Charge: 1,422.97	Labor Charge: 765.00			

Workorder: 1508143

Problem: Steering wheel cover.

Meter Reading: 115078		Labor		Parts	
In Date: 08/13/2015	Close Date: 08/19/2015	Hours	Description		Quantity
- Install Steering Wheel Cover.		0.30	STG WHEEL COV - FORD		1.00
	Parts Charge: 18.75	Labor Charge: 18.00			

Workorder: 1508429

Problem: 10 - Wash ticket(s) issued

Meter Reading: 115078		Labor		Parts	
In Date: 08/21/2015	Close Date: 08/21/2015	Hours	Description		Quantity
- 10 - Wash Ticket(S) Issued					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 95.40		

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 1509374 **Problem:** Right headlamp inop

Meter Reading:	116723	Labor	Parts	
In Date:	09/17/2015	Hours	Description	Quantity
-	Test And Replace Defective Right Headlamp Bulb.	0.50	HALOGEN CAPSULE	1.00
	Parts Charge: 18.67		Labor Charge: 30.00	

Workorder: 1510897 **Problem:** Pm service.

Meter Reading:	117915	Labor	Parts	
In Date:	10/28/2015	Hours	Description	Quantity
-	Pm Service.	8.25	WIPER BLADE	2.00
-	Replace And Balance All Four Tires.		USED FIRE X REFURBISHED	1.00
-	Replace Both Defective Front Sway Bar Links.		PEDAL PAD	1.00
-	Complete Front End Alignment.		255 70R17 ADVENTURE WRL	4.00
-	Shop Supplies		SWAY BAR LINK	2.00
			5W20 ENGINE OIL	7.00
			BIGG DEGREASER	1.00
			TIRE DISPOSAL FEE	4.00
			NAPAGOLD OIL FILTER	1.00
			SHOP SUPPLIES	1.00
	Parts Charge: 1,282.34		Labor Charge: 495.00	

Workorder: 1512886 **Problem:** Cneck battery.Check four wheel drive operation.

Meter Reading:	119269	Labor	Parts	
In Date:	12/21/2015	Hours	Description	Quantity
-	Charge Battery Fully.Test Battery And Charging System.Replace Defective Battery.	2.50	BATTERY	1.00
-	Diagnose Four Wheel Drive Staying Engaged.Repair Broken Vacume Line From Intake To Vacume Canister.Retest.		SHOP SUPPLIES	1.00
-	Shop Supplies			
	Parts Charge: 120.41		Labor Charge: 150.00	

3/2/2017
9:57:10AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: L00021 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab

Workorder: 1605661

Problem: P.M. service and towed in for no start.

Meter Reading: 121208		Labor		Parts	
In Date: 06/02/2016	Close Date: 06/15/2016	Hours	Description	Quantity	
-	P.M. Service.	9.75	9008 BULB		1.00
-	Test Battery And Charging System.Replace Bad Battery,		TAG LAMP SOCKET		1.00
-	Replace Right Front Marker Lamp An Head Lamp Bulb.		BULB		1.00
-	Replace Left Upper Control Arm.		Ball Joint - Upper - Front Susp		1.00
-	Rotate And Balance Tires.		SHOP SUPPLIES		1.00
-	Complete Wheel Alignment.Test Drive.		BATTERY		1.00
-	Shop Supplies		NAPAGOLD AIR FILTER		1.00
			20" WIPER BLADE		2.00
			NAPAGOLD OIL FILTER		1.00
			CONTROL ARM AND BALL		1.00
			WASHER FLUID CONCENTR		1.00
			5W20 ENGINE OIL		7.00
	Parts Charge: 233.89	Labor Charge:	585.00		

Workorder: 1605714

Problem: No start

Meter Reading: 121023		Labor		Parts	
In Date: 06/02/2016	Close Date: 06/02/2016	Hours	Description	Quantity	
-	Tow From: 3700 Belvedere Rd To: Fleet				
	Parts Charge: 0.00	Labor Charge:	0.00	Commercial Charge:	96.00

Workorder: 1702130

Problem: Transport to Surplus

Meter Reading: 123895		Labor		Parts	
In Date: 02/28/2017	Close Date: 03/01/2017	Hours	Description	Quantity	
-	Tow From: 2455 Vista Parkway To: Surplus				
	Parts Charge: 0.00	Labor Charge:	0.00	Commercial Charge:	96.00

Total Parts Charges:	19,740.35	Total Labor Charges:	12,771.00	Total Comm. Charges:	734.94
----------------------	------------------	----------------------	------------------	----------------------	---------------