

3/2/2017
10:10:28AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170995 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 746262		Problem: PRE-DELIVERY INSPECTION		
Meter Reading: 0		Labor	Parts	
In Date: 10/25/2007	Close Date: 10/25/2007	Hours	Description	Quantity
- Pre-Delivery Inspection		2.00		
	Parts Charge: 0.00	Labor Charge:	120.00	

Workorder: 746765		Problem: INSTALL TOOL BOX		
Meter Reading: 304		Labor	Parts	
In Date: 11/05/2007	Close Date: 11/07/2007	Hours	Description	Quantity
- Install Toolbox In Back Of Bed		1.00	TBSD72LP TOOL BOX (UNITED WELDING)	1.00
- Shop Supplies			SHOP SUPPLIES	1.00
	Parts Charge: 429.20	Labor Charge:	60.00	

Workorder: 834987		Problem: REPLACE REAR WINDOW		
Meter Reading: 3710		Labor	Parts	
In Date: 03/04/2008	Close Date: 03/11/2008	Hours	Description	Quantity
- Set Up Repair For Rear Glass, Clear & Reasset		1.00	SHOP SUPPLIES	1.00
- Shop Supplies				
	Parts Charge: 2.00	Labor Charge:	60.00	Commercial Charge: 524.14

Workorder: 841822		Problem: P.M. SERVICE.		
Meter Reading: 8056		Labor	Parts	
In Date: 07/23/2008	Close Date: 07/28/2008	Hours	Description	Quantity
- Pm Service		3.75	CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
- High Speed Balance All Four Tires And Nitro Fill.			SHOP SUPPLIES	1.00
- Shop Supplies			1372 OIL FILTER FRM PH2 WIX 51372	1.00
			G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
			5W20 ENGINE OIL	7.00
	Parts Charge: 53.05	Labor Charge:	60.00	

3/2/2017
10:10:28AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170995 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 843512

Problem: INSTALL CUSTOMERS COMP STAND

Meter Reading: 8960		Labor		Parts	
In Date: 08/29/2008	Close Date: 08/29/2008	Hours	Description		Quantity
-	Fabricated & Install Computor Stand & Wiring Harness.	4.00	SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge:		2.00	Labor Charge:	240.00	

Workorder: 932183

Problem: P.M. SERVICE.CHECK TIRES.

Meter Reading: 12765		Labor		Parts	
In Date: 01/02/2009	Close Date: 01/08/2009	Hours	Description		Quantity
-	Pm Service	8.25	5W20 ENGINE OIL		7.00
-	Mount 2 Nw Tires On Frt,Rep R/R Tire.Dismount/Turn		CA10262 AIR FILTER MTC FA1883 WIX 49883		1.00
	Both Reartires Inside Out.Hi Speed 4 Tires,Nitrofill To		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
	Specs.Install 4Nw Steel Vlv Stm		31-20 WIPER BLADES 20" BLADE		2.00
-	Complete Front End Alignment And Test Drive.		748636189 245/75R17 WRG SLT ARMOUR E		2.00
-	Shop Supplies		SHOP SUPPLIES		1.00
			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			TR416 VALVE STEM		4.00
			TIRE DISPOSAL FEE		2.00
Parts Charge:		482.65	Labor Charge:	495.00	

Workorder: 932639

Problem: INSTALL APS FUEL TANK

Meter Reading: 12776		Labor		Parts	
In Date: 01/12/2009	Close Date: 01/16/2009	Hours	Description		Quantity
-	Mount Fuel Tank.Remv Toolbox-Empty Bed Of	8.50	SHOP SUPPLIES		1.00
	Truck,Mount & Wirefuel Tank.		30055-20 CKT BREAKER 20 AMP		2.00
-	Shop Supplies		80865 FUSEHOLDER IMPERIAL 80865		2.00
Parts Charge:		25.75	Labor Charge:	510.00	

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170995 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 932660

Problem: DONAL MOSS CORPORATION TOW FROM - TOW TO

Meter Reading: 0	Labor	Parts
In Date: 01/12/2009	Hours	Description
Close Date: 01/12/2009	Quantity	
- Donal Moss Corporation Tow From - Tow To		
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 90.00

Workorder: 934652

Problem: 002 KEYS ISSUED OUT 03/02/09

Meter Reading: 0	Labor	Parts
In Date: 03/02/2009	Hours	Description
Close Date: 03/02/2009	Quantity	
- 002 Keys Issued Out 03/02/09	0.40	DUPLICATE VEHICLE KEYS 2.00
Parts Charge: 6.00	Labor Charge: 24.00	

Workorder: 944916

Problem: P.M service, aux fuel tank nozzle broken.

Meter Reading: 19375	Labor	Parts
In Date: 10/22/2009	Hours	Description
Close Date: 11/13/2009	Quantity	
- P.M Service.	10.00	1372 OIL FILTER FRM PH2 WIX 51372 1.00
- Diagnose Sir Light On, Pinpoint Test & Montior Pid'S On		5W20 ENGINE OIL 7.00
- Driver Side Seat Belt Buckle, Replace Seat Belt Buckle		USED FIREX REFURBED FIRE EXTINGSHERS 1.00
- Due To Open Circuit In Buckle, Clear Codes.		TIRE DISPOSAL FEE 2.00
- Mount Two New Tires, Rotate & Balance All Four Tires.		TR416 VALVE STEM 2.00
- Test Starting & Charging System.Replace Defective		FLOOR MAT SET 1.00
- Battery,Failed Load Test.		SHOP SUPPLIES 1.00
- Replace Broken Hitch Pin & Chain.		70236 FUEL FILTER 10 MICRON BIODIESEL 1.00
- Inspect & Service Aux Fuel Tank, Replace Broken		53232772401274 HOSE 3/4"X12' (GOODYEAR) 1.00
- Dispensing Nozzle & Damaged Hose.		DRIVER SEAT BUCKLE 1.00
- Shop Supplies		179636492 LT245/75R17 WRANGLER SR-A E 2.00
		18410 PINTLE PIN 1.00
		11B-0400 BLACK NOZZLE LEADED (OPW) 1.00
		GROUP 65 BATTERY (MTC BXT-65-850) 1.00
Parts Charge: 868.59	Labor Charge: 600.00	

3/2/2017
10:10:28AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170995 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1000139		Problem: Rear flat tire			
Meter Reading: 20608		Labor		Parts	
In Date: 12/29/2009		Close Date: 01/05/2010		Hours	
				Description	Quantity
-	8100 Forest Hill Blvd				
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 66.00

Workorder: 1002929		Problem: Needs hitch receiver			
Meter Reading: 22120		Labor		Parts	
In Date: 03/23/2010		Close Date: 03/23/2010		Hours	
				Description	Quantity
-	Assemble Pintal Hitch & Mount, Install On Truck.		0.80	SHOP SUPPLIES	1.00
-	Shop Supplies			2535 D.P. HITCH MOUNT	1.00
				2571 RECEIVER LOCK 5/8"	1.00
				6033 MOUNTED PINTLES BALL/PINTLE HITCH	1.00
	Parts Charge:	150.90	Labor Charge:	48.00	

Workorder: 1009438		Problem: P.M. Service.			
Meter Reading: 26828		Labor		Parts	
In Date: 08/31/2010		Close Date: 09/13/2010		Hours	
				Description	Quantity
-	P.M. Service.		3.75	5W20 ENGINE OIL	7.00
-	Rotate And Balance All Tires.			CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
-	Shop Supplies			1401 BRAKE FLUID BRAKE FLUID	1.00
				D3TZ2457B BRAKE PEDAL PAD	1.00
				31-20 WIPER BLADES 20" BLADE	2.00
				1372 OIL FILTER FRM PH2 WIX 51372	1.00
				G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
				USED FIREX REFURBED FIRE EXTINGSHERS	1.00
				SHOP SUPPLIES	1.00
	Parts Charge:	62.39	Labor Charge:	225.00	

3/2/2017
10:10:28AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170995 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1014142

Problem: Left front tire flat.

Meter Reading: 30100		Labor		Parts	
In Date: 12/29/2010	Close Date: 12/31/2010	Hours	Description		Quantity
-	Repair Flat Left Front Tire And Balance Same.	1.00	SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge:		2.00	Labor Charge:	60.00	

Workorder: 1104395

Problem: P.M. service.

Meter Reading: 32747		Labor		Parts	
In Date: 04/25/2011	Close Date: 05/03/2011	Hours	Description		Quantity
-	Perform Pm Service.	8.25	5W20 ENGINE OIL		7.00
-	Install Four New Tires.Nitrogen Fill And Balance All Four.		1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Perform Auxiliary Fuel Tank Service And Replace Fuel Filter With New.		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
-	Perform Wheel Alignment Complete.		31-20 WIPER BLADES 20" BLADE		2.00
-	Shop Supplies		179636492 LT245/75R17 WRANGLER SR-A E		4.00
			TIRE DISPOSAL FEE		4.00
			SHOP SUPPLIES		1.00
			TR416 VALVE STEM		4.00
			70236 FUEL FILTER 10 MICRON BIODIESEL		1.00
Parts Charge:		552.50	Labor Charge:	495.00	

Workorder: 1106334

Problem: Both side tool boxes lock cylinders pushed in,will not open.

Meter Reading: 33720		Labor		Parts	
In Date: 06/16/2011	Close Date: 07/20/2011	Hours	Description		Quantity
-	Fabricate And Open Both Failed Locks For Side Tool Boxes In Bed Of Truck.Replace Both Failed Locks With New And Adjust To Open And Close.	2.00	LOCK CYLINDER AND KEY		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
Parts Charge:		190.63	Labor Charge:	120.00	

3/2/2017
10:10:28AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170995 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1109954

Problem: P.M. service and check battery.

Meter Reading: 34840 In Date: 09/19/2011	Close Date: 09/28/2011	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		7.75	5W20 ENGINE OIL		7.00
- Inspect And Service Transmission.Flush And Renew Transmission Fluid.			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
			GROUP 65 BATTERY (MTC BXT-65-850)		1.00
- Fabricate And Replace Broken Right Tail Lamp Assembly With New.			24006 FUEL FILTER DIESEL AND GAS		1.00
			RIGHT REAR TAIL LIGHT ASSY		1.00
- Test Starting And Charging System.Battery Failed Load Test After Recharge.Replace Failed Battery With New.			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			SYN/ATF TRANS FLUID SYNTHETIC		20.00
- Inspect And Service Auxiliary Fuel Tank In Bed Of Truck.			SHOP SUPPLIES		1.00
- Rotate And Balance All Four Tires.					
- Shop Supplies					
Parts Charge:		307.59	Labor Charge:		465.00

Workorder: 1207531

Problem: Pm service and wiper blades.

Meter Reading: 46110 In Date: 08/10/2012	Close Date: 08/22/2012	Labor Hours	Description	Parts	Quantity
- P.M. Service		5.25	USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Inspect And Service Aux. Fuel Tank.			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
- Replace Cup Holder.			24006 FUEL FILTER DIESEL AND GAS		1.00
- Rotate And Balance All Tires.			31-20 WIPER BLADES 20" BLADE		2.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
- Shop Supplies			CUP HOLDER		1.00
			SHOP SUPPLIES		1.00
			5W20 ENGINE OIL		7.00
Parts Charge:		145.81	Labor Charge:		315.00

3/2/2017
10:10:28AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170995 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1211334

Problem: Noisy catalytic converters.Ignition switch tumbler failed.

Meter Reading: 48655		Labor		Parts	
In Date: 11/26/2012	Close Date: 12/06/2012	Hours	Description		Quantity
-	Re-Key And Replace Ignition Cylinder.	4.00	SHOP SUPPLIES		1.00
-	Transport Vehicle To Dealer For Defective Catalytic Converter.		INGITION LOCK		1.00
-	Shop Supplies				
Parts Charge:		84.50	Labor Charge:	240.00	

Workorder: 1212392

Problem: Right brake lamp inop.

Meter Reading: 49362		Labor		Parts	
In Date: 12/28/2012	Close Date: 01/08/2013	Hours	Description		Quantity
-	Test And Replace Failed Right Brake Lamp Bulb With New.Repair And Secure Wiring Harness.	0.75	MINIATURE BULB		1.00
-	Shop Supplies		60 40 ROS COR SL 1 4		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		14.42	Labor Charge:	45.00	

Workorder: 1304405

Problem: P.M. service and low tire light on and retrieve keys for defroster.

Meter Reading: 51634		Labor		Parts	
In Date: 05/03/2013	Close Date: 05/09/2013	Hours	Description		Quantity
-	Perform Pm Service.	16.75	NAPAGOLD AIR FILTER		1.00
-	Inspect And Replace Both Failed Left And Right Headlamp Sealbeams With New.Install New Right Tail Lamp Assembly.		HALOGEN LAMP		2.00
			PADS		1.00
-	Install New Front And Rear Brake Pads And Resurface All Four Brake Rotors.Service Calipers And Flush Brake Fluid.Automated Bleed Hydraulic System With Scan Tool And Roadtest.		SHOP SUPPLIES		1.00
			NAPAGOLD OIL FILTER		1.00
-	Install Four New Tires.Nitrogen Fill And Balance All Four.		1401 BRAKE FLUID BRA		1.00
-	Inspect And Service Auxiliary Fuel Tank.		179636492 LT245-75R17		4.00
-	Perform Wheel Alignment Complete.		TIRE DISPOSAL FEE		4.00
-	Shop Supplies		FUEL FILTER		1.00
			REAR PADS		1.00
			SEAL		2.00
			LAMP ASY		1.00
			TR416 VALVE STEM		4.00
			31-20 WIPER BLADES 20		2.00
			5W20 ENGINE OIL		7.00
Parts Charge:		1,305.53	Labor Charge:	1,005.00	

3/2/2017
10:10:28AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170995 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1306083

Problem: Right rear turn signal inop.

Meter Reading: 52442	Labor	Parts	
In Date: 06/18/2013	Hours	Description	Quantity
- Replace Right Rear Signal Light Bulb.	0.25	3157 TAIL LIGHT BULBS	1.00
Parts Charge: 1.63	Labor Charge: 15.00		

Workorder: 1311958

Problem: P.M. service.

Meter Reading: 60465	Labor	Parts	
In Date: 12/02/2013	Hours	Description	Quantity
- P.M. Service.	5.50	5W20 ENGINE OIL	7.00
- Replace Brake Bulb And Dome Lamp Bulb.		NAPAGOLD OIL FILTER	1.00
- Inspect And Service Aux. Fuel System.		USED FIRE X REFURBISHED	1.00
- Rotate And Balance All Tires.		NAPAGOLD FUEL FILTER	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		BULB	1.00
		ACCUFIT CONVENTIONAL	2.00
		NAPAGOLD FUEL FILTER	1.00
Parts Charge: 68.40	Labor Charge: 330.00		

Workorder: 1312800

Problem: Right rear turn signal inop.

Meter Reading: 60993	Labor	Parts	
In Date: 12/26/2013	Hours	Description	Quantity
- Test And Replace Failed Right Rear Turnsignal Lamp Bulb And Socket With New.	0.50	BULB	1.00
		STP TRN TL LGT SOCKET	1.00
Parts Charge: 7.53	Labor Charge: 30.00		

3/2/2017
10:10:28AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170995 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1407006

Problem: Pm service.

Meter Reading: 66522 In Date: 07/16/2014	Close Date: 08/22/2014	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		21.50	TR416 VALVE STEM		2.00
- Inspect And Service Auxilliary Fuel Tank And Replace Hose Nozzle.			LT245/75R17 HANKOOK TIRE		2.00
- Install Two New Tires And Balance All Four.			SPARK PLUG		8.00
- Perform Wheel Alignment Complete.			7H-0400 FUEL TRUCK N		1.00
- Diagnose For Run Rough.Replace Eight Spark Plugs And One Ignition Coil.Had Additional Labor To Extract Broken Spark Plug			FUEL PUMP W/SENDER		1.00
- Remove Fuel Tank.Drain And Clean.Replace Failed Fuel Pump.Filter And Fuel Lines Assembly With New.			UNLEADED BLACK NOZZLE		1.00
- Perform Induction Service And Flush Fuel Injectors.			408 FUEL INJECTION CL		1.00
- Test Battery And Charging System.Replace Bad Battery.			HOSE CLAMP		1.00
- Shop Supplies			BATTERY		1.00
			NAPAGOLD FUEL FILTER		1.00
			KA8A THROTTLE BODY- U		1.00
			COIL ASSEMBLY		1.00
			NAPAGOLD FUEL FILTER		1.00
			TIRE DISPOSAL FEE		2.00
			5W20 ENGINE OIL		7.00
			SHOP SUPPLIES		1.00
			WIPER BLADE		2.00
			NAPAGOLD AIR FILTER		1.00
			NAPAGOLD OIL FILTER		1.00
			FUEL LINE ASSMEBLY		1.00
			USED FIRE X REFURBISHED		1.00
	Parts Charge: 2,076.48	Labor Charge: 1,290.00			

Workorder: 1409276

Problem: Rear turnsignal light inop and front bumper damage.

Meter Reading: 67593 In Date: 09/16/2014	Close Date: 09/22/2014	Labor Hours	Description	Parts	Quantity
- Diagnose For Right Rear Turnsignal Light Inop.Replace Burnt Bulb And Socket And Retest.		0.50	BULB		1.00
			STP TRN TL LGT SOCKET		1.00
	Parts Charge: 7.29	Labor Charge: 30.00			

3/2/2017
10:10:28AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170995 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1410120 **Problem:** damage to frt bumper, grille & cond

Meter Reading: 67593 **Labor**

In Date: 09/17/2014 **Hours** **Parts**

Description	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	1,713.98
- Damage To Frt Bumper, Grille & Cond						

Workorder: 1501155 **Problem:** 1 - Wash ticket(s) issued

Meter Reading: 68029 **Labor**

In Date: 01/30/2015 **Hours** **Parts**

Description	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	9.54
- 1 - Wash Ticket(S) Issued						

Workorder: 1501540 **Problem:** Pm service,Drain auxiliary fuel tank of bad fuel.Need new diesel fuel card.

Meter Reading: 68608 **Labor**

In Date: 02/11/2015 **Hours** **Parts**

Description	Parts Charge:	468.32	Labor Charge:	645.00		
- Pm Service.			10.75			1.00
- Inspect And Service Auxiliary Fuel Tank.Replace Defective Fuel Dispenser Nozzle.Remove Bad Fuel.Clean Tank And Replace Filter.Replace Hitch Pin And Pintle Pin.						1.00
- Computer Diagnose For Check Engine Light On.Code P0442.Inspect And Replace Defective Gas Cap.Clear Code With Scan Tool And Retest Evap.System.						2.00
- Replace Two Tires.Rotate And Balance All Four.						1.00
- Shop Supplies						1.00
						1.00
						1.00
						1.00
						1.00
						1.00
						1.00
						1.00
						1.00
						1.00

Workorder: 1502902 **Problem:** Left brake lamp inop.

Meter Reading: 70227 **Labor**

In Date: 03/19/2015 **Hours** **Parts**

Description	Parts Charge:	0.75	Labor Charge:	30.00		
- Test And Replace Defective Left Brake Lamp Bulb.			0.50			1.00

3/2/2017
10:10:28AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170995 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1505023 **Problem:** 1 - Key(s) issued

Meter Reading: 72464	Labor	Parts
In Date: 05/18/2015	Hours	Description
Close Date: 05/18/2015		Quantity
- 1 - Key(S) Issued	0.30	DUPLICATE VEHICLE KEYS
Parts Charge: 3.00	Labor Charge: 18.00	1.00

Workorder: 1505983 **Problem:** P.M. service.

Meter Reading: 74088	Labor	Parts
In Date: 06/16/2015	Hours	Description
Close Date: 06/25/2015		Quantity
- Pm Service.	9.25	SHOP SUPPLIES
- Replace Two Front Body Mounts And Four Tool Box Shocks.		NAPAGOLD OIL FILTER
		WIPER BLADE
- Perform Coolant Flush And Refill System.		5W20 ENGINE OIL
- Inspect And Service Auxiliary Fuel System.		BODY MOUNT KIT
- Rotate And Balance All Four Tires.		USED FIRE X REFURBISHED
- Shop Supplies		PEAK GLOBAL
		NAPAGOLD FUEL FILTER
		SUPPORT
		NAPAGOLD AIR FILTER
Parts Charge: 322.49	Labor Charge: 555.00	1.00
		1.00
		2.00
		7.00
		2.00
		1.00
		2.00
		1.00
		4.00
		1.00

Workorder: 1509684 **Problem:** 2 - Key(s) issued

Meter Reading: 77255	Labor	Parts
In Date: 09/24/2015	Hours	Description
Close Date: 09/24/2015		Quantity
- 2 - Key(S) Issued	0.60	DUPLICATE VEHICLE KEYS
Parts Charge: 6.00	Labor Charge: 36.00	2.00

3/2/2017
10:10:28AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170995 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1511126 **Problem:** Pm service.Ac blows hot air intermittently.Brake and trailer lights inop.

Meter Reading: 79030 In Date: 10/30/2015	Close Date: 11/16/2015	Labor Hours	Description	Parts	Quantity
- Pm Service.		10.25	SHOP SUPPLIES		1.00
- Ac Performance Test.Check All Pressures.Check Voltage			5W20 ENGINE OIL		7.00
At Relay And Pressure Switches.Evacuate And Recharge			NAPAGOLD OIL FILTER		1.00
Systemtest And Replace Pressure Switch At			WIPER BLADE		2.00
Accumulator.Replace Defective Ac Relay And Blower R			WASHER FLUID CONCENTR		1.00
- Check And Replace Defective Left Tail Lamp Bulb.			R134A LV SHOP 1		1.00
- Inspect And Service Aps Fuel System.			BLOWER MOTOR RESISTOR		1.00
- Inspect Damage Right Front Door Lock Cylinder.R&I Front			SWITCH		1.00
Door Trim.R&I Damage Cylinder And Recode To Original			A /C COMORESSOR RELAY		1.00
Key.Repair Locking Actuator Rod And Fabricate Linkages			LOCK CYLINDER		1.00
- Rotate And Balance All Four Wheels.			NAPAGOLD FUEL FILTER		1.00
- Shop Supplies			BULB		1.00
Parts Charge:		216.63	Labor Charge:		615.00

Workorder: 1601275 **Problem:** Check engine light on.Battery dies.

Meter Reading: 80920 In Date: 02/05/2016	Close Date: 02/11/2016	Labor Hours	Description	Parts	Quantity
- Computer Diagnose For Check Engine Light On.Code		4.80	GAS CAP		1.00
P0442.Perform Evap Test.Replace Defective Evap			SPOT MIRROR		1.00
Canister And Fuel Cap.Retest And Clear Code.			CANNISTER		1.00
- Replace Missing Right Spot Mirror.			SHOP SUPPLIES		1.00
- Charge Battery Fully.Test Battery And Charging					
System.Perform Draw Test.Disconnect Power Inverter.006					
Amp Draw After 30 Minuites.Ok.					
- Shop Supplies					
Parts Charge:		157.50	Labor Charge:		288.00

3/2/2017
10:10:28AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170995 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1604829

Problem: P.M. service and saddle tan inop and trailer connector inop.

Meter Reading: 84766	Labor	Parts	Quantity
In Date: 05/09/2016	Hours	Description	Quantity
- P.M. Service.	8.50	SHOP SUPPLIES	1.00
- Replace Left Headlamp.		PEDAL PAD	1.00
- Check And Repair Wiring For Aux. Fuel Tank		trailer plug	1.00
Pump.Inspect Abd Service System.		USED FIRE X REFURBISHED	2.00
- Replace Two Tires,Rotate And Bal;Ance All Four.		5W20 ENGINE OIL	7.00
- Replace Corroded Trailer Plug.Fabricate And Replace		NAPAGOLD FUEL FILTER	1.00
Wiring.		STG WHEEL COV - FORD	1.00
- Shop Supplies		20" WIPER BLADE	2.00
		NAPAGOLD OIL FILTER	1.00
		WD40 16OZ	1.00
		NAPAGOLD FUEL FILTER	1.00
		TR416 VALVE STEM	2.00
		179636492 LT245-75R17	2.00
		TIRE DISPOSAL FEE	2.00
		HALOGEN LAMP	1.00
Parts Charge:	616.68	Labor Charge:	510.00

Workorder: 1608702

Problem: Rear shocks making noise and no power under load.

Meter Reading: 88675	Labor	Parts	Quantity
In Date: 08/22/2016	Hours	Description	Quantity
- Replace Worn Out Rear Shocks.	3.00	NAPAGOLD AIR FILTER	1.00
- Perform Scan Test And Poer Balance Test.No Problem		SHOP SUPPLIES	1.00
Found.Service And Clean Throttle Body And Replace Air		REFLEX TRUCK SHOCK	2.00
Filter.Test Drive.			
- Shop Supplies			
Parts Charge:	143.99	Labor Charge:	180.00

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170995 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1610535

Problem: P.M. Service.Brake lights inop.

Meter Reading: 89835 In Date: 10/12/2016	Close Date: 11/08/2016	Labor Hours	Description	Parts	Quantity
- P.M. Service.		6.75	NAPAGOLD FUEL FILTER		1.00
- Inspect And Service Aux. Fuel System.			NAPAGOLD FUEL FILTER		1.00
- Replace Left Side Headlamp.			SLIP PLATE SPRAY 12OZ		1.00
- Replace Brake Lamp Bulbs.			SHOP SUPPLIES		1.00
- Replace Two Tires,Rotate And Balance All Four.			BULB		2.00
- Shop Supplies			USED FIRE X REFURBISHED		1.00
			HALOGEN LAMP		1.00
			LT245/75R17 TIRES		2.00
			STG WHEEL COV - FORD		1.00
			TR416 VALVE STEM		2.00
			20" WIPER BLADE		2.00
			5W20 ENGINE OIL		7.00
			NAPAGOLD OIL FILTER		1.00
Parts Charge:		392.42	Labor Charge:		405.00

Workorder: 1611818

Problem: Noise in front over bumps.

Meter Reading: 90157 In Date: 11/16/2016	Close Date: 11/29/2016	Labor Hours	Description	Parts	Quantity
- Replace Worn Out Front Shocks.Retorque Front Bumper Bolts To Correct Noise Complain.		1.50	GAS GRANDE FLEET SHOC		2.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge:		108.80	Labor Charge:		90.00

Workorder: 1612717

Problem: Transition Prep Charge

Meter Reading: 90157 In Date: 12/13/2016	Close Date: 12/13/2016	Labor Hours	Description	Parts	Quantity
- Transition Prep Charge		2.00			
Parts Charge:		0.00	Labor Charge:		0.00

Total Parts Charges:	9,283.42	Total Labor Charges:	10,254.00	Total Comm. Charges:	2,403.66
----------------------	-----------------	----------------------	------------------	----------------------	-----------------