Palm Beach County Fleet Management Asset Maintenance History 10202147 2017 FORD F150 Pickup, 1/2 Ton

Total Hours: 144.45	Labor: 10,270.60	Parts: 9,356.59	Comm: 775.46 Charged: 20402.65		;		
Work Order: 1700589 Problem: 1061 - F	9 Mete Pre Delivery Inspection	r: 322 n		In Date:	01/19/2017	Closed:	01/19/2017
Work Completed							
- Pre Delivery Inspe	ection						
	Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: 1706909 Problem: P.M. se		r: 6526		In Date:	07/14/2017	Closed:	07/31/2017
Work Completed			Parts Issued			Qı	uantity
- P.m. service.			5w20 Engine Oil				6.00
- Balance and rotate	e all four tires.		Napagold Oil Filte	r			1.00
- Shop Supplies			Floor Mat-2pc Rub	Bk			1.00
			Stg Wheel Cov - Fo	ord			1.00
			Shop Supplies				1.00
	Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 62.	81	Total:	242.81
Work Order: 1711603 Problem: Trailer p	Mete olug fault message dis	r: 10302 splay on dash		In Date:	11/28/2017	Closed:	11/30/2017
Work Completed			Parts Issued			Qı	uantity
- Replace and rewir	e trailer socket.		trailer plug				1.00
- Shop Supplies			Shop Supplies				1.00

Labor: 150.00

Parts: 13.10

Total: 163.10

Comm: 0.00

Hours: 2.50

Palm Beach County Fleet Management Asset Maintenance History 2017 FORD F150 Pickup, 1/2 Ton 10202147

Work Order: 1801437 Meter: 14539 02/06/2018 **Closed**: 02/20/2018 In Date:

Problem: PM Service

Work Completed		Parts Issued		Quantity
- Pm Service.		Napagold Oil Filter		1.00
- Rotate and balance four tires.		Napa Quart 5w20		7.00
- Shop Supplies		22" Wiper Blade		2.00
		Washer Fluid Conce	entr	1.00
		Shop Supplies		1.00
Hours: 2.75	Comm: 0.00	Labor: 165.00	Parts: 41.47	Total: 206.47

Work Order: 1802542 Meter: 15850 In Date: 03/07/2018 **Closed:** 03/12/2018

Problem: Right rear tire flat.

Parts Issued Quantity **Work Completed Shop Supplies** 1.00 - Repair and balance right rear tire.

- Shop Supplies

Comm: 0.00 Hours: 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1806596 Meter: 20411 06/27/2018 **Closed**: 07/12/2018 In Date: Problem: PM Service. Check brakes, tires and strobe lights

Work Completed		Parts Issued		Quantity
- P.m.service.		Napagold Air Filte	er	1.00
- Mount And Balance 4 Tires		Napa Quart 5w20		7.00
- Replace Toggle Switch W/led Light For Emergency Sti	robe Lights.	Napagold Oil Filte	r	1.00
- Shop Supplies	-	Washer Fluid Concentr		1.00
		22" Wiper Blade 183114470 P245-70r17 Universal Switch Shop Supplies		2.00
				4.00
				1.00
				1.00
		Tire Disposal Fee		4.00
Hours: 5.00	Comm: 0.00	Labor: 300.00	Parts: 887.89	Total: 1,187.89

Palm Beach County Fleet Management Asset Maintenance History 10202147 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 1811065 Meter: 26019 10/26/2018 **Closed:** 10/31/2018 In Date: Problem: PM Service. **Work Completed Parts Issued** Quantity Napagold Oil Filter 1.00 - Pm Service. Napa Quart 5w20 7.00 - Rotate and balance four tires. 22" Wiper Blade 2.00 - Shop Supplies Washer Fluid Concentr 1.00 **Shop Supplies** 1.00 Hours: 2.75 Comm: 0.00 Labor: 184.25 Parts: 44.01 Total: 228.26 Work Order: 1904361 Meter: 29945 04/22/2019 Closed: 04/30/2019 In Date: Problem: PM Service. **Work Completed Parts Issued** Quantity 7.00 Napa Quart 5w20 - Pm Service. Napagold Oil Filter 1.00 - Installed (how is my driving)sticker and steering wheel cover. Washer Fluid Concentr 1.00 - Rotate and balance four tires. 22" Wiper Blade 2.00 - Clean debris from air cowl. Ford Triton Pvc Swc 1.00 - Shop Supplies **Shop Supplies** 1.00 Comm: 0.00 Hours: 3.75 Labor: 251.25 Parts: 62.03 Total: 313.28 07/26/2019 **Closed**: 07/29/2019 Work Order: 1907783 Meter: 32719 In Date: Problem: Right rear tire flat **Work Completed Parts Issued** Quantity **Shop Supplies** 1.00 - Repair and balance right rear.nitrogen fill all. - Shop Supplies Labor: 67.00 Hours: 1.00 Comm: 0.00 Parts: 3.00 Total: 70.00

Palm Beach County Fleet Management Asset Maintenance History 10202147 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 1907847 Meter: 32802 In Date: 07/30/2019 Closed: 07/31/2019

Problem: HAVE TO JUMP OFF EVERY MORNING

Work Completed Parts Issued Quantity
- Transport vehicle to and from dealer for replacing battery under warranty. Shop Supplies 1.00

- Shop Supplies

Hours: 2.00 Comm: 0.00 Labor: 134.00 Parts: 3.00 Total: 137.00

Work Order: 1909318 Meter: 34310 In Date: 09/10/2019 Closed: 09/16/2019

Problem: Left front tire flat.Off rim.Vehicle was towed in.

Work Completed Parts Issued Quantity 183114470 P245-70r17 1.00 - Replace and balance right front tire.nitrogen fill all. **Shop Supplies** 1.00 - Shop Supplies Tire Disposal Fee 1.00 Comm: 0.00 Labor: 67.00 Parts: 215.48 Total: 282.48 Hours: 1.00

Work Order: 1909346 Meter: 34310 In Date: 09/09/2019 Closed: 09/11/2019

Problem: Towed in for bad tire. Tire is off rim.

Work Completed

- Tow From: Kimberly Blvd.and Liberty Court.boca To: To 13026 Jog Road

Delray.

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Palm Beach County Fleet Management Asset Maintenance History 10202147 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 1910352 Meter: 34750 In Date: 10/07/2019 Closed: 10/21/2019

Problem: P.M. service.

Work Completed	Parts Issued	Quantity
- P.m. service.	Napagold Oil Filter	1.00
- Resurface front and rear rotors and service all four calipers . Replace fr	ont 5w20 Engine Oil	7.00
and rear brake pads . Flush and bleed brake system . Road test .	22" Wiper Blade	2.00
- Rotate and balance all four tires . Nitrofill all.	Washer Fluid Concentr	1.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Brake Pad	1.00
	Brk Fluid Dot 4-12oz	2.00
	Brake Pad	1.00
	Shop Supplies	1.00
Hours: 10.00 Comm: 0.00	Labor: 730.00 Parts: 211.84	Total: 941.84

Work Order: 2002616 Meter: 40060 In Date: 03/13/2020 Closed: 03/19/2020

Problem: PM Service

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Replace cabin air filter and clean fresh air intake .		5w20 Engine Oil		7.00
- Replace all four tires and balance . Nitrofill all and re	eset Tpms .	Napagold Air Filte	er	1.00
- Perform complete front end alignment and road test	t.	Washer Fluid Cond	centr	1.00
- Shop Supplies		22" Wiper Blade		2.00
		Cabin Air Filter		1.00
		245/70/17 Tire Mich		4.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 7.00	Comm: 0.00	Labor: 511.00	Parts: 999.80	Total: 1,510.80

Palm Beach County Fleet Management Asset Maintenance History 10202147 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2007176 Meter: 45474 In Date: 07/22/2020 Closed: 07/30/2020

Problem: P.M. service and recalls 17S33 and 18S27.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filter		1.00
- Rotate and high speed balance all four wheels . Nitrofill all.		5w20 Engine Oil		7.00
- Transport to and from dealer for recalls 17s33 and 18s27 .		22" Wiper Blade		2.00
- Shop Supplies		Washer Fluid Concentr		1.00
		Shop Supplies		1.00
Hours: 5.00	Comm: 0.00	Labor: 365.00	Parts: 36.51	Total: 401.51

Work Order: 2008398 Meter: 46482 In Date: 08/20/2020 Closed: 08/24/2020

Problem: Flat tire repair

Work Completed

- Tire Service 350 Lamancha Ave, Rpb - Flat tire repair

Hours: 0.00 Comm: 70.25 Labor: 0.00 Parts: 0.00 Total: 70.25

Work Order: 2009815 Meter: 48240 In Date: 09/29/2020 Closed: 10/08/2020

Problem: Check engine light and long crank , A/c inop and spare on right front .

Work Completed		Parts Issued		Quantity
- Computer diagnose check engine light , Code P1289 . Perform pinpo		Gasket		2.00
test . Remove upper and lower intake to replace cylinder head temp	•	Anti Freeze Motor	craft	1.00
and harness . Pressure test and inspect cooling system . Flush cooling system . Clear code and retest .		Wire Assy		1.00
- Repair right front tire and balance . Nitrofill all.- Shop Supplies		Gasket		1.00
		Gasket		6.00
- Shop Supplies		Gasket		1.00
		Tep Sensor		1.00
		Shop Supplies		1.00
Hours: 6.50	Comm: 0.00	Labor: 474.50	Parts: 155.53	Total: 630.03

Palm Beach County Fleet Management Asset Maintenance History 10202147 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2011534 Meter: 49775 In Date: 11/18/2020 Closed: 11/30/2020

Problem: P.M. service, spare tire on right rear and check alignment and in accident.

Work Completed		Parts Issued		Quantity
- performed pm service		Used Fire X Refurb	oished	1.00
- check ,replace tire due to damage tire r/r,balance and rotate all 4 - completed front end alignment and road test		Napa Quart 5w20 Napagold Oil Filter		7.00
				1.00
- Shop Supplies		22" Wiper Blade		2.00
		Napagold Air Filt	er	1.00
		245/70/17 Tire Mi	ich	1.00
		Shop Supplies		1.00
		Tire Disposal Fee		1.00
Hours: 6.50	Comm: 0.00	Labor: 474.50	Parts: 302.36	Total: 776.86

Work Order: 2012000 Meter: 49775 In Date: 11/17/2020 Closed: 12/01/2020

Problem: Emergency Service repair

Work Completed

- Tire Service: 1601 Belvedere Rd Problem: Emergency Service repair

Hours: 0.00 Comm: 70.25 Labor: 0.00 Parts: 0.00 Total: 70.25

Work Order: 2103701 Meter: 55698 In Date: 03/31/2021 Closed: 04/12/2021

Problem: P.M. service.

Work Completed		Parts Issued		Quantity				
 - Preventive Maint. Service - Mount Two New Tires; Rotate And Balance Four. Nitro Fill Tires - R&r Front Asset Number Peeling From Windshield. - Shop Supplies 		Napagold Oil Filter 5w20 Engine Oil Washer Fluid Concentr 22" Wiper Blade Steering Wheel Cover Large		1.00				
				7.00 1.00 2.00				
					1.00			
							245/70/17 Tire Mich	
						Shop Supplies		1.00
		Tire Disposal Fee		2.00				
Hours: 4.50	Comm: 0.00	Labor: 328.50	Parts: 628.99	Total: 957.49				

Palm Beach County Fleet Management Asset Maintenance History 10202147 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2104405 Meter: 55860 In Date: 04/20/2021 Closed: 04/20/2021

Problem: put spare on right rear , flat in bed of truck . Detail .

Work CompletedParts IssuedQuantity- Repair right rear tire and balance . Nitro fill all.Shop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 4.00 Total: 77.00

Work Order: 2104464 Meter: 55860 In Date: 04/21/2021 Closed: 04/22/2021

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2104591 Meter: 56060 In Date: 04/19/2021 Closed: 04/26/2021

Problem: put spare on

Work Completed

- Tow From: 8100 Foresthill, Croc, O&m building hood up To:

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 2107991 Meter: 59993 In Date: 07/23/2021 Closed: 07/30/2021

Problem: PM Service . Check alignment steering wheel off center

Work Completed		Parts Issued		Quantity
Preventive Maint. ServiceReplaced 2 tires. Rotated and balanced all 4 tires. Nitrogen filled all tires.		Napagold Oil Filter 5w20 Engine Oil		1.00
				6.00
- Diagnose steering wheel off center. Found to have w	vorn out bushing on Rf	Washer Fluid Cond	centr	1.00
lower control arm. Replaced lower control arm assemb		22" Wiper Blade		2.00
- Performed full front end alignment.		245/70/17 Tire Mi	ch	2.00
- Shop Supplies		Control Arm Assy		1.00
		Cam		2.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 8.00	Comm: 0.00	Labor: 584.00	Parts: 863.26	Total: 1,447.26

Palm Beach County Fleet Management Asset Maintenance History 10202147 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2111262 Meter: 63657 In Date: 10/20/2021 Closed: 10/20/2021

Problem: Towed in for right rear tire flat .

Work CompletedParts IssuedQuantity- Repair right rear tire and balance . Nitro fill all and reset Tpms .Shop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Work Order: 2111430 Meter: 63657 In Date: 10/18/2021 Closed: 10/25/2021

Problem: FLAT TIRE CHANGE OUT

Work Completed

- Tow From: Croc To: Lv Shop

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2113199 Meter: 65425 In Date: 12/14/2021 Closed: 12/22/2021

Problem: PM Service.

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Filter	1.00
- replaced cabin a/c filter and refresh intake air	5w20 Engine Oil	6.00
- check,and replaced defective high mount brakes light bulb	Washer Fluid Concentr	1.00
- check,resurfaced both rear brakes rotors ,service calipers,bleed and flush	22" Wiper Blade	2.00
system then road test	Used Fire X Refurbished	1.00
- balance and rotate all 4 tires	Cabin Filter	1.00
- Computer diagnose engine misfire . performed major tune up by replaced all 6 spark plugs and intake gasket then clean throttle body	ed Boxed Miniatures	1.00
	Brake Pad	1.00
- performed injector flush and top engine decab	Brake Pad Set	1.00
- Shop Supplies	Gasket	1.00
	Spark Plugs	6.00
	Throttle Body Cleaner	1.00
-	Motor Tune-up 16oz	1.00
	Intake Cleaner Kit	1.00
	Shop Supplies	1.00
Hours: 13.70 Comm: 0.00	Labor: 1,000.10 Parts: 227.56	Total: 1,227.66

Palm Beach County Fleet Management Asset Maintenance History 10202147 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2205290 Meter: 70212 In Date: 05/18/2022 Closed: 05/25/2022

Problem: pm--sometimes the gears almost seem stuck--little delay when going from park to drive etc. Pulls left

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filter		1.00
- check battery,charging system,after fully charge t	fails load test,replaced	5w20 Engine Oil		6.00
defective battery and reset bms		Washer Fluid Conce	ntr	1.00
- replaced two tires ,balance and rotate all 4 . Nitro	fill all.	22" Wiper Blade Battery		2.00
- check,completed front end alignment and road to	est			1.00
- check,r&r both front rotors ,pads ,calipers ,flush a	and bleed fluid ,than road	245/70/17 Tire Mich	1	2.00
to verify normal operation - Inspect and service trans r&i new filter ,performed atf flush	formed atf flush ,then road test. $\frac{1}{100}$	Brake Rotor		2.00
		Brk Fluid Dot 4-32o	Z	1.00
also prior to service road test, check for code none to be found	found and no abnormal	Bracketed Caliper		1.00
- Shop Supplies		Bracketed Caliper		1.00
		Brake Pad		1.00
		Tram Filter		1.00
		oil auto		14.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 14.00	Comm: 0.00	Labor: 1,022.00	Parts: 1,124.10	Total: 2,146.10

Work Order: 2205953 Meter: 70569 In Date: 06/06/2022 Closed: 06/08/2022

Problem: passenger taillight damage

Work Completed		Parts Issued		Quantity	
- check ,sop,replaced damaged r/r tail lamp assembly and r&i installed strobes light		Lamp Assy		1.00	
		Shop Supplies		1.00	
- Shop Supplies					
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 86.36	Total: 159.36	

Hours: 1.00

Palm Beach County Fleet Management Asset Maintenance History 10202147 2017 FORD F150 Pickup, 1/2 Ton

Meter: 72014 Work Order: 2209420 09/09/2022 **Closed:** 09/12/2022 In Date: Problem: nail in tire **Parts Issued Work Completed** Quantity 245/70/17 Tire Mich 1.00 - Replace left rear tire, balance and nitro service 1.00 **Shop Supplies** - Shop Supplies Tire Disposal Fee 1.00 Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 228.34 Total: 264.84 Work Order: 2212139 Meter: 73555 In Date: 12/02/2022 **Closed**: 12/08/2022 Problem: PM Service. Send for Detail. Quantity **Parts Issued Work Completed** Napagold Oil Filter 1.00 - Preventive Maint. Service completed 5w20 Engine Oil 6.00 - replaced one tire, rotate and balance all 4. Nitro fill all 22" Wiper Blade 2.00 - Shop Supplies Used Fire X Refurbished 1.00 245/70/17 Tire Mich 1.00 **Shop Supplies** 1.00 1.00 Tire Disposal Fee Comm: 0.00 Labor: 292.00 Parts: 256.85 Total: 548.85 Hours: 4.00 Work Order: 2212341 Meter: 73555 In Date: 12/08/2022 Closed: 12/08/2022 Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2212139 for: dean **Work Completed** - 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2212139 for: dean Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40 Work Order: 2301863 Meter: 75898 In Date: 02/27/2023 **Closed**: 02/27/2023 **Problem:** right front has spare on ,flat in bed **Work Completed Parts Issued** Quantity **Shop Supplies** 1.00 - Repair right front tire and balance. Nitro fill all. Remount spare. - Shop Supplies

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

Palm Beach County Fleet Management Asset Maintenance History 10202147 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2302799 Meter: 76755 In Date: 02/22/2023 Closed: 03/20/2023

Problem: EMERGENCY SERVICE FLAT TIRE CHANGE OUT

Work Completed

- Tow From: 8100 Forest Hill Blvd, Wpb(next To Carwash) To: Flat Tire

Change Out

Hours: 0.00 Comm: 47.46 Labor: 0.00 Parts: 0.00 Total: 47.46

Work Order: 2303949 Meter: 78611 In Date: 04/21/2023 Closed: 04/26/2023

Problem: PM Service. Send for Detail.

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Oil Filter	1.00
- Rotated and balanced all 4 tires. Nitrogen filled all tires.	5w20 Engine Oil	6.00
 Computer diagnose check engine light. Code- P1450. Found to have faulty purge valve solenoid. Replaced faulty purge valve assembly. Cleared code and test drove. Diagnose clunk in front end. Found to have worn out Lf upper control arm. Remove and replaced Lf upper control arm assembly. Performed full front end alignment. Replaced cabin filter. Cleaned debris from fresh air intake. 	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
	Valve Asm	1.00
	Cabin Air Filter	1.00
	Control Arm Assy	1.00
	Shop Supplies	1.00

Comm: 0.00

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2303949 for: Michael Brown

Work Completed

- Shop Supplies

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2303949 for: Michael Brown

Hours: 9.80

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Labor: 715.40

Parts: 201.06

Total: 916.46

Palm Beach County Fleet Management Asset Maintenance History 10202147 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2306198 Meter: 81895 In Date: 06/23/2023 Closed: 06/29/2023

Problem: power steering goes out at times with no warning lights on truck.

Work Completed		Parts Issued		Quantity
 Computer diagnose power assist steering , scan for codes B1d23 and U3000 . Perform pinpoint test . Clear codes and retest . Road test according to test . Code did not return . Check battery and charging system . Charge battery fully . Road test more Test drive Machine front rotors for pulsation , replace rear brake pads and rotors .service calipers . Flush and bleed brake system .road test . Perform complete alignment and road test . 		Non-chlor Brake Clnr		1.00
		Brake Fl-dot 3-4 32oz		2.00
		Brake Pad		1.00
		Brake Rotor		2.00
		Rotor		2.00
		Shop Supplies		1.00
- Shop Supplies				
Hours: 9.20	Comm: 0.00	Labor: 671.60	Parts: 399.19	Total: 1,070.7

Work Order: 2307526 Meter: 83186 In Date: 07/28/2023 Closed: 08/10/2023

Problem: PM Service. Power Steering intermittently goes out while driving the truck.

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	22" Wiper Blade	2.00
- mount 2 rotate and balance all 4 tires nitro fill all	Washer Fluid Concentr	1.00
- Customer states power steering intermittently goes out. Pin point tes	5w20 Engine Oil	6.00
found Power Steering Module faulty remove and replace.	Napagold Oil Filter	1.00
- replace pass side brake bulb	245/70/17 Tire Mich	2.00
- Driver seat found to be cave in. Seat cushion, springs found broken	Boxed Miniatures	1.00
remove & replace cushion along with seat spring	Support Seat	1.00
- perform front end alignment after steering rack replacement	Pad Seat	1.00
- Shop Supplies	Pad Seat	1.00
	Steering Gear Asm	1.00
	Track Assy	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 12.50 Comm: 0.00	Labor: 912.50 Parts: 2,090.71	Total: 3,003.2

Work Order: 2308168

Palm Beach County Fleet Management Asset Maintenance History 10202147 2017 FORD F150 Pickup, 1/2 Ton

Meter: 83474 In Date: 08/15/2023 Closed: 08/17/2023

Problem: Towed in for driver rear tire flat, NE side of the plaza near laundromat

Work Completed		Parts Issued		Quantity	
 Replace left rear tire and balance , ridden on flat . Nitro fill all and reset Tpms . Shop Supplies 		245/70/17 Tire Mich		1.00	
		Tire Pressure Monitoring System Sensor (Shop Supplies Tire Disposal Fee		1.00	
					1.00
					Hours: 0.50

Work Order: 2308588 Meter: 83903 In Date: 08/15/2023 Closed: 08/28/2023

Problem: driver rear tire flat, NE side of the plaza near laundromat

Work Completed

- Tow From: 5021 okeechobee blvd To: fleet vista Lv shop

Hours: 0.00 Comm: 124.30 Labor: 0.00 Parts: 0.00 Total: 124.30

Work Order: 2311553 Meter: 87663 In Date: 11/17/2023 Closed: 11/17/2023

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 144.45 Total Labor: 10,270.60 Total Comm: 775.46 Total Parts: 9,356.59