

2/1/2024
3:56:23 PM

Palm Beach County Fleet Management Asset Maintenance History
10198476 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Total Hours: 198.60 Labor: 13,485.60 Parts: 12,694.56 Comm: 1,214.43 Charged: 27394.59

Work Order: 1508314 **Meter:** 436 **In Date:** 08/19/2015 **Closed:** 08/19/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection
- Minor weld repair or machining

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 0.00 Total: 180.00

Work Order: 1509119 **Meter:** 791 **In Date:** 09/11/2015 **Closed:** 09/30/2015
Problem: Install Fire Pump

Work Completed

- install and fab fire pump mounting brackets in bed of truck
- wire in equipment. install breaker and quick connect plug
- Shop Supplies

| Parts Issued | Quantity |
|---------------------|-----------------|
| Cable Tie | 2.00 |
| Shop Supplies | 1.00 |

Hours: 15.00 Comm: 0.00 Labor: 900.00 Parts: 11.00 Total: 911.00

Work Order: 1601338 **Meter:** 4264 **In Date:** 02/08/2016 **Closed:** 02/24/2016
Problem: P.M. Service.

Work Completed

- P.m. Service.
- Inspect and service winch.
- Rotate and balance all tires.
- Transport vehicle to dealer for leaking left rear axle seal.
- Shop Supplies

| Parts Issued | Quantity |
|----------------------|-----------------|
| 5w20 Engine Oil | 7.00 |
| Napagold Oil Filter | 1.00 |
| Pintle Pin W/chain | 1.00 |
| Floor Mat-2pc Rub Bk | 1.00 |
| Stg Wheel Cov - Ford | 1.00 |
| Shop Supplies | 1.00 |

Hours: 6.75 Comm: 0.00 Labor: 405.00 Parts: 67.07 Total: 472.07

Work Order: 1603290 **Meter:** 5714 **In Date:** 03/29/2016 **Closed:** 03/31/2016
Problem: Wiper blades

Work Completed

- Replace both wiper blades.

| Parts Issued | Quantity |
|---------------------|-----------------|
| 22" Wiper Blade | 2.00 |

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 6.60 Total: 36.60

2/1/2024
3:56:24 PM

Palm Beach County Fleet Management Asset Maintenance History
10198476 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 1706621 **Meter:** 18033 **In Date:** 07/06/2017 **Closed:** 07/10/2017
Problem: needs 2 spare keys

Work Completed

- Make and program 2 spare keys
- Shop Supplies

Hours: 1.00

Comm: 0.00

Parts Issued

| | Quantity |
|-------------------------|-----------------|
| Ford Ignition Key Blank | 2.00 |
| Shop Supplies | 1.00 |
| Labor: 60.00 | Parts: 55.22 |
| Total: 115.22 | |

Work Order: 1711342 **Meter:** 21453 **In Date:** 11/16/2017 **Closed:** 11/30/2017
Problem: P.M. service.

Work Completed

- P.m. service.
- Replace all four tires.nitrogen fill tires .high speed balance all four tires.
- Inspect and service winch .replace damaged cable with new.
- Perform front end alignment.
- Shop Supplies

Hours: 10.50

Comm: 0.00

Parts Issued

| | Quantity |
|-------------------------|-----------------|
| 5w20 Engine Oil | 7.00 |
| Napagold Oil Filter | 1.00 |
| 22" Wiper Blade | 2.00 |
| Stg Wheel Cov - Ford | 1.00 |
| Napagold Air Filter | 1.00 |
| Used Fire X Refurbished | 1.00 |
| 35x12.5r17 Nitto Grap | 4.00 |
| Rep/rope | 1.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 4.00 |
| Labor: 630.00 | Parts: 2,199.88 |
| Total: 2,829.88 | |

2/1/2024
3:56:24 PM

Palm Beach County Fleet Management Asset Maintenance History
10198476 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 1804259 **Meter:** 24537 **In Date:** 04/25/2018 **Closed:** 05/04/2018
Problem: P.M. service and tire pressure light on and broken windshield.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Remove right front door panel to replace melted right outside mirror assembly.
- Wash mud from all wheel assemblies .replace tire pressure sensor in left front wheel .rotate and high speed balance all four tires. Nitrofill.
- Inspect and service winch . Test and replace remote controller for winch.
- Shop Supplies

| | |
|-------------------------|------|
| 5w20 Engine Oil | 7.00 |
| Napagold Oil Filter | 1.00 |
| Napagold Air Filter | 1.00 |
| 22" Wiper Blade | 2.00 |
| Used Fire X Refurbished | 1.00 |
| Tpms12 Sensor Tire Pr | 1.00 |
| Seal Asy | 1.00 |
| Mirror | 1.00 |
| Remote Ctrl Ser. Part | 1.00 |
| Shop Supplies | 1.00 |

Hours: 8.00

Comm: 0.00

Labor: 480.00 Parts: 714.77 Total: 1,194.77

Work Order: 1804519 **Meter:** 24537 **In Date:** 05/01/2018 **Closed:** 05/09/2018
Problem: replace cracked windsheild

Work Completed

Parts Issued

Quantity

- set up repairs and reasset
- Shop Supplies

| | |
|---------------|------|
| Shop Supplies | 1.00 |
|---------------|------|

Hours: 1.00

Comm: 316.28

Labor: 60.00 Parts: 2.00 Total: 378.28

2/1/2024
3:56:24 PM

Palm Beach County Fleet Management Asset Maintenance History
10198476 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 1811764

Meter: 30726

In Date: 11/16/2018 **Closed:** 12/05/2018

Problem: P.M. service , check engine light on and noise when slowing down.

Work Completed

- P.m. service.
- Resurface front and rear rotors and service all four calipers . Replace brake pads . Flush and bleed brake system . Road test.
- Computer diagnose check engine light ,code P06b6. Perform tune up . Replace all sixteen spark plugs and four coils and wires . Replace defective fuel line from injector rail to rear lines . Replace defective purge valve connector .clear codes ,retest
- Perform injector flush and air intake decarb and cleaning.
- Inspect and service transfer case .
- Check and replace missing pintle pin.
- Balance and rotate all four tires. Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

| | |
|--------------------------|-------|
| Napagold Oil Filter | 1.00 |
| Napa Quart 5w20 | 7.00 |
| 22" Wiper Blade | 2.00 |
| Ford Triton Pvc Swc | 1.00 |
| Real Brake Pad | 1.00 |
| Brake Pad | 1.00 |
| Coil | 1.00 |
| Coil | 2.00 |
| Spark Plug | 16.00 |
| Espak Plug Wire | 4.00 |
| Espak Plug Wire | 4.00 |
| Injector Cleaner | 1.00 |
| Intake Cleaner Kit | 1.00 |
| Pintle Pin W/clip | 1.00 |
| Ford Transfer Case Fluid | 3.00 |
| Coil | 1.00 |
| Tube | 1.00 |
| Wire Asy | 1.00 |
| Shop Supplies | 1.00 |

Hours: 25.40

Comm: 0.00

Labor: 1,701.80

Parts: 1,244.82

Total: 2,946.62

2/1/2024
3:56:24 PM

Palm Beach County Fleet Management Asset Maintenance History
10198476 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2005157 **Meter:** 46250 **In Date:** 05/21/2020 **Closed:** 06/09/2020
Problem: P.M. service and check tires for plugs .

Work Completed

Parts Issued

Quantity

- P.m. service.
- Test and replace high mounted brake light bulb .
- Test and replace broken winch assembly. straight and weld bumper mount for winch . Inspect and service new winch . Test operation .
- Mount and balance all four new tires . Nitrofill all.
- Replace broken pintle pin.
- Perfrom complete front end alignment and road test .
- Shop Supplies

| | |
|-------------------------|-------|
| Napagold Oil Filter | 1.00 |
| 5w20 Engine Oil | 21.00 |
| Washer Fluid Concentr | 1.00 |
| 22" Wiper Blade | 2.00 |
| Napagold Air Filter | 1.00 |
| Used Fire X Refurbished | 1.00 |
| Lamp Asy | 1.00 |
| Boxed Miniatures | 2.00 |
| Warn Vr12 Winch | 1.00 |
| Pintle Pin W/clip | 1.00 |
| Tire 35x12.50r17lt | 4.00 |
| Shop Supplies | 1.00 |

Hours: 17.30

Comm: 0.00

Labor: 1,262.90 Parts: 2,829.97 Total: 4,092.87

Work Order: 2012985 **Meter:** 51951 **In Date:** 12/30/2020 **Closed:** 01/07/2021
Problem: PM Service - Thank you.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- check and installed new pintle pin
- check ,pin point test and r@r the reverse light bulb l/r
- Pressure test and inspect cooling system . performed engine coolant flush and refill
- Inspect and service transmission . Replace trans filter , flush fluid and refill to spec
- inspect and service winch
- balance and rotate all 4 tires . Nitro fill all.
- Shop Supplies

| | |
|-----------------------|-------|
| Napagold Oil Filter | 1.00 |
| 5w20 Engine Oil | 7.00 |
| Washer Fluid Concentr | 1.00 |
| 22" Wiper Blade | 2.00 |
| Pintle Pin W/clip | 1.00 |
| Boxed Miniatures | 1.00 |
| Trams Filter | 1.00 |
| oil auto | 16.00 |
| Coolant Ford Gold | 2.00 |
| Coolent | 2.00 |
| Shop Supplies | 1.00 |

Hours: 11.30

Comm: 0.00

Labor: 824.90 Parts: 315.07 Total: 1,139.97

2/1/2024
3:56:24 PM

Palm Beach County Fleet Management Asset Maintenance History
10198476 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2309993 **Meter:** 77851 **In Date:** 09/29/2023 **Closed:** 10/16/2023
Problem: PM Service

Work Completed

- Preventive Maint. Service
- mount 2 tires rotate and balance all 4 tires nitro fill all
- during inspection water was found in front diff the diff was drain cleaned and refilled .
- inspect winch and lubricate all moving parts
- Shop Supplies

Parts Issued

Quantity

| | | |
|------------------------------|----------------------|------------------------|
| Napagold Oil Filter | 1.00 | |
| 5w20 Engine Oil | 7.00 | |
| Used Fire X Refurbished | 1.00 | |
| Napagold Air Filter | 1.00 | |
| 22" Wiper Blade | 2.00 | |
| 35x12.50/r17 Tire Countrym/t | 2.00 | |
| 7 Spline Wheel Lock Key | 1.00 | |
| Non-chlor Brake Clnr | 2.00 | |
| Px Grey Rtv Silicone | 1.00 | |
| Lucas Gear Oil 75 90 | 3.00 | |
| Shop Supplies | 1.00 | |
| Tire Disposal Fee | 2.00 | |
| Freight Charge | 1.00 | |
| Labor: 584.00 | Parts: 628.33 | Total: 1,212.33 |

Hours: 8.00 Comm: 0.00

Work Order: 2311277 **Meter:** 77984 **In Date:** 11/09/2023 **Closed:** 11/09/2023
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 198.60 Total Labor: 13,485.60 Total Comm: 1,214.43 Total Parts: 12,694.56