Palm Beach County Fleet Management Asset Maintenance History 10201464 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Total Hours: 93.30 Labor: 6,431.35 Parts: 5,929.29 Comm: 667.03 Charged: 13027.67

Work Order: 1605886 Meter: 298 In Date: 06/08/2016 Closed: 06/08/2016

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1607276 Meter: 596 In Date: 07/18/2016 Closed: 07/18/2016

Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.08 Labor: 0.00 Parts: 0.00 Total: 19.08

Work Order: 1611886 Meter: 2696 In Date: 11/17/2016 Closed: 11/30/2016

Problem: P.M. service and right rear tire going flat and right headlight inop.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		7.00
- Replace and rewire corroded trailer p	lug.	Napagold Oil Filte	r	1.00
- Replace inop right headlamp bulb.		Floor Mat-2pc Ruk	o Bk	1.00
- Replace damaged right tire, rotate and	d balance all four.	trailer plug		1.00
- Shop Supplies		bulb		1.00
		Shop Supplies		1.00
		Lt245/75r17 Tire		1.00
Hours: 6.00	Comm: 0.00	Labor: 360.00	Parts: 235.93	Total: 595.93

Palm Beach County Fleet Management Asset Maintenance History 10201464 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 1705094 Meter: 4428 In Date: 05/23/2017 Closed: 05/31/2017

Problem: P.M. service and had to jump start in AM.

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		7.00
- Check battery and charging system.fully charge battery.re	echeck.failed load	Napagold Oil Filte	er	1.00
test .replace defective battery.		Used Fire X Refurb	oished	1.00
- Balance and rotate all four tires.		Wd40 Spr		1.00
- Shop Supplies		22" Wiper Blade		2.00
		Napa Quart 5w30		7.00
		Battery 65		1.00
		Shop Supplies		1.00
Hours: 4.75	Comm: 0.00	Labor: 285.00	Parts: 227.71	Total: 512.71

Work Order: 1711261 Meter: 5775 In Date: 11/15/2017 Closed: 11/29/2017

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napa Quart 5w30		7.00
- Rotate and balance all four tires.top off with nitro fill.		Napagold Oil Filte	r	1.00
- Shop Supplies		22" Wiper Blade		2.00
		Washer Fluid Cond	centr	2.00
		Mac Wite Lithium	Gres	1.00
		Shop Supplies		1.00
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 47.69	Total: 272.69

Palm Beach County Fleet Management Asset Maintenance History 10201464 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 1804713 Meter: 9300 In Date: 05/04/2018 Closed: 05/14/2018

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filter		1.00
- Diagnoise strobes inop. R&r defective switch and re	etest.	5w20 Engine Oil		7.00
- Balance and rotate all four wheels .nitrofill and rese	et Tpms.	22" Wiper Blade		2.00
- Shop Supplies	•	Washer Fluid Cond	centr	1.00
		Used Fire X Refurb	pished	1.00
		Universal Switch		1.00
		oil auto		1.00
		Shop Supplies		1.00
Hours: 4.25	Comm: 0.00	Labor: 255.00	Parts: 62.05	Total: 317.05

Work Order: 1900443 Meter: 14908 In Date: 01/11/2019 Closed: 01/22/2019

Problem: PM Service

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Replace all four tires . Balance and nitrogen fill all tires.		Napa Quart 5w30		7.00
- Replace broken pintle pin .		Napagold Air Filte	er	1.00
- Complete front end alignment and road test.		Washer Fluid Cond	centr	1.00
- Shop Supplies		Used Fire X Refurb	ished	1.00
		Pedal Pad		1.00
		Lt245/75r17 Mich	Defend Ltx	4.00
		Pintle Pin W/clip		1.00
		22" Wiper Blade		2.00
		245/75/17/tire Nit	iro	4.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 7.55	Comm: 0.00	Labor: 505.85	Parts: 2,166.25	Total: 2,672.10

Palm Beach County Fleet Management Asset Maintenance History 10201464 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 1902711 Meter: 15795 In Date: 03/12/2019 Closed: 03/13/2019

Problem: Right rear tire has screw.

Work CompletedParts IssuedQuantity- Repair right rear tire and balance . Nitrofill all.Shop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 3.00 Total: 70.00

Work Order: 1905405 Meter: 17768 In Date: 05/20/2019 Closed: 05/22/2019

Problem: Right brake light inop.

Work CompletedParts IssuedQuantity- Test and replace right brake light bulb and socket and retest .Stp Trn Tl Lgt Socket1.00Boxed Miniatures1.00Hours: 0.50Comm: 0.00Labor: 33.50Parts: 9.77Total: 43.27

Palm Beach County Fleet Management Asset Maintenance History 10201464 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 1907542 Meter: 18800 In Date: 07/22/2019 Closed: 08/06/2019

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Napa Quart 5w30		8.00
- Test battery and charging system.recharge and	d retest battery,fail load	Napagold Oil Filte	r	1.00
test.replace defective battery.	·	Used Fire X Refurb	pished	1.00
- Resurface front brake rotors, replace calipers ar	nd pads.replace front brake	22" Wiper Blade		2.00
hoses.flush and bleed system.test drive		Ford Triton Pvc Sw	/C	1.00
- Rotate and balance tires.		oil auto		1.00
- Shop Supplies		Mac Wite Lithium	Gres	1.00
		Battery 65		1.00
		Brake Hose		1.00
		Brake Hose		1.00
		Reman/ca		1.00
		Reman/ca		1.00
		Non-chlor Brake C	Clnr	1.00
		B Fluid Dot 3-32oz	Z	1.00
		Brake Pad		1.00
		Shop Supplies		1.00
Hours: 9.25	Comm: 0.00	Labor: 619.75	Parts: 810.09	Total: 1,429.84

Work Order: 1912962 Meter: 20693 In Date: 12/18/2019 Closed: 12/18/2019

Problem: Broken rear window

Work Completed

- Tow From: Bg water plant To: Vista

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Palm Beach County Fleet Management Asset Maintenance History 10201464 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 1913176 Meter: 20693 In Date: 12/30/2019 Closed: 01/07/2020

Problem: replace rear cab window

Work CompletedParts IssuedQuantity- set up repairs & reassetShop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 551.95 Labor: 73.00 Parts: 4.00 Total: 628.95

Work Order: 2002209 Meter: 20822 In Date: 03/03/2020 Closed: 03/11/2020

Problem: P.M. service.

- P.m. service. Napagold Oil Filter 1.00 - Rotate and high speed balance all four tires . Nitrofill all. Napa Quart 5w30 7.00 - Shop Supplies 22" Wiper Blade 2.00 Washer Fluid Concentr 1.00 Pintle Pin W/clip 1.00 Shop Supplies 1.00 Hours: 3.75 Comm: 0.00 Labor: 273.75 Parts: 49.24 Total: 322.99	Work Completed		Parts Issued		Quantity	
- Shop Supplies 22" Wiper Blade 2.00 Washer Fluid Concentr 1.00 Pintle Pin W/clip 1.00 Shop Supplies 1.00	- P.m. service.		n. service.		Napagold Oil Filter	
Washer Fluid Concentr 1.00 Pintle Pin W/clip 1.00 Shop Supplies 1.00	- Rotate and high speed balance all four tires .	. Nitrofill all.	Napa Quart 5w30		7.00	
Pintle Pin W/clip 1.00 Shop Supplies 1.00	- Shop Supplies		22" Wiper Blade		2.00	
Shop Supplies 1.00			Washer Fluid Con	centr	1.00	
			Pintle Pin W/clip		1.00	
Hours: 3.75 Comm: 0.00 Labor: 273.75 Parts: 49.24 Total: 322.99			Shop Supplies		1.00	
	Hours: 3.75	Comm: 0.00	Labor: 273.75	Parts: 49.24	Total: 322.99	

Work Order: 2007805 Meter: 24380 In Date: 08/07/2020 Closed: 08/12/2020

Problem: PM Service, Engine oil light on, Battery is weak, Screw in right rear tire.

Work Completed	Parts Issued	Quantity
- P.m. service.	F75z6730ba Drain Plug	1.00
- Check battery and charging system after fully charging battery . Battery	Napagold Oil Filter	1.00
failed load test . R&r defective battery .	Napa Quart 5w30	8.00
- Repair right rear tire . Rotate and balance all four tires . Nitrofill all.	Washer Fluid Concentr	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Battery 65	1.00
	Shop Supplies	1.00
Hours: 5.75 Comm: 0.00	Labor: 419.75 Parts:	255.45 Total: 675.20

Palm Beach County Fleet Management Asset Maintenance History 10201464 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2101182 Meter: 27841 In Date: 02/01/2021 Closed: 02/09/2021

Problem: P.M. service and check lights and right rear tire going flat .

Work Completed	Parts Issued		Quantity
- Preventive Maint. Service	Napa Quart 5w30		8.00
- Diagnose engine misfire .performed major engine tune up by r@r all 16	Napagold Oil Filter		1.00
spark plugs and wires	22" Wiper Blade		2.00
- performed injector flush and top engine decab	Espak Plug Wire		4.00
- inspect,replace defective trailer plug and fabricated wires as needed	Espak Plug Wire		4.00
- installed missing pintle pin	Spark Plug		16.00
- check ,pin point test R&r defective both rear turn signal light bulbs .	Motor Tune-up 16o)Z	1.00
- repair r/r tire,balance and rotate all 4 . Nitro fill all.	Intake Cleaner Kit		1.00
- Shop Supplies	trailer plug		1.00
	Pintle Pin W/clip		1.00
	Boxed Miniatures		2.00
	Shop Supplies		1.00
Hours: 14.05 Comm: 0.00	Labor: 1,025.65	Parts: 310.11	Total: 1,335.76

Work Order: 2108811 Meter: 30157 In Date: 08/13/2021 Closed: 08/25/2021

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napa Quart 5w30		7.00
- Load Test Battery And Failed. R&r Battery, Check Chargin	g System At 13.9	Napagold Oil Filter	•	1.00
Volts Ok, Test Current Draw Within Range Of 0.005 Amps.		22" Wiper Blade		2.00
- R&r Blown High Mount Lamps.		Used Fire X Refurb	ished	1.00
- Perform Automatic Transmission Flush Service.		Battery		1.00
- Drain And Fill Transfer Case Service.		Boxed Miniatures		3.00
- Rotate And Balance Four Tires. Nitro Fill All.		oil auto		20.00
- Shop Supplies		oil auto		2.00
		Shop Supplies		1.00
Hours: 7.75	Comm: 0.00	Labor: 565.75	Parts: 342.76	Total: 908.51

Palm Beach County Fleet Management Asset Maintenance History 10201464 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2201934 Meter: 32984 In Date: 02/22/2022 Closed: 02/28/2022

Problem: PM Service. Right fron tire has a screw in it and is leaking very slowly.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Washer Fluid Con-	centr	1.00
- Check and R & I four new tires, speed balance, nitro f	ill	22" Wiper Blade		2.00
- Perform complete alignment, road test		Napagold Oil Filte	er	1.00
- Replace missing pintle		Napa Quart 5w30		7.00
- Shop Supplies		Napagold Air Filt	er	1.00
		Pintle Pin W/clip		1.00
		Lt 245/75/17titr M	1ic	4.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 7.45	Comm: 0.00	Labor: 543.85	Parts: 956.69	Total: 1,500.54

Work Order: 2212468 Meter: 34589 In Date: 12/13/2022 Closed: 12/19/2022

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Performed P.m. Service & Ispection.		Napagold Oil Filte	r	1.00
- Performed Tire Rotation Balance On All 4 Whe	els, Add Nitro Fill Reset	Napa Quart 5w30		7.00
Tpms.		Washer Fluid Cond	centr	1.00
- Vehicle Is Misfiring And Runs Rough, Plug In S	22" Wiper Blade		2.00	
Fault Code P0306 & Defective Igntion Coil Relate		Used Fire X Refurb	pished	1.00
Replaced Then Erase Fault Code And Test Drove	venicle, working as Design.	Pedal Pad		1.00
- Shop Supplies		Al3z12029b		1.00
		Shop Supplies		1.00
Hours: 5.45	Comm: 0.00	Labor: 397.85	Parts: 182.75	Total: 580.60

Palm Beach County Fleet Management Asset Maintenance History 10201464 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Work Order: 2308320 Meter: 35535 In Date: 08/21/2023 Closed: 09/12/2023

Problem: PM Service and recall 22S35.

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Oil Filter	1.00
- R&r Broken Windshield Washer Jets.	Napa Quart 5w30	7.00
- Load Test Battery, Had To Recharge And Retest. R&r Faile	tery Due To Washer Fluid Concentr	1.00
Normal Wear.	22" Wiper Blade	2.00
- Rotate And Balance Four Tires. Relearn Tire Sensors.	Used Fire X Refurbished	1.00
- transport to and from dealer for recall 22s35	Washer Jet	2.00
- Shop Supplies	Battery	1.00
	Shop Supplies	1.00
Hours: 7.05 Comm: 0.00	Labor: 514.65 Parts: 265.83	Total: 780.48

Work Order: 2312380 Meter: 35769 In Date: 12/14/2023 Closed: 12/14/2023

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 93.30 Total Labor: 6,431.35 Total Comm: 667.03 Total Parts: 5,929.29