

2/29/2024
2:16:09 PM

Palm Beach County Fleet Management Asset Maintenance History
10201964 2016 BOBCAT 7186695 Misc Attachments-Mixer

Total Hours: 24.00 Labor: 1,466.00 Parts: 830.47 Comm: 0.00 Charged: 2296.46

Work Order: 1607142 **Meter:** 0 **In Date:** 07/14/2016 **Closed:** 07/14/2016
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1702495 **Meter:** 0 **In Date:** 03/10/2017 **Closed:** 04/07/2017
Problem: Mixer Chain

Work Completed

- Replace broken drive chain
- Replace hoses
- To Mako
- Shop Supplies

Parts Issued

Quantity

roller chain 50	1.00
chain	1.00
hose made	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 5.50 Comm: 0.00 Labor: 330.00 Parts: 490.72 Total: 820.72

Work Order: 1705224 **Meter:** 0 **In Date:** 05/26/2017 **Closed:** 06/09/2017
Problem: Repair hoses

Work Completed

- Replace hyd. hoses from mixer to Bobcat
- Exstend electric cable from mixer to Bobcat
- Shop Supplies

Parts Issued

Quantity

hose made mako	1.00
Shop Supplies	1.00

Hours: 11.00 Comm: 0.00 Labor: 660.00 Parts: 311.78 Total: 971.78

Work Order: 1807516 **Meter:** 0 **In Date:** 07/24/2018 **Closed:** 08/10/2018
Problem: mixer chain off

Work Completed

- Repair mixer chain and lube mixer
- Shop Supplies

Parts Issued

Quantity

Chain	1.00
Shop Supplies	1.00

Hours: 3.50 Comm: 0.00 Labor: 210.00 Parts: 27.97 Total: 237.97

2/29/2024
2:16:09 PM

Palm Beach County Fleet Management Asset Maintenance History
10201964 2016 BOBCAT 7186695 Misc Attachments-Mixer

Work Order: 2401779 **Meter:** 0 **In Date:** 02/15/2024 **Closed:** 02/15/2024
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 24.00

Total Labor: 1,466.00

Total Comm: 0.00

Total Parts: 830.47