

4/1/2024
2:35:49 PM

Palm Beach County Fleet Management Asset Maintenance History
10198284 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Total Hours: 143.25 Labor: 9,886.25 Parts: 6,981.55 Comm: 3,611.63 Charged: 20479.43

Work Order: 1509636 **Meter:** 334 **In Date:** 09/23/2015 **Closed:** 09/23/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1603987 **Meter:** 4772 **In Date:** 04/15/2016 **Closed:** 04/22/2016
Problem: P.M. service.

Work Completed

- P.m. Service.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00
Labor: 300.00 Parts: 38.51 Total: 338.51	

Work Order: 1611046 **Meter:** 5491 **In Date:** 10/26/2016 **Closed:** 10/31/2016
Problem: P.M. service.

Work Completed

- P.m. Service.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Accufit Beam	1.00
Wiper Blade - Accufit - Passenger's Side	1.00
Shop Supplies	1.00
Labor: 300.00 Parts: 51.41 Total: 351.41	

Hours: 5.00 Comm: 0.00

4/1/2024
2:35:49 PM

Palm Beach County Fleet Management Asset Maintenance History
10198284 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 1704089 **Meter:** 10399 **In Date:** 04/24/2017 **Closed:** 05/11/2017
Problem: P.M. service ,tire pressure light on,mount ladder stop in middle.

Work Completed

- P.m. Service.
- Replace one defective Tpms.rotate and balance tires.retrain sensors.
- Install stop on ladder rack.(parts n/c.)
- Transport vehicle to dealer for leaking differential and driver door hard to close.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade - Accufit - Passenger's Side	1.00
Washer Fluid Concentr	1.00
Accufit Beam	1.00
Tpms12 Sensor Tire Pr	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 8.50

Comm: 0.00

Labor: 510.00 Parts: 143.75 Total: 653.75

Work Order: 1709656 **Meter:** 16543 **In Date:** 10/03/2017 **Closed:** 10/16/2017
Problem: P.M. service and tie light on.

Work Completed

- P.m. service.
- Replace two front tires.balance and rotate all four.
- Complete front end alignment and road test.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Wiper Blade	1.00
Wiper Blade	1.00
235/65/16 Tire Hankook	2.00
235/65/16 Tire Hankook	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 8.50

Comm: 0.00

Labor: 510.00 Parts: 756.38 Total: 1,266.38

4/1/2024
2:35:49 PM

Palm Beach County Fleet Management Asset Maintenance History
10198284 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 1802904 **Meter:** 22400 **In Date:** 03/19/2018 **Closed:** 03/23/2018
Problem: P.M. service and mumming noise from rear end at 45 mph.

Work Completed

- P.m. Service.test drive for humming noise.unable to duplicate.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Napa Air Filter	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 5.00

Comm: 0.00

Labor: 300.00 Parts: 78.56 Total: 378.56

Work Order: 1810885 **Meter:** 28562 **In Date:** 10/23/2018 **Closed:** 10/31/2018
Problem: P.M. service recalls 17S15 and 17S34 .

Work Completed

- P.m. service.
- Replace all four tires . Nitrogen fill and high speed balance all four tires.
- Resurface rear rotors . Replace rear brake pads and service calipers . Flush and bleed brake system . Road test.
- Complete front end alignment and road test.
- Transport to and from dealer for recalls 17s15 and 17s34 .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Used Fire X Refurbished	1.00
235/65/16 Tire Hankook	4.00
Brk Fluid Dot 4-12oz	1.00
Brake Pad	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 14.50

Comm: 0.00

Labor: 971.50 Parts: 1,194.59 Total: 2,166.09

4/1/2024
2:35:49 PM

Palm Beach County Fleet Management Asset Maintenance History
10198284 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 1904120 **Meter:** 31710 **In Date:** 04/16/2019 **Closed:** 04/29/2019
Problem: P.M. service.

Work Completed

- P.m. service.
- Check battery and charging system after fully charging battery . Battery failed load test . R&r defective battery .
- Check and replace defective trailer plug connector . Rewire as needed.
- Balance and rotate all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	1.00
Wiper Blade	1.00
Ford Triton Pvc Swc	1.00
2pc Hd Mat Set Blk	3.00
Battry Motorcraft	1.00
trailer plug	1.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 469.00

Parts: 376.11

Total: 845.11

Work Order: 1910404 **Meter:** 34127 **In Date:** 10/08/2019 **Closed:** 10/24/2019
Problem: P.M. service and fuel door broken .

Work Completed

- P.m. service.
- R&r broken fuel door assembly .
- Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Housing	1.00
Door Fuel	1.00
Shop Supplies	1.00

Hours: 5.80

Comm: 0.00

Labor: 423.40

Parts: 158.59

Total: 581.99

Work Order: 2001328 **Meter:** 37804 **In Date:** 02/06/2020 **Closed:** 02/18/2020
Problem: Towed in for stall and crank but no start.

Work Completed

- Computer diagnose no start . No codes . Perform fuel pressure test . Test fuel pump circuit . R&r defective fuel pump driver module Retest .
- Shop Supplies

Parts Issued

Quantity

Fuel Pump Module	1.00
Shop Supplies	1.00

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 67.78

Total: 177.28

4/1/2024
2:35:49 PM

Palm Beach County Fleet Management Asset Maintenance History
10198284 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 2107651 **Meter:** 55012 **In Date:** 06/10/2021 **Closed:** 07/14/2021
Problem: Damage to right rear body panel, tail lamp assembly, door & hinges, rear bumper.

Work Completed

- Damage to right rear body panel, tail lamp assembly, door & hinges, rear bumper.

Hours: 0.00 Comm: 3,515.63 Labor: 0.00 Parts: 0.00 Total: 3,515.63

Work Order: 2108334 **Meter:** 55358 **In Date:** 08/02/2021 **Closed:** 08/05/2021
Problem: back tire got one nail

Work Completed

Parts Issued	Quantity
Shop Supplies	1.00

- Tire Repair
- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Work Order: 2109604 **Meter:** 57282 **In Date:** 09/02/2021 **Closed:** 09/15/2021
Problem: PM Service. Recall 19S38.

Work Completed

Parts Issued	Quantity
Wiper Blade	1.00
Wiper Blade	1.00
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Napa Air Filter	1.00
Used Fire X Refurbished	1.00
Cabin Air Filter	1.00
Latch Asm	1.00
Shop Supplies	1.00

- Preventive Maint. Service
- Test and replace right rear door lower latch assembly . Retest operation .
- check,replaced cabin a/c filter and refresh intake air
- balance and rotate all 4 tires
- computer diag codeb1b44,b1b46,b1b48 &b1b50 pin point test ,reomoved rear bumper,repair damaged wires from prior body bamaged,clear light,and verify normal operation
- Transport to and from dealer for recall 19s38 and 20b563
- Shop Supplies

Hours: 12.30 Comm: 0.00 Labor: 897.90 Parts: 214.35 Total: 1,112.25

4/1/2024
2:35:49 PM

Palm Beach County Fleet Management Asset Maintenance History
10198284 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 2209673

Meter: 68626

In Date: 09/16/2022 **Closed:** 10/03/2022

Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Left Rear Tail Light Cracked With Water In Light R&r Tail Light And Retest, License Plate Light Bulb Burnt R&r Light Bulb And Retest
- R&r Cabin Air Filter And Clean Fresh Air Intake
- Rotate And Balance Tires With Nitro Fill
- Inspected Rear Brakes Pads At Minmum Deapth R&r Brake Pads, Rotors, Bleed And Service Calipers Road Test .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Used Fire X Refurbished	1.00
Boxed Miniatures	1.00
Air Refresh- Black	1.00
Cabin Filter A/c	1.00
Gasket	1.00
Non-chlor Brake Clnr	1.00
Permatex	1.00
Brake Fl-dot 3-4 32oz	1.00
Rotor Rear	2.00
Brake Pad	1.00
Lamp Assy	1.00
Shop Supplies	1.00

Hours: 10.30

Comm: 0.00

Labor: 751.90

Parts: 626.52

Total: 1,378.42

4/1/2024
2:35:49 PM

Palm Beach County Fleet Management Asset Maintenance History
10198284 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 2308881 **Meter:** 78851 **In Date:** 08/31/2023 **Closed:** 09/11/2023
Problem: PM Service .

Work Completed

- Preventive Maint. Service
- R & i two new on font, Rotate and speed balance, nitro fill
- Shop Supplies

Parts Issued

Quantity

Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Used Fire X Refurbished	1.00
235/65/16 Tire Gooyer	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 6.00 Comm: 0.00

Labor: 438.00 Parts: 427.19 Total: 865.19

Work Order: 2400116 **Meter:** 83002 **In Date:** 01/04/2024 **Closed:** 01/05/2024
Problem: key fob inop

Work Completed

- Test and replace battery in key fob and retest .

Hours: 0.30 Comm: 0.00

Parts Issued

Quantity

Enr Elect Battery	1.00
-------------------	------

Labor: 21.90 Parts: 6.75 Total: 28.65

Work Order: 2402696 **Meter:** 84797 **In Date:** 03/15/2024 **Closed:** 03/21/2024
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 143.25

Total Labor: 9,886.25

Total Comm: 3,611.63

Total Parts: 6,981.55