# Palm Beach County Fleet Management Asset Maintenance History 10202151 2017 FORD F150 Pickup, 1/2 Ton

Total Hours: 135.45	Parts: 5,277.80	Comm: 747.06	Charge	ed: 15653.16
Work Order: 1700392 Me Problem: 1061 - Pre Delivery Inspec	ter: 305		In Date: 01/12/201	7 <b>Closed:</b> 01/12/201
Work Completed				
- Pre Delivery Inspection				
Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.00	Total: 120.00
Work Order: 1706284 Me Problem: P.M. Service.Relocate exti	<b>ter:</b> 363 nguisher		In Date: 06/26/201	7 <b>Closed:</b> 06/30/201
Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		7.00
- R&r extinguisher and mount behind	seat.	Napagold Oil Filter		1.00
- Rotate and balance tires.		Washer Fluid Conc	entr	1.00
- Shop Supplies		Stg Wheel Cov - Fo	ord	1.00
		Floor Mat-2pc Rub	Bk	1.00
		Shop Supplies		1.00
Hours: 3.50	Comm: 0.00	Labor: 210.00	Parts: 66.95	Total: 276.95
Work Order: 1707904 Me Problem: Trailer warning signals who	ter: 516 en braking.		In Date: 08/11/201	7 <b>Closed:</b> 08/16/201
Work Completed		Parts Issued		Quantity
- Check and replace defective trailer p	lug connector six pin.	trailer plug		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 1.25	Comm: 0.00	Labor: 75.00	Parts: 13.10	Total: 88.10
Work Order: 1710350 Me Problem: Replace noisy wipers.	ter: 853		In Date: 10/20/201	7 <b>Closed:</b> 10/25/201
Work Completed		Parts Issued		Quantity
- Replace wiper blades because of noi	se and dry rotted.	22" Wiper Blade		2.00
Hours: 0.20	Comm: 0.00	Labor: 12.00	Parts: 6.78	Total: 18.78

# Palm Beach County Fleet Management Asset Maintenance History 10202151 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 1712241 Meter: 1106 In Date: 12/13/2017 Closed: 12/19/2017

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		7.00
- Rotate and balance all four tires.nitrogen filled tires.		Napagold Oil Filte	r	1.00
- Shop Supplies		Washer Fluid Cond	centr	1.00
		Used Fire X Refurb	ished	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 36.20	Total: 216.20

Work Order: 1806209 Meter: 1421 In Date: 06/18/2018 Closed: 06/25/2018

Problem: P.M. Service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Napagold Oil Filter		1.00
- Rotate and balance tires.		5w20 Engine Oil		6.00
- Shop Supplies		22" Wiper Blade		2.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 25.21	Total: 205.21

Work Order: 1811609 Meter: 6690 In Date: 11/13/2018 Closed: 11/19/2018

**Problem:** P.M. service, Check battery and spare on vehicle.

Work Completed	Parts Issued	Quantity
- P.m. service.	Napagold Oil Filter	1.00
- Charge battery fully . Test battery and charging system . Battery failed load	Napa Quart 5w20	7.00
test . R&r defective battery .	22" Wiper Blade	2.00
- Repair right rear tire and remount spare . Rotate and balance all four tires.	Washer Fluid Concentr	1.00
Nitrofill all.	Used Fire X Refurbished	1.00
- Shop Supplies	Battry Motorcraft	1.00
	Shop Supplies	1.00
Hours: 5.00 Comm: 0.00	Labor: 335.00 Parts: 236.19	Total: 571.19

### Palm Beach County Fleet Management Asset Maintenance History 10202151 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 1812175 Meter: 7229 In Date: 11/29/2018 Closed: 11/29/2018

Problem: 3 - Wash ticket(s) issued

**Work Completed** 

- 3 - Wash ticket(s) issued

Hours: 0.00 Comm: 28.62 Labor: 0.00 Parts: 0.00 Total: 28.62

Work Order: 1901565 Meter: 11837 In Date: 02/11/2019 Closed: 02/20/2019

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	er	1.00
- Rotate and balance all four tires . Nitrofill all.		5w20 Engine Oil		7.00
- Shop Supplies		Washer Fluid Con	centr	1.00
		22" Wiper Blade		2.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 201.00	Parts: 31.94	Total: 232.94

Work Order: 1904940 Meter: 17185 In Date: 05/07/2019 Closed: 05/16/2019

**Problem:** P.M. service and detail.

- P.m. service.       Napagold Oil Filter       1.00         - Rotate and high speed balance all four tires . Nitrofill all.       5w20 Engine Oil       6.00         - Shop Supplies       22" Wiper Blade       2.00         Shop Supplies       1.00         Hours: 3.00       Comm: 0.00       Labor: 201.00       Parts: 27.90       Total: 228.90	Work Completed		Parts Issued		Quantity
- Shop Supplies 22" Wiper Blade 2.00 Shop Supplies 1.00	- P.m. service.		Napagold Oil Filte	er	1.00
Shop Supplies 1.00	- Rotate and high speed balance all four tires . I	Nitrofill all.	5w20 Engine Oil		6.00
	- Shop Supplies		22" Wiper Blade		2.00
Hours: 3.00 Comm: 0.00 Labor: 201.00 Parts: 27.90 Total: 228.90			Shop Supplies		1.00
	Hours: 3.00	Comm: 0.00	Labor: 201.00	Parts: 27.90	Total: 228.90

Work Order: 1905197 Meter: 17107 In Date: 05/14/2019 Closed: 05/14/2019

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

**Work Completed** 

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

### Palm Beach County Fleet Management Asset Maintenance History 10202151 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 1907666 Meter: 21628 In Date: 07/24/2019 Closed: 07/25/2019

**Problem:** Tire light on, Check wiper blades.

Work CompletedParts IssuedQuantity- Test and replace defective wiper blades and clean bugs from windshield .22" Wiper Blade2.00- Repair left rear tire and balance . Nitrofill all.Shop Supplies1.00

- Shop Supplies

Hours: 1.20 Comm: 0.00 Labor: 80.40 Parts: 9.96 Total: 90.36

Work Order: 1908066 Meter: 22490 In Date: 08/05/2019 Closed: 08/15/2019

**Problem:** PM Service, Detail.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Rotate and balance all four tires . Nitrofill all.		5w20 Engine Oil		6.00
- Shop Supplies		22" Wiper Blade		2.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 201.00	Parts: 30.89	Total: 231.89

Work Order: 1908445 Meter: 22489 In Date: 08/13/2019 Closed: 08/13/2019

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

#### **Work Completed**

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

### Palm Beach County Fleet Management Asset Maintenance History 10202151 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 1912616 Meter: 29629 In Date: 12/10/2019 Closed: 12/18/2019

Problem: PM Service, Detail.

Work Completed		Parts Issued		Quantity
- P.m. service .		Napagold Oil Filte	r	1.00
- Rotate and high speed balance all four tires . Nitrofi	ll all.	5w20 Engine Oil		6.00
- Shop Supplies		22" Wiper Blade		2.00
		Napagold Air Filte	er	1.00
		Ford Triton Pvc Sw	/C	1.00
		Used Fire X Refurb	ished	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 219.00	Parts: 77.01	Total: 296.01

Work Order: 2001949 Meter: 34557 In Date: 02/26/2020 Closed: 03/02/2020

**Problem:** P.M. service, left rear tire going flat and detail.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Repair left rear tire . Rotate and balance all four	r tires . Nitrofill all.	5w20 Engine Oil		7.00
- Shop Supplies		22" Wiper Blade		2.00
		Washer Fluid Cond	centr	1.00
		Shop Supplies		1.00
Hours: 4.00	Comm: 0.00	Labor: 292.00	Parts: 36.37	Total: 328.37

Work Order: 2002119 Meter: 34472 In Date: 02/28/2020 Closed: 02/28/2020

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

#### **Work Completed**

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

#### Palm Beach County Fleet Management Asset Maintenance History 2017 FORD F150 Pickup, 1/2 Ton 10202151

Work Order: 2006311 Meter: 39760 In Date: 06/25/2020 **Closed**: 07/02/2020

Problem: PM Service, Check drivers side front tire for screw.Recall

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	er	1.00
- Replace cabin air filter and clean fresh air inta	ake . Replace broken glove	5w20 Engine Oil		7.00
box stop.		22" Wiper Blade		2.00
- Rotate and balance all four tires . Nitrofill all	and inspect for screw .	Washer Fluid Con	centr	1.00
- Transport to and from dealer for recalls 17s3	3 and 18s27 .	Cabin Air Filter		1.00
- Shop Supplies		Retainer Glove		1.00
		Shop Supplies		1.00
Hours: 5.50	Comm: 0.00	Labor: 401.50	Parts: 91.54	Total: 493.04

Work Order: 2009448 Meter: 45129 09/18/2020 **Closed:** 09/29/2020 In Date:

Problem: PM Service, Check GPS connection. Nails in two tires.

Work Completed	Parts Issued	Quantity
- P.m. service.	5w20 Engine Oil	7.00
- Replace all four tires and balance . Nitrofill all.	22" Wiper Blade	2.00
- Test and replace defective strobe light switch . Computer diagnose door	Washer Fluid Concentr	1.00
ajar light staying on . R&r left front door panel to replace latch assembly .	245/70/17 Tire Mich	4.00
Retest . Inspect Gps connection and install tie strap . Retest .	Universal Switch	1.00
- Perform complete front end alignment and road test .	Latch	1.00
- Shop Supplies	Napagold Oil Filter	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00

Hours: 9.20 Total: 1,720.40 Comm: 0.00 Labor: 671.60 Parts: 1,048.80

# Palm Beach County Fleet Management Asset Maintenance History 10202151 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2012996 Meter: 51240 In Date: 12/31/2020 Closed: 01/07/2021

Problem: P.M. Service

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filte	er	1.00
- Rotate and Balance all four wheels and tires. Nitrogen fill all t	ires and reset	5w20 Engine Oil		7.00
Tpms.		Washer Fluid Con	centr	1.00
- Shop Supplies		22" Wiper Blade		2.00
		Used Fire X Refurb	oished	1.00
		Napagold Air Filt	er	1.00
		Shop Supplies		1.00
Hours: 3.00 Com	m: 0.00	Labor: 219.00	Parts: 61.57	Total: 280.57

Work Order: 2103530 Meter: 56830 In Date: 03/29/2021 Closed: 04/08/2021

Problem: P.M. Service

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filter		1.00
<ul> <li>Check all brakes, R &amp; I new front and rear brake pads. Resurface all four rotors, service caliper slide pins, bleed brakes &amp; road test</li> <li>Rotate and speed balance all four, nitro fill</li> <li>Shop Supplies</li> </ul>		5w20 Engine Oil		7.00
		22" Wiper Blade		2.00
		Washer Fluid Concentr		1.00
		Non-chlor Brake Clnr		1.00
		Brk Fluid Dot 4-12oz		1.00
		Brake Pad		1.00
		Brake Pad		1.00
		Shop Supplies		1.00
Hours: 10.00 Co	mm: 0.00	Labor: 730.00	Parts: 200.11	Total: 930.11

## Palm Beach County Fleet Management Asset Maintenance History 10202151 2017 FORD F150 Pickup, 1/2 Ton

 Work Order:
 2107212
 Meter:
 62579
 In Date:
 07/01/2021
 Closed:
 07/09/2021

Work Completed		Parts Issued		Quantity
<ul><li>Preventive Maint. Service</li><li>Charge battery fully . Test battery and charging system . R&amp;r defective</li></ul>		Napagold Oil Filter  5w20 Engine Oil		1.00
				6.00
battery . Hook up lds to reset Bsm				2.00
<ul> <li>R&amp;r Broken Right Rear Tail Light, Drill For Strobe Light</li> <li>Balance And Rotate All four Tires With Nitro Fill</li> <li>Test Drive And Perform Front End Alignment And Retest</li> <li>Shop Supplies</li> </ul>		Washer Fluid Concentr  Battery  Drain Plug  Battry Motorcraft		1.00
				1.00
				1.00
				1.00
		Lamp Assy		1.00
		Shop Supplies		1.00
Hours: 7.80	Comm: 0.00	Labor: 569.40	Parts: 356.49	Total: 925.89

Work Order: 2109410 Meter: 66310 In Date: 08/30/2021 Closed: 08/30/2021

Problem: low drivers side tire

Work Completed	Parts Issued	Quantity
- Repair Left Front Tire Flat, Mount And Balance.	Shop Supplies	1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Work Order: 2111376 Meter: 68670 In Date: 10/22/2021 Closed: 10/28/2021

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filte	r	1.00
- rotate and balance all 4 tires nitro fill all		5w20 Engine Oil		7.00
- Shop Supplies		22" Wiper Blade		2.00
		Used Fire X Refurb	pished	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 219.00	Parts: 44.26	Total: 263.26

## Palm Beach County Fleet Management Asset Maintenance History 10202151 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2201187 Meter: 74718 In Date: 02/02/2022 Closed: 02/09/2022

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Performed P.m. Service & Inspection.		5w20 Engine Oil		7.00
- Performed Flat Repair On Both Passenger S	Side Tires Then Balance And	Napagold Oil Filter		1.00
Rotate All 4 Tires.		Washer Fluid Concentr		1.00
- Check Engine Light On, Plug In Scan Tool, Found Fault Code P		22" Wiper Blade		2.00
Proceed With Test Plan, Found Coolant Temp Leaking. R & R W-pump, T-stat, Temp Sensor	•	V Belt		1.00
System & Check, Test Drive.	A/C & Drive Beil. Pressure rest	V Belt		1.00
- Performed Tune-up, Removed Intake & Re	place All 6 Spark Plugs.	Gasket		1.00
- Performed Decarb Service & Fuel Injection		Anti Freeze Motorcr	aft	2.00
Body And Clean.	<i>J</i> ,	Connection Assy	1.00	
- Removed And Replaced Cabin Air Filter. Clo	ean A/c Vents & Check.	Water Pump		1.00
- Shop Supplies		Tep Sensor		1.00
		Gasket		6.00
		Gasket		2.00
		Gasket		1.00
		Spark Plugs		6.00
		Motor Tune-up 16o	Z	1.00
		Intake Cleaner Kit		1.00
		Cabin Filter		1.00
		Throttle Body Clean	er	1.00
		Shop Supplies		1.00
Hours: 16.00	Comm: 0.00	Labor: 1,168.00	Parts: 526.14	Total: 1,694.14
Mark Ordar: 2202006	Motor: 77210		In Data: 02/19/202	22 Closed: 02/21/2022

Work Order: 2202996 Meter: 77310 In Date: 03/18/2022 Closed: 03/21/2022

Problem: right rear tire has screww in it

Work Completed		Parts Issued		Quantity
- Repair right rear tire, balance and nitro service		Shop Supplies		1.00
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 2.65	Total: 75.65

### Palm Beach County Fleet Management Asset Maintenance History 10202151 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2203849 Meter: 79066 In Date: 04/11/2022 Closed: 04/25/2022

Problem: Left front flat tire and nail left rear

Work Completed Parts Issued Quantity
- Repair left front and rear tire . Balance both . Nitro fill all and reset Tpms . Shop Supplies 1.00

- Shop Supplies

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 2.65 Total: 148.65

Work Order: 2204944 Meter: 81386 In Date: 05/06/2022 Closed: 05/16/2022

Problem: PM Service. Wipers

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Oil Filter	2.00
- Replaced 2 tires. Rotated and balanced all 4 tires. Nitrogen filled	all tires. 5w20 Engine Oil	7.00
- Shop Supplies	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	White Lithium Grease	1.00
	245/70/17 Tire Mich	2.00
	Washer Fluid Concentr	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 4.00 Comm: 0	.00 Labor: 292.00 Parts	: 504.86 Total: 796.86

Work Order: 2208786 Meter: 85626 In Date: 08/22/2022 Closed: 08/29/2022

Problem: PM Service and cracked windshield

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		5w20 Engine Oil		7.00
- rotate and balance all 4 tire nitro fill all		Napagold Oil Filte	er	1.00
- Shop Supplies		22" Wiper Blade		2.00
		Washer Fluid Con-	centr	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 219.00	Parts: 37.84	Total: 256.84

Hours: 6.50

#### Palm Beach County Fleet Management Asset Maintenance History 10202151 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2208941 Meter: 85625 08/25/2022 **Closed:** 08/30/2022 In Date: Problem: replace cracked windshield **Parts Issued Work Completed** Quantity **Shop Supplies** 1.00 - set up repairs & reasset - Shop Supplies Hours: 1.00 Comm: 430.44 Labor: 73.00 Parts: 2.65 Total: 506.09 Work Order: 2209194 Meter: 85919 In Date: 09/01/2022 **Closed:** 09/06/2022 Problem: flat tire **Parts Issued** Quantity **Work Completed** 245/70/17 Tire Mich 1.00 - Replace blown out left rear tire, balance and nitro service **Shop Supplies** 1.00 - Shop Supplies Tire Disposal Fee 1.00 Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 228.34 Total: 264.84 Work Order: 2210809 In Date: Meter: 89882 10/24/2022 Closed: 10/24/2022 Problem: leaky tire Right front tire flat .spare on vehicle . **Work Completed Parts Issued** Quantity **Shop Supplies** 1.00 - Repair right front tire and balance . Nitro fill all. Remount spare under vehicle. - Shop Supplies Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65 Work Order: 2211602 Meter: 91527 **In Date:** 11/16/2022 **Closed:** 11/28/2022 Problem: PM Service. **Work Completed Parts Issued** Quantity Napagold Oil Filter 1.00 - Preventive Maint, Service 5w20 Engine Oil 7.00 - mount 2 rotate and balance all 4 tires nitro fill all Washer Fluid Concentr 1.00 - peform front end alignment 245/70/17 Tire Mich 2.00 - Shop Supplies **Shop Supplies** 1.00 Tire Disposal Fee 2.00

Comm: 0.00

Labor: 474.50

Parts: 421.17

Total: 895.67

### Palm Beach County Fleet Management Asset Maintenance History 10202151 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2212764 Meter: 93571 In Date: 12/21/2022 Closed: 12/21/2022

Problem: right rear tire flat

Work CompletedParts IssuedQuantity- Repair right rear tire and balance . Nitro fil all.Shop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Work Order: 2301450 Meter: 97455 In Date: 02/14/2023 Closed: 02/21/2023

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napa Quart 5w20		7.00
- rotate and balance all 4 tires nitro fill all		Napagold Oil Filte	r	1.00
- Shop Supplies		Washer Fluid Cond	centr	1.00
		22" Wiper Blade		2.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 219.00	Parts: 45.54	Total: 264.54

Work Order: 2304432 Meter: 103961 In Date: 05/03/2023 Closed: 05/12/2023

Problem: P.M. Service, under a load the drive train vibrates between shifting only sparaticaly

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filter		1.00
- Rotate and speed balance, nitro fill	e and speed balance, nitro fill			7.00
<ul> <li>Perform Ids diagnoses check for codes, none, Perform trans flush &amp; filter change, Reset trans adaptive shifts &amp; , Road test</li> <li>Check and replace cabin filter and clean fresh air intake</li> <li>Shop Supplies</li> </ul>		Washer Fluid Concentr		1.00
		22" Wiper Blade		2.00
		Used Fire X Refurbished  Screen Asy oil auto		1.00
				1.00
				14.00
		Shop Supplies		1.00
Hours: 6.00	Comm: 0.00	Labor: 438.00	Parts: 191.65	Total: 629.65

# Palm Beach County Fleet Management Asset Maintenance History 10202151 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2309220 Meter: 110699 In Date: 09/12/2023 Closed: 09/21/2023

Problem: PM Service

Work Completed		Parts Issued		Quantity
- Performed P.m. Service & Inspection.		Oil Filter		1.00
- Performed Tire Rotation Balance On All 4 Wheels, Add Nitro Fill Reset		5w20 Engine Oil		7.00
Tpms.		22" Wiper Blade		2.00
- Front Brake Pads Were Below Manufac Specs, Removed & Replaced Both		Napagold Air Filte	er	1.00
Front Brake Pads, Rotors & Calipers. Then Bleed A System. Test Drove Vehicle And Burnish Brakes.	eck Power & Ground. Power & Ground Ok, Found			1.00
			Bracketed Caliper	
- Strobe Light Mop, Check Power & Ground, Pow Switch Defective, Removed & Replaced Then Che				2.00
- Shop Supplies	3	Brake Pad Brake Fl-dot 3-4 32oz Non-chlor Brake Clnr		1.00
1 11				1.00
				1.00
		Led Rocker Switch Round		1.00
		Shop Supplies		1.00
Hours: 7.00	Comm: 0.00	Labor: 511.00	Parts: 328.82	Total: 839.82

Work Order: 2311747 Meter: 115225 In Date: 11/27/2023 Closed: 12/04/2023

Problem: leaking driver side tire and right front not reading

Work Completed		Parts Issued		Quantity
- Test Tpms system . Replace both front Tpms sensors and repair left front tire . Nitro fill all and balance . Retrain Tpms sensors.		Tpms Sens Kit		2.00
		Shop Supplies		1.00
- Shop Supplies				
Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 112.94	Total: 258.94

#### **Palm Beach County Fleet Management Asset Maintenance History** 10202151

2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2312126 **Meter:** 116033 In Date: 12/06/2023 **Closed:** 12/15/2023

Problem: PM Service

<ul><li>Work Completed</li><li>- Preventive Maint. Service</li><li>- Rotate and balance four tires. Relearn tire sensors.</li></ul>		Parts Issued  5w20 Engine Oil  Napagold Oil Filter		Quantity
				1.00
Wiper Blade		2.00		
Silicone Spray 10oz		1.00		
245/70/17 Tire Mich Drain Plug		2.00		
		1.00		
		Shop Supplies		1.00
		Tire Disposal Fee		0.00
Hours: 3.00	Comm: 0.00	Labor: 219.00	Parts: 463.35	Total: 682.35
Verla Ordena 0404040	oton: 440077		In Data - 04/00/00	004 <b>Classel</b> : 04/20/2002

Work Order: 2401019 **Meter:** 119277 In Date: 01/29/2024 Closed: 01/30/2024

Comm: 0.00

**Problem:** Please check the GPS connections

#### **Work Completed**

- Unplug Gps and check connection. Refasten.

Hours: 0.30

Work Order: 2402133 **Meter:** 121704 In Date: 02/28/2024 Closed:

Labor: 21.90

Parts: 0.00

Total: 21.90

Problem: PM Service

#### **Work Completed**

- Preventive Maint. Service

Comm: 0.00 Hours: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 2402361 **Meter:** 121704 **In Date:** 03/05/2024 **Closed:** 03/07/2024

Problem: Transition Prep Charge

#### **Work Completed**

- Transition Prep Charge

Hours: 3.50 Comm: 0.00 Labor: 255.50 Parts: 0.00 Total: 255.50

Total Parts: 5,277.80 Total Hours: 135.45 Total Labor: 9,628.30 Total Comm: 747.06