Palm Beach County Fleet Management Asset Maintenance History 10179130 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Total Hours: 147.5	0 Labor: 9,591	.00	Parts: 7,137.25	Comm: 8,555.63		Charged	25283.88	
Work Order: 938 ⁻ Problem: PRE	152 E-DELIVERY INSF	Meter: PECTION			In Date:	05/26/2009	Closed:	05/26/2009
Work Complete	ed							
- Pre-delivery Ir	nspection							
	Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: 1000 Problem: P.M		Meter:	4537		In Date:	01/26/2010	Closed:	02/04/2010
Work Complete	ed			Parts Issued			Qı	ıantity
- P.m service.				Shop Supplies				1.00
- Rotate & bala	nce all four tires.			1372 Oil Filter Frm	n Ph2 Wix 51	372		1.00
- Shop Supplies	;			5w20 Engine Oil				7.00
				Used Firex Refurbed	d Fire Extings	hers		1.00
	Hours: 3.75		Comm: 0.00	Labor: 225.00	Parts: 31.	.08	Total:	256.08
Work Order: 1008 Problem: Pm		Meter:	8567		In Date:	08/02/2010	Closed:	08/09/2010
Work Complete	ed			Parts Issued			Qı	ıantity
- Perform pm se	ervice.			Shop Supplies				1.00
•	front tire and bala	ance all fo	our.	1372 Oil Filter Frm	n Ph2 Wix 51	372		1.00
- Shop Supplies				5w20 Engine Oil				7.00
				31-20 Wiper Blades	20" Blade			2.00
				7090blk Frt Floor M	lats (rubber (Queen)		1.00
	Hours: 4.75		Comm: 0.00	Labor: 285.00	Parts: 87.	.25	Total:	372.25
Work Order: 1008 Problem: refla	8444 ish canceiver	Meter:	8567		In Date:	08/05/2010	Closed:	08/09/2010
Work Complete	ed			Parts Issued			Qı	ıantity
- Reflash Cance	iver			Shop Supplies				1.00
- Shop Supplies	;							
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0			62.00

Palm Beach County Fleet Management Asset Maintenance History 10179130 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1102352 Problem: Pm service.	Meter:	13021		In Date:	03/02/2011	Closed:	03/10/2011
Work Completed			Parts Issued			Qı	uantity
- Perform pm service.			Shop Supplies				1.00
- Rotate and balance all four tires.			1372 Oil Filter Fri	m Ph2 Wix 51	372		1.00
- Shop Supplies			Ca10262 Air Filter	Mtc Fa1883 W	/ix 49883		1.00
			5w20 Engine Oil				7.00
			31-22 Wiper Blade	es 22" Wiper B	lade		2.00
			Used Firex Refurbe	ed Fire Extings	hers		1.00
Hours: 3.75		Comm: 0.00	Labor: 225.00	Parts: 46.	86	Total:	271.86
Work Order: 1110410 Problem: P.M. Service.	Meter:	18077		In Date:	09/29/2011	Closed:	10/06/2011
Work Completed			Parts Issued			Qı	uantity
- P.m. Service.			Shop Supplies				1.00
- Rotate and balance tires.			1372 Oil Filter Fri	m Ph2 Wix 51	372		1.00
- Shop Supplies			5w20 Engine Oil				7.00
			31-20 Wiper Blade	es 20" Blade			2.00
Hours: 3.75		Comm: 0.00	Labor: 225.00	Parts: 31.	99	Total:	256.99
Work Order: 1204009 Problem: Pm service	Meter:	22501		In Date:	04/27/2012	Closed:	05/07/2012
Work Completed			Parts Issued			Qı	uantity
- Perform pm service.			Shop Supplies				1.00
- Rotate and balance all four tires.			1372 Oil Filter Fri	m Ph2 Wix 51	372		1.00
- Shop Supplies			5w20 Engine Oil				7.00
			31-22 Wiper Blade	es 22" Wiper B	lade		2.00
			Used Firex Refurbe	ed Fire Extings	hers		1.00
Hours: 3.75		Comm: 0.00	Labor: 225.00	Parts: 46.	13	Total:	271.13

Palm Beach County Fleet Management Asset Maintenance History 10179130 2009 FORD F150 Pickup, 1/2 Ton, 4X4

 Work Order:
 1301024
 Meter:
 28187
 In Date:
 01/29/2013
 Closed:
 02/07/2013

 Problem:
 Pm service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		7.00
- Rotate and balance all tires.		1372 Oil Filter		1.00
- Shop Supplies	Shop Supplies 31-22 Wiper Blades 22		es 22	2.00
		Shop Supplies		1.00
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 39.37	Total: 264.37

Work Order: 1307691 Meter: 32617 In Date: 08/01/2013 Closed: 08/20/2013

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Tpms Kit		1.00
- Test battery and charging system.replace bad b	pattery.	5w20 Engine Oil Napagold Oil Filter		7.00
- Replace one defective tire pressure sensor,rotat	te and balance all four tires.			1.00
- Shop Supplies		Wiper Blade		2.00
		Washer Fl		1.00
		Battery		1.00
		Shop Supplies		1.00
Hours: 5.75	Comm: 0.00	Labor: 345.00	Parts: 216.02	Total: 561.02

Work Order: 1401882 Meter: 36523 In Date: 02/26/2014 Closed: 03/11/2014

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- Perform pm service		5w20 Engine Oil Napagold Oil Filter		6.00
- Rotate and balance all four tires.				1.00
- Install new front brake pads and resurface both	Napagold Air Filter		1.00	
calipers and flush brake fluid.automated bleed hy	calipers and flush brake fluid.automated bleed hydraulic system with scan			1.00
- Shon Supplies		Ceramic Brake Lube Shop Supplies		1.00
				1.00
Hours: 7.75	Comm: 0.00	Labor: 465.00	Parts: 117.40	Total: 582.40

Palm Beach County Fleet Management Asset Maintenance History 10179130 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1409082 Meter: 41104 In Date: 09/09/2014 Closed: 09/22/2014

Problem: Pm service and request to detail vehicle.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		6.00
- Replace and balance four new tires.		Napagold Oil Filte	r	1.00
- Complete wheel alignment.test drive.		Napagold Air Filte	er	1.00
- Shop Supplies		Used Fire X Refurb	ished	1.00
		Brake Cleaner		1.00
		235 75r17 Advent	ure	4.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 7.25	Comm: 0.00	Labor: 435.00	Parts: 1,011.37	Total: 1,446.37

Work Order: 1409484 Meter: 41104 In Date: 09/22/2014 Closed: 09/22/2014

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 97.92 Labor: 0.00 Parts: 0.00 Total: 97.92

Work Order: 1502927 Meter: 42968 In Date: 03/20/2015 Closed: 03/31/2015

Problem: Pm service.

Work Completed		Parts Issued	Quantity
- Pm service.		5w20 Engine Oil	7.00
- Perform transmission flush service.	Napagold Oil Filter		1.00
- Perform transfer case service.		Wiper Blade	2.00
- Rotate and balance all four tires.		Mac Wite Lithium Gres	1.00
- Shop Supplies		Syn-atf Trans Fluid S	14.00
		Ford Transfer Case Fluid	2.00
	Shop Supplies		1.00
Hours: 6.25	Comm: 0.00	Labor: 375.00 Parts: 120.22	Total: 495.22

Palm Beach County Fleet Management Asset Maintenance History 10179130 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1508327 Meter: 44316 In Date: 08/19/2015 Closed: 08/25/2015

Problem: A/C inop

Work Completed	Parts Issued	Quantity
- Ac performance test.diagnose ac blower inop.replace defective relay.retest	Relay	1.00
	Shop Supplies	1.00

- Shop Supplies

Hours: 1.25 Comm: 0.00 Labor: 75.00 Parts: 31.52 Total: 106.52

Work Order: 1511673 Meter: 44655 In Date: 11/16/2015 Closed: 11/23/2015

Problem: Pm service.

Work Completed		Parts Issued		Quantity
- Pm service.		5w20 Engine Oil		7.00
- Rotate and balance all four wheels.		Napagold Oil Filte	r	1.00
- Shop Supplies		Wiper Blade		2.00
		Washer Fluid Cond	centr	1.00
		Shop Supplies		1.00
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 34.87	Total: 259.87

Work Order: 1610631 Meter: 47061 In Date: 10/13/2016 Closed: 10/14/2016

Problem: Winch Out

Work Completed

- Tow From: 2450 Oswego

Hours: 0.00 Comm: 60.00 Labor: 0.00 Parts: 0.00 Total: 60.00

Palm Beach County Fleet Management Asset Maintenance History 10179130 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1610869 Meter: 47414 In Date: 10/21/2016 Closed: 10/31/2016

Problem: P.M. service and check lights and tire going flat R/F and left mirror glass broken.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		6.00
- Replace right rear signal light bulb.		Napagold Oil Filte	er	1.00
- R&r driver side door panel and replace broken mirro	Washer Fluid Cond	centr	1.00	
- Replace broken transfer case shift lever.	22" Wiper Blade Used Fire X Refurbished 4057 Bulb Coolant Ford Gold		2.00	
- Pressure test and inspect cooling system.flush and r			1.00	
- Repair right front tire, rotate and balance all four.			1.00	
- Fabricate and replace front asset #.			2.00	
- Shop Supplies		mirror asy		1.00
		Lever		1.00
		Shop Supplies		1.00
Hours: 9.75	Comm: 0.00	Labor: 585.00	Parts: 382.39	Total: 967.39

Work Order: 1707995 Meter: 51001 In Date: 08/15/2017 Closed: 08/23/2017

Problem: PM Service

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		6.00
Serviced rear differential.High speed balanced all four tires.nitro filled.		Napagold Oil Filte	r	1.00
		20" Wiper Blade		2.00
- Shop Supplies		Washer Fluid Concentr		1.00
		Napagold Air Filter Ptex Ultra Grey 3oz		1.00
				1.00
	Non-chl	Non-chlor Brake C	Inr	1.00
		Friction Modifier 75w140 Ford Axle Lube		1.00
				2.00
		Shop Supplies		1.00
Hours: 4.75	Comm: 0.00	Labor: 285.00	Parts: 111.23	Total: 396.23

Palm Beach County Fleet Management Asset Maintenance History 10179130 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1802235 Meter: 51994 In Date: 02/28/2018 Closed: 03/06/2018

Problem: P.M. service.

rk Completed Parts Issued		Quantity		
- P.m. service.		5w20 Engine Oil Napagold Oil Filter Used Fire X Refurbished 22" Wiper Blade		6.00
- Rotated and balanced all four tires.nitrogen filled a	1.00			
- Shop Supplies	1.00			
				2.00
		Shop Supplies		1.00
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 39.08	Total: 264.08

Work Order: 1806061 Meter: 52963 In Date: 06/13/2018 Closed: 06/14/2018

Problem: Left front tire low.

Work CompletedParts IssuedQuantity- Repair and balance left tire.Shop Supplies1.00

Comm: 0.00

- Shop Supplies

Work Order: 1808991 Meter: 53527 In Date: 08/30/2018 Closed: 09/10/2018

Labor: 60.00

Parts: 2.00

Total: 62.00

Problem: P.M. Service. Check engine light comes on intermittenly.

Hours: 1.00

Work Completed		Parts Issued		Quantity
- P.m. service.	service.		Napagold Oil Filter	
failed load test. R&r defective battery.		5w20 Engine Oil		6.00
		20" Wiper Blade		2.00
		Washer Fluid Concentr		1.00
- Perform computer diagnose check engine light , Code P	Battery		1.00	
Perform Pcm reprogram per Tsb 13-03-05 . Clear codes and road test.		Shop Supplies		1.00
- Shop Supplies				
Hours: 6.75	Comm: 0.00	Labor: 405.00	Parts: 143.75	Total: 548.75

Work Order: 1812138 Meter: 54452 In Date: 11/28/2018 Closed: 11/28/2018

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 134.00 Parts: 0.00 Total: 134.00

Palm Beach County Fleet Management Asset Maintenance History 10179130 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1903770 Meter: 55603 In Date: 04/08/2019 Closed: 04/15/2019

Problem: pm service

Work Completed		Parts Issued		Quantity
- Pm Service	Napagold Oil Filter		1.00	
- Tire light on- replace all 4 tire pressure monitor sensors	10w30 Motor Oil		6.00	
sensors; nitro fill - Wash		20" Wiper Blade		2.00
		Non-chlor Brake Clnr		1.00
		Tpms12 Sensor Tire Pr		4.00
Hours: 5.75	Comm: 0.00	Labor: 385.25	Parts: 327.17	Total: 712.42

Work Order: 1904129 Meter: 55603 In Date: 04/16/2019 Closed: 04/16/2019

Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.54 Labor: 0.00 Parts: 0.00 Total: 9.54

Work Order: 1909377 Meter: 58655 In Date: 09/12/2019 Closed: 09/18/2019

Problem: pm/ spare tire

Work Completed		Parts Issued		Quantity					
- Pm Service		Napagold Oil Filter		1.00					
- Repl. 4 tires, nitro, reset Tpm sensors; install spare tire u	e under	Napa 10w30 Qt		6.00					
		20" Wiper Blade Non-chlor Brake Clnr Hankook P235 75r17 Dp At		2.00 1.00 4.00					
							Tire Disposal Fee		4.00
					Hours: 5.25	Comm: 0.00	Labor: 351.75	Parts: 962.81	Total: 1,314.56

Work Order: 1912916 Meter: 59652 In Date: 12/17/2019 Closed: 12/26/2019

Problem: runs rough, slow to take off, slipping

Work Completed

- road test for complaints. no problem found

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 0.00 Total: 73.00

Palm Beach County Fleet Management Asset Maintenance History 10179130 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2002266 Meter: 60886 In Date: 03/04/2020 **Closed:** 03/20/2020 Problem: pm service **Parts Issued Work Completed** Quantity Napagold Oil Filter 1.00 - pm service 6.00 10w30 Motor Oil - replace broken right rear tail light assy 20" Wiper Blade 2.00 - rotate and balance all 4 tires Tail Ligth Ass 1.00 Hours: 4.75 Comm: 0.00 Labor: 346.75 Parts: 182.75 Total: 529.50 Work Order: 2005309 Meter: 62161 In Date: 05/27/2020 **Closed**: 05/29/2020 **Problem:** brakes dragging **Work Completed Parts Issued** Quantity B Fluid Dot 3-12oz 1.00 - replace front pads, calipers, rotors and Lf hose. bleed system Front Pads 1.00 Caliper 1.00 Caliper 1.00 2.00 Rotor 1.00 Caliper 1.00 Caliper **Brake Hose** 1.00 Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 605.24 Total: 897.24 Work Order: 2008918 Meter: 62588 09/03/2020 **Closed:** 09/15/2020 In Date: Problem: pm service **Parts Issued Work Completed** Quantity Napagold Oil Filter 1.00 - pm service 10w30 Motor Oil 6.00 - replace right front tire 20" Wiper Blade 2.00 - replace left rear tail light bulbs Non-chlor Brake Clnr 1.00

Hankook P235 75r17 Dp At

Boxed Miniatures

1.00

2.00

Palm Beach County Fleet Management Asset Maintenance History 10179130 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2012052 Meter: 63965 In Date: 12/03/2020 Closed: 12/04/2020

Problem: left front tire has nail

Work Completed

- Repair tire

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 0.00 Total: 73.00

Work Order: 2100530 Meter: 65290 In Date: 01/14/2021 Closed: 01/29/2021

Problem: brake system light on

Work CompletedParts IssuedQuantity- Diagnos Brake Syatem Warning Lights On. Code C1300 Abs Pump FailureAbs Module1.00B Fluid Dot 3-32oz2.00

Hours: 5.00 Comm: 0.00 Labor: 365.00 Parts: 1,466.99 Total: 1,831.99

Work Order: 2102306 Meter: 65871 In Date: 03/01/2021 Closed: 03/12/2021

Problem: pm service

/ork Completed		Parts Issued		Quantity
- Preventive Maint. Service	Napa Quart 5w20		6.00	
- Check charging system battery failed load test re	Napagold Oil Filter		1.00	
- Replace broken third brake light assembly		Napagold Air Filter		1.00
		22" Wiper Blade		2.00
		Used Fire X Refurbished Battery Lamp Assy		1.00
				1.00
				1.00
Hours: 4.75	Comm: 0.00	Labor: 346.75	Parts: 316.52	Total: 663.27

Work Order: 2107035 Meter: 67201 In Date: 05/07/2021 Closed: 06/28/2021

Problem: : Damage to right side of bed, cab, door front right fender & rear bumper.

Work Completed

- : Damage to right side of bed, cab, door front right fender & rear bumper.

Hours: 0.00 Comm: 6,991.20 Labor: 0.00 Parts: 0.00 Total: 6,991.20

Palm Beach County Fleet Management Asset Maintenance History 10179130 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2108230 Meter: 67488 07/29/2021 **Closed**: 08/30/2021 In Date: Problem: ac intermittent/ power point **Work Completed Parts Issued** Quantity Napagold Oil Filter 1.00 - pm service Napa Quart 5w20 6.00 - Diagnose 12 volt power point not working, check fuses, wiring, replace socket Non-chlor Brake Clnr 2.00 - Replace rear brakes rotors and pads 22" Wiper Blade 2.00 - Check intermittent ac issue, check for leaks, check freon level, a/c cooling **Soket Pawer Outlet** 1.00 down to 32 degrees Brake Pads 1.00 Brake Rotor-dih Parki 2.00 Cover 1.00 Hours: 8.75 Comm: 0.00 Labor: 638.75 Parts: 270.07 Total: 908.82 Work Order: 2201515 Meter: 68851 In Date: 02/10/2022 Closed: Problem: pm service **Work Completed** - Preventive Maint. Service Comm: 0.00 Hours: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 Work Order: 2201533 Meter: 68855 In Date: 02/10/2022 **Closed**: 02/22/2022 Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filter		1.00
- Rotate and speed balance, nitro fill		5w20 Engine Oil		6.00
		Washer Fluid Concentr 22" Wiper Blade Used Fire X Refurbished		1.00
				2.00
				1.00
		Steering Wheel Co	over Large	1.00
Hours: 3.75	Comm: 0.00	Labor: 273.75	Parts: 57.02	Total: 330.77

Palm Beach County Fleet Management Asset Maintenance History 10179130 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2209989 Meter: 69640 In Date: 09/27/2022 Closed: 10/03/2022

Problem: pm service

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napa Quart 5w20		6.00
- Ck Blower Speed 1&2 Inop. Replace Blower Resistor	or	Napagold Oil Filte	Napagold Oil Filter	
		Washer Fluid Con-	centr	1.00
		22" Wiper Blade		2.00
		Non-chlor Brake (Clnr	2.00
		High Gloss Coating Used Fire X Refurbished		1.00
				1.00
		Blower Motor Res	istor	1.00
Hours: 3.75	Comm: 0.00	Labor: 273.75	Parts: 101.44	Total: 375.19

Work Order: 2302864 Meter: 72010 In Date: 03/21/2023 Closed:

Problem: pm service

Work Completed

- Preventive Maint. Service

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 2302975 Meter: 72015 In Date: 03/23/2023 Closed: 03/28/2023

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service	Napagold Oil Filter		r	1.00
- Rotate and speed balance, nitro fill - Inspect leaking at washer tank, R & I new pump . Refill and retest		Napa Quart 5w20 Washer Fluid Concentr 22" Wiper Blade		1.00
Hours: 4.25	Comm: 0.00	Labor: 310.25	Parts: 58.54	Total: 368.79

Palm Beach County Fleet Management Asset Maintenance History 10179130 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2303640 Meter: 72015 In Date: 03/28/2023 Closed: 04/12/2023

Problem: Damage to tail gate.

Work Completed

- Damage to tail gate.

Hours: 0.00 Comm: 1,396.97 Labor: 0.00 Parts: 0.00 Total: 1,396.97

Work Order: 2309979 Meter: 72827 In Date: 09/29/2023 Closed: 10/06/2023

Problem: pm service

Parts Issued Quantity **Work Completed** Napagold Oil Filter 1.00 - Preventive Maint. Service Washer Fluid Concentr 1.00 22" Wiper Blade 2.00 Napa Quart 5w20 6.00 Comm: 0.00 Labor: 200.75 Hours: 2.75 Parts: 41.07 Total: 241.82

Work Order: 2403876 Meter: 74904 In Date: 04/19/2024 Closed:

Problem: pm service/ detail after

Work Completed

- Preventive Maint. Service

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 2404004 Meter: 74904 In Date: 04/23/2024 Closed: 04/23/2024

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 147.50 Total Labor: 9,591.00 Total Comm: 8,555.63 Total Parts: 7,137.25