

3/27/2017
3:19:34PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178723 2009 FORD EXPLORER Suv, Large, 4X4, W/Tow Pkg

Workorder: 938050 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 05/21/2009	Hours	Description
Close Date: 05/21/2009	Quantity	
- Pre-Delivery Inspection	2.00	
Parts Charge: 0.00	Labor Charge: 120.00	

Workorder: 944602 **Problem:** P.M. Service.

Meter Reading: 7662	Labor	Parts
In Date: 10/15/2009	Hours	Description
Close Date: 10/21/2009	Quantity	
- P.M Service.	4.25	10W30 MOTOR OIL 5.00
- Replace Broken R/R Tail Lamp Assembly.		1372 OIL FILTER FRM PH2 WIX 51372 1.00
- Rotate & Balance All Four Tires.		RIGHT TAIL LIGHT ASSEMBLY 1.00
- Shop Supplies		SHOP SUPPLIES 1.00
Parts Charge: 137.21	Labor Charge: 255.00	

Workorder: 1004014 **Problem:** PM service

Meter Reading: 13750	Labor	Parts
In Date: 04/19/2010	Hours	Description
Close Date: 04/23/2010	Quantity	
- P.M Service.	5.55	1372 OIL FILTER FRM PH2 WIX 51372 1.00
- Mount Fire Extingusher & Bracket.		CA9332 AIR FILTER LBF AF1695 WIX 42484 1.00
- To/From Dealer For Replacement Of Both Leaking Rear Struts.		G10166 FUEL FILTER MTC FG1083 WIX 33243 1.00
- Shop Supplies		10W30 MOTOR OIL 6.00
		SHOP SUPPLIES 1.00
		31-20 WIPER BLADES 20" BLADE 2.00
		USED FIREX REFURBED FIRE EXTINGSHERS 1.00
		CUSTOM5LB BRACKET FIREX STOCK #340060300 1.00
Parts Charge: 91.28	Labor Charge: 273.00	

Workorder: 1004570 **Problem:** 10 - Wash ticket(s) issued

Meter Reading: 13963	Labor	Parts
In Date: 05/03/2010	Hours	Description
Close Date: 05/03/2010	Quantity	
- 10 - Wash Ticket(S) Issued		
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 95.40

3/27/2017
3:19:34PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178723 2009 FORD EXPLORER Suv, Large, 4X4, W/Tow Pkg

Workorder: 1006791

Problem: Install emergency lights and P.A system.

Meter Reading: 15979 In Date: 06/29/2010	Close Date: 06/30/2010	Labor Hours	Description	Parts	Quantity
- Transport Vehicle To Vendor For Emergency Light Installation		2.00	SHOP SUPPLIES		1.00
- Shop Supplies			EMERGENCY LIGHTING SYSTEM		1.00
Parts Charge:		2,373.56	Labor Charge:		60.00
			Commercial Charge:		714.00

Workorder: 1007814

Problem: Emergency Lighting System-Installed by Vendor

Meter Reading: 16706 In Date: 07/22/2010	Close Date: 07/22/2010	Labor Hours	Description	Parts	Quantity
- Emergency Lighting System, Part & Installation					
Parts Charge:		0.00	Labor Charge:		0.00

Workorder: 1009743

Problem: P.M. service and mount power outlet and flash light ,canceiver.

Meter Reading: 19377 In Date: 09/03/2010	Close Date: 09/14/2010	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		6.25	05046 BATTERY PROTECTOR (CRC)		1.00
- Install Rechargeable Flash Light Assembly.Fabricate Wiring And Install New Power Outlet.Alter Trim Pannel For Access.			SHOP SUPPLIES		1.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			80865 FUSEHOLDER IMPERIAL 80865		1.00
- Rotate And Balance All Four Tires.			PM12701 AUX POWER SUPPLY (DYANA CHRM)		1.00
- Shop Supplies			10W30 MOTOR OIL		5.00
Parts Charge:		40.62	Labor Charge:		375.00

Workorder: 1009995

Problem: flash canceiver--spot #217

Meter Reading: 19383 In Date: 09/13/2010	Close Date: 09/15/2010	Labor Hours	Description	Parts	Quantity
- Reflash Canceiver		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:		60.00

3/27/2017
3:19:34PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178723 2009 FORD EXPLORER Suv, Large, 4X4, W/Tow Pkg

Workorder: 1101368 **Problem:** Pm service also see notes on oil service reset.wiper blades and detail vehicle.

Meter Reading: 25182	Labor	Parts		
In Date: 02/03/2011	Hours	Description	Quantity	
- Perform Pm Service.	3.75	10W30 MOTOR OIL	6.00	
- Rotate And Balance All Four Tires		BIG G DEGREASER STOCK# 485180002	1.00	
- Shop Supplies		31-13 WIPER BLADE	1.00	
		CA9332 AIR FILTER LBF AF1695 WIX 42484	1.00	
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00	
		SHOP SUPPLIES	1.00	
		1372 OIL FILTER FRM PH2 WIX 51372	1.00	
		31-20 WIPER BLADES 20" BLADE	2.00	
Parts Charge:	58.37	Labor Charge:	225.00	

Workorder: 1101498 **Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 25034	Labor	Parts		
In Date: 02/08/2011	Hours	Description	Quantity	
- 1 - Detail Vehicle Wash Ticket(S) Issued				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 97.92

Workorder: 1106649 **Problem:** Pm service.

Meter Reading: 30685	Labor	Parts		
In Date: 06/23/2011	Hours	Description	Quantity	
- P.M. Service	4.75	SHOP SUPPLIES	1.00	
- Test Battery And Charging System.Recharge Battery And Retest,Fail Load Test.Replace Defective Battery.		1372 OIL FILTER FRM PH2 WIX 51372	1.00	
- Rotate And Balance All Tires.		31-20 WIPER BLADES 20" BLADE	2.00	
- Shop Supplies		31-13 WIPER BLADE	1.00	
		GROUP 65 BATTERY (MTC BXT-65-850)	1.00	
		10W30 MOTOR OIL	6.00	
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00	
Parts Charge:	182.85	Labor Charge:	285.00	

3/27/2017
3:19:34PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178723 2009 FORD EXPLORER Suv, Large, 4X4, W/Tow Pkg

Workorder: 1112039 **Problem:** Pm service.Check tires and wipers,see notes

Meter Reading: 37377	Labor	Parts	
In Date: 11/09/2011	Hours	Description	Quantity
- P.M. Service.	3.75	SHOP SUPPLIES	1.00
- Rotate And Balance All Tires.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Shop Supplies		31-20 WIPER BLADES 20" BLADE	2.00
		CA9332 AIR FILTER LBF AF1695 WIX 42484	1.00
		10W30 MOTOR OIL	6.00
Parts Charge:	33.32	Labor Charge:	225.00

Workorder: 1204032 **Problem:** P.M. service.

Meter Reading: 43464	Labor	Parts	
In Date: 04/30/2012	Hours	Description	Quantity
- Perform Pm Service.	3.75	USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Rotate And Balance All Four Tires.		SHOP SUPPLIES	1.00
- Shop Supplies		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		10W30 MOTOR OIL	6.00
Parts Charge:	39.00	Labor Charge:	225.00

Workorder: 1209160 **Problem:** Pm service.Test battery and replace damage right tail lamp assembly.

Meter Reading: 49183	Labor	Parts	
In Date: 09/25/2012	Hours	Description	Quantity
- P.M. Service.	5.75	SHOP SUPPLIES	1.00
- Replace And Balance Four Tire.		right rear tail light asy	1.00
- Install Strobe Bulb In New Right Tail Light And Install On Vehicle.		PH2 OIL FILTER LBF PH	1.00
		31-20 WIPER BLADES 20	2.00
- Shop Supplies		31-13 WIPER BLADE	1.00
		183407418 P235-70R16	4.00
		3157 TAIL LIGHT BULBS	2.00
		10W30 MOTOR OIL	6.00
		TPMS3 SENSOR TIRE PRE	2.00
		CA9332 AIR FILTER LBF	1.00
Parts Charge:	1,122.44	Labor Charge:	345.00

3/27/2017
3:19:34PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178723 2009 FORD EXPLORER Suv, Large, 4X4, W/Tow Pkg

Workorder: 1209547

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 49156	Labor	Parts
In Date: 10/04/2012	Hours	Description
Close Date: 10/04/2012		Quantity
- 1 - Detail Vehicle Wash Ticket(S) Issued		
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 97.92

Workorder: 1210001

Problem: Air flow through ac vents inop.

Meter Reading: 50373	Labor	Parts
In Date: 10/18/2012	Hours	Description
Close Date: 10/25/2012		Quantity
- Diagnose No Air Flow From Vents.R&R Dash Board And Replace Broken Air Flow Phenum.	6.00	AIR DUCT SHOP SUPPLIES
- Shop Supplies		
Parts Charge: 161.62	Labor Charge: 360.00	

Workorder: 1303112

Problem: Pm service.

Meter Reading: 54507	Labor	Parts
In Date: 03/29/2013	Hours	Description
Close Date: 04/05/2013		Quantity
- Perform Pm Service.	6.55	SHOP SUPPLIES
- Ac Performance And Leak Test.Recover Freon.Test And Replace Failed Leaking Ac Compressor Discharge Hose With New.Vacume And Recharge System To Specs With Freon And Oil.		1372 OIL FILTER R134A REFRIGERANT E8 A-C OIL R134A A-C NAPAGOLD FUEL FILTER TUBE ASY
- Rotate And Balance All Four Tires.		F75Z6730BA DRAIN PLUG
- Shop Supplies		31-20 WIPER BLADES 20 USED FIREX REFURBED F 10W30 MOTOR OIL
Parts Charge: 203.55	Labor Charge: 393.00	

3/27/2017
3:19:34PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178723 2009 FORD EXPLORER Suv, Large, 4X4, W/Tow Pkg

Workorder: 1307570

Problem: Right rear turn signal inop.

Meter Reading: 58134	Labor	Parts	
In Date: 07/30/2013	Hours	Description	Quantity
- Replace Right Rear Signal Light Bulb And Socket.	0.75	BULB	1.00
- Shop Supplies		SOCKET	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	18.95	Labor Charge:	45.00

Workorder: 1309622

Problem: Pm service and check for water leak at right rear door carpet.

Meter Reading: 60044	Labor	Parts	
In Date: 09/23/2013	Hours	Description	Quantity
- P.M. Service.	6.75	10W30 MOTOR OIL	6.00
- Rotate And Balance All Four Tires.		NAPAGOLD OIL FILTER	1.00
- Check For Water Leak.Remove Cowl Cover And Right Front Splash Guard And Reseal Right Front Body Seam.		31-20 WIPER BLADES 20	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	31.40	Labor Charge:	405.00

Workorder: 1401490

Problem: Pm service and check for noise around 45 mph.

Meter Reading: 65333	Labor	Parts	
In Date: 02/13/2014	Hours	Description	Quantity
- P.M. Service.	6.25	NAPAGOLD OIL FILTER	1.00
- Replace Left Front Hub Assemble.		10W30 MOTOR OIL	6.00
- Test Battery And Charging System,Replace Bad Battery.		BATTERY 65	1.00
- Rotate And Balance All Tires.		USED FIRE X REFURBISHED	1.00
- Shop Supplies		BRAKE CLEANER	1.00
		ACCUFIT CONVENTIONAL	2.00
		hub asy	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	419.73	Labor Charge:	375.00

3/27/2017
3:19:34PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178723 2009 FORD EXPLORER Suv, Large, 4X4, W/Tow Pkg

Workorder: 1402192 **Problem:** 10 - Wash ticket(s) issued

Meter Reading: 65560	Labor	Parts
In Date: 03/05/2014	Hours	Description
Close Date: 03/05/2014	Quantity	
- 10 - Wash Ticket(S) Issued		
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 97.32

Workorder: 1408641 **Problem:** Pm service.

Meter Reading: 72684	Labor	Parts
In Date: 08/27/2014	Hours	Description
Close Date: 09/08/2014	Quantity	
- Pm Service.	3.75	BAT TERM PROTECTOR
- Rotate And Balance All Four Tires.		ENGINE SEAL 12OZ
- Shop Supplies		SHOP SUPPLIES
		10W30 MOTOR OIL
		USED FIRE X REFURBISHED
		NAPAGOLD OIL FILTER
		WIPER BLADE
		ACCUFIT REAR
Parts Charge: 67.83	Labor Charge: 225.00	

Workorder: 1410342 **Problem:** Check engine light comes on and off.

Meter Reading: 76100	Labor	Parts
In Date: 10/15/2014	Hours	Description
Close Date: 10/27/2014	Quantity	
- Computer Diagnose For Check Engine Light On.Code	3.00	SHOP SUPPLIES
P0401 Perform Egr Flow Test.Replace Defective Egr		EGR VALVE
Valve.Clear Code With Scan Tool And Road Test.		5068 PENETRATING OIL
- Shop Supplies		
Parts Charge: 209.36	Labor Charge: 180.00	

Workorder: 1410869 **Problem:** Left rear tire flat

Meter Reading: 76291	Labor	Parts
In Date: 10/30/2014	Hours	Description
Close Date: 10/31/2014	Quantity	
- Repair And Balance Left Rear Tire.	1.00	SHOP SUPPLIES
- Shop Supplies		
Parts Charge: 2.00	Labor Charge: 60.00	

3/27/2017
3:19:34PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178723 2009 FORD EXPLORER Suv, Large, 4X4, W/Tow Pkg

Workorder: 1412640

Problem: damage to rgt frt fender, hood, grille, light & bumper

Meter Reading: 76456	Labor	Parts	
In Date: 11/04/2014	Hours	Description	Quantity
-	Damage To Rgt Frt Fender, Hood, Grille, Light & Bumper		
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	3,181.80

Workorder: 1500905

Problem: P.M. Service.

Meter Reading: 77748	Labor	Parts	
In Date: 01/26/2015	Hours	Description	Quantity
-	Pm Service.		
-	Inspect And Replace Both Leaking Rear Shock Absorbers.	NAPAGOLD OIL FILTER	1.00
-	Perform Cooling System Flush And Replace Defective Thermostat.	STRUT	2.00
-	Rotate And Balance All Four Tires.	THERMOSTAT	1.00
-	Complete Alignment And Test Drive.	WIPER BLADE	2.00
-	Shop Supplies	THERMOSTAT	1.00
		10W30 MOTOR OIL	6.00
		SHOP SUPPLIES	1.00
		NAPAGOLD AIR FILTER	1.00
		PEAK GLOBAL	2.00
		MACS BATTERY CLEANER	1.00
Parts Charge:	292.43	Labor Charge:	663.00

Workorder: 1502047

Problem: damage to frt bumper

Meter Reading: 77748	Labor	Parts	
In Date: 02/05/2015	Hours	Description	Quantity
-	Damage To Frt Bumper		
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	434.36

3/27/2017
3:19:34PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178723 2009 FORD EXPLORER Suv, Large, 4X4, W/Tow Pkg

Workorder: 1506673

Problem: Pm service.Left front wheel panel loose.

Meter Reading: 82691 In Date: 07/02/2015	Close Date: 07/21/2015	Labor Hours	Description	Parts	Quantity
- P.M. Service.		7.75	SHOP SUPPLIES		1.00
- Replace Spark Plugs.			5W20 ENGINE OIL		6.00
- Flush Injectors.Clean Throttle Body And Induction System.			WIPER BLADE		2.00
- Rotate And Balance Tires.			THRTL PLT INTAKE CLNR		1.00
- Fabricate And Re-Install Bumper Fascia Cover.			INTAKE CLEANER KIT		1.00
- Shop Supplies			INJECTOR CLEANER		1.00
			NAPAGOLD OIL FILTER		1.00
			WASHER FLUID CONCENTR		1.00
			NAPAGOLD FUEL FILTER		1.00
			ACCUFIT REAR		1.00
			SPARK PLUG		6.00
	Parts Charge: 128.06		Labor Charge: 465.00		

Workorder: 1507138

Problem: wont fuel

Meter Reading: 82690 In Date: 07/17/2015	Close Date: 07/22/2015	Labor Hours	Description	Parts	Quantity
- Test And Remove Canceiver Issue Fuel Card		2.00	SHOP SUPPLIES		1.00
- R&R Tire To Patch, Nitro And Balance					
- Shop Supplies					
	Parts Charge: 2.00		Labor Charge: 120.00		

3/27/2017
3:19:34PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178723 2009 FORD EXPLORER Suv, Large, 4X4, W/Tow Pkg

Workorder: 1512026

Problem: P.M. service.

Meter Reading: 88018 In Date: 11/30/2015	Close Date: 12/08/2015	Labor Hours	Description	Parts	Quantity
- Pm Service.		7.75	5W20 ENGINE OIL		6.00
- Resurface Both Rear Brake Rotors.Replace Rear Brake Pads.Service Calipers.Bleed Brake Ststem.Roadtest.			CERAMIC BRAKE LUBE		1.00
			SHOP SUPPLIES		1.00
- Rotate And Balance All Four Tires.			NAPAGOLD OIL FILTER		1.00
- Shop Supplies			REAL BRAKE PAD		1.00
			B FLUID DOT 3-32OZ		1.00
			USED FIRE X REFURBISHED		1.00
			BRAKE CLEANER		1.00
			ACCUFIT REAR		1.00
			WIPER BLADE		2.00
Parts Charge:		157.31	Labor Charge:		465.00

Workorder: 1600800

Problem: Check engine light on and transmission slipping.

Meter Reading: 89146 In Date: 01/25/2016	Close Date: 01/28/2016	Labor Hours	Description	Parts	Quantity
- Computer Diagnose For Check Engine Light On.Code P0302.Perform Power Balance Test.Replace Defective Coil Pack And Spark Plug Wires.Clear Codes.Reset Kam.Test Drive.		3.75	IGNI COIL ASY		1.00
			SHOP SUPPLIES		1.00
- Shop Supplies			SPARK PLUG WIRE SET		1.00
Parts Charge:		124.75	Labor Charge:		225.00

Workorder: 1601397

Problem: Noise under rear of vehicle more so when turning left.

Meter Reading: 89665 In Date: 02/09/2016	Close Date: 02/18/2016	Labor Hours	Description	Parts	Quantity
- Test Drive And Diagnose Noise.Replace Both Defective Rear Sway Bar Links.		1.00	SHOP SUPPLIES		1.00
			REAL SWAY BAR LINK		2.00
- Shop Supplies			6L2Z5C491AA		2.00
Parts Charge:		57.44	Labor Charge:		60.00

3/27/2017
3:19:34PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178723 2009 FORD EXPLORER Suv, Large, 4X4, W/Tow Pkg

Workorder: 1605327

Problem: P.M. service.

Meter Reading: 93734	Labor	Parts	
In Date: 05/23/2016	Hours	Description	Quantity
- P.M. Service.	14.75	TIRE DISPOSAL FEE	2.00
- Pressure Test And Inspect Cooling System.		SHOP SUPPLIES	1.00
- Leaking Thermostat Housing And Bypass Hose.		10W30 MOTOR OIL	6.00
- Radiator Cap.Flush And Refill Cooling System.		NAPAGOLD OIL FILTER	1.00
- Replace Two Tires,Rotate And Balance All Four.		20" WIPER BLADE	2.00
- Replace Left Front Marker Lamp Bulb.		WASHER FLUID CONCENTR	1.00
- Resurface Front Brake Rotors,Replace Front Pads.		THERMOSTAT	1.00
- Service And Lube Calipers.Flush And Bleed System.		BY PASS HOSE	1.00
- Complete Wheel Alignment.Test Drive.		BULB	1.00
- Shop Supplies		FRONT BRAKE PAD	1.00
		NAPAGOLD FUEL FILTER	1.00
		BRAKE CLEANER	1.00
		183407418 P235-70R16	2.00
		RADIADETOR CAP	1.00
Parts Charge:	600.21	Labor Charge:	885.00

Workorder: 1610463

Problem: P.M. service.

Meter Reading: 99240	Labor	Parts	
In Date: 10/11/2016	Hours	Description	Quantity
- P.M. Service.	4.25	ACCUFIT REAR	1.00
- Test Battery And Charging System.		BATTERY	1.00
- Replace Front Sway Bar Links.		SWAY BAR REPAIR KIT	1.00
- Shop Supplies		NAPAGOLD OIL FILTER	1.00
		20" WIPER BLADE	2.00
		SHOP SUPPLIES	1.00
		5W20 ENGINE OIL	6.00
Parts Charge:	187.07	Labor Charge:	255.00

3/27/2017
3:19:34PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178723 2009 FORD EXPLORER Suv, Large, 4X4, W/Tow Pkg

Workorder: 1701529

Problem: remove emergency lights, get ready for auction

Meter Reading: 103158	Labor	Parts	
In Date: 02/14/2017	Hours	Description	Quantity
- Remove All Emergency Lights	3.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	180.00

Workorder: 1701541

Problem: Transition Prep Charge

Meter Reading: 102948	Labor	Parts	
In Date: 02/14/2017	Hours	Description	Quantity
- Transition Prep Charge	2.00		
Parts Charge:	0.00	Labor Charge:	0.00

Total Parts Charges:	6,746.36	Total Labor Charges:	7,809.00	Total Comm. Charges:	4,718.72
----------------------	-----------------	----------------------	-----------------	----------------------	-----------------