

3/27/2017
3:54:08PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169423 2008 FORD F250 Pickup, 3/4 Ton, W/Crewcab, Toolbox

Workorder: 741260 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 07/11/2007	Hours	Description
Close Date: 07/11/2007		Quantity
- Pre-Delivery Inspection	2.00	
Parts Charge: 0.00	Labor Charge: 110.00	

Workorder: 741489 **Problem:** INSTALL LADDER RACK.

Meter Reading: 302	Labor	Parts
In Date: 07/16/2007	Hours	Description
Close Date: 07/24/2007		Quantity
- Fabricate And Install New Ladder Rack	2.50	T-1 BLACK PAINT GLOSS 1.00
- Shop Supplies		SHOP SUPPLIES 1.00
		1450 LADDER RACK 1.00
Parts Charge: 313.69	Labor Charge: 55.00	

Workorder: 834404 **Problem:** P.M SERVICE

Meter Reading: 4097	Labor	Parts
In Date: 02/20/2008	Hours	Description
Close Date: 02/22/2008		Quantity
- Pm Service	3.25	5W20 ENGINE OIL 7.00
- Replace Right Rear Reverse Light		SHOP SUPPLIES 1.00
- Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372 1.00
Parts Charge: 19.20	Labor Charge: 30.00	

Workorder: 843538 **Problem:** P.M SERVICE

Meter Reading: 7745	Labor	Parts
In Date: 08/29/2008	Hours	Description
Close Date: 09/05/2008		Quantity
- Pm Service	3.75	5W20 ENGINE OIL 7.00
- Rotate & High Speed Balance All 4 Tires.Nitro Fill All		CA10262 AIR FILTER MTC FA1883 WIX 49883 1.00
Tires To Spec.		1372 OIL FILTER FRM PH2 WIX 51372 1.00
- Shop Supplies		G10166 FUEL FILTER MTC FG1083 WIX 33243 1.00
		SHOP SUPPLIES 1.00
Parts Charge: 52.96	Labor Charge: 60.00	

3/27/2017
3:54:08PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169423 2008 FORD F250 Pickup, 3/4 Ton, W/Crewcab, Toolbox

Workorder: 935473

Problem: PM SERVICE.

Meter Reading: 11526	Labor	Parts	
In Date: 03/23/2009	Hours	Description	Quantity
- Pm Service	3.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Rotate And Hi Speed Balance All 4 Tires.Nitro Fill All		5W20 ENGINE OIL	7.00
- Tiresto Specs.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Shop Supplies		31-20 WIPER BLADES 20" BLADE	2.00
		SHOP SUPPLIES	1.00
Parts Charge:	45.93	Labor Charge:	225.00

Workorder: 940288

Problem: Check lights

Meter Reading: 13401	Labor	Parts	
In Date: 07/06/2009	Hours	Description	Quantity
- Check All Lights. Replace R/R Tail Light Bulb.	0.50	SHOP SUPPLIES	1.00
- Shop Supplies		4114K BULB (ACD)	1.00
Parts Charge:	4.85	Labor Charge:	30.00

Workorder: 944785

Problem: P.M service

Meter Reading: 15967	Labor	Parts	
In Date: 10/20/2009	Hours	Description	Quantity
- P.M Service.	7.55	TR416 VALVE STEM	4.00
- Mount, Balance & Nitro Fill Four New Tires.		TIRE DISPOSAL FEE	4.00
- Test & Replace Third Brake Light Bulb.		179636492 LT245/75R17 WRANGLER SR-A E	4.00
- Alignment.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Shop Supplies		31-20 WIPER BLADES 20" BLADE	2.00
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
		5W20 ENGINE OIL	7.00
		SHOP SUPPLIES	1.00
Parts Charge:	799.41	Labor Charge:	453.00

3/27/2017
3:54:08PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169423 2008 FORD F250 Pickup, 3/4 Ton, W/Crewcab, Toolbox

Workorder: 1004388

Problem: P.M service.

Meter Reading: 19910 In Date: 04/28/2010	Close Date: 04/29/2010	Labor Hours	Description	Parts	Quantity
- P.M Service		2.75	5W20 ENGINE OIL		7.00
- Shop Supplies			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			SHOP SUPPLIES		1.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
Parts Charge: 30.98		Labor Charge:	165.00		

Workorder: 1006318

Problem: Left tail light out.

Meter Reading: 20809 In Date: 06/15/2010	Close Date: 06/15/2010	Labor Hours	Description	Parts	Quantity
- Remove Left Tail Lamp And Replace Failed Bulb With New.		0.50	3157 TAIL LIGHT BULBS		1.00
Parts Charge: 0.79		Labor Charge:	30.00		

Workorder: 1006494

Problem: Has to jumpstart engine all the time.Smells acid.

Meter Reading: 20873 In Date: 06/21/2010	Close Date: 06/22/2010	Labor Hours	Description	Parts	Quantity
- Test Starting And Charging System.Battery Failed Load		1.00	SHOP SUPPLIES		1.00
- Test After Recharge.Replace Failed Battery With New.			GROUP 65 BATTERY (MTC BXT-65-850)		1.00
- Shop Supplies					
Parts Charge: 136.01		Labor Charge:	60.00		

3/27/2017
3:54:08PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169423 2008 FORD F250 Pickup, 3/4 Ton, W/Crewcab, Toolbox

Workorder: 1011978

Problem: P.M. service.

Meter Reading: 23175		Labor		Parts	
In Date: 10/26/2010	Close Date: 10/29/2010	Hours	Description	Quantity	
-	Perform Pm Service.	4.25	1372 OIL FILTER FRM PH2 WIX 51372	1.00	
-	Test And Replace Failed Left Reverse Lamp Bulb With New.		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00	
-	Rotate And Balance All Four Tires.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00	
-	Shop Supplies		FLOOR MATS	1.00	
			31-20 WIPER BLADES 20" BLADE	2.00	
			5W20 ENGINE OIL	7.00	
			SHOP SUPPLIES	1.00	
Parts Charge: 107.19		Labor Charge: 255.00			

Workorder: 1104318

Problem: Pm service

Meter Reading: 26028		Labor		Parts	
In Date: 04/21/2011	Close Date: 04/28/2011	Hours	Description	Quantity	
-	P.M. Service.	3.75	D3TZ2457B BRAKE PEDAL PAD	1.00	
-	Rotate And Balance All Tires.		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00	
-	Shop Supplies		SHOP SUPPLIES	1.00	
			5W20 ENGINE OIL	7.00	
			1372 OIL FILTER FRM PH2 WIX 51372	1.00	
			31-20 WIPER BLADES 20" BLADE	2.00	
Parts Charge: 30.33		Labor Charge: 225.00			

Workorder: 1111011

Problem: P.M. service.

Meter Reading: 29357		Labor		Parts	
In Date: 10/17/2011	Close Date: 10/27/2011	Hours	Description	Quantity	
-	P.M. Service.	3.75	5W20 ENGINE OIL	7.00	
-	Rotate And Balance All Tires.		1372 OIL FILTER FRM PH2 WIX 51372	1.00	
-	Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS	1.00	
			G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00	
			SHOP SUPPLIES	1.00	
			31-20 WIPER BLADES 20" BLADE	2.00	
Parts Charge: 51.65		Labor Charge: 225.00			

3/27/2017
3:54:08PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169423 2008 FORD F250 Pickup, 3/4 Ton, W/Crewcab, Toolbox

Workorder: 1112175 **Problem:** Install knox box.

Meter Reading: 29574	Labor	Parts
In Date: 11/15/2011	Hours	Description
Close Date: 11/17/2011		Quantity
- Install Knox Box.Fabricate And Install Wiring.	4.00	SHOP SUPPLIES
- Shop Supplies		1.00
Parts Charge: 2.00		Labor Charge: 240.00

Workorder: 1113388 **Problem:** Towed in Left rear tire flat.

Meter Reading: 29741	Labor	Parts
In Date: 12/21/2011	Hours	Description
Close Date: 12/29/2011		Quantity
- Replace And Balance Both Rear Tires.	1.00	179636492 LT245/75R17 WRANGLER SR-A E
- Shop Supplies		TIRE DISPOSAL FEE
		SHOP SUPPLIES
		2.00
		2.00
		1.00
Parts Charge: 375.39		Labor Charge: 60.00

Workorder: 1113412 **Problem:** left rear flat

Meter Reading: 29603	Labor	Parts
In Date: 12/21/2011	Hours	Description
Close Date: 12/27/2011		Quantity
- Tow From: 160 Austrailian Airport Ctr To: Lv Shop		
Parts Charge: 0.00		Labor Charge: 0.00
		Commercial Charge: 104.15

Workorder: 1201292 **Problem:** Left turn signal light inop.

Meter Reading: 30623	Labor	Parts
In Date: 02/08/2012	Hours	Description
Close Date: 02/09/2012		Quantity
- Test And Replace Failed Left Rear Turn Signal Lamp Bulb With New.	0.50	3157 TAIL LIGHT BULBS
		1.00
Parts Charge: 0.61		Labor Charge: 30.00

3/27/2017
3:54:08PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169423 2008 FORD F250 Pickup, 3/4 Ton, W/Crewcab, Toolbox

Workorder: 1203944

Problem: P.M. service.

Meter Reading: 32224	Labor	Parts	
In Date: 04/26/2012	Hours	Description	Quantity
- Perform Pm Service.	4.75	31-20 WIPER BLADES 20" BLADE	2.00
- Test Starting And Charging System.Battery Failed		GROUP 65 BATTERY (MTC BXT-65-850)	1.00
Loadtest After Recharge.Replace Failed Battery With		5W20 ENGINE OIL	7.00
New.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Rotate And Balance All Four Tires.		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	160.72	Labor Charge:	285.00

Workorder: 1207377

Problem: Has to jump start all the time.

Meter Reading: 33354	Labor	Parts	
In Date: 08/07/2012	Hours	Description	Quantity
- Test Starting And Charging System.Battery Failed	1.00	SHOP SUPPLIES	1.00
Loadtest After Recharge.Replace Failed Battery With			
New.			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1208671

Problem: Turn signal light inop

Meter Reading: 33696	Labor	Parts	
In Date: 09/12/2012	Hours	Description	Quantity
- Remove Right Tail Lamp Assembly.Test And Replace	0.50	3157 TAIL LIGHT BULBS	1.00
Failed Right Rear Turnsignal Lamp Bulb With New.			
Parts Charge:	0.60	Labor Charge:	30.00

Workorder: 1209141

Problem: Right front headlight inop.

Meter Reading: 33880	Labor	Parts	
In Date: 09/25/2012	Hours	Description	Quantity
- Remove Right Headlamp Assembly.Test And Replace	0.75	SHOP SUPPLIES	1.00
Failed Right Headlamp Seal Beam With New.		H6054 SEALED BEAM	1.00
- Shop Supplies			
Parts Charge:	10.67	Labor Charge:	45.00

3/27/2017
3:54:08PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169423 2008 FORD F250 Pickup, 3/4 Ton, W/Crewcab, Toolbox

Workorder: 1210986

Problem: Pm service.

Meter Reading: 34597	Labor	Parts	
In Date: 11/09/2012	Hours	Description	Quantity
- Perform Pm Service.	6.25	SYN-ATF TRANS FLUID S	20.00
- Inspect And Service Transmission.Flush And Renew Transmission Fluid.		TR416 VALVE STEM	2.00
		SHOP SUPPLIES	1.00
- Install Two New Tires To The Front Wheels.Nitrogen Fill And Balance All Four.		5W20 ENGINE OIL	7.00
		PH2 OIL FILTER LBF PH	1.00
- Shop Supplies		31-20 WIPER BLADES 20	2.00
		USED FIREX REFURBED F	1.00
		179636492 LT245-75R17	2.00
		FORD FUEL FILTER	1.00
		15319476 FUSE 20 AMP	1.00
Parts Charge:	750.22	Labor Charge:	375.00

Workorder: 1305114

Problem: Pm service

Meter Reading: 37143	Labor	Parts	
In Date: 05/23/2013	Hours	Description	Quantity
- P.M. Service.	3.75	SHOP SUPPLIES	1.00
- Rotate And Balance All Tires.		31-20 WIPER BLADES 20	2.00
- Shop Supplies		COVER	1.00
		5W20 ENGINE OIL	7.00
		NAPAGOLD OIL FILTER	1.00
Parts Charge:	93.29	Labor Charge:	225.00

Workorder: 1311801

Problem: P.M. service.

Meter Reading: 38916	Labor	Parts	
In Date: 11/22/2013	Hours	Description	Quantity
- P.M. Service.	3.75	WIPER BLADE	2.00
- Rotate And Balance All Tires.		NAPAGOLD FUEL FILTER	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		USED FIRE X REFURBISHED	1.00
		5W20 ENGINE OIL	7.00
		NAPAGOLD OIL FILTER	1.00
Parts Charge:	53.90	Labor Charge:	225.00

3/27/2017
3:54:08PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169423 2008 FORD F250 Pickup, 3/4 Ton, W/Crewcab, Toolbox

Workorder: 1405221

Problem: P.m. service.

Meter Reading: 40758	Labor	Parts	
In Date: 05/29/2014	Hours	Description	Quantity
- P.M. Service.	4.25	HBE	1.00
- Replace Broken Ashtray.		NAPAGOLD OIL FILTER	1.00
- Rotate And Balance All Tires.		5W20 ENGINE OIL	7.00
- Shop Supplies		WIPER BLADE	2.00
		SHOP SUPPLIES	1.00
Parts Charge:	97.11	Labor Charge:	255.00

Workorder: 1411992

Problem: Pm service.

Meter Reading: 42638	Labor	Parts	
In Date: 12/01/2014	Hours	Description	Quantity
- Pm Service.	3.75	NAPAGOLD OIL FILTER	1.00
- Rotate And Balance All Four Tires.		NAPAGOLD FUEL FILTER	1.00
- Shop Supplies		MACS BATTERY CLEANER	1.00
		5W20 ENGINE OIL	7.00
		USED FIRE X REFURBISHED	1.00
		SHOP SUPPLIES	1.00
		BAT TERM PROTECTOR	1.00
		WIPER BLADE	2.00
Parts Charge:	67.73	Labor Charge:	225.00

Workorder: 1503742

Problem: Hitch safety pin broken.

Meter Reading: 43750	Labor	Parts	
In Date: 04/13/2015	Hours	Description	Quantity
- Inspect And Replace Broken Hitch Safety Pintle Pin And Chain.	0.50	PINTLE PIN W/CHAIN	1.00
Parts Charge:	2.61	Labor Charge:	30.00

3/27/2017
3:54:08PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169423 2008 FORD F250 Pickup, 3/4 Ton, W/Crewcab, Toolbox

Workorder: 1506208

Problem: Pm service.

Meter Reading: 44390	Labor	Parts	
In Date: 06/22/2015	Hours	Description	Quantity
- P.M. Service.	7.25	NAPAGOLD OIL FILTER	1.00
- Pressure Test And Inspect Cooling System..Flush And Refill System.		5W20 ENGINE OIL	7.00
		20" WIPER BLADE	2.00
- Repair Left Rear Tire,Rotate And Balance All Four.		SHOP SUPPLIES	1.00
- Repair Trailer Plug Mounting Bracket.		PEAK GLOBAL	2.00
- Shop Supplies			
Parts Charge:	66.35	Labor Charge:	435.00

Workorder: 1512683

Problem: P.M. service and A/C not cold.

Meter Reading: 45727	Labor	Parts	
In Date: 12/16/2015	Hours	Description	Quantity
- Pm Service.	15.25	BATTERY	1.00
- Check Battery And Charging System.Battery Failed		R134A LV SHOP 2	2.00
Loadtest After Recharge.Replace Defective Battery.		BODY MOUNT KIT	6.00
- Inspect And Replace All Eight Defective Body Mounts.		NAPAGOLD OIL FILTER	1.00
- Ac Performance And Leak Test.Evacuate		USED FIRE X REFURBISHED	1.00
System.Replace Defective Expansion Valve.Vacume And		NAPAGOLD FUEL FILTER	1.00
Recharge System To Specs.		BODY MOUNT KIT	2.00
- Rotate And Balance All Four Tires.		5W20 ENGINE OIL	7.00
- Shop Supplies		ORIFICE TUBE	1.00
		20" WIPER BLADE	2.00
		SHOP SUPPLIES	1.00
Parts Charge:	842.48	Labor Charge:	915.00

Workorder: 1603028

Problem: 1 - Wash ticket(s) issued

Meter Reading: 45866	Labor	Parts	
In Date: 03/22/2016	Hours	Description	Quantity
- 1 - Wash Ticket(S) Issued			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	9.54

3/27/2017
3:54:08PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169423 2008 FORD F250 Pickup, 3/4 Ton, W/Crewcab, Toolbox

Workorder: 1606719

Problem: P.M. Service.

Meter Reading: 46604	Labor	Parts	
In Date: 07/01/2016	Hours	Description	
Close Date: 07/12/2016		Quantity	
- P.M. Service.	4.25	MAC WITE LITHIUM GRES	1.00
- Replace Front Bump Stops.		WASHER FLUID CONCENTR	1.00
- Rotate And Balance All Tires.		bumper	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
		WD40 16OZ	1.00
		USED FIRE X REFURBISHED	1.00
		20" WIPER BLADE	2.00
		NAPAGOLD OIL FILTER	1.00
		5W20 ENGINE OIL	7.00
Parts Charge:	77.29	Labor Charge:	255.00

Workorder: 1610536

Problem: service call to ESS for flat tire

Meter Reading: 46878	Labor	Parts	
In Date: 10/12/2016	Hours	Description	
Close Date: 10/19/2016		Quantity	
- Fill Tire And Ess, Take To Lv Shop	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1610544

Problem: Left rear tire flat.

Meter Reading: 46775	Labor	Parts	
In Date: 10/12/2016	Hours	Description	
Close Date: 10/18/2016		Quantity	
- Replace And Balance Left Rear Tire.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

3/27/2017
3:54:08PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169423 2008 FORD F250 Pickup, 3/4 Ton, W/Crewcab, Toolbox

Workorder: 1700246

Problem: P.M. service.

Meter Reading: 47245		Labor		Parts	
In Date: 01/09/2017	Close Date: 01/23/2017	Hours	Description	Quantity	
-	P.M. Service.	5.75	SHOP SUPPLIES	1.00	
-	Replace Rear Axle Bump Stoppers.		TIRE DISPOSAL FEE	2.00	
-	Replace Two Tires, Rotate And Balance All Four.		WASHER FLUID CONCENTR	1.00	
-	Replace Front Asset #.		179636492 LT245-75R17	2.00	
-	Shop Supplies		MAC BATTERY PROTECT	1.00	
			NAPAGOLD OIL FILTER	1.00	
			REAL SUSPENSION BUMPSTOPS	2.00	
			20" WIPER BLADE	2.00	
			5W20 ENGINE OIL	7.00	
Parts Charge: 624.28		Labor Charge: 345.00			

Workorder: 1702072

Problem: remove knox box

Meter Reading: 47597		Labor		Parts	
In Date: 02/28/2017	Close Date: 03/09/2017	Hours	Description	Quantity	
-	Remove Knox Box	1.00	SHOP SUPPLIES	1.00	
-	Shop Supplies				
Parts Charge: 2.00		Labor Charge: 60.00			

Workorder: 1702108

Problem: Transition Prep Charge

Meter Reading: 47525		Labor		Parts	
In Date: 03/01/2017	Close Date: 03/01/2017	Hours	Description	Quantity	
-	Transition Prep Charge	2.00			
Parts Charge: 0.00		Labor Charge: 0.00			

Total Parts Charges:	4,826.24	Total Labor Charges:	6,138.00	Total Comm. Charges:	113.69
----------------------	-----------------	----------------------	-----------------	----------------------	---------------