

3/27/2017  
4:33:42PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166556 2006 HARPER/GOOSEN TV40 Lawn Vacuum, Rotary Brush

Workorder: 641732

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	
In Date: 06/30/2006	Hours	Description	Quantity
- Pre-Delivery Inspection	2.00		
Parts Charge: 0.00	Labor Charge: 100.00		

Workorder: 834341

Problem: P.M.

Meter Reading: 0	Labor	Parts	
In Date: 02/19/2008	Hours	Description	Quantity
- Pm Service	4.50	10W30 MOTOR OIL	2.00
- Test Run		1348 OIL FILTER FRM PH3614 WIX 51348	1.00
- Unable To Lower Roller Brush-Stop For Lever Seized On		3031 FUEL FILTER 1/4" FRM G1 WIX 33031	1.00
Frame Fire Up Bracket & Remove To Clean & Lube With		4788303 AIR FILTER KIT KOHLER	1.00
Anti-Seized Lube		HYD FILTER	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		BKR5E SPARK PLUG 7938	2.00
Parts Charge: 36.75	Labor Charge: 60.00		

Workorder: 934426

Problem: PM SERVICE, BATTERY DEAD

Meter Reading: 97	Labor	Parts	
In Date: 02/25/2009	Hours	Description	Quantity
- Pm Service	10.50	3031 FUEL FILTER 1/4" FRM G1 WIX 33031	1.00
- Replace Battery		GROUP U1 BATTERY (ACD U1240W)	1.00
- Replace Seals On Trailer/Service		46760 SEAL	2.00
- Hydro Service		BKR5E SPARK PLUG 7938	2.00
- Replace Fuel Tank Drain Fuel Tank Flush And Replace		66060 LOCK PIN 3/8"X2-1/2"	1.00
W/New Fuel.		HYD FILTER	1.00
- Wash		AW68 HYDRO FLUID HYDRAULIC OIL 68	6.00
- Shop Supplies		AUX FUEL TANK	1.00
		SHOP SUPPLIES	1.00
		1348 OIL FILTER FRM PH3614 WIX 51348	1.00
		2488303 AIR FILTER KIT KOHLER, JDEER GY20576	1.00
		10W30 MOTOR OIL	2.00
Parts Charge: 257.37	Labor Charge: 630.00		

3/27/2017  
4:33:42PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166556 2006 HARPER/GOOSEN TV40 Lawn Vacuum, Rotary Brush

Workorder: 1004126

Problem: pm and flat tire

Meter Reading: 97	Labor	Parts	
In Date: 04/21/2010	Hours	Description	Quantity
- Pm	7.00	10W30 MOTOR OIL	2.00
- Tire Repari And Replace One Tire		18.5X8.5-8 TIRE C	1.00
- Ign Sys Service		GROUP U1 BATTERY (ACD U1240W)	1.00
- Service Trailer		66060 LOCK PIN 3/8"X2-1/2"	1.00
- Test Charging Sys Replace Battery		BKR5E SPARK PLUG 7938	2.00
- Shop Supplies		3031 FUEL FILTER 1/4" FRM G1 WIX 33031	1.00
		SHOP SUPPLIES	1.00
		1348 OIL FILTER FRM PH3614 WIX 51348	1.00
		TIRE DISPOSAL FEE	1.00
<b>Parts Charge:</b>	137.90	<b>Labor Charge:</b>	420.00

Workorder: 1111073

Problem: PM

Meter Reading: 97	Labor	Parts	
In Date: 10/18/2011	Hours	Description	Quantity
- Pm	7.00	BKR5E SPARK PLUG 7938	2.00
- Service Trailer		SHOP SUPPLIES	1.00
- New Rotchet Jack		09997 BRAKE CLEAN	1.00
- Ignition System Service		FREIGHT	1.00
- Hydro Service		1348 OIL FILTER FRM PH3614 WIX 51348	1.00
- Shop Supplies		3031 FUEL FILTER 1/4" FRM G1 WIX 33031	1.00
		RATCHET JACK	1.00
		HYD FILTER	1.00
		AW68 HYDRO FLUID HYDRAULIC OIL 68	6.00
		SAE 30W OIL	1.00
<b>Parts Charge:</b>	234.56	<b>Labor Charge:</b>	420.00

3/27/2017  
4:33:42PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166556 2006 HARPER/GOOSEN TV40 Lawn Vacuum, Rotary Brush

**Workorder:** 1211755

**Problem:** pm service

Meter Reading: 97	Labor	Parts	
In Date: 12/05/2012	Hours	Description	Quantity
- Pm	7.00	fuel filter	1.00
- Ignition System Service		FILTER	1.00
- Clean Out Carb		AIR FILTER KIT	1.00
- Decals New Asset #S		BKR5E SPARK PLUG 7938	2.00
- Shop Supplies		NAPA 10W30 QT	1.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	37.98	<b>Labor Charge:</b>	420.00

**Workorder:** 1402502

**Problem:** pm service

Meter Reading: 97	Labor	Parts	
In Date: 03/14/2014	Hours	Description	Quantity
- Pm Service	6.00	SPARK PLUG	2.00
- Ign Service		NAPAGOLD FUEL FILTER	1.00
- Hyd Service		NAPA HYDRAULIC FILTR	1.00
- Shop Supplies		10W30 MOTOR OIL	2.00
		AIR FILTER	1.00
		SHOP SUPPLIES	1.00
		NAPAGOLD OIL FILTER	1.00
<b>Parts Charge:</b>	33.19	<b>Labor Charge:</b>	360.00

**Workorder:** 1406745

**Problem:** brush handle broke/ smal wheel/ see notes

Meter Reading: 97	Labor	Parts	
In Date: 07/09/2014	Hours	Description	Quantity
- R/R Brush Unit And Hydraulic Pump, Replace Brush	5.00	NUT	2.00
Handle Assy. Install Unit Back		WASHER	4.00
- Replace Both Caster Wheel Assy And Fabricate Brackets		Freight Charge	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		CASTER WHEEL	2.00
		BOLT	2.00
		BROOM LIFT WELDMENT	2.00
		NUT	2.00
<b>Parts Charge:</b>	567.91	<b>Labor Charge:</b>	300.00

3/27/2017  
4:33:42PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166556 2006 HARPER/GOOSEN TV40 Lawn Vacuum, Rotary Brush

**Workorder:** 1507458

**Problem:** pm service

Meter Reading: 97	Labor	Parts	
In Date: 07/27/2015	Hours	Description	
Close Date: 07/31/2015		Quantity	
- Pm Service	<b>9.00</b>	SHOP SUPPLIES	1.00
- Ignition Service. Check Spark & Compression		NAPAGOLD OIL FILTER	1.00
- Hydrauluc Service		TINY-TACH HOURMETER	1.00
- Repack Bearings & Replace Seals		AIR FILTER	1.00
- Replace Battery		NAPAGOLD FUEL FILTER	1.00
- Repair Rear Tire & Clean For Patch		SPARK PLUG	2.00
- Shop Supplies		AW68 HYDRO FLUID HYDR	8.00
		BATTERY	1.00
		BRAKE CLEANER	2.00
		10W30 MOTOR OIL	2.00
		NAPA HYDRAULIC FILTR	1.00
		SEAL 1.250 1.979 .250	2.00
<b>Parts Charge:</b>	211.79	<b>Labor Charge:</b>	540.00

**Workorder:** 1512653

**Problem:** pm/ hydraulic leak/ ratchet inop

Meter Reading: 118	Labor	Parts	
In Date: 12/15/2015	Hours	Description	
Close Date: 01/08/2016		Quantity	
- Pm	<b>9.50</b>	NAPAGOLD OIL FILTER	1.00
- Remove Brush And Motor To Seperate And Order		NAPAGOLD FUEL FILTER	1.00
Parts-Reseal Brush Motor And Reinstall Ad Test Run		10W30 MOTOR OIL	2.00
- Replace Ratchet Jack On Hitch		NAPA HYDRAULIC FILTR	1.00
- Replace Fuel Primer Bulb Leaking		SPARK PLUG	2.00
- Ign Servic		RATCHET JACK	1.00
- Shop Supplies		EPA PRIMER BULB-1 4	1.00
		Freight Charge	1.00
		EATON SEAL KIT	1.00
		SHAFT SEAL	1.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	372.30	<b>Labor Charge:</b>	570.00

3/27/2017  
4:33:42PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166556 2006 HARPER/GOOSEN TV40 Lawn Vacuum, Rotary Brush

Workorder: 1701557

Problem: Transition Prep Charge

Meter Reading: 118

Labor

Parts

In Date: 02/14/2017

Close Date: 02/14/2017

Hours

Description

Quantity

---

- Transition Prep Charge

2.00

Parts Charge: 0.00

Labor Charge: 0.00

Total Parts Charges: **1,889.75**

Total Labor Charges: **3,820.00**

Total Comm. Charges: **0.00**