

7/7/2025  
4:06:25 PM

10210007

**Palm Beach County Fleet Management Asset Maintenance History**  
**2019 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)**

---

**Total Hours: 67.00    Labor: 4,870.00    Parts: 6,609.60    Comm: 0.00    Charged: 11479.60**

---

**Work Order:** 1900671      **Meter:** 1      **In Date:** 01/16/2019    **Closed:** 01/18/2019  
**Problem:** pre delivery inspection

**Work Completed**

- pre delivery inspection
- Shop Supplies

Hours: 2.00      Comm: 0.00

**Parts Issued**

**Quantity**

Receiver Extension	1.00
Ball Mount 3/4"	1.00
Pin W/clip 5/8 For Hitch	2.00
Shop Supplies	1.00
Labor: 134.00    Parts: 122.36    Total: 256.36	

---

**Work Order:** 1901099      **Meter:** 1      **In Date:** 01/29/2019    **Closed:** 01/31/2019  
**Problem:** needs 2 2" trailer balls

**Work Completed**

- Secure parts for dept
- Shop Supplies

Hours: 0.50      Comm: 0.00

**Parts Issued**

**Quantity**

Trailer Ball	2.00
Shop Supplies	1.00
Labor: 33.50    Parts: 27.51    Total: 61.01	

---

**Work Order:** 1904124      **Meter:** 42      **In Date:** 04/16/2019    **Closed:** 05/02/2019  
**Problem:** shuts off while driving

**Work Completed**

- Test for stalling; found debris in fuel; Jeffrey Allen Inc. Warranty
- Shop Supplies

Hours: 1.00      Comm: 0.00

**Parts Issued**

**Quantity**

Shop Supplies	1.00
Labor: 67.00    Parts: 3.00    Total: 70.00	

7/7/2025  
4:06:25 PM

10210007

**Palm Beach County Fleet Management Asset Maintenance History**  
**2019 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)**

**Work Order:** 1911340      **Meter:** 316      **In Date:** 10/31/2019      **Closed:** 12/13/2019  
**Problem:** pm/ key switch broken/ no parking brake

**Work Completed**

- pm service
- replace ignition switch with key
- replace parking brake mechanism and adjust brakes
- undercoat equipment
- replace rear turn signal bulbs and clean terminals
- Shop Supplies

**Parts Issued**

**Quantity**

Diesel Key Switch	1.00
Boxed Miniatures	2.00
15-40 Oil	3.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Fuel Filter	1.00
Macs Chain Cable Lube	1.00
Non-chlor Brake Clnr	1.00
Mobil 424 Fluid	4.00
Caliper Mech Park Brake	1.00
Rubberized Undercoat	1.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 657.00

Parts: 273.48

Total: 930.48

**Work Order:** 2008685      **Meter:** 686      **In Date:** 08/28/2020      **Closed:** 09/30/2020  
**Problem:** pm/ jerks/ lights/ steering tilt/ see notes

**Work Completed**

- pm service
- install new led lights. fab new light mounts
- diagnose and send to dealer for rear diff, tilt steering, light relay warranty
- Shop Supplies

**Parts Issued**

**Quantity**

15-40 Oil	3.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Fuel Filter	1.00
Mobil 424 Fluid	4.00
Led Lh S T T W Lic	1.00
Led Rh S T T Lamp	1.00
Shop Supplies	1.00

Hours: 7.50

Comm: 0.00

Labor: 547.50

Parts: 172.51

Total: 720.01



7/7/2025  
4:06:25 PM

10210007

**Palm Beach County Fleet Management Asset Maintenance History**  
**2019 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)**

**Work Order:** 2305777

**Meter:** 1412

**In Date:** 06/09/2023 **Closed:** 07/03/2023

**Problem:** PM Service tail gate latch/ comments

**Work Completed**

- Preventive Maint. Service
- fabricate light bracket
- replace 2 tires rotate
- replace 2 drive shafts - cut off old shafts do to rust clean splines
- replace 2 axles
- replace upper and lower control arm bushings and 4 ball joints - replace all hardware
- replace parking brake asm and disk rotor
- replace front dif
- fix latch on tail gate
- Shop Supplies

**Parts Issued**

**Quantity**

Napa Qt 15w40	3.00
Napagold Oil Filter	1.00
Fuel Filter	1.00
air filter	1.00
Tran Flu Qt Dexron3i	1.00
Mobil 424 Fluid	4.00
Non-chlor Brake Clnr	2.00
25 X 11.00 X 12 Tire Kenda	2.00
propshaft	1.00
Lower Arm Bushing	12.00
Rotor Park Brake	1.00
Caliper Mech Park Brake	1.00
Front Halfshaft Awd	2.00
Arm Bushing	8.00
Rear Propshaft	1.00
Ball Joint	4.00
differential	1.00
Lower Arm Sleeve	2.00
Upper Sleeve	4.00
Shop Supplies	1.00
Tire Disposal Fee	2.00
Freight Charge	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 21.50

Comm: 0.00

Labor: 1,569.50

Parts: 3,655.31

Total: 5,224.81

7/7/2025  
4:06:25 PM

10210007

**Palm Beach County Fleet Management Asset Maintenance History**  
**2019 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)**

---

**Work Order:** 2307110      **Meter:** 2284      **In Date:** 07/19/2023      **Closed:** 08/10/2023

**Problem:** 30A fuse in fuse box blew out. Club car shut down and would not start./ comments

**Work Completed**

- Diag Inop Bed Switch, Replaced Switch
- Center Coolant Pipes Leaking, Replaced Pipes, Bleed Coolant
- Shop Supplies

**Parts Issued**

**Quantity**

Rocker Switch	1.00
1gal Rtu Antifreeze	2.00
Coolant Pipes	1.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 4.50

Comm: 0.00

Labor: 328.50

Parts: 454.99

Total: 783.49

---

**Work Order:** 2310632      **Meter:** 2373      **In Date:** 10/20/2023      **Closed:** 11/16/2023

**Problem:** Stalls intermittently. Clicks intermittently when trying to start vehicle. No Start

**Work Completed**

- Remove Starter Rebuild Starter Solenoid, Install
- Replaced Clutch Drive And Belt, Test Drove
- Rust Treatment
- Replaced Passenger Rear Trailing Link Assy
- Shop Supplies

**Parts Issued**

**Quantity**

Electronic Cleaner	1.00
Extend Rust Cntr Aero	2.00
Fleet Coat Gloss Blk	2.00
Clutch Drive	1.00
Belt	1.00
Trailing Link Assy	1.00
Pl Epoxy Syringe 25ml	1.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 6.00

Comm: 0.00

Labor: 438.00

Parts: 1,004.74

Total: 1,442.74

7/7/2025  
4:06:25 PM

10210007

**Palm Beach County Fleet Management Asset Maintenance History**  
**2019 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)**

---

**Work Order:** 2408169      **Meter:** 2696      **In Date:** 08/23/2024      **Closed:** 08/29/2024  
**Problem:** PM Service comments

**Work Completed**

**Parts Issued**

**Quantity**

- rust issues. not cost effective to repair
- Shop Supplies

Shop Supplies

1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

---

**Work Order:** 2506191      **Meter:** 2696      **In Date:** 07/02/2025      **Closed:** 07/03/2025  
**Problem:** Transition Prep Charge

**Work Completed**

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

**Total Hours: 67.00**

**Total Labor: 4,870.00**

**Total Comm: 0.00**

**Total Parts: 6,609.60**