



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V871

In Date: 12/09/2005
Close Date: 12/19/2005

Meter Reading: 26,163.00

Problem?

B inspection escort1

Task performed:

See B Inspection pre-printed form

<u>Parts</u>	<u>Quantity</u>
PH3506OIL FILTER 51042	1

Workorder: V898

In Date: 12/13/2005
Close Date: 12/30/2005

Meter Reading:

Problem?

a/c fan control knob not working on highest setting ESC1

Task performed:

<u>Parts</u>	<u>Quantity</u>
NO PARTS USED	

Workorder: V1195

In Date: 01/17/2006
Close Date: 01/20/2006

Meter Reading:

Problem?

WILL NOT START ESC1

Task performed:

<u>Parts</u>	<u>Quantity</u>
78-72BATTERY GROUP 78	1

Workorder: V1206

In Date: 01/17/2006
Close Date: 01/26/2006

Meter Reading:

Problem?

SPEEDOMETER INOP, ESC-1

Task performed:

<u>Parts</u>	<u>Quantity</u>
NO PARTS USED	



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V1619

In Date: 02/23/2006
Close Date: 03/27/2006

Meter Reading: 29,502.00

Problem?

Check for noise in rear end Escort1

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1848

In Date: 03/14/2006
Close Date: 03/29/2006

Meter Reading: 30,478.00

Problem?

B INSPECTION ESC1

Task performed:

Parts

Quantity

See B Inspection pre-printed form

PH3506OIL FILTER 51042

1

Vendor?: TCI

Workorder: V2041

In Date: 03/30/2006
Close Date: 04/03/2006

Meter Reading: 31,288.00

Problem?

REPLACE 2 TIRES ESCORT1

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2724

In Date: 05/23/2006
Close Date: 06/05/2006

Meter Reading:

Problem?

turn signals 10-7 Sta 81 Escort 1

Task performed:

Parts

Quantity

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V2983

In Date: 06/14/2006
Close Date: 06/19/2006

Meter Reading: 35,067.00

Problem?

B inspection Escort 1

Task performed:

Parts	Quantity
PH3506OIL FILTER 51042	1
CA875642487 FILTER AIR	1

Workorder: V3064

In Date: 06/20/2006
Close Date: 06/29/2006

Meter Reading:

Problem?

dead battery, ESC-1

Task performed:

Parts	Quantity
78-72BATTERY GROUP 78	1

Workorder: V3042

In Date: 01/01/1900
Close Date: 07/14/2006

Meter Reading:

Problem?

REPLACE 4 TIRES ESC-1 (CALLAGHAN)

Task performed:

Parts	Quantity
NO PARTS USED	

Vendor?: VC-15214

Workorder: V3995

In Date: 08/18/2006
Close Date: 08/28/2006

Meter Reading:

Problem?

front right tire has a screw in it. No air lost. ESC 1

Task performed:

Parts	Quantity
NO PARTS USED	



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V4435

In Date: 09/14/2006 Meter Reading: 39,271.00
Close Date: 09/26/2006

Problem?

B INSPECTION AND REPAIRS AS NEEDED

Task performed:

1. B-INSPECTION PERFORMED.

Parts

PH3506OIL FILTER 51042

Quantity

1

Workorder: V5712

In Date: 12/07/2006 Meter Reading: 43,079.00
Close Date: 12/12/2006

Problem?

replace tires at callaghan ent esc 1

Task performed:

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN

Workorder: V5673

In Date: 12/04/2006 Meter Reading:
Close Date: 12/13/2006

Problem?

right front tire is worn ESC1

Task performed:

1. check tires if worn out schedual for tires.
2. take unit to Callaghan for tire replacement.

Parts

NO PARTS USED

Quantity

Workorder: V5764

In Date: 12/11/2006 Meter Reading: 3,994.00
Close Date: 01/09/2007

Problem?

SPEEDOMETER DOES NOT WORK ESC-1

Task performed:

1. Cchecked speedometer and ordered sensor for trans
2. R&R 2 speed sensors at veh. trans

Parts

24203876SPEED SENSOR FOR GMC

Quantity

2



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V5832

In Date: 12/15/2006
Close Date: 01/09/2007

Meter Reading: 4,016.00

Problem?

light on dash reads " change engine oil" ESC 1

Task performed:

B Inspection

Parts

PH3506OIL FILTER 51042

Quantity

1

Workorder: V5950

In Date: 12/25/2006
Close Date: 01/09/2007

Meter Reading: 4,074.00

Problem?

change oil message comes out on dash board ESC1

Task performed:

Work and repairs done on W/O V5832

Parts

NO PARTS USED

Quantity

Workorder: V6168

In Date: 01/09/2007
Close Date: 01/30/2007

Meter Reading: 44,505.00

Problem?

Hand light dead check wiring

Task performed:

1. HAND LIGHTS WIRED FOR KE ON HOT. N.G. FIND 12V SOURCE. RUN NEW WIRE & FUSE TO HOT ALWAYS & MAKE WIRING CONNECTIONS.
2. BRING SALES PERSON TO STN 81 TO INSPECT VR FOR FUTURE SALE. RETURN TO C/S WITH SALES PERSON AFTER VIEWING.
3. MEETING WITH AIRPORTS SUPERVISOR ABOUT SERVICE BAY FOR MAINTANCE ON CRASH TRUCKS WHEN CENTRAL SHOP MOVES.

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V6205

In Date: 01/10/2007 Meter Reading: 4,127.00
Close Date: 01/30/2007

Problem?

SPEEDODOMETER IS STUCK ON 80 MPH ESC1

Task performed:

Parts

Quantity

- CHECK SPEEDOMETER. DASH UNIT FAULTY MADE APPT WITH GEN GMC FOR REPAIR.
- DRIVE VEH TO GEN GMC FOR REPAIRS & RETURN TO STN 81.

NO PARTS USED

Workorder: V6888

In Date: 02/22/2007 Meter Reading: 46,208.00
Close Date: 03/16/2007

Problem?

replace rear tires at callaghan

Task performed:

Parts

Quantity

- Drive esc1 and esc2 back and forth to and from shop and wait for swap out so tires can be exchanged
- Measure bed of truck, check gvw. Measure foam/dry chem skid unit in foam 81 to see if it will fit in esc1. checked weight of skid unit

NO PARTS USED

Vendor?: CALLAGHAN ENT

Workorder: V6279

In Date: 01/15/2007 Meter Reading: 44,748.00
Close Date: 03/20/2007

Problem?

SPEEDOMETER INOP, ESC-1

Task performed:

Parts

Quantity

Speedometer inop ESC1

NO PARTS USED

Vendor?: GENERAL GMC TRUCK

Workorder: V7320

In Date: 03/22/2007 Meter Reading:
Close Date: 03/29/2007

Problem?

Please repair hand held Q-Beam light. esc1

Task performed:

Parts

Quantity

R/R Q. beam spotlight.
Cord damaged; Replaced light assy

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V7270

In Date: 03/19/2007
Close Date: 04/18/2007

Meter Reading: 47,280.00

Problem?

map light 10-7 (esc1)

Task performed:

Checked map light for power and ground ok. R&R bulb

Parts

78166BULB

Quantity

1

Workorder: V8332

In Date: 05/20/2007
Close Date: 06/05/2007

Meter Reading:

Problem?

left rear brake light is not working. ESC1

Task performed:

1. Morning meeting with Ed Ehrke, fuel up service truck, drive to Sta 81 from C/S
2. R&R lens assembly, R&R bulb
3. Clean Mech's Bay at Sta 81 as per Chief Howowitz. Risk Mgt coming to do safety insp of Sta 81 on 05/22/07

Parts

NO PARTS USED

Quantity

Workorder: V8673

In Date: 06/08/2007
Close Date: 06/21/2007

Meter Reading: 51,327.00

Problem?

ESCORT 1 NEEDS B INSPECTION

Task performed:

1. B Insp
2. Bring waste oil container, dirty rags old oil filter etc to c/s. Empty waste oil, crush filters etc Return to ST 81
3. R & R wiper blades

Parts

CA875642487 FILTER AIR

91-22WIPER BLADE

PH3506OIL FILTER 51042

Quantity

1

2

1

Workorder: V8671

In Date: 06/08/2007
Close Date: 07/09/2007

Meter Reading: 4,787.00

Problem?

driver seat cover is torn, needs to be replaced esc1

Task performed:

1. DRIVE VEHICLE TO TRUCK AND TRAILER USA FOR THEM TO ORDER SEAT COVERS.
2. R&R 2 FRONT SEAT BACKREST & SEAT BOTTOM SEAT COVERS.

Parts

SSC-3SEAT COVERS

Quantity

1



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V9102

In Date: 07/02/2007 Meter Reading: 4,864.00
Close Date: 07/09/2007

Problem?

screw in driver front tire. ESC1

Task performed:

Parts

Quantity

1. REMOVE SCREW FROM TIRE- AIR LEAKING.
CALLED CALLAHAN TIRE- MAKE APPT FOR 2 NEW
TIRES AS R/F WORN ALSO. CALLED C/S FOR
PURCHASE ORDER FOR TIRE REPLACEMENT.

NO PARTS USED

Workorder: V9105

In Date: 07/02/2007 Meter Reading: 51,915.00
Close Date: 07/30/2007

Problem?

REPLACE TIRES AT CALLAGHAN ENT

Task performed:

Parts

Quantity

Replace tires - Callaghan

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V10350

In Date: 09/10/2007 Meter Reading: 5,781.70
Close Date: 09/25/2007

Problem?

a/c blower not working. ESC1

Task performed:

Parts

Quantity

1. DIAGNOSE WHY A/C BLOWER NOT WORKING,
FOUND BURNED CONNECTOR AT BLOWER
RESISTOR UNDER DASH- ORDERED PARTS.

15862656CONNECTOR

1

2. GET PARTS IN THE A.M. THEN DRIVE TO STA 81
FROM CENTRAL SHOP.

89019088RESISTOR

1

3. R/R BLOWER RESISTOR ASSEMBLY, R/R
UPDATED WIRING HARNESS TO BLOWER
RESISTOR.

4. AS PER ED EHRKE- DRIVE TO OLD CENTRAL
SHOP FROM STA 81 TO OPEN GATE FOR OUTSIDE
VENDOR.



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V10411

In Date: 09/13/2007

Meter Reading: 55,353.00

Close Date: 09/26/2007

Problem?

B INSPECTION AND REPAIRS AS NEEDED ESC1

Task performed:

- 1. Get parts/travel to Stn81 from CS
- 2. Meeting at CS
- 3. B-Inspection
- 4. Bring all old oil (filters/waste oil to CS, crush filters & empty waste oil container from ST81)

Parts

Quantity

PH3506OIL FILTER 51042

1

CA875642487 FILTER AIR

1

Workorder: V10315

In Date: 09/07/2007

Meter Reading: 5,167.00

Close Date: 09/28/2007

Problem?

Right/Rear tire has 2 screws in it. esc1 at callaghan

Task performed:

REPLACE 2 TIRES

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN TIRE

Workorder: V11638

In Date: 11/16/2007

Meter Reading: 5,451.20

Close Date: 11/27/2007

Problem?

Front left head light out. Thanks.

Task performed:

- 1. R/R L/F headlight hsnng asy; R/R/ low beam bulb
- 2. Screw in R/R tire; soap test-leaks; rem screw; install plugin tire; ok now

Parts

Quantity

90069006 BULB ASSY

1



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V12088

In Date: 12/15/2007

Meter Reading:

Close Date: 01/04/2008

Problem?

ELECTRICAL SHORT, 360 LIGHT BAR REMAINS ON WITH POWER TURNED OFF. ESC-1

Task performed:

1. R headlight Inop, bulb replaced bulb also day time running bulb and marker.
2. Eng. stalls, throttle body clogged also plugs and wires need replacemtn and cleaned throtle body.
3. Eng. dings excessivly when accelerating, needs a tune up, tested fuel and ignision system no faults codes, replaced plugs and wires road test brought to shop and delivered back.

Parts

Quantity

12571164SPARK PLUGS 04 GMC 2500HD	8
90069006 BULB ASSY	1
4114DAYLITE BULB 15199562	1

Workorder: V12723

In Date: 01/21/2008

Meter Reading: 5,697.60

Close Date: 02/01/2008

Problem?

LT FR LIGHT BAR LIGHT NOT WORKING ESC1

Task performed:

Left front corner strobe inop; replc bulb j

Parts

Quantity

02036273300 TURBO94 CORNERLINEAR REFLECTOR	1
--	---

Workorder: V13585

In Date: 02/28/2008

Meter Reading: 62,249.00

Close Date: 03/11/2008

Problem?

b inspection and repairs as needed esc1

Task performed:

1. "B" inspection
2. R & R tag light
3. R & R headlight assembly, R & R daytime driving light bulb and socket, splice and heat shrink wires
3. R & R battery

Parts

Quantity

15W40BSYN OIL BULK QTS	6
15W40QSYN OIL QT	7
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	1
78-72BATTERY GROUP 78	1
194BULB	1
4114DAYLITE BULB 15199562	1
15306157PIG TAIL FOR 4114	1
PH3506OIL FILTER 51042	1



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V13859

In Date: 03/12/2008
Close Date: 03/20/2008

Meter Reading:

Problem?

ES1 NEEDS HOLD DOWN BRACKET FOR 30 LB EXTINGUISHER IN BED

Task performed:

1. Drive to St 81 from C/S, Drive CSC-1 to Callaghan Tire Co from St 81 for 4 tires and alignment. return to St 81 from Callaghan Tire. Drive to C/S from St 81
2. Travel to St 81 from C/S, Travel to C/S from St 81
3. Drill holes and mount 30 Lb, fire extinguisher bracket to slide out tray in bed of vehicle.

Parts

Quantity

NO PARTS USED

Workorder: V13980

In Date: 03/19/2008
Close Date: 03/24/2008

Meter Reading: 63,152.00

Problem?

driving lt full of water

Task performed:

1. drive to and return from sta 81
2. r/r /r/s driving /turn sig housing assy, r/r driving light bulb.

Parts

Quantity

4114DAYLITE BULB 15199562

1

15199561RF LAMP

1

3157NAAMBER BULB

3

Workorder: V13936

In Date: 03/17/2008
Close Date: 03/26/2008

Meter Reading: 63,152.00

Problem?

front end alignment callaghan ent esc1

Task performed:

Front end alignment - Callaghan

j

Parts

Quantity

NO PARTS USED

Vendor?: CALLGHAN



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V13937

In Date: 03/17/2008

Meter Reading: 63,152.00

Close Date: 03/26/2008

Problem?

replace tires at callaghan esc 1

Task performed:

Parts

Quantity

Replace tires ESC1 - Callghan

j

NO PARTS USED

Vendor?: CALLGHAN

Workorder: V14170

In Date: 03/30/2008

Meter Reading:

Close Date: 04/01/2008

Problem?

There is no brake fluid in station. Brake reservoir needs servicing.esc1

Task performed:

Parts

Quantity

1. Drive to St 81 from C/S and return to C/S from St 81
2. check brake fluid reservoir. Fluid level is 1/4" from max line normal. As disk brakes wear, fluid level drops. OK

NO PARTS USED

Workorder: V14407

In Date: 04/11/2008

Meter Reading:

Close Date: 04/29/2008

Problem?

ES-1 has a dead battery.

Task performed:

Parts

Quantity

1. Drive from Central Shop to St. 81, Return from St. 81 to Central shop
2. R & R Battery check for draw check for any lights or radios staying on. Check charging system. No problems found.
3. Map Light - Check charging system for ground problems, R & R Bulb

78-72BATTERY GROUP 78

1

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

1



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V15666

In Date: 06/10/2008
Close Date: 07/08/2008

Meter Reading: 66,496.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED ESC1

Task performed:

1. B-Inspection with all filters & oil change; reset oil life reminder on dashboard display.
2. R/R serpentine fan belt; R/R A/C fanbelt. j

Parts

Quantity

K040378BELT SUBURBANS 2002/2003	1
K060923BELT	1
15W40BSYN OIL BULK QTS	6
PH3506OIL FILTER 51042	1

Workorder: V16401

In Date: 07/17/2008
Close Date: 07/30/2008

Meter Reading:

Problem?

REMOVE COMMAND CENTER FROM THIS VEHICLE AND INSTALL IN NEW ESCORT 1 VEHICLE

Task performed:

1. Travel to St81 from C/S; from St81 to C/S at day's end.
2. Rem command center from vehicle j

Parts

Quantity

NO PARTS USED

Workorder: V17175

In Date: 08/20/2008
Close Date: 09/08/2008

Meter Reading: 6,524.20

Problem?

right front siren speaker needs repaired or replaced it is not working ESC1

Task performed:

- report of siren speakers not working. diagnose cause found both speakers working and a bad indicator light.

Parts

Quantity

NO PARTS USED

Workorder: V20306

In Date: 01/12/2009
Close Date: 01/26/2009

Meter Reading: 6,570.00

Problem?

screw in left rear tire, please repair esc1

Task performed:

- 1- Find screw soap area remove screw, no leak detector
- 2- Meeting with Tim Calhoun.

Parts

Quantity

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V19638

In Date: 12/09/2008
Close Date: 03/06/2009

Meter Reading: 6,547.00

Problem?

FRONT END HAS NOISE PLEASE CHECK, SOUNDS LIKE SOMETHING IS LOOSE

Task performed:

Ck all front steering/suspension components-ok; road test veh; noise heard; grease steering/suspension; noise still there; further ck; fnd play in steering column; might need new or end play adj? j

Parts

CB031/4X2-1/2 BELTING

Quantity

1

Workorder: V21396

In Date: 02/27/2009
Close Date: 03/11/2009

Meter Reading: 71,041.00

Problem?

B inspection and related repairs ESC-2

Task performed:

1. Travel to Stn81 from C/S.
2. B-Inspection.
3. Rotate tires. j

Parts

PH3506OIL FILTER 51042

15W40BSYN OIL BULK QTS

Quantity

1

6

Workorder: V21899

In Date: 03/18/2009
Close Date: 04/07/2009

Meter Reading: 6,586.70

Problem?

drivers side daytime running light 10-7 please repair esc 2

Task performed:

1. Travel to Stn81 from C/S; travel to C/S from Stn81.
2. R/R L/S headlight hsnng asy to gain access to daytime running light; R/R bulb. j

Parts

9006XSLLEHEADLAMP M2 HI

4114DAYLITE BULB 15199562

Quantity

1

1

Workorder: V24062

In Date: 06/14/2009
Close Date: 06/18/2009

Meter Reading: 6,646.10

Problem?

ES2 air conditioner shutting on and off.

Task performed:

Did performance test on A/C sys; normal in/out of evap & accumulator cold; sweating back to compt; 42 degrees coming out of dash vent; clutch cyls on low fan w/ idle. j

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V22457

In Date: 04/10/2009

Close Date: 07/02/2009

Meter Reading:

Problem?

Dead battery (Escort 2)

Task performed:

Charge/test; NPF.

No parts or labor. j

Parts

Quantity

NO PARTS USED

Workorder: V24917

In Date: 07/20/2009

Close Date: 08/03/2009

Meter Reading: 71,787.00

Problem?

a/c 10-7

Task performed:

1. Chkd A/C sys; no proble found.
2. Got more infor frm drv; chk frm clutch & hi-side press; let veh run; fnd pass side ducts blow hot; pass side blows cool by themselves after time; R/R dash; chk controls for A/C sys; ordered parts.
3. Travel to Stn81 from C/S; travel to C/S frm Stn81.
4. More dia on A/C sys for repair.
5. Travel to Stn81 from C/S; travel to C/S from Stn81.
6. Tried to get veh to fail (heat from drivers side vents when A/C on); wld not fail.

Parts

Quantity

NO PARTS USED

Workorder: V25349

In Date: 08/06/2009

Close Date: 08/10/2009

Meter Reading: 72,009.00

Problem?

replace wiper blades ESC-2

Task performed:

R/R wiper blades. j

Parts

Quantity

91-22WIPER BLADE

2



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V26750

In Date: 10/07/2009

Meter Reading:

Close Date: 10/22/2009

Problem?

heater hose is leaking. esc2

Task performed:

Parts

Quantity

1. Travel to Stn81 from C/S; travel to C/S from Stn81.
2. Dia cooling sys leak; adapter betwn heater hose & heater core NG; called parts dept; GMC dealer has in stock; drive to GMC for parts; return to Stn81; R/R adapter; reconnect hose; press test; cooling system-ok; refill coolant. j

NO PARTS USED

Workorder: V27286

In Date: 10/30/2009

Meter Reading: 72,114.00

Close Date: 10/30/2009

Problem?

pick up and deliver unit to callaghan tire ESC2

Task performed:

Parts

Quantity

- Travel to Stn81; then travel to Callaghan; PU driver; return to Stn81. j

NO PARTS USED

Workorder: V27256

In Date: 10/28/2009

Meter Reading: 72,114.00

Close Date: 11/16/2009

Problem?

replace all 4 tires ESC2 (outside agency-callaghan tire)

Task performed:

Parts

Quantity

- Replc all (4) tires ESC2 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V30130

In Date: 02/22/2010

Meter Reading: 75,535.00

Close Date: 03/19/2010

Problem?

head liner is starting to come apart above the driver, please repair ESC2

Task performed:

Parts

Quantity

1. check headliner mask surrounding area apply spray adhesive

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V30310

In Date: 03/01/2010 Meter Reading: 75,535.00
Close Date: 03/25/2010

Problem?

B inspection and repairs ESC 2

Task performed:

- B-Inspection
- 2. R/R R&L lower control arm bumpers.
- 3. Adj all tire pressures. j

Parts	Quantity
15835666306E BUMPERS	2
PH3506OIL FILTER 51042	1
CA875642487 FILTER AIR	1

Workorder: V28785

In Date: 01/04/2010 Meter Reading:
Close Date: 04/14/2010

Problem?

Service past due by date on windshield sticker 07/2009. Please complete.

Task performed:

completed On wo 30310

Parts	Quantity
NO PARTS USED	

Workorder: V33063

In Date: 06/22/2010 Meter Reading: 72,009.00
Close Date: 06/29/2010

Problem?

won't start ESC-2

Task performed:

- 1. Btry dead; put charger on veh after charging; test btry; failed test.
- 2. R/R btry; cln connections. j

Parts	Quantity
78-72BATTERY GROUP 78	1
BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY	1

Workorder: V35832

In Date: 10/21/2010 Meter Reading: 80,040.00
Close Date: 11/01/2010

Problem?

B inspection and repairs ESC 2

Task performed:

- 1. Travel to Stn81 from CS; Do B-Inspection on veh.
- 2. Rep map light; R/R lens, reflector & bulb rep bulb contacts.
- 3. R/R R/R taillight lens; R/R B/U lt bulb.
- 4. Rotate tires - inspect brakes.
- 5. Adj all tire press; 80 PSI rear, 50 PSI frnt. j

Parts	Quantity
18047512MASTER CLY	1
PH3506OIL FILTER 51042	1
3157TAIL LIGHT BULBS	1



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V38220

In Date: 02/02/2011
Close Date: 02/14/2011

Meter Reading: 72,009.00

Problem?

brake fluid leak ESC-2

Task performed:

Dia whether hydro boost on mast cyl leaking; R/R master cyl; bleed brakes & road test. j

Parts

NO PARTS USED

Quantity

Workorder: V39204

In Date: 03/15/2011
Close Date: 03/22/2011

Meter Reading: 82,891.00

Problem?

Dead battery please check

Task performed:

Get parts, travel to Stn81; chk veh; btry 100% dead; R/R btry; test charging sys; look for any lights left on; none fnd. j

Parts

78-72BATTERY GROUP 78
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

Quantity

1
1

Workorder: V39464

In Date: 03/27/2011
Close Date: 04/04/2011

Meter Reading: 82,891.00

Problem?

Right rear tire flat. foam 81

Task performed:

Travel to Stn81 frm C/S; air up tire then mov veh to mech bay; screw in tire; called Ehrke; will send tire rep co. out to Stn81; escort tire tech into/out of airport Stn81. j

Parts

NO PARTS USED

Quantity

Workorder: V39527

In Date: 03/29/2011
Close Date: 04/04/2011

Meter Reading: 82,891.00

Problem?

Replace wiper blades the driver side is torn on both ends

Task performed:

Get parts; travel to Stn81; R/R wiper blades. j

Parts

91-22WIPER BLADE

Quantity

2



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V39504

In Date: 03/28/2011
Close Date: 04/25/2011

Meter Reading: 82,891.00

Problem?

repair flat ESC 1

Task performed:

Repair flat ESC1 - Boulevard j

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD

Workorder: V40856

In Date: 05/25/2011
Close Date: 05/25/2011

Meter Reading: 82,891.00

Problem?

ground control raido is not working.

Task performed:

reported to radio shop on 5/25/2011.

Parts

NO PARTS USED

Quantity

Workorder: V42151

In Date: 07/20/2011
Close Date: 08/08/2011

Meter Reading: 82,891.00

Problem?

B Inspection @ Roger Dean

Task performed:

B Inspection @ Roger Dean. Replaced rear brake pads and resurfaced rotors. Engine was leaking oil so the oil cooler line was replaced. A/C unit was recharged. A/C belt was replaced. Repaired the engine oil pan that was leaking. Replaced wiper blades.

Vendor?: ROGER DEAN

Parts

91-22WIPER BLADE
ACX-84534LUG NUT COVER PK10
322502BULB PATIENT GH22
AST4000ASENSOR O2 REGULATOR

Quantity

2
1
1
1

Workorder: V42577

In Date: 08/05/2011
Close Date: 08/12/2011

Meter Reading: 82,891.00

Problem?

Replace all four tires.

Task performed:

Replace all (4) tires - Boulevard j

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V42774

In Date: 08/12/2011

Meter Reading: 82,891.00

Close Date: 08/31/2011

Problem?

map light is broken, Sta 81.

Task performed:

R/R map light; new light diff; had to drill new holes & rewire. j

Parts

LF18TS-LEDMAP LIGHT LED 18 IN

Quantity

1

Workorder: V44438

In Date: 10/17/2011

Meter Reading: 86,279.00

Close Date: 10/19/2011

Problem?

Repair A/C.

Task performed:

ASSIST IN DIAGNOSING AIR SUSP. FAULT

Parts

NO PARTS USED

Quantity

CHECK OUT PROBLEM, TO GET SYSTEM TO FAULTER

CHECKED TRUCK BUILDS BRAKE AIR SLOWLY
CHECKED DISCHARGE LINE BYPASSED GOV
CHECKED INTAKE RESTRICTION FINALLY TRACED
PROBLEM TO FAULTY GOV REPLACED GOV TRUCK
BUILDS AIR NORMALLY NOW

R&R COMPRESSOR DISCHARGE FITTING TO
TIGHTEN AND REASEL (LOOSE AND LEAKING)

Vendor?: ROGER DEAN



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V43769

In Date: 09/19/2011

Meter Reading: 85,382.00

Close Date: 10/26/2011

Problem?

A/C blows only hot air. Sta 81.

Task performed:

Parts

Quantity

CHECK OUT VEH, CHECK DASH CONTROLS, HEATER VALVE AND BLEND DOOR NO PROBLEM FOUND, VEH IS BLOWING OLD AIR NOW

NO PARTS USED

CHECKED R&L BLEND DOOR MOTORS FOR OPERATION FROM HOT TO COLD, BOTH WORK FIN

RUN VEH AND TEST DRIVE A/C OK CANT REPRODUCE FAULT

DELIVER VEH TO RODGER DEAN CHEVROLET

RODGER DEAN HAD VEH 3 DAYS - THEY CANT FIND PROBLEM, RETURNED VEH TO US SPOKE TO SERV MAGR SEVERAL TIMES TO HELP DIAGNOSIS

Workorder: V44609

In Date: 10/22/2011

Meter Reading:

Close Date: 11/15/2011

Problem?

ES2 MAKING SQUEAKING NOISE @ REAR DRIVE SHAFT AREA.

Task performed:

Parts

Quantity

checked veh, remove driveshaft at rear axle flange, u joint bad

88964413U-JOINT 04 GMC SIERA

3

get parts travel to st 81 t&r 2 piece drive shaft and --bring r&r u joint retap test vett

aslo attached to this work order is wo 44694

Workorder: V44694

In Date: 10/26/2011

Meter Reading:

Close Date: 11/15/2011

Problem?

drive shaft making squeeking noise while driving forward. Sta 81.

Task performed:

Parts

Quantity

ref to wo 44609 for work completed

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V45347

In Date: 11/21/2011

Meter Reading:

Close Date: 12/08/2011

Problem?

Engine light on constantly

Task performed:

Parts

Quantity

TRAVEL TO ST-81 FROM C/S HOOKUP SCAN TOOL TO GET FAULT CODE. CHECK ALL EVAPORATIVE EMISSION HOSES, CONNECTIONS ETC.

NO PARTS USED

Workorder: V44732

In Date: 10/27/2011

Meter Reading:

Close Date: 12/15/2011

Problem?

AC on the driver side blows hot. Blows cold on the passenger side.

Task performed:

Parts

Quantity

CHECK WITH KEN HE SAID THAT WHEN THIS HAPPEN, TRUCK NEED TO GO RIGHT TO RODGER DEAN TO SEE PROBLEM. ON GOING PROBLEM.

NO PARTS USED

Workorder: V47503

In Date: 02/22/2012

Meter Reading: 88,521.00

Close Date: 03/06/2012

Problem?

The anti freeze is low.

Task performed:

Parts

Quantity

ADDED ANTIFREEZE TO CORRECT LEVEL.

ALA00350-50 EXTENDED LIFE COOLANT GAL

1

Workorder: V44151

In Date: 10/04/2011

Meter Reading: 85,892.00

Close Date: 03/09/2012

Problem?

A/C blows hot air on Drivers side after short periods of driving with no change back to cold. at sta 81

Task performed:

Parts

Quantity

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V48344

In Date: 04/02/2012
Close Date: 04/05/2012

Meter Reading: 88,758.00

Problem?

UNIT INVOLVED IN ACCIDENT ON CALL

Task performed:

TRAVEL TO STA 81 TOW VEHICLE TO SHOP. TRAVEL HOME.

Parts

NO PARTS USED

Quantity

Workorder: V48564

In Date: 04/10/2012
Close Date: 05/29/2012

Meter Reading: 88,758.00

Problem?

repair accident damage

Task performed:

REPAIRED ACCIDENT DAMAGE.

Parts

NO PARTS USED

Quantity

Vendor?: ALPACKER FORD

Workorder: V49801

In Date: 06/01/2012
Close Date: 06/13/2012

Meter Reading: 89,595.00

Problem?

broken gas cap esc 1

Task performed:

REPLACED FUEL CAP ON TRUCK.

Parts

225253006817 GAS CAP - SUBURB
2582733520915842 FUEL CAP SUBURBAN

Quantity

1
1

Workorder: V50278

In Date: 06/20/2012
Close Date: 07/12/2012

Meter Reading: 89,753.00

Problem?

headliner coming down near windshield.

Task performed:

CHECKED HEADLINER REPORTED TO SHOP.

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V51294

In Date: 08/01/2012

Meter Reading: 90,474.00

Close Date: 08/09/2012

Problem?

ESC 2 ANTI FREEZE LEAK @ HEATER HOSE Y.

Task performed:

REMOVED DAMAGED HEATER HOSE ASSEMBLY
INSTALLED NEW FILLED FLUIDS AND CHECKED.

Parts

15792820HEATER HOSE Y

Quantity

1

Workorder: V51623

In Date: 08/15/2012

Meter Reading:

Close Date: 09/17/2012

Problem?

Vehicle will not start. Battery seems okay. AT 81

Task performed:

INSTALLED NEW BATTERY

Parts

78-72BATTERY GROUP 78

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

8C3Z9030CFUEL CAP F350

Quantity

1

1

1

Workorder: V52215

In Date: 09/06/2012

Meter Reading: 90,474.00

Close Date: 09/19/2012

Problem?

LIGHT BAR 10-7 F 81

Task performed:

LIGHT BAR INOP/ PIN CORRODED B-STROBE PACK
INSIDE LIGHTS BAR/ DISASSYM LIGHT BAR
TROUBLSHOOT REPAIR CONNECTOR AT STROBE
PACK TEST OK.

Parts

NO PARTS USED

Quantity

Workorder: V47814

In Date: 03/07/2012

Meter Reading: 89,250.00

Close Date: 10/03/2012

Problem?

Change oil came up on digital display. per FF Britt, Sta 81

Task performed:

B inspection
oil and filter change

Vendor?: ROGER DEAN

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V52686

In Date: 09/28/2012
Close Date: 10/15/2012

Meter Reading: 91,502.00

Problem?

transmission and/or coolant leak

Task performed:

TRANSMISSION AND/OR COOLANT LEAK.

Parts

NO PARTS USED

Quantity

Vendor?: ROGER DEAN CHEVROLE

Workorder: V53145

In Date: 10/17/2012
Close Date: 12/10/2012

Meter Reading:

Problem?

Hand light not working. L-side alley light burned out.

Task performed:

FOUND BAD CONNECTIONS ON WIRING HARNESS.

Parts

H35SN12BULB

Quantity

2

Workorder: V53241

In Date: 10/22/2012
Close Date: 12/10/2012

Meter Reading:

Problem?

A/C inop in setting 1, 2, and 3. A/C working in setting 4 and 5. Escort truck

Task performed:

INSTALLED NEW BLOWER MOTOR RESISTER.

Parts

22807123MODULE BLOWER CONTROL

Quantity

1

Workorder: V54763

In Date: 01/02/2013
Close Date: 01/09/2013

Meter Reading:

Problem?

Needs oil. Its at the low mark on the dipstick

Task performed:

CORRECTED OIL TO PROPER LEVEL.

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V54990

In Date: 01/10/2013
Close Date: 01/22/2013

Meter Reading: 92,898.00

Problem?

replace front tire

Task performed:

REPLACE FRONT TIRE.

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

Workorder: V55580

In Date: 02/06/2013
Close Date: 02/08/2013

Meter Reading:

Problem?

Need engine oil ASAP.....engine states 5w-30

Task performed:

DELIVERED OIL FOUND UNIT LOW CORRECTED
LEVEL RESET WARNING MESSAGE IN DASH.

Parts

Quantity

NO PARTS USED

Workorder: V54279

In Date: 12/06/2012
Close Date: 04/15/2013

Meter Reading:

Problem?

escort 2's ground radio's mic wire is split and showing

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V57149

In Date: 04/23/2013
Close Date: 04/23/2013

Meter Reading: 41,110.40

Problem?

Replace 3 tires

Task performed:

REPLACE 3 TIRES.

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN TIRE



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V55526

In Date: 02/04/2013

Close Date: 04/24/2013

Meter Reading:

Problem?

change oil light is on.

Task performed:

pm not done on this ticket

Parts

Quantity

NO PARTS USED

Workorder: V56717

In Date: 03/29/2013

Close Date: 04/24/2013

Meter Reading: 94,490.00

Problem?

B-inspection [Roger Dean]

Task performed:

B INSPECTION
REPLACE SPARK PLUGS
IGNITION WIRES
VALVE COVER GASKET
REPAIR TEMPERATURE GAUGE
Vendor?: ROGER DEAN

Parts

Quantity

NO PARTS USED

Workorder: V57407

In Date: 05/01/2013

Close Date: 05/07/2013

Meter Reading:

Problem?

Driver side top light bar white strobe light is out Foam truck ?

Task performed:

CHECK OUT LT BAR POWER SUPPLY, NO POWER
TO REAR PACK PULL CONSOLE GO TO LT BAR
CABLE FIND FUSES MISSING FUSE TO REAR
POWER REPLACE FUSE PUT TRUCK TOGETHER.

Parts

Quantity

H27W12VH27W12V BULB

1

SL6POWER SUPPLY - WHELEN LIGHT BAR

1

Workorder: V56664

In Date: 03/27/2013

Close Date: 09/10/2013

Meter Reading: 96,479.00

Problem?

passenger side front tire needs to be replace.

Task performed:

REPAIRED ON DO-440-041513-15332

Parts

Quantity

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V60660

In Date: 09/21/2013
Close Date: 09/27/2013

Meter Reading: 97,007.00

Problem?

engine has an oil leak,found with no oil on the dipstick. AT 81

Task performed:

CHECK OUT OIL LEAK ON MOTOR FOUND REAR MAIN ON OIL PAN LEAKING NEEDS TO GOO TO SHOP FOR REPAIR LET FORMAN KNOW OF PROBLEM OIL LEVEL OK.

Parts

NO PARTS USED

Quantity

Workorder: V60646

In Date: 09/20/2013
Close Date: 10/09/2013

Meter Reading: 97,007.00

Problem?

no engine oil on the dipstick.

Task performed:

i check oil and it looks good.

Parts

NO PARTS USED

Quantity

Workorder: V60551

In Date: 09/17/2013
Close Date: 10/10/2013

Meter Reading: 97,007.00

Problem?

batteries dead

Task performed:

INSTALLED NEW BATTERIES CHECKED CHARGING SYSTEM.

Parts

78-72BATTERY GROUP 78

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

Quantity

2

2



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V61084

In Date: 10/07/2013
Close Date: 10/15/2013

Meter Reading: 97,402.00

Problem?

B inspection Escort 2

Task performed:

1. B-INSPECTION.
2. ASSIST B INSPECTION.

Parts	Quantity
PH3506OIL FILTER 51042	1
CA875642487 FILTER AIR	1
2421095658608 TRANSFILTER 4L80 DEEP PAN	1
91-22WIPER BLADE	2
TRANSYNDALLISON TRANS FLUID GAL	2
15W40BSYN OIL BULK QTS	6

Workorder: V61108

In Date: 10/08/2013
Close Date: 10/15/2013

Meter Reading: 97,402.00

Problem?

check oil and trans fluid level. check alternator voltage

Task performed:

CHECK OIL, TRANS. FLUID AND CHECK VOLTAGE.

Parts	Quantity
NO PARTS USED	

Workorder: V60916

In Date: 10/01/2013
Close Date: 10/21/2013

Meter Reading: 97,402.00

Problem?

check engine light is on at 81

Task performed:

TRANY CODE REPAIRED ON ANOTHER WORK ORDER #

Parts	Quantity
NO PARTS USED	

Workorder: V61113

In Date: 10/08/2013
Close Date: 10/21/2013

Meter Reading: 97,402.00

Problem?

Engine Trouble light is on. Also, having transmission shifting issues. Transmission high revs before the vehicle upshifts.

Task performed:

repaired on another work order #

Parts	Quantity
NO PARTS USED	



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V61428

In Date: 10/21/2013
Close Date: 10/23/2013

Meter Reading: 97,402.00

Problem?

replace transmission

Task performed:

REPLACE TRANSMISSION.

Parts

Quantity

NO PARTS USED

Vendor?: ROGER DEAN CHEVROLE

Workorder: V61580

In Date: 10/28/2013
Close Date: 10/31/2013

Meter Reading: 97,402.00

Problem?

Repair front end and align

Task performed:

REPLACE TRANSMISSION.

Parts

Quantity

NO PARTS USED

Vendor?: GOOD YEAR

Workorder: V61584

In Date: 10/28/2013
Close Date: 11/05/2013

Meter Reading: 97,402.00

Problem?

replace worn shifter

Task performed:

REPLACE WORN SHIFTER

Parts

Quantity

NO PARTS USED

Vendor?: ROGER DEAN

Workorder: V62017

In Date: 11/14/2013
Close Date: 11/15/2013

Meter Reading:

Problem?

Fix oil leak please.

Task performed:

CHECKED TRUCK NEEDS REAR MAIN SEAL.

Parts

Quantity

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V61975

In Date: 11/13/2013

Meter Reading:

Close Date: 11/26/2013

Problem?

Leaking antifreeze

Task performed:

TRAVEL TO ST-81 CHCK OUT COOLING LEAK CHECK MOTOR PRESSURE TRUCK CANT FIND LARGER LEAK NEEDS RAD AND BELT. TRIED TO TIGHTEN FITTING ON OIL COOLER.

Parts

Quantity

12637202BELT FAN	1
15075118RAD CAP WPB	1
15190249CONNECTOR	2
15226661CONNECTOR	2
22840116RADIATOR ASSY	1

Workorder: V62570

In Date: 12/08/2013

Meter Reading: 97,909.00

Close Date: 12/12/2013

Problem?

REPLACE RADIATOR

Task performed:

WENT TO AIRPORT TO PICK UP TRUCK BROUGHT BACK TO SHOP R&R RAD FOUND NAIL IN TIRE AND HAD IT FIXED. FOUND TRANS LOCK ED E SAID TO SEND TO ROGER DEAN.

Parts

Quantity

NO PARTS USED

Workorder: V62573

In Date: 12/08/2013

Meter Reading:

Close Date: 12/13/2013

Problem?

screw in left rear tire. leaking air. AT 81

Task performed:

PERPAIRED ON 62677.

Parts

Quantity

NO PARTS USED

Workorder: V62677

In Date: 12/12/2013

Meter Reading: 98,484.00

Close Date: 12/23/2013

Problem?

REPAIR FLAT

Task performed:

REPAIR FLAT

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V63038

In Date: 12/30/2013

Meter Reading:

Close Date: 01/03/2014

Problem?

leaking transmission fluid

Task performed:

Parts

Quantity

TRAVEL TO ST-81 CHECK TRANS LEAKS. CLEAN TRANS GO OUTSIDE TEST DRIVE UNIT RECHECK REAR SEAL LEAKING NEEDS TO GO BACK.

NO PARTS USED

Workorder: V64367

In Date: 02/19/2014

Meter Reading:

Close Date: 03/10/2014

Problem?

Replace bulb Support 81

Task performed:

Parts

Quantity

CHECK ALL LIGHT NO BAD BULB FOUND.

NO PARTS USED

Workorder: V65604

In Date: 04/10/2014

Meter Reading:

Close Date: 04/14/2014

Problem?

Brake light out for a while.

Task performed:

Parts

Quantity

CHECK BRAKE LIGHTS AND ALL OTHER LIGHT FOUND DOME OUT RIGHT SIDE BRAKE LIGHT OUT.

NO PARTS USED

Workorder: V65124

In Date: 03/22/2014

Meter Reading:

Close Date: 04/29/2014

Problem?

Passenger brake light is out

Task performed:

Parts

Quantity

CHECKED OK.

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V66621

In Date: 05/20/2014
Close Date: 05/21/2014

Meter Reading: 100,742.00

Problem?

dead battery and Left rear brake light out

Task performed:

TRAVEL TO STA-81. CHECK CHARGING SYSTEM OK
REPLACED BATTERY. REPLACED L/REAR TAIL LIGHT
BULBS. TRAVEL TO SHOP TO GET TIRE FOR
BOULEVARD TRAVEL HOME.

Parts

Quantity

BATTERY EPA TAX	1
BATTERY EPA TAX \$1.50 PER BATTERY	1
3157TAIL LIGHT BULBS	1
65-72BXT65750 BATTERY	1

Workorder: V68690

In Date: 08/14/2014
Close Date: 08/19/2014

Meter Reading: 102,292.00

Problem?

Tires worn

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: ELPEX

Workorder: V68825

In Date: 08/20/2014
Close Date: 08/20/2014

Meter Reading: 102,292.00

Problem?

Align front end

Task performed:

Alignment

Parts

Quantity

388863HOSE KIT	2
1841760C1TENSIONER	1

Vendor?: ELPEX TIRESOLES



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V68641

In Date: 08/13/2014

Meter Reading: 102,420.00

Close Date: 08/27/2014

Problem?

B-inspection oil change light on l/f tire bald

Task performed:

Parts

Quantity

B-inspection
Repaired a/c
Replaced battery
Replaced engine and trans mount
Replaced steering gear
Replace r/s upper control arm
Replaced steering wheel
Replaced l/f A post molding
Replace r/r seat belt cover
Replaced r/s headlight assy and auto headlight sensor
Complete brake job and rotors

NO PARTS USED

Vendor?: AL PACKER

Workorder: V69811

In Date: 10/01/2014

Meter Reading: 103,378.00

Close Date: 10/24/2014

Problem?

A/C works intermittently. Cool at first then gets hot like the heaters on.

Task performed:

Parts

Quantity

Prep for and drive to airport. Check A/C unit. Found blend door motor is not good. Remove motor and order a new one.

89018374ACTUATOR A/C DOOR

1

Workorder: V69726

In Date: 09/26/2014

Meter Reading: 102,109.00

Close Date: 10/29/2014

Problem?

ES2 A/C BLOWING HOT ON DRIVERS SIDE, BLOWING COLD ON PASS SIDE.

Task performed:

Parts

Quantity

Blend door inoporable

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V70403

In Date: 10/23/2014
Close Date: 11/06/2014

Meter Reading: 103,378.00

Problem?

replace ac blend motor

Task performed:

1. Replace driver side blend door motor for A/C. Test operation. It is good now.

Parts

NO PARTS USED

Quantity

2. Assist with repair.

Workorder: V71880

In Date: 12/27/2014
Close Date: 01/05/2015

Meter Reading:

Problem?

vehicle wont start ESC 1

Task performed:

Check out, no start battery dead-R/R battery,check starting and charging system ok.

Parts

78-72BATTERY GROUP 78

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

Quantity

1

1

Workorder: V71849

In Date: 12/24/2014
Close Date: 01/08/2015

Meter Reading: 104,366.00

Problem?

Dead Battery

Task performed:

Checked truck and on board charger-ok

Parts

NO PARTS USED

Quantity

Workorder: V71968

In Date: 12/31/2014
Close Date: 01/08/2015

Meter Reading: 104,466.00

Problem?

ES2 NEEDS WINDSHIELD WIPERS.

Task performed:

Installed windshield wiperblades

Parts

91-22WIPER BLADE

Quantity

2



10/17/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11498

GMC Sierra FULLSIZE 4X4 SUV

Workorder: V72062

In Date: 01/05/2015

Meter Reading: 104,466.00

Close Date: 01/08/2015

Problem?

Dead battery. Truck wont start.

Task performed:

1. Checked system for shorts or load when not running-checked batterys. Batterys and alternator went to Al packer picked up escort 1 delivered to airport.
2. Assist with above

Parts

Quantity

78-72BATTERY GROUP 78	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2
7C3Z10346EAALTERNATOR	1
65-72BXT65750 BATTERY	1

Workorder: V72307

In Date: 01/14/2015

Meter Reading:

Close Date: 01/20/2015

Problem?

Vehicle won't start. kph

Task performed:

1. Went to airport to check battery which was bad. R & R battery. Check for draw and found hand light drawing 2 amps. Unplug handlight and draw went away. Put in another handlight and draw was gone.
2. Found map light not working. Found bad connection. Put in new fuse holder and light worked.

Parts

Quantity

78-72BATTERY GROUP 78	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	1

Workorder: V72390

In Date: 01/16/2015

Meter Reading: 104,551.00

Close Date: 02/10/2015

Problem?

Replace AM/FM Radio escort 2

Task performed:

1. Install new radio.

Parts

Quantity

25916154XRADIO EXCHANGE	1
-------------------------	---



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (K11498) 2004 - GMC SIERRA Fullsize 4X4

K11498

CSHOP-2015-1640

Comments: **NO START K11498 CHARGE BATTERIES IS OK NOW**

Date Opened 7-8-2015 Date Finished 7-23-2015 Meter 1 Reading: 106,906

TASKS PERFORMED

NO PARTS USED

BATTERY

- 2 BATTERY; BATTERY GROUP 78
- 2 BATTERY; BATTERY GROUP 78
- 2 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
- 2 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY

CSHOP-2015-204

Comments: **ESCORT 2 GMC SIERRA FM RADIO IN CAB NOT WORKING. SHORTING AND CAUSING THE TRUCK TO NEED TO BE JUMP STARTED.**

Date Opened 4-22-2015 Date Finished 5-14-2015 Meter 1 Reading: 105,857

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DIAGNOSE ELECTRICAL

CSHOP-2015-4287

Date Opened 12-3-2015 Date Finished 2-8-2016 Meter 1 Reading: 112,235

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

- 12/02/2015 ENGINE / 19: LOOSE / INSPECT
CHECK ENGINE LIGHT ON AND NEEDS SERVICING.
- 12/02/2015 SERVICE REQUEST / 18: LEAKING / INSPECT
AM/FM RADIO NOT WORKING
- 01/08/2016 ENGINE / 19: LOOSE / INSPECT
1. CHECK ENGINE LIGHT HAS BEEN ON FOR AT LEAST A MONTH. 2. RADIO DOES NOT WORK OR TURN ON.

CSHOP-2015-954

Comments: **B-INSPECTION AL PACKER QC BEFORE SENDING BACK TO ST 81**

Date Opened 6-2-2015 Date Finished 6-2-2015 Meter 1 Reading: 106,905

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

Asset Work Order History K11498

CSHOP-2015-975

Comments: **B-INSPECTION**

Date Opened 6-3-2015 Date Finished 6-4-2015 Meter 1 Reading: 106,906

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2016-1563

Comments: **ESCORT 2 POWER STEERING PUMP NO FLUID**

Date Opened 4-1-2016 Date Finished 4-1-2016 Meter 1 Reading: 113,650

POWER STEERING LOW

TASKS PERFORMED

NO PARTS USED

RESERVOIR

Service Requests:

04/01/2016 SERVICE REQUEST / 19: LOOSE / INSPECT
ESCORT 2 - THE PS PUMP IS SCREAMING WHILE TURNING AND BRAKING. I CHECKED DIPSTICK, NOTHING ON
DIPSTICK. I FOUND A 1/2 BOTTLE OF PS FLUID FOR GM VEHICLES. AFTER ADDING THAT THE DIPSTICK STILL IS DRY

CSHOP-2016-2035

Date Opened 4-28-2016 Date Finished 5-12-2016 Meter 1 Reading: 114,412

TASKS PERFORMED

Q PARTS

FLUID STEERING 1 FLUID; P/S FLUID

CSHOP-2016-3555

Comments: **ON-CALL POWER STEERING PUMP MAKING NOISE**

Date Opened 7-25-2016 Date Finished 7-28-2016 Meter 1 Reading: 115,669

TASKS PERFORMED

Q PARTS

POWER STEERING PUMP 2 FLUID; P/S FLUID
2 FLUID; GAL CONTAINER TRANS FLUID

Service Requests:

07/24/2016 STEERING / 17: INSUFFICIENT LUBRICANT / LUBRICATE
POWER STEERING SQUEALING/ MAKING NOISE.

CSHOP-2016-358

Date Opened 1-25-2016 Date Finished 1-25-2016 Meter 1 Reading: 112,235

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

Asset Work Order History K11498

CSHOP-2016-3743

Date Opened 8-2-2016 Date Finished 8-2-2016 Meter 1 Reading: 115,751

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2016-3854

Comments: **CHECK ENGINE LIGHT**

Date Opened 8-8-2016 Date Finished 10-31-2016 Meter 1 Reading: 116,412

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FAULT CODE

Service Requests:

08/08/2016 ENGINE / 33: REGISTERS WRONG / PREFORMED DIAGNOSTICS. SENT TO DEALER FOR REPAIRS
SERVICE ENGINE SOON LIGHT ON

09/09/2016 WINDOW / 12: BROKEN / SENT TO DEALER FOR REPAIRS.
DRIVERS DOOR WINDOW IS NOT OPERATING. STUCK HALFWAY OPEN.

CSHOP-2016-5429

Date Opened 11-19-2016 Date Finished 11-19-2016 Meter 1 Reading: 116,629

TASKS PERFORMED

NO PARTS USED

WINDOW REGULATOR

VENDOR? AL PACKER

CSHOP-2016-5829

Date Opened 12-13-2016 Date Finished 12-21-2016 Meter 1 Reading: 116,761

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

3 A/C; FREON LB

CSHOP-2016-5978

Date Opened 12-26-2016 Date Finished 12-26-2016 Meter 1 Reading: 116,917

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS

VENDOR? AL PACKER

Asset Work Order History K11498

CSHOP-2016-792

Comments: **K11498**

Date Opened 2-19-2016 Date Finished 6-9-2016 Meter 1 Reading: 114,700

TASKS PERFORMED

Q PARTS

AM - FM RADIO
FAULT CODE
TURN SIGNAL LIGHTS

1 BULB; TAIL LIGHT BULBS

Service Requests:

02/18/2016 LIGHTS / 12: BROKEN / FOUND FAILED L/R TURN SIGNAL BULB. REPLACED FAILED BULB.
LEFT BLINKERS NOT WORKING

02/18/2016 RADIO / 38: SHORTED / NO 12V BATTERY OR IGNITION AT THE BACK OF THE RADIO. ALL FUSES,
AM/FM RADIO NOT WORKING

05/25/2016 ENGINE / 18: LEAKING / PREFORMED DIAGNOSTICS. EVAP SYSTEM SMALL LEAK DTC PRESENT.
SERVICE ENGINE LIGHT ON

CSHOP-2017-1399

Comments: **UNIT NOT DUE BY MILEAGE AT THIS TIME**

Date Opened 3-7-2017 Date Finished 4-7-2017 Meter 1 Reading: 118,673

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

Service Requests:

03/06/2017 LIGHTS / 12: BROKEN / INSPECT
1-R/R TURN SIGNAL INOP. 2- SERVICE ENGINE SOON LIGHT ON.

CSHOP-2017-2147

Date Opened 4-12-2017 Date Finished 4-12-2017 Meter 1 Reading: 118,673

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-3558

Date Opened 6-15-2017 Date Finished 6-30-2017 Meter 1 Reading: 119,660

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
CRANKING SYSTEM

3 MAC; SILICONE SPRAY 10OZ

Service Requests:

06/15/2017 ENGINE / 12: BROKEN / PREFORMED INSPECTION AND DIAGNOSTICS. FOUND NO RPM SIGNAL I
ENGINE WONT START. ENGINE TURNS OVER BUT WILL NOT FIRE.

Asset Work Order History K11498

CSHOP-2017-3776

Date Opened 6-26-2017 Date Finished 6-26-2017 Meter 1 Reading: 119,662

TASKS PERFORMED

NO PARTS USED

COMMERCIAL WORK - OUTSIDE AGENCY

VENDOR? AL PACKER

CSHOP-2017-4322

Date Opened 7-25-2017 Date Finished 7-27-2017 Meter 1 Reading: 120,482

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
TURN SIGNAL LIGHTS
HVAC SYSTEM

1 9IP; TAIL LIGHT BULBS
1 1GM; A/C TUBE
1 1GM; ACCUMULATOR

CSHOP-2017-6723

Comments: **B-INSPECTION ONLY NO OIL/FILTER CHANGE**

Date Opened 11-21-2017 Date Finished 11-27-2017 Meter 1 Reading: 122,136

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

CSHOP-2017-6731

Date Opened 11-22-2017 Date Finished 12-1-2017 Meter 1 Reading: 122,136

TASKS PERFORMED

Q PARTS

WASHER RESERVOIR
AIR FILTER
FAULT CODE
WIRING
HOSES-LINES & FITTINGS
WHEEL COVERS

1 1GM; CAP
1 FIL; NAPAGOLD AIR FILTER
2 BK; TAPE-ELECTRIC 5COLORS

CSHOP-2017-7039

Date Opened 12-11-2017 Date Finished 12-14-2017 Meter 1 Reading: 122,614

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
CAB-INTERIOR ACCESSORIES

1 NOE; CNSLELID

Service Requests:

12/07/2017 BODY / 12: BROKEN / PREFORMED INSPECTION. CONSOLE LID ON ORDER. DISASSEMBLED FRC
FRONT SEAT CONSOLE LID BROKE APART

Asset Work Order History K11498

CSHOP-2018-1530

Comments: **NO CRANK, HAD TO BE JUMP STARTED L/R TURN SIGNAL INOP**

Date Opened 3-15-2018 Date Finished 3-15-2018 Meter 1 Reading: 123,483

TASKS PERFORMED

Q PARTS

TURN SIGNAL LIGHTS
BATTERY

1 LMP; BULB
1 1AD; BATTERY
1 1AD; BATTERY

CSHOP-2018-4576

Date Opened 8-15-2018 Date Finished 8-15-2018 Meter 1 Reading: 124,427

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2018-4661

Date Opened 8-20-2018 Date Finished 10-18-2018 Meter 1 Reading: 125,046

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
VENDOR TIRE REPAIR/CHANGE

Service Requests:

- 08/19/2018 ENGINE / 18: LEAKING / VERIFIED MIL LAMP ON. PREFORMED DIAGNOSTICS. FOUND DTC P0442 CHECK ENGINE LIGHT
- 08/19/2018 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / TEST DROVE. COULD NOT DUPLICATE STEERING RACK FEEL IS VERY HEAVEY. TRUCK TURNS MUCH SHARPER GOING LEFT. STEERING WHEEL DOESNT RETURN TO CENTER WHEN GOING SHARP LEFT
- 08/19/2018 TIRES / 15: FOREIGN MATERIAL / INSPECTED AND VERIFIED THE LEAK. CALLED CALLAHAN AND LEFT FRONT TIRE HAS A NAIL, AND TIRE IS LOW

CSHOP-2018-6731

Date Opened 11-28-2018 Date Finished 12-12-2018 Meter 1 Reading: 125,050

TASKS PERFORMED

NO PARTS USED

FAULT CODE

Service Requests:

- 11/28/2018 ENGINE / 18: LEAKING / ADJUST CHECK ENGINE LIGHT IS ON.

Asset Work Order History K11498

CSHOP-2018-7308

Date Opened 12-26-2018 Date Finished 12-27-2018 Meter 1 Reading: 125,050

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2019-3832

Date Opened 7-24-2019 Date Finished 7-24-2019 Meter 1 Reading: 128,161

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2019-4016

Date Opened 8-1-2019 Date Finished 8-1-2019 Meter 1 Reading: 128,180

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2019-5839

Date Opened 11-6-2019 Date Finished 12-23-2019 Meter 1 Reading: 128,161

TASKS PERFORMED

NO PARTS USED

FAULT CODE

Service Requests:

11/06/2019 ENGINE / 18: LEAKING / PREFORMED DIAGNOSTICS USING A SCAN TOOL. DTC P0442 (EVAP SYS ENGINE, SERVICE ENGINE LIGHT ON).

CSHOP-2020-187

Date Opened 1-13-2020 Date Finished 1-28-2020 Meter 1 Reading: 130,216

TASKS PERFORMED

Q PARTS

DOOR PROP CYLINDER

1 9AP; GAS SHOCK SUSPA 2PK 15 71
8 4AH; BALL STUD 10MM STAINLESS
2 9AP; GAS SHOCK SUSPA 2PK
4 5AH; 10MM BALL STUD

Service Requests:

01/10/2020 SERVICE REQUEST / 43: WEAK / PREFORMED INSPECTION. ALL OF THE TOPPER DOOR PROPS, HYDRAULIC PISTONS ON THE DOOR OF THE TRUCK BED TOPPER ARE NOT WORKING.

Asset Work Order History K11498

CSHOP-2020-2376

Date Opened 5-4-2020 Date Finished 5-4-2020 Meter 1 Reading: 130,899

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2020-2390

Comments: 2 LIGHT BAR STROBES INOP 2 BODY STROBES INOP 2 TAIL LIGHT STROBES INOP 2 HEADLAMP STROBES INOP
DRIVER`S SEAT CUSHION TORN, DAMAGED HEADLINER FALLING

Date Opened 5-5-2020 Date Finished 6-2-2020 Meter 1 Reading: 130,907

TASKS PERFORMED

Q PARTS

PRE TRIP INSPECTION
STROBE LIGHTS
UPHOLSTERY

2 9IP; S30HACP STROBE CLEAR
2 1WL; CORNER TUBE REFELCTOR
2 1WL; LIGHT LED RED TIR6
1 9IP; POWER SUPPLY

CSHOP-2020-2796

Comments: CAN YOU TELL THEM THAT WE NEED THE EXPEDITION IN FOR A PM K11601 IT`S WAY OVERDUE. I`LL SEND
THEM A LOANER THANK YOU

Date Opened 5-27-2020 Date Finished 6-16-2020 Meter 1 Reading: 131,347

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES
BRAKES

1 2IH; BRAKE FLUID

Service Requests:

05/26/2020 BRAKES / 12: BROKEN / REPAIR
BRAKE ISSUES

CSHOP-2020-3050

Date Opened 6-10-2020 Date Finished 6-27-2020 Meter 1 Reading: 131,347

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
ENGINE AND ACCESSORIES
BATTERY
REPAIR FROM PM - DECALS/CLEANLINESS

1 1AD; BATTERY

Service Requests:

06/06/2020 ENGINE / 12: BROKEN / EXCHANGE - NEW WENT TO DEALER FOR WORK AND REPAIRS
ENGINE, VEHICLE HAS A "LOW ENGINE POWER" READING ON THE INST PANEL. WILL NOT GO FASTER THAN 25 MPH.

Asset Work Order History K11498

CSHOP-2020-4233

Date Opened 8-16-2020 Date Finished 8-19-2020 Meter 1 Reading: 131,957

TASKS PERFORMED

Q PARTS

FAULT CODE

1 1GM; THROTTLE BODY

CSHOP-2020-4684

Date Opened 9-9-2020 Date Finished 9-17-2020 Meter 1 Reading: 132,336

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
TRANSMISSION

Service Requests:

09/06/2020 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / PREFORMED DIAGNOSTICS. MIL LAM
NOT MOVING INTO HIGH GEAR/DRIVE GEAR--DRIVES SLOW 20MPH

CSHOP-2021-1358

Date Opened 3-11-2021 Date Finished 3-11-2021 Meter 1 Reading: 133,994

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FAULT CODE

Service Requests:

03/11/2021 ENGINE / 19: LOOSE / VERIFIED CONCERN. NO THROTTLE. PREFORMED DIAGNOSTICS. ACTIVE
ENGINE WHILE DRIVING A MESSAGE CAME UP ON THE DASH READING "LOW ENGINE POWER" AND THE TRUCK WAS
SLOW TO ACCELERATE AND WOULD ONLY REACH 30 MPH.

CSHOP-2021-2384

Date Opened 4-29-2021 Date Finished 5-4-2021 Meter 1 Reading: 134,500

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

Asset Work Order History K11498

CSHOP-2021-3024

Date Opened 6-1-2021 Date Finished 10-22-2021 Meter 1 Reading: 136,294

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SHORELINE CHARGER

2 MMM; ELECTRICAL TAPE
1 NW; MAXI FUSE HOLDER
1 8HD; CORD EXTENSION 50 10AWG
1 6KU; AC2000 12V PLC TEN 8
1 PTX; PERMATEX
1 6KU; AUTO EJECT

Service Requests:

05/29/2021 SERVICE REQUEST / 12: BROKEN / REPAIR
THIS UNIT NEED A SHORELINE CHARGER ADD TO IT. THANK YOU

CSHOP-2021-5846

Date Opened 10-18-2021 Date Finished 10-19-2021 Meter 1 Reading: 136,291

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BATTERY
CHARGING SYSTEM

1 1AD; BATTERY
1 NNE; NEW ALTERNATOR

CSHOP-2021-6261

Comments: **STARTER NOT WORKING**

Date Opened 11-9-2021 Date Finished 11-16-2021 Meter 1 Reading: 136,525

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
CRANKING SYSTEM

1 1AD; BATTERY
-1 9PH; CORE DEPOSIT
1 9PH; CORE DEPOSIT
1 9PH; STARTER

Service Requests:

11/09/2021 STARTER / 12: BROKEN / REPAIR
VEHICLE WILL NOT START THE STARTER SEEMS TO BE NOT WORKING.

CSHOP-2021-6885

Date Opened 12-17-2021 Date Finished 12-21-2021 Meter 1 Reading: 136,525

TASKS PERFORMED

Q PARTS

DOOR

1 1GM; HANDLE
1 1GM; BEZEL

Service Requests:

12/16/2021 SERVICE REQUEST / 12: BROKEN / REPLACED
TYPE PROBLEM INTO DESCRIPTION, TAILGATE LATCH HANDLE BROKEN.. THE MECHANISM FOR LATCHING THE GATE IS RUSTED. THE MECHANISM STICKS.. THE PLASTIC HANDLE BROKE OPENING THE TAILGATE.

Asset Work Order History K11498

CSHOP-2022-1181

Comments: **REPLACE WINDOW TINT**

Date Opened 3-1-2022 Date Finished 9-15-2022 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

DOOR GLASS

1 9PB; TINT CUSTOM

CSHOP-2022-158

Comments: **DAYTIME RUNNING LIGHT OUT L/F CHECK ENGINE LIGHT ON RATTLE NOISE / MAY BE CATALYTIC CONVERTER HEADLIGHTS FADED**

Date Opened 1-11-2022 Date Finished 2-17-2022 Meter 1 Reading: 137,176

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2022-1653

Date Opened 3-24-2022 Date Finished 4-12-2022 Meter 1 Reading: 137,846

TASKS PERFORMED

NO PARTS USED

ELECTRICAL

Service Requests:

03/24/2022 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / POSSIBLY DUE TO THE LOOSE BATTE TYPE PROBLEM INTO DESCRIPTION ESCORT 2, WAS REPORTED BY OFF GOING CREW THAT IT STALLED AND WAS HARD TO START. I PERSONALLY CHECKED TRUCK OUT AND FOUND NOTHING TO SPEAK OF, FURTHERMORE, I DROVE IT TO STORE FOR SUPPLIES. EVERYTHING WORKED AS IT SHOULD. THEN.... WHILE STOPPING AT GUARD SHACK AND CUTTING THE WHEEL TO LEFT (GOING TO EAST GATE). IT STALLED, I TURNED KEY OFF AND TRIED FOR ABOUT 20 SECONDS TO START. IT FINALLY DID, SPUTTERED A LITTLE AND THEN OPERATING WITHOUT A PROBLEM. ENGINE SPEED WAS AT IDLE AND VEHICLE WAS STOPPED AND PROCEEDED TO GO , WHEN IT HAPPENED. MDB 16207

CSHOP-2022-1930

Comments: **CALLAGHAN TIRE**

Date Opened 4-7-2022 Date Finished 5-16-2022 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

04/06/2022 TIRES / 18: LEAKING / EXCHANGE - NEW
BAD TIRES --- NAIL IN BACK DRIVER SIDE TIRE. IT'S MARKED ON SIDEWALL. TIRE IS WITHOUT AIR-DUE TO LEAKING OUT

Asset Work Order History K11498

CSHOP-2022-2013

Comments: **DEAD BATTERY, NO START**

Date Opened 4-11-2022 Date Finished 4-12-2022 Meter 1 Reading: 137,846

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ELECTRICAL

CSHOP-2022-2925

Comments: **CK FOR STALLING OUT**

Date Opened 5-31-2022 Date Finished 6-30-2022 Meter 1 Reading: 138,020

TASKS PERFORMED

Q PARTS

HIGH-LOW PRESSURE REGULATOR (1	1GM; FUEL RAIL RIGHT
FUEL PUMP	1	1GM; FUEL RAIL LEFT
FAULT CODE	1	9AP; FUEL INJECTION PRESSURE REGULATOR
ENGINE AND ACCESSORIES	1	MPE; CRANKSHAFT SENSOR
REPAIR FROM PM - BELTS	8	CRB; FUELINJECTORMFI
DOOR	1	LUC; LUCAS FUEL TREAT 5OZ
	1	1GM; DOWN STREAM 02
	1	1GM; FUEL PUMP W SENSORS
	1	1GM; MASS AIR FLOW
	1	1GM; DOWN STREAM 02
	1	1GM; UP STREAM 02
	1	1GM; UP STREAM 02
	8	NGK; SPARKPLUG
	1	FIL; NAPAGOLD AIR FILTER
	1	1AD; SPARK PLUG WIRE SET
	1	BEL; PREMIUMPLUGWIRESET
	1	1GM; BELT IDLER
	1	1GM; A C BELT
	1	1GM; SEP BELT
	1	1GM; A C TENSAINER
	1	1GM; BELT TENSAINER
	1	NBH; SERPENTINE BELT

Service Requests:

05/26/2022 SERVICE REQUEST / 12: BROKEN / REPAIR
VEHICLE STALLS WILL STALL OUT WHILE DRIVING, AND AT IDLE.

CSHOP-2022-571

Comments: **AIRPORT TRUCK CK FOR NOT RUNNING**

Date Opened 1-31-2022 Date Finished 1-31-2022 Meter 1 Reading: 137,197

TASKS PERFORMED

NO PARTS USED

FAULT CODE

Asset Work Order History K11498

CSHOP-2022-909

Comments: **CALLAGHAN TIRE**

Date Opened 2-16-2022 Date Finished 2-16-2022 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2023-5729

Comments: **EQUIPMENT MOUNTING**

Date Opened 11-7-2023 Date Finished 11-13-2023 Meter 1 Reading: 142,829

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
EMERGENCY EQUIPMENT

6 6ZA; STRAP 16 25

Service Requests:

11/07/2023 SERVICE REQUEST / 19: REQUEST TO INSTALL 3 EXTINGUISHER MOUNTS. / INSTALLED NEW EX
Need to secure 3 extinguishers in the bed of the truck. The extinguishers roll around and one had accidently discharge. Please
get secured with Velcro strapping or a extinguisher tray. Thank you

CSHOP-2023-6229

Comments: **EMERGENCY LIGHTS**

Date Opened 12-12-2023 Date Finished 12-14-2023 Meter 1 Reading: 143,771

TASKS PERFORMED

Q PARTS

TURN SIGNAL LIGHTS

1 LMP; LAMP

Service Requests:

12/12/2023 LIGHTS / 12: BROKEN / REPLACED FAILED TURN SIGNAL BULB.
VEHICLE LIGHTS NOT WORKING, drivers side rear turn signal out.

CSHOP-2023-6346

Comments: **MAP LIGHT**

Date Opened 12-19-2023 Date Finished 1-9-2024 Meter 1 Reading: 143,771

TASKS PERFORMED

Q PARTS

CAB-INTERIOR ACCESSORIES

1 8AM; 924 798 DOME LAMP SWITCH

CSHOP-2023-6431

Date Opened 12-24-2023 Date Finished 2-12-2024 Meter 1 Reading: 143,771

TASKS PERFORMED

NO PARTS USED

TIRE

Asset Work Order History K11498

CSHOP-2023-712

Date Opened 2-7-2023

Date Finished

2-13-2023

Meter 1 Reading:

139,735

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2024-1257

Date Opened 3-7-2024

Date Finished

6-15-2024

Meter 1 Reading:

143,925

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

2	1GM; A C BELT
2	1GM; FAN BELT
1	9AP; FRONT SEAT COVERS

CSHOP-2024-446

Comments: AC

Date Opened 1-23-2024

Date Finished

2-12-2024

Meter 1 Reading:

143,771

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER

TURN SIGNAL LIGHTS

BATTERY

AXLES-HUBS-AND BEARINGS

HVAC SYSTEM

1	1AD; BATTERY
1	1AD; ALTERNATOR
1	1AD; CORE DEPOSIT
2	1GM; FRONT WHEEL HUB
1	1GM; BLEND DOOR ACTURATOR

Service Requests:

01/21/2024 A/C / 12: PREFORMED DIAGNOSTICS. FOUND DRIVER'S SIDE BLEND DOOR ACTUATOR HAD MECHANICAL AIR CONDITIONING ISSUE, temperature control stuck on heat. Can not get cool air when AC is turned on, Rear turn signal not working, front strobe not working and NOISE coming from front wheels. Not sure if it is a tire or bearing issue. It is only there when vehicle is in motion. It gets louder when speed is increased.

01/28/2024 LIGHTS / 19: BULB FELL OUT OF THE SOCKET. / INSPECTED SOCKET AND REINSTALLED BULB. \ Left turn signal out

01/28/2024 RADIO / 12: BROKEN / REPAIR
Ground radio does not work when truck was turned on. After turning off and on just the radio, it worked okay. This has happened to me a couple of times over the last few shifts, but at random times.

01/29/2024 SERVICE REQUEST / 43: BATTERY FAILED DUE TO OVERCHARGING. / PREFORMED DIAGNOSTIC
Radio shop states vehicle battery has low voltage which is causing issues with the mobile radio

Asset Work Order History K11498

CSHOP-2024-6117

Comments: **TIRES, check and advise**

Date Opened 12-23-2024 Date Finished 2-4-2025 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? EARL COLVARD BOULEVARD TIRE

Service Requests:

12/18/2024 TIRES / 12: BROKEN / EXCHANGE - NEW
Tires need replacement all 4

CSHOP-2024-6151

Comments: **FLUID LEAKING, check and advise**

Date Opened 12-26-2024 Date Finished 12-30-2024 Meter 1 Reading: 13,720

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

12/24/2024 SERVICE REQUEST / 18: LEAKING / VERIFIED CONCERN. ENGINE OIL 4.5 QUARTS LOW. EVIDENC
Check Engine Light On and Leaking Engine Fluids

CSHOP-2024-838

Date Opened 2-12-2024 Date Finished 2-12-2024 Meter 1 Reading: 143,850

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

CSHOP-2025-2364

Comments: **INSPECTION 1. check engine light is on, not repairing at this time truck is going to surplus.**

Date Opened 5-30-2025 Date Finished 7-7-2025 Meter 1 Reading: 13,740

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

CSHOP-2025-2738

Comments: **surplus**

Date Opened 6-25-2025 Date Finished 10-14-2025 Meter 1 Reading: 13,740

TASKS PERFORMED

NO PARTS USED

SURPLUS PREP

Service Requests:

06/23/2025 STARTER / 12: BROKEN / REPAIR
VEHICLE WILL NOT START, dead battery, battery placed on charger. No improvement.

Asset Work Order History K11498

CSHOP-2025-570

Comments: **BOULEVARD TIRE**

Date Opened 2-4-2025 Date Finished 2-4-2025 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

FRONT TIRES

VENDOR? EARL COLVARD BOULEVARD TIRE

RADIO-2017-343

Date Opened 6-26-2017 Date Finished 11-29-2017 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

06/22/2017 RADIO / /
RADIO ISSUES ATCT GROUND RADIO AND 800 MHZ RADIOS NOT WORKING NO POWER TO THEM

RADIO-2018-662

Comments: **TESTED RADIO AND IT WAS WORKING. INSPECTED THE ANTENNA AND CABLE. THE ANTENNA HAD A CRACKED INSULATOR AND THE CABLE SHOWED A POTENTIAL BREAK AT THE ADAPTER ON THE PL259. REPLACED THE ANTENNA AND CONNECTOR.**

Date Opened 6-15-2018 Date Finished 6-15-2018 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

ANTENNA

Service Requests:

06/08/2018 RADIO / /
RADIO ISSUES, ESCORT 2 GROUND RADIO STOPPED WORKING.. IT WOULD TRANSMIT FINE WHEN CLOSE TO THE TOWER. IT WOULD NOT TRANSMIT OR RECEIVE FAR AWAY.

RADIO-2020-368

Date Opened 4-14-2020 Date Finished 4-14-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

04/10/2020 RADIO / /
RADIO ISSUES TROUBLE TRANSMITTING TO ATCT. VEHICLE NEEDS A CHARGER. BATTERY WAS LOW.

Asset Work Order History K11498

RADIO-2020-970

Date Opened 11-10-2020 Date Finished 11-10-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

11/08/2020 RADIO / /
RADIO ISSUES GROUND RADIO DOE NOT TRANSMIT. . CHECKED THE RADIO ON 11/10/2020 NO TROUBLE FOUND

RADIO-2023-1689

Comments: **RADIO DEAD, REPLACED EF JOHNSON RADIO.**

Date Opened 12-11-2023 Date Finished 12-11-2023 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

12/10/2023 RADIO / /
RADIO ISSUES ---POWER IS ON AND THE UNIT IS NOT FUNTIONING AND NOT DISPLAYING TAC CHANNELS

RADIO-2024-1132

Comments: **REWIRED MOBILE RADIO.**

Date Opened 9-13-2024 Date Finished 9-13-2024 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

09/13/2024 RADIO / /
RADIO ISSUES, MOBILE Radio not powering up

RADIO-2024-497

Comments: **ISSUED A NEW PORTABLE BATTERY READER AND ADJUSTED THE BACKLIGHT ON THE TOWER RADIO.**

Date Opened 4-15-2024 Date Finished 4-15-2024 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

04/15/2024 RADIO / /
RADIO ISSUES, back light not working, can not read the display at night.+ BATTERY READER

Asset Work Order History K11498

RADIO-2025-1142

Comments: **Surplus Prep on K11498.**

Date Opened 10-14-2025 Date Finished 10-10-2025 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

SURPLUS PREP

Service Requests:

10/09/2025 RADIO / /
SURPLUS PREP ON K11498.

RADIO-2025-378

Comments: **FULLSIZE 4X4: RADIO ISSUES**

Date Opened 4-14-2025 Date Finished 4-14-2025 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

04/09/2025 RADIO / /
RADIO ISSUES VHF Radio wires are exposed and damaged.
