

3/4/2026
11:24:13 AM

Palm Beach County Fleet Management Asset Maintenance History
10174469 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Total Hours: 159.95 Labor: 10,495.20 Parts: 7,882.43 Comm: 326.56 Charged: 18704.19

Work Order: 838385 **Meter:** 0 **In Date:** 05/12/2008 **Closed:** 05/12/2008
Problem: PRE-DELIVERY INSPECTION

Work Completed

- Pre-delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 932156 **Meter:** 2002 **In Date:** 01/02/2009 **Closed:** 01/06/2009
Problem: P.M. SERVICE.

Work Completed

- Pm Service
- Rotate And Hi Speed Balance All 4 Tires.nitro Fill All Tiresto Spec.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
5w20 Engine Oil	7.00
Used Firex Refurbed Fire Extingshers	1.00
Labor: 180.00 Parts: 52.77 Total: 232.77	

Work Order: 937561 **Meter:** 0 **In Date:** 05/06/2009 **Closed:** 05/08/2009
Problem: 001 WASH TICKET ISSUED OUT 05/06/09

Work Completed

- 001 Wash Ticket Issued Out 05/06/09

Hours: 0.00 Comm: 8.34 Labor: 0.00 Parts: 0.00 Total: 8.34

3/4/2026
11:24:13 AM

Palm Beach County Fleet Management Asset Maintenance History
10174469 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1004747 **Meter:** 5988 **In Date:** 05/07/2010 **Closed:** 05/10/2010

Problem: Erase and program all keys asper lost key.

Work Completed

- Lost key.erase and reprogram all Pats keys with new identification code.
- Shop Supplies

Parts Issued

Parts Issued	Quantity
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1009046 **Meter:** 7347 **In Date:** 08/20/2010 **Closed:** 08/30/2010

Problem: Pm service.

Work Completed

- Perform pm service.
- Replace damage right Tail lamp assembly with new.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Parts Issued	Quantity
Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	7.00
Rh Tail Light Assy	1.00

Hours: 3.50 Comm: 0.00 Labor: 210.00 Parts: 75.43 Total: 285.43

Work Order: 1009095 **Meter:** 7240 **In Date:** 08/23/2010 **Closed:** 08/24/2010

Problem: reflash canceiver/ give to Cynthia for detail

Work Completed

- Flash Canceiver
- Shop Supplies

Parts Issued

Parts Issued	Quantity
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1009180 **Meter:** 7240 **In Date:** 08/25/2010 **Closed:** 08/25/2010

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

3/4/2026
11:24:13 AM

Palm Beach County Fleet Management Asset Maintenance History
10174469 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1104622 **Meter:** 10478 **In Date:** 04/29/2011 **Closed:** 05/03/2011
Problem: Pm servicve.

Work Completed

- P.m. Service.
- Test battery and charging system.charge and retest battery,fail load test.replace defective battery.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00	
1372 Oil Filter Frm Ph2 Wix 51372	1.00	
G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00	
5w20 Engine Oil	7.00	
Wd40 Spray Lube Stock# 405540002	1.00	
Used Firex Refurbed Fire Extingshers	1.00	
31-20 Wiper Blades 20" Blade	2.00	
Group 65 Battery (mtc Bxt-65-850)	1.00	
Labor: 240.00	Parts: 186.37	Total: 426.37

Hours: 4.00

Comm: 0.00

Work Order: 1111190 **Meter:** 12917 **In Date:** 10/21/2011 **Closed:** 10/28/2011
Problem: Pm service

Work Completed

- P.m. Service.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00	
1372 Oil Filter Frm Ph2 Wix 51372	1.00	
5w20 Engine Oil	7.00	
31-20 Wiper Blades 20" Blade	2.00	
Labor: 180.00	Parts: 31.99	Total: 211.99

Hours: 3.00

Comm: 0.00

Work Order: 1207861 **Meter:** 16382 **In Date:** 08/20/2012 **Closed:** 08/22/2012
Problem: P.M. Service.Tire prssire light on.

Work Completed

- P.m. Service.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00	
1372 Oil Filter Frm Ph2 Wix 51372	1.00	
G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00	
5w20 Engine Oil	7.00	
31-20 Wiper Blades 20" Blade	2.00	
Used Firex Refurbed Fire Extingshers	1.00	
Labor: 180.00	Parts: 51.13	Total: 231.13

Hours: 3.00

Comm: 0.00

3/4/2026
11:24:13 AM

Palm Beach County Fleet Management Asset Maintenance History
10174469 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1309393 **Meter:** 19800 **In Date:** 09/16/2013 **Closed:** 09/16/2013

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 97.92 Labor: 0.00 Parts: 0.00 Total: 97.92

Work Order: 1402800 **Meter:** 21439 **In Date:** 03/21/2014 **Closed:** 03/27/2014

Problem: Pm service

Work Completed

- Perform pm service.
- Remove instrument cluster to access and replace failed odometer lamp bulb with new.
- Diagnose for humming noise and replace both failed front wheel bearings/rotor assemblies with new.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Bulb	1.00
Disc Brk Rotor Drum	2.00
Spindle Nut	2.00
Shop Supplies	1.00

Hours: 6.00 Comm: 0.00 Labor: 360.00 Parts: 250.40 Total: 610.40

Work Order: 1409999 **Meter:** 22851 **In Date:** 10/03/2014 **Closed:** 10/08/2014

Problem: Pm service

Work Completed

- Pm service
- Check charging system and test battery. battery failed loadtest. replace defective battery.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Battery 65	1.00
Shop Supplies	1.00

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 185.57 Total: 425.57

3/4/2026
11:24:13 AM

Palm Beach County Fleet Management Asset Maintenance History
10174469 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1504264 **Meter:** 23854 **In Date:** 04/24/2015 **Closed:** 04/30/2015
Problem: Pm service.

Work Completed

- Pm service.
- Perform transmission fluid flush.
- Test and replace defective left reverse lamp bulb.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Wiper Blade	2.00
Napagold Air Filter	1.00
Syn-atf Trans Fluid S	12.00
3156 Wagner Bulb	1.00
Shop Supplies	1.00

Hours: 5.00

Comm: 0.00

Labor: 300.00

Parts: 114.04

Total: 414.04

Work Order: 1511146 **Meter:** 25397 **In Date:** 10/30/2015 **Closed:** 11/03/2015
Problem: Pm service.

Work Completed

- Pm service.
- Resurface both front brake rotors.replace brake pads.service calipers.
- Replace both defective front sway bar links.
- Perform engine coolant flush and refill,
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
20" Wiper Blade	2.00
Disc Brake Pads	1.00
Sway Bar Link - Front Susp	2.00
Peak Global	2.00
Shop Supplies	1.00

Hours: 11.00

Comm: 0.00

Labor: 660.00

Parts: 226.70

Total: 886.70

Work Order: 1511606 **Meter:** 25453 **In Date:** 11/12/2015 **Closed:** 11/18/2015
Problem: check canceiver

Work Completed

- Check and remove canceiver for intremittent errors
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 2.00

Total: 62.00

3/4/2026
11:24:13 AM

Palm Beach County Fleet Management Asset Maintenance History
10174469 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1710073 **Meter:** 28735 **In Date:** 10/13/2017 **Closed:** 10/19/2017

Problem: PM Service, Front end shake.

Work Completed

- P.m. service.
- Battery failed load test after recharge.check electrical system.replace bad battery.
- Perfrom rear differential service.
- Inspect for shake condition .measure tire road force.rteplace one wheel out of limits.rebalance four tires.nitrfill. test drive.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
20" Wiper Blade	2.00
Battery	1.00
75w140 Ford Axle Lube	3.00
Friction Modifier	1.00
Ptex Ultra Grey 3oz	1.00
Non-chlor Brake Clnr	1.00
Wheel Asy	1.00
Tpms Strap	1.00
Shop Supplies	1.00

Hours: 6.00

Comm: 0.00

Labor: 360.00 Parts: 477.08 Total: 837.08

Work Order: 1804168 **Meter:** 29642 **In Date:** 04/20/2018 **Closed:** 04/25/2018

Problem: PM Service

Work Completed

- P.m. service.
- Replace left rear door latch assembly . Retest door operation.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
20" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Napagold Fuel Filter	1.00
Door Latch	1.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 240.00 Parts: 283.18 Total: 523.18

3/4/2026
11:24:13 AM

Palm Beach County Fleet Management Asset Maintenance History
10174469 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1911118 **Meter:** 31845 **In Date:** 10/28/2019 **Closed:** 10/29/2019
Problem: pm service, asset numbers & install tag

Work Completed

- pm service
- replace asset numbers
- top off fuel

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	7.00
Used Fire X Refurbished	1.00
Non-chlor Brake Clnr	1.00

Hours: 3.50 Comm: 0.00 Labor: 255.50 Parts: 57.59 Total: 313.09

Work Order: 2003645 **Meter:** 34709 **In Date:** 04/13/2020 **Closed:** 04/27/2020
Problem: pm service

Work Completed

- pm service

Parts Issued

Quantity

Napagold Oil Filter	1.00
10w30 Motor Oil	7.00
20" Wiper Blade	2.00
Napagold Fuel Filter	1.00

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 30.48 Total: 176.48

Work Order: 2010818 **Meter:** 38116 **In Date:** 10/28/2020 **Closed:** 11/02/2020
Problem: pm service/ battery dead

Work Completed

- Preventive Maint. Service
- test & replace battery & check charging system
- replace center mount stop light bulb

Parts Issued

Quantity

Napa Quart 5w20	7.00
Napagold Oil Filter	1.00
20" Wiper Blade	2.00
Battery	1.00
Boxed Miniatures	1.00

Hours: 3.50 Comm: 0.00 Labor: 255.50 Parts: 184.23 Total: 439.73

3/4/2026
11:24:13 AM

Palm Beach County Fleet Management Asset Maintenance History
10174469 2008 FORD F150 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 2510809 **Meter:** 73378 **In Date:** 11/17/2025 **Closed:** 11/20/2025
Problem: windshield washer sprayer

Work Completed

Parts Issued

Quantity

- Diagnose windshield washer inoperable - Replace washer pump and blow out washer pump lines

Washer Pump

1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 16.91

Total: 89.91

Work Order: 2600656 **Meter:** 73939 **In Date:** 01/23/2026 **Closed:** 01/29/2026
Problem: check engine light on - feels like a misfire

Work Completed

- Diag, Engine Issues

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 0.00

Total: 109.50

Work Order: 2600846 **Meter:** 73939 **In Date:** 01/28/2026 **Closed:** 01/30/2026
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 159.95

Total Labor: 10,495.20

Total Comm: 326.56

Total Parts: 7,882.43