

5/31/2017
9:46:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175039 2009 TORO WORKMAN E2065 Utility Cart, Electric, W/Dump Bed

Workorder: 847228	Problem: PRE-DELIVERY INSPECTION				
Meter Reading: 0		Labor	Parts		
In Date: 11/18/2008	Close Date: 11/18/2008	Hours	Description		Quantity
- Pre-Delivery Inspection		2.00			
	Parts Charge: 0.00	Labor Charge:	120.00		

Workorder: 934339	Problem: NOISE WHEN BACKING UP				
Meter Reading: 0		Labor	Parts		
In Date: 02/24/2009	Close Date: 02/24/2009	Hours	Description		Quantity
- Check Front Brakes For Noise Toro To Come Do Warranty Work		1.50			
- Adj Front Suspension Height					
	Parts Charge: 0.00	Labor Charge:	90.00		

Workorder: 941003	Problem: Test Batteries, Runs Bad				
Meter Reading: 47		Labor	Parts		
In Date: 07/20/2009	Close Date: 08/17/2009	Hours	Description		Quantity
- Charge Batteries-Test Specific Gravity In All Batteries 1285		1.00			
	Parts Charge: 0.00	Labor Charge:	60.00		

Workorder: 945743	Problem: PM Service				
Meter Reading: 47		Labor	Parts		
In Date: 11/05/2009	Close Date: 11/10/2009	Hours	Description		Quantity
- Pm Service		5.00			
- Wash					
	Parts Charge: 0.00	Labor Charge:	600.00		

5/31/2017
9:46:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175039 2009 TORO WORKMAN E2065 Utility Cart, Electric, W/Dump Bed

Workorder: 947432

Problem: GIVE ATTENTION TO CART

Meter Reading: 47	Labor	Parts	
In Date: 12/31/2009	Hours	Description	Quantity
- Wash-Detail-Wash Battery And Wax	2.00		
- Replace County Decals And Asset#S			
Parts Charge:	0.00	Labor Charge:	240.00

Workorder: 1012569

Problem: PM

Meter Reading: 90	Labor	Parts	
In Date: 11/09/2010	Hours	Description	Quantity
- Pm Cart	5.00	SEAL	2.00
- Service Rear Diff		10W30 MOTOR OIL	2.00
Parts Charge:	17.50	Labor Charge:	300.00

Workorder: 1111827

Problem: PM SERVICE

Meter Reading: 125	Labor	Parts	
In Date: 11/03/2011	Hours	Description	Quantity
- Pm	4.50	97819 SPOT MIRROR 6" BOLT ON (VELVAC 708515)	1.00
- Install Side View Mirror			
Parts Charge:	17.04	Labor Charge:	270.00

Workorder: 1210347

Problem: pm service/ update accelerator

Meter Reading: 171	Labor	Parts	
In Date: 10/29/2012	Hours	Description	Quantity
- Pm	6.50	Freight Charge	1.00
- Repalce Potentiometer With Revised Part Adjusted And Calibrated Potentiometer		POTENTIONMETER KIT	1.00
Parts Charge:	261.40	Labor Charge:	390.00

5/31/2017
9:46:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175039 2009 TORO WORKMAN E2065 Utility Cart, Electric, W/Dump Bed

Workorder: 1306301		Problem: batteries wont hold charge		
Meter Reading: 171		Labor	Parts	
In Date: 06/24/2013	Close Date: 07/10/2013	Hours	Description	Quantity
-	Add Water And Charge Batteries. Check Charge System. Full Charge. Clean Terminal. Repalce Broken Terminal.	2.00	DISTILLED WATER 1GAL	3.00
	Parts Charge: 5.89	Labor Charge:	120.00	
Workorder: 1308482		Problem: batteries		
Meter Reading: 207		Labor	Parts	
In Date: 08/22/2013	Close Date: 08/26/2013	Hours	Description	Quantity
-	Test And Replace Batteries And Charge	4.00	BATTERY	8.00
	Parts Charge: 1,149.24	Labor Charge:	240.00	
Workorder: 1311635		Problem: pm service		
Meter Reading: 230		Labor	Parts	
In Date: 11/19/2013	Close Date: 12/10/2013	Hours	Description	Quantity
-	Pm	4.00		
	Parts Charge: 0.00	Labor Charge:	240.00	
Workorder: 1407845		Problem: ck. lights/ck. bed lift/ pm service		
Meter Reading: 284		Labor	Parts	
In Date: 08/11/2014	Close Date: 08/22/2014	Hours	Description	Quantity
-	Pm	7.00	CONTACTOR	1.00
-	Diagnose Check Engine Light-Not Working And Bad Lift		Freight Charge	1.00
-	Replace Two Solenoids		ROCKER SWITCH	1.00
-	Clean And Readjust Rear Shoes And Drums		SOLENOID	1.00
	Parts Charge: 291.86	Labor Charge:	420.00	

5/31/2017
9:46:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175039 2009 TORO WORKMAN E2065 Utility Cart, Electric, W/Dump Bed

Workorder: 1505943

Problem: pm service

Meter Reading: 284	Labor	Parts	Quantity
In Date: 06/15/2015	Hours	Description	Quantity
- Pm	6.00	10W30 MOTOR OIL	2.00
- Service Rear Diff		SEAL	2.00
- Adjust Clean Rear Brakes Adj Parking Brake			
Parts Charge:	20.10	Labor Charge:	360.00

Workorder: 1605627

Problem: pm service

Meter Reading: 503	Labor	Parts	Quantity
In Date: 06/01/2016	Hours	Description	Quantity
- Pm	5.00	DISTILLED WATER 1GAL	1.00
- Wash		MACS BATTERY CLEANER	1.00
Parts Charge:	7.22	Labor Charge:	300.00

Workorder: 1705172

Problem: Transition Prep Charge

Meter Reading: 503	Labor	Parts	Quantity
In Date: 05/25/2017	Hours	Description	Quantity
- Transition Prep Charge	2.00		
Parts Charge:	0.00	Labor Charge:	0.00

Total Parts Charges: **1,770.25** Total Labor Charges: **3,750.00** Total Comm. Charges: **0.00**