

10/17/2016
2:49:07PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155224 2004 GMC 3500 Utility Truck, W/Heavy Duty Vise, Strobes

Workorder: 444497 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	Quantity
In Date: 05/13/2004	Hours	Description	
- Pre-Delivery Inspection	2.00		
Parts Charge:	0.00	Labor Charge:	100.00

Workorder: 446132 **Problem:** TAG CHARGE

Meter Reading: 17	Labor	Parts	Quantity
In Date: 05/28/2004	Hours	Description	
- Tag Charge		TAG CHARGE	1.00
Parts Charge:	51.85	Labor Charge:	0.00

Workorder: 447054 **Problem:** TIRESOLES OF BROWARD INC T070156

Meter Reading: 0	Labor	Parts	Quantity
In Date: 06/03/2004	Hours	Description	
- Tiresoles Of Broward Inc T070156			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	12.00

Workorder: 462479 **Problem:** P.M SERVICE

Meter Reading: 6704	Labor	Parts	Quantity
In Date: 11/22/2004	Hours	Description	
- Pm	4.00	15/40 OIL	10.00
- Shop Supplies		SHOP SUPPLIES	1.00
		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
		10003 INJECTOR CLEANER DON'T REORDER	1.00
		7701 TRANS FILTER ALISSON 29539579 WIX 57701	1.00
Parts Charge:	35.44	Labor Charge:	200.00

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155224 2004 GMC 3500 Utility Truck, W/Heavy Duty Vise, Strobes

Workorder: 545292

Problem: P.M SERVICE,BRAKE WARNING ON INSTRUMENT CLUSTER

Meter Reading: 12719		Labor		Parts	
In Date: 05/19/2005	Close Date: 06/01/2005	Hours	Description	Quantity	
- Pm Service		6.00	10003 INJECTOR CLEANER DON'T REORDER		1.00
- Transport To Dealer For Instrument Cluster			15/40 OIL		10.00
Reprogramming			6678 AIR FILTER FRM CA8755A WIX 46678		1.00
- Shop Supplies			PH5 OIL FILTER LBF PH1218 WIX 51060		1.00
			PS9059B FUEL FILTER LBF LFF8736 WIX 33960XE		1.00
			85/140 GEAR OIL GEAR LUBE		2.00
			SHOP SUPPLIES		1.00
Parts Charge:		70.68	Labor Charge:	300.00	

Workorder: 547430

Problem: 1 800 AUTO TOW FLORIDA INC 50606023

Meter Reading: 0		Labor		Parts	
In Date: 06/04/2005	Close Date: 06/13/2005	Hours	Description	Quantity	
- 1 800 Auto Tow Florida Inc 50606023 Tow From 3307 Capri Rd. Cabana Colonys Dev.In P.B.G. - Tow To Lv Shop					
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 48.00

Workorder: 554697

Problem: P.M SERVICE

Meter Reading: 18054		Labor		Parts	
In Date: 09/08/2005	Close Date: 09/09/2005	Hours	Description	Quantity	
- Pm Service		5.80	15/40 OIL		10.00
- Repair Wiring & Ground			6678 AIR FILTER FRM CA8755A WIX 46678		1.00
- Repair Strobe			PH5 OIL FILTER LBF PH1218 WIX 51060		1.00
- Shop Supplies			10003 INJECTOR CLEANER DON'T REORDER		1.00
			PS9059B FUEL FILTER LBF LFF8736 WIX 33960XE		1.00
			SHOP SUPPLIES		1.00
			31-22 WIPER BLADES 22" WIPER BLADE		2.00
Parts Charge:		71.42	Labor Charge:	290.00	

10/17/2016
2:49:07PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155224 2004 GMC 3500 Utility Truck, W/Heavy Duty Vise, Strobes

Workorder: 634647

Problem: P.M SERVICE,SEE NOTE

Meter Reading: 23723	Labor	Parts	
In Date: 02/16/2006	Hours	Description	Quantity
- Pm Service	10.90	6678 AIR FILTER FRM CA8755A WIX 46678	1.00
- Repair Marker Lights		744821900 215/85R16 WRANGLER HT E	6.00
- Replace All 6 Tires And Balance		PS9059B FUEL FILTER LBF LFF8736 WIX 33960XE	1.00
- Batteries Test And Replace Both Batteries		78-72 BATTERY GROUP 78	2.00
- Tail Gate Cable		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Road Test		SHOP SUPPLIES	1.00
- Shop Supplies		10003 INJECTOR CLEANER DON'T REORDER	1.00
		15/40 OIL	10.00
		L/F PH1218 FRM PH5 WIX 51060 OIL FILTER	1.00
Parts Charge:	1,037.92	Labor Charge:	25.00

Workorder: 640617

Problem: CHECK TAIL GATE STRAPS & DOOR STOPS

Meter Reading: 25260	Labor	Parts	
In Date: 06/08/2006	Hours	Description	Quantity
- R&R Necc Trim And Replace Door Check	1.50	SHOP SUPPLIES	1.00
- Replace Tail Gate Straps		15173407 DRIVERS SIDE DOOR CHECK	1.00
- Shop Supplies			
Parts Charge:	32.95	Labor Charge:	25.00

Workorder: 640805

Problem: CHECK TAIL LIGHTS

Meter Reading: 25260	Labor	Parts	
In Date: 06/13/2006	Hours	Description	Quantity
- Test And Replace 2 Rear Tail Lamps	0.80	SHOP SUPPLIES	1.00
- Shop Supplies		44202R TAIL LIGHT 4" RED 42 LED	2.00
Parts Charge:	96.54	Labor Charge:	40.00

10/17/2016
2:49:07PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155224 2004 GMC 3500 Utility Truck, W/Heavy Duty Vise, Strobes

Workorder: 645810

Problem: P.M SERVICE,SEE LIST

Meter Reading: 27705	Labor	Parts	Quantity
In Date: 09/19/2006	Hours	Description	Quantity
- Pm Service; No Problem Found W/Ft End At This Time	4.50	15/40 OIL	10.00
- Road Test		10003 INJECTOR CLEANER DON'T REORDER	1.00
- Shop Supplies		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		PS9059B FUEL FILTER LBF LFF8736 WIX 33960XE	1.00
		SHOP SUPPLIES	1.00
		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
Parts Charge:	68.88	Labor Charge:	25.00

Workorder: 737337

Problem: P.M.SERVICE

Meter Reading: 30927	Labor	Parts	Quantity
In Date: 04/18/2007	Hours	Description	Quantity
- Pm Service	8.00	15/40 OIL	10.00
- Fill Tires W/Nitrogen		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
- Transmission Flush		PS9059B FUEL FILTER LBF LFF8736 WIX 33960XE	1.00
- Differential Service		10003 INJECTOR CLEANER DON'T REORDER	1.00
- Road Test		85/140 GEAR OIL GEAR LUBE	5.00
- Shop Supplies		SYN/ATF TRANS FLUID SYNTHETIC	16.00
		SHOP SUPPLIES	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
Parts Charge:	152.12	Labor Charge:	27.50

10/17/2016
2:49:07PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155224 2004 GMC 3500 Utility Truck, W/Heavy Duty Vise, Strobes

Workorder: 747249

Problem: P.M.SERVICE.

Meter Reading: 33709	Labor	Parts	
In Date: 11/13/2007	Hours	Description	Quantity
- Pm Service	5.75	PS9059B FUEL FILTER LBF LFF8736 WIX 33960XE	1.00
- Replace Driver'S Rear Marker Light		15/40 OIL	10.00
- R&R Tire; Remount & Balance		SHOP SUPPLIES	1.00
- Shop Supplies		10003 INJECTOR CLEANER DON'T REORDER	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
		19200R RED MARK/LIGHT 4" MARKER LIGHT	1.00
		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
Parts Charge:	86.33	Labor Charge:	60.00

Workorder: 840442

Problem: P.M.SERVICE,L/FRONT TIRE FLAT.

Meter Reading: 36606	Labor	Parts	
In Date: 06/24/2008	Hours	Description	Quantity
- Pm Service	12.00	PS9059B FUEL FILTER LBF LFF8736 WIX 33960XE	1.00
- R&R Filter		15/40 OIL	10.00
- Remove Lens Assy To Access Light; R&R R/F Bulb;		7701 TRANS FILTER ALISSON 29539579 WIX 57701	1.00
Repair Clip Light Marker Assy; Repair Connection To		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
Backup Light		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Repair Ground Circuit For Strobe		744821900 215/85R16 WRANGLER HT E	3.00
- Tighten Body Hold-Downs		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
- R&R 3 Tires & Balance		TIRE DISPOSAL FEE	3.00
- Repair 1 Tire		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Road Test		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	553.64	Labor Charge:	30.00

10/17/2016
2:49:07PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155224 2004 GMC 3500 Utility Truck, W/Heavy Duty Vise, Strobes

Workorder: 845772

Problem: BAD FUEL GAUGE; TROUBLE STARTING

Meter Reading: 37669	Labor	Parts	
In Date: 10/16/2008	Hours	Description	Quantity
- Ck Charging Sys; R&R Batteries	3.25	GROUP 78 BATTERY (ACD 78PS)	2.00
- Ck Starting Sys; R&R Starter		STARTER	1.00
- Test Drive		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	658.72	Labor Charge:	30.00

Workorder: 933727

Problem: P.M.SERVICE/SEE NOTE

Meter Reading: 38600	Labor	Parts	
In Date: 02/09/2009	Hours	Description	Quantity
- Pm Service	14.00	15/40 OIL	10.00
- C/S Fuel Gauge Inop; Verify; Scan For Codes-P2636;		PS9059B FUEL FILTER LBF LFF8736 WIX 33960XE	1.00
Scan To Ck Gauges&Sensors; Pinpoint Test & Found		31-22 WIPER BLADES 22" WIPER BLADE	2.00
Bad Transfer Pump; Replace,Clear&Test		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
- Remove Rear Brake & Hub Assy; Replace Leaking Axle		27140 RED LOCKTITE	1.00
Seal For R/R		R/R AXLE SEAL	1.00
- Replace Both R/R Tires & 1 L/R Tire; Rotate New Tires To		744821900 215/85R16 WRANGLER HT E	4.00
Front & 1 On R/R		TIRE DISPOSAL FEE	4.00
- Install New Decal		09997 BRAKE CLEAN	2.00
- Remove & Lube Steering Shaft		TRANSFER PUMP	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		GASKET	1.00
Parts Charge:	870.78	Labor Charge:	840.00

Workorder: 946100

Problem: P. M. MAINTENANCE

Meter Reading: 40993	Labor	Parts	
In Date: 11/17/2009	Hours	Description	Quantity
- P. M.	6.00	PS9059B FUEL FILTER LBF LFF8736 WIX 33960XE	1.00
- Repair Roof Rack & Back Window, Replace Multiple		15/40 OIL	10.00
Bolts. Install Lock Tight.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
Parts Charge:	69.52	Labor Charge:	720.00

10/17/2016
2:49:07PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155224 2004 GMC 3500 Utility Truck, W/Heavy Duty Vise, Strobes

Workorder: 1005408

Problem: P. M., Speedomter not working, fuel gauge not working, arm rest cover

Meter Reading: 41322	Labor	Parts	
In Date: 05/25/2010	Hours	Description	Quantity
- P. M.	8.75	15/40 OIL	10.00
- R&R Trans Filter.		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
- R&R Tail Light. Repaired Ground For Body Light.		SHOP SUPPLIES	1.00
- Retightened Body Hold Downs.		44202R TAIL LIGHT 4" RED 42 LED	1.00
- Repaired Leak At Fuel Cooler.		7701 TRANS FILTER ALISSON 29539579 WIX 57701	1.00
- R&R Hitch Pintle Pin.		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
- Installed Driving Decal.		18410 PINTLE PIN	1.00
- Shop Supplies		PS9059B FUEL FILTER LBF LFF8736 WIX 33960XE	1.00
Parts Charge: 120.68		Labor Charge: 525.00	

Workorder: 1013703

Problem: P. M., & Screw in L/F tire.

Meter Reading: 42520	Labor	Parts	
In Date: 12/14/2010	Hours	Description	Quantity
- P.M.	8.50	31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Repaired Ground To Body Lights. R&R Bulb.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Beacon Inop, Repaired Bad Connection At Light.		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
- Retightened Body Hold Downs.		PS9059B FUEL FILTER LBF LFF8736 WIX 33960XE	1.00
- Unsiezed & Lubed Hitch.		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
- Tire Repair.		SHOP SUPPLIES	1.00
- Shop Supplies		15/40 OIL	10.00
Parts Charge: 87.13		Labor Charge: 510.00	

Workorder: 1101553

Problem: TRUCK HAS A HARD TIME TO START.

Meter Reading: 42904	Labor	Parts	
In Date: 02/09/2011	Hours	Description	Quantity
- Checked Fuel Filter & Checked For Fuel Leak.	2.50	SHOP SUPPLIES	1.00
- Installed Scanner, Checked For Codes. (None Present).		GROUP 78 BATTERY (ACD 78PS)	2.00
- Charged Both Batteries & Checked Batts. R&R Batteries, Checked Charge Rate.			
- Shop Supplies			
Parts Charge: 188.65		Labor Charge: 150.00	

10/17/2016
2:49:07PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155224 2004 GMC 3500 Utility Truck, W/Heavy Duty Vise, Strobes

Workorder: 1107035

Problem: P. M. SERVICE

Meter Reading: 43837	Labor	Parts	
In Date: 07/01/2011	Hours	Description	Quantity
- Performed P.M.	7.00	PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
- R&R Trans Filter.		PS9059B FUEL FILTER LBF LFF8736 WIX 33960XE	1.00
- Unsiezed & Lubed Hook.		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
- Retightened Body Hold Downs.		15/40 OIL	10.00
- Repaired Grounds For Running Lights.		7701 TRANS FILTER ALISSON 29539579 WIX 57701	1.00
- Shop Supplies		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		SHOP SUPPLIES	1.00
Parts Charge:	84.39	Labor Charge:	420.00

Workorder: 1113593

Problem: P.M.SERVICE,TRUCK WILL NOT START

Meter Reading: 44112	Labor	Parts	
In Date: 12/30/2011	Hours	Description	Quantity
- P. M. Service.	13.00	744821900 215/85R16 WRANGLER HT E	4.00
- Repaired Wiring To Lights.		TIRE DISPOSAL FEE	4.00
- Retightened Hold Downs.		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
- Unsiezed & Lube Hitch.		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- R&R And Balance 4 Tires.		SHOP SUPPLIES	1.00
- Repaired Right Rear Tire.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Batteries Failed Load. Checked For Draw. Recharged		PS9059B FUEL FILTER LBF LFF8736 WIX 33960XE	1.00
Batteries & Recheck, Ok, Batteries Passed.		15/40 OIL	10.00
- Resealed Lines To Fuel Cooler.			
- Shop Supplies			
Parts Charge:	785.38	Labor Charge:	780.00

10/17/2016
2:49:07PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155224 2004 GMC 3500 Utility Truck, W/Heavy Duty Vise, Strobes

Workorder: 1206202

Problem: pm, ck speedometer

Meter Reading: 46279	Labor	Parts	
In Date: 07/02/2012	Hours	Description	Quantity
- Pm	16.00	SHOP SUPPLIES	1.00
- Rr Trans Filter		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
- Repaired Grounds For Two Reversing Light Rr Bulb For Clip Light		PS9059B FUEL FILTER LBF LFF8736 WIX 33960XE	1.00
- Unsiezed And Lubed Hook		6678 AIR FILTER FRM CA8755A WIX 46678	2.00
- Rr And Balanced 2 Tires		744821900 215/85R16 WRANGLER HT E	2.00
- Tire Repaired Rr Tire		INSTRUMENT CLUSTER	1.00
- Removed Washer Reservoir Unplugged Washer Poupn And Reinstall Assy		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Tightened Body Hold Downs		TIRE DISPOSAL FEE	2.00
- Installed Lap Top Performed Gauge Test All Good But No Reponse From Speedo Ck Pm Generator Oood Removed Dash And Icp Installed New Icp And Programed		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Shop Supplies		15/40 OIL	10.00
		7701 TRANS FILTER ALISSON 29539579 WIX 57701	1.00
Parts Charge: 958.81		Labor Charge: 960.00	

Workorder: 1300592

Problem: pm

Meter Reading: 47090	Labor	Parts	
In Date: 01/16/2013	Hours	Description	Quantity
- Pm	8.50	NAPAGOLD OIL FILTER	1.00
- Repaired Ground For Body Lights		NAPAGOLD FUEL FILTER	1.00
- Dtightened Hold Downs And Replace One Bolt		CA8755A AIR FILTER LB	1.00
- Unsiezed And Lubed Hook		15w40 BULK SOUTH REG	10.00
- Repaired Lr Tire		SHOP SUPPLIES	1.00
- Reinstalled Stabilizer Bushing And Retightened		31-22 WIPER BLADES 22	2.00
- Shop Supplies			
Parts Charge: 93.20		Labor Charge: 510.00	

10/17/2016
2:49:07PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155224 2004 GMC 3500 Utility Truck, W/Heavy Duty Vise, Strobes

Workorder: 1307258

Problem: pm,

Meter Reading: 47553	Labor	Parts	
In Date: 07/22/2013	Hours	Description	Quantity
- Pm	9.00	NAPAGOLD AIR FILTER	1.00
- Rr Light Assy Repaired Ground For Running Light		WIPER BLADE	2.00
- Tightened Body Hold Downs		USED FIRE X REFURBISHED	1.00
- Unsiezed And Lubed Hook		SHOP SUPPLIES	1.00
- Repaired Rr Tire		NAPAGOLD FUEL FILTER	1.00
- Tighened Ladder Rack		MARKER LIGHT	1.00
- Ck Ip No Problem At This Time		15w40 BULK SOUTH REG	10.00
- Shop Supplies		PH5 OIL FILTER LBF PH	1.00
Parts Charge: 104.14		Labor Charge: 540.00	

Workorder: 1404222

Problem: pm, gauges incorrect fuel oil or speedmeter

Meter Reading: 47988	Labor	Parts	
In Date: 05/01/2014	Hours	Description	Quantity
- Pm	8.25	FUEL FILTER 6.6 GM	1.00
- Repair Grounds For Lights		15w40 BULK SOUTH REG	10.00
- Freed And Lube Vise		WIPER BLADE	2.00
- Tightened Rack Assy		NAPAGOLD OIL FILTER	1.00
- Tire Repair Rr		NAPA TRANS FILTER	1.00
- Rr Trans Filter		SHOP SUPPLIES	1.00
- No Problems Found At This Time			
- Shop Supplies			
Parts Charge: 97.04		Labor Charge: 495.00	

Workorder: 1408806

Problem: wont start

Meter Reading: 48159	Labor	Parts	
In Date: 09/02/2014	Hours	Description	Quantity
- Ck Battery Chared Failed Load Rr Battery Checked	1.50	GROUP 78 BATTERY	2.00
- Charge Rater And Pass		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 193.19		Labor Charge: 90.00	

10/17/2016
2:49:07PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155224 2004 GMC 3500 Utility Truck, W/Heavy Duty Vise, Strobes

Workorder: 1410861

Problem: PM

Meter Reading: 48450	Labor	Parts	
In Date: 10/30/2014	Hours	Description	Quantity
- Pm	8.50	LED M C LAMP	1.00
- Rr Tail Light And Marker Light Assy Repaired Ground For One Running Light		WASHER FL 15w40 BULK SOUTH REG	1.00 10.00
- Unsiezed And Lubed Hitch Tightned Ladder Rack		LED SUP MDL 44 42 DIO	1.00
- Repaired Rr Tire		FUEL FILTER 6.6 GM	1.00
- Latch And Striker For Tail Gate		USED FIRE X REFURBISHED	1.00
- Shop Supplies		NAPAGOLD AIR FILTER WIPER BLADE SHOP SUPPLIES NAPAGOLD OIL FILTER	1.00 2.00 1.00 1.00
Parts Charge:	191.95	Labor Charge:	510.00

Workorder: 1411300

Problem: driver side rear outer tire stem leaking

Meter Reading: 48470	Labor	Parts	
In Date: 11/12/2014	Hours	Description	Quantity
- Ck Left Rear Tire Flat Repair Left Rear Tire	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

10/17/2016
2:49:07PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155224 2004 GMC 3500 Utility Truck, W/Heavy Duty Vise, Strobes

Workorder: 1504485

Problem: pm, air bag warring light

Meter Reading: 48669	Labor	Parts	
In Date: 05/01/2015	Hours	Description	Quantity
- Pm	13.50	USED FIRE X REFURBISHED	1.00
- Repaired Grounds For Running Light Ordered Rear Light Assy Adn Retrofitted And Installed		LED ID BAR 6 CTRS 744821900 215-85R16	1.00 6.00
- Tightened Ladder Rack And Unsiezed And Lubled Hitch		15w40 BULK SOUTH REG	10.00
- Rr And Balanced Six Tires		WIPER BLADE	2.00
- Remove Door Panel And Adj And Lubed Track Assy		NAPAGOLD OIL FILTER	1.00
- Installed Scanner To Ck Air Bag Light Repaired No Communication Due To Bad Connections Ck For Codes And Rr Fuse And Perfomred Wiggle Test Rd Tested Ok		FUEL FILTER 6.6 GM ONLY SHOP SUPPLIES TIRE DISPOSAL FEE	1.00 1.00 6.00
- Shop Supplies			
Parts Charge: 1,685.63		Labor Charge: 810.00	

Workorder: 1511404

Problem: P.M.SERVICE,AIR BAG LIGHT ON, FUEL INOP.

Meter Reading: 49322	Labor	Parts	
In Date: 11/06/2015	Hours	Description	Quantity
- Pm	10.00	FUEL FILTER 6.6 GM ONLY	1.00
- Repaired Grounds For Running Lights		15w40 BULK SOUTH REG	10.00
- Repaired L Rear Tire		WASHER FLUID CONCENTR	1.00
- Batt Failed Load Recharged And Retested And Passed		NAPAGOLD OIL FILTER	1.00
- Removed Washer Bittle And Repaired Hose And Reinstalled		SHOP SUPPLIES 22" WIPER BLADE	1.00 2.00
- Tightened Ladder Rack			
- Scanned Veh For Codes None Present Unable To Reproduce Problem			
- Shop Supplies			
Parts Charge: 94.89		Labor Charge: 600.00	

10/17/2016
2:49:07PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155224 2004 GMC 3500 Utility Truck, W/Heavy Duty Vise, Strobes

Workorder: 1604610

Problem: Pm service and fuel gauge inop

Meter Reading: 49890		Labor		Parts	
In Date: 05/02/2016	Close Date: 05/06/2016	Hours	Description		Quantity
- Pm Service.		7.00	NAPAGOLD OIL FILTER		1.00
- Trans.Filter Service.			15w40 BULK SOUTH REG		10.00
- Repair Grounds For Running Lights.			WASHER FLUID CONCENTR		1.00
- Repaired Right Rear Tire.			SHOP SUPPLIES		1.00
- Shop Supplies			NAPA TRANS FILTER		1.00
			NAPAGOLD AIR FILTER		1.00
			22" WIPER BLADE		2.00
			FUEL FILTER 6.6 GM ONLY		1.00
Parts Charge: 116.32		Labor Charge: 420.00			

Workorder: 1607091

Problem: Towed in for brake concern

Meter Reading: 49890		Labor		Parts	
In Date: 07/13/2016	Close Date: 07/29/2016	Hours	Description		Quantity
- Replace Leaking Brake Line/Hose From Master Cylinder To Abs Pump And Bleed System.		7.75	SHOP SUPPLIES		1.00
- Repair Leaking Coolant Hose Clamp And Top Off Cooling System.			B FLUID DOT 3-32OZ		1.00
- Test Drive After Repairs.			BRAKE CLEANER		2.00
- Shop Supplies			PEAK GLOBAL ANTIFRZ		1.00
			LINE BRAKE		1.00
Parts Charge: 57.08		Labor Charge: 465.00			

Workorder: 1607224

Problem: Towed in for brakes concern

Meter Reading: 49890		Labor		Parts	
In Date: 07/13/2016	Close Date: 07/15/2016	Hours	Description		Quantity
- Tow From: 1275 Hagen Ranch Road.Boyton Beach To: 13026 N Jog Road Delray Beach					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 96.00	

10/17/2016
2:49:07PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155224 2004 GMC 3500 Utility Truck, W/Heavy Duty Vise, Strobes

Workorder: 1609240

Problem: Transition Prep Charge

Meter Reading: 49890

Labor

Parts

In Date: 09/06/2016

Close Date: 09/06/2016

Hours

Description

Quantity

- Transition Prep Charge

2.00

Parts Charge: 0.00

Labor Charge: 0.00

Total Parts Charges: **8,717.27**

Total Labor Charges: **10,557.50**

Total Comm. Charges: **156.00**