Asset: 10175062 2009 IMPERIAL TI717TT Trailer, 17 Ft. Tilt, Dual Axle

Problem: INSTALL REGISTRATION HOLDER Workorder: 933267

Meter Reading: 0 Labor **Parts** 

In Date: 01/28/2009 Close Date: 01/30/2009 Hours Description Quantity Install Water Proof Reg Holder 1.00 **REGISTRATION HOLDER 97960** 1.00 Shop Supplies SHOP SUPPLIES 1.00

> 13.70 60.00 Parts Charge: Labor Charge:

PRE-DELIVERY INSPECTION Workorder: 934270 Problem:

Meter Reading: 0 Labor **Parts** 

In Date: 02/20/2009 Hours Close Date: 02/20/2009 Description Quantity

Pre-Delivery Inspection 2.00

120.00 Parts Charge: 0.00 Labor Charge:

Problem: P.M. Service Workorder: 947028

Meter Reading: 0 Labor **Parts** 

Quantity In Date: 12/15/2009 Close Date: 12/15/2009 Hours Description P.M. Service 5.00 PS1250F1 BATTERY (POWER SONIC PS-1250-F1) 1.00 SHOP SUPPLIES 1.00

Replace Emergency Brake-Away Battery, Clean & Tighten All Connections

**Shop Supplies** 

41.93 600.00 Parts Charge: Labor Charge:

WELD D RING ON FRONT OF TRAILER Workorder: 947421 Problem:

Meter Reading: 0 Labor **Parts** 

In Date: 12/31/2009 Close Date: 01/13/2010 **Hours** Description Quantity Weld New D-Ring Tie Down To Front Of Trlr 2.00 SHOP SUPPLIES 1.00

Paint Area That Was Welded 6001 TIE DOWN RING 5/8 "D" RING 1.00

Shop Supplies

240.00 Parts Charge: 8.15 Labor Charge:

### Asset: 10175062 2009 IMPERIAL TI717TT Trailer, 17 Ft. Tilt, Dual Axle

				TIT ITAILET, TT I L. TIIL, DUALF	AXIC	
Workorder: 1000632	Proble	em: FIX FLAT	ΓTIRE			
Meter Reading: 0			Labor		Parts	
In Date: 01/15/2010	Close Date: 03/	/02/2010	Hours	Description		Quantity
<ul> <li>Repair &amp; Mount Tire</li> </ul>			6.50	235/80-R16 TIRE / 10841		1.00
<ul> <li>Nitrogen Service</li> </ul>				1/2" THREADED ROD		1.00
<ul> <li>Repair Lock Mech On Be</li> </ul>	d Install & Adjust Nev	v Linkage		6001 TIE DOWN RING 5/8 "D" RII	NG	3.00
<ul> <li>Weld D- Rings On Traile</li> </ul>	r			SHOP SUPPLIES		1.00
<ul> <li>Mount Tire On Spare Rim</li> </ul>	1			16X6 RIM / 10676		1.00
<ul> <li>Shop Supplies</li> </ul>						
	Parts Charge:	270.57	Labor Charge	390.00		
<b>Workorder</b> : 1001080	Proble	em: REPAIR F	FLAT TIRE			
Meter Reading: 0			Labor		Parts	
In Date: 01/29/2010	Close Date: 01/	/29/2010	Hours	Description		Quantity
- Repair Tire & Mount			1.50	SHOP SUPPLIES		1.00
<ul> <li>Check All Tires &amp; Fill With</li> </ul>	n Nitrogen					
- Shop Supplies						
	Parts Charge:	2.00	Labor Charge	90.00		
<b>Workorder:</b> 1002937	Proble	em: TILT BED	LOCK LINKAGE	IS BROKEN		
Meter Reading: 0			Labor		Parts	
In Date: 03/23/2010	Close Date: 04/	/26/2010	Hours	Description		Quantity
- Order Parts And Repair .			1.00	THERADED ROD 1/2 20 X 6 / 47	476	1.00
- Shop Supplies				SHOP SUPPLIES	•	1.00
	Parts Charge:	59.17	Labor Charge			
	J		J			
Workorder: 1012753	Proble	m: Flat tire				
Meter Reading: 0			Labor		Parts	
In Date: 11/16/2010	Close Date: 02/	/07/2011	Hours	Description		Quantity
<ul><li>Repaired Tire</li><li>Shop Supplies</li></ul>			1.00	SHOP SUPPLIES		1.00
Chop Cappiles						

60.00

2.00

Labor Charge:

Parts Charge:

Repair Lights / Clean Contacts

Parts Charge:

## Palm Beach County Fleet Management Asset Maintenance History

### Asset: 10175062 2009 IMPERIAL TI717TT Trailer, 17 Ft. Tilt, Dual Axle

				/		
Workorder: 1101558	Problem:	PM Service	ce			
Meter Reading: 0			Labor		Parts	
In Date: 02/09/2011	Close Date: 03/08/2	2011	Hours	Description		Quantity
- Pm Service			4.00 SHO	P SUPPLIES		1.00
<ul> <li>Shop Supplies</li> </ul>						
	Parts Charge:	2.00	Labor Charge:	240.00		
Workorder: 1102856	Problem:	brake ligh	t out			
Meter Reading: 0			Labor		Parts	
In Date: 03/16/2011	Close Date: 03/22/2	2011	Hours	Description		Quantity
- Rewire Trailer Plug			<b>1.50</b> SHO	P SUPPLIES		1.00
<ul> <li>Shop Supplies</li> </ul>						
	Parts Charge:	2.00	Labor Charge:	90.00		
Workorder: 1106726	Problem:	left rear b	rake light out .			
Meter Reading: 0			Labor		Parts	
In Date: 06/27/2011	Close Date: 07/05/2	2011	Hours	Description		Quantity
- Replaced Light Bulb, Te	sted Circuit		0.50			
	Parts Charge:	0.00	Labor Charge:	30.00		
Workorder: 1200531	Problem:	CHECK L	IGHTS			
Meter Reading: 0			Labor		Parts	
In Date: 01/18/2012	Close Date: 01/23/2	2012	Hours	Description	-	Quantity

30.00

0.50

Labor Charge:

0.00

### Asset: 10175062 2009 IMPERIAL TI717TT Trailer, 17 Ft. Tilt, Dual Axle

Workorder: 1202445 Prob	olem: PM & Lower hitch down one hole
-------------------------	--------------------------------------

Workorder: 1202445	Prob	lem: PM & Lo	wer hitch down one ho	le		
Meter Reading: 0			Labor		Parts	
In Date: 03/12/2012	Close Date: 0	5/25/2012	Hours	Description		Quantity
- Pm Service			<b>7.50</b> SH	OP SUPPLIES		1.00
<ul> <li>Replaced Break Away C</li> </ul>	Cable		408	37 SWITCH CABLE		1.00
- Re-Fasten Battery Box			TIR	RES / 235/80R16		4.00
- Replaced Four Tires, Mo	ount & Balanced		TIR	RE FEE		4.00
- Lower Hitch One Hole			099	997 BRAKE CLEAN		2.00
- Shop Supplies						
	Parts Charge:	643.39	Labor Charge:	450.00		
Workorder: 1206691	Prob	lem: repair / v	veld vanlinda			
Meter Reading: 0			Labor		Parts	
In Date: 07/18/2012	Close Date: 0	7/27/2012	Hours	Description		Quantity
- Repair / Fab /Weld Left	Pivot Bv Vanlinda					

-	Repail / Fab / Weld Left Fivot by Varillida		
		0.00	

1,695.00 **Commercial Charge:** 0.00 Parts Charge: 0.00 Labor Charge:

Workorder: 1206752	Problem:	Transprot for repair
--------------------	----------	----------------------

Meter Reading: 0 Labor **Parts** 

In Date: 07/19/2012 **Close Date:** 07/19/2012 Hours Description Quantity

Tow From: He Shop To: 3787 Boutwell Rd, (Vandlinda)

0.00 0.00 **Commercial Charge:** 134.77 Parts Charge: Labor Charge:

Workorder: 1207922 REPLACE BREAK AWAY CABLE Problem:

Meter Reading: 0 Labor **Parts** 

In Date: 08/21/2012 **Close Date:** 08/27/2012 Hours Description Quantity Replace Break Away Cable 0.50 4087 SWITCH CABLE 1.00

> Parts Charge: 5.03 30.00 Labor Charge:

Parts Charge:

37.47

Labor Charge:

# Palm Beach County Fleet Management Asset Maintenance History

### Asset: 10175062 2009 IMPERIAL TI717TT Trailer, 17 Ft. Tilt, Dual Axle

- Shop Supplies    Parts Charge:   2.00   Labor Charge:   90.00		Asset: 101750			Trailer, 17 Ft. Tilt, Dual Ax	ile	
In Date: 10/02/2012   Close Date: 10/17/2012   Hours   Description   Quantity	Workorder: 1209400	Problem:	BED LOC	CK DOWN MECHANISM	M NEEDS ADJUSTMENT		
- Reweld Broken Lock Arm Stop	_					Parts	
Shop Supplies	In Date: 10/02/2012	Close Date: 10/17	/2012	Hours	Description		Quantity
Parts Charge:   2.00   Labor Charge:   90.00		n Stop		<b>1.50</b> SHO	P SUPPLIES		1.00
Meter Reading: 0		Parts Charge:	2.00	Labor Charge:	90.00		
In Date: 05/06/2013   Close Date: 06/24/2013   Hours   Description   Quantity	Norkorder: 1304453	Problem:	Fab. side	boards .			
- Fabricate Side Boards.	Meter Reading: 0			Labor		Parts	
- Shop Supplies	In Date: 05/06/2013	Close Date: 06/24	/2013	Hours	Description		Quantity
Workorder: 1307127 Problem: Pm service  Meter Reading: 0 Labor Parts  In Date: 07/17/2013 Close Date: 07/18/2013 Hours Description Quantity  - Pm Service. 4.50 SHOP SUPPLIES  - Repair Rr Marker Light Wiring.  - Shop Supplies  Parts Charge: 2.00 Labor Charge: 270.00  Workorder: 1311618 Problem: Repair lights  Meter Reading: 0 Parts  In Date: 11/19/2013 Close Date: 12/03/2013 Hours Description Quantity  - Replace Damaged Light Bar. 1.50 15050R ID BAR RED MOD		Porto Chargo	305 24	2/0 S SHO T-1 E GLO 3 IN PIN SAFI	STRAIGHT LINK CHAIN 10 P SUPPLIES BLACK PAINT GLOSS S BLK 4.1 STEEL CHANNEL		1.00 1.00 1.00 2.00 6.00 40.00 4.00 6.00
Meter Reading: 0		Faits Charge.		_	720.00		
In Date: 07/17/2013   Close Date: 07/18/2013   Hours   Description   Quantity		Problem:	Pm servi				
- Pm Service Repair Rr Marker Light Wiring Shop Supplies  Parts Charge: 2.00 Labor Charge: 270.00  Norkorder: 1311618 Problem: Repair lights Meter Reading: 0 In Date: 11/19/2013 Close Date: 12/03/2013 Hours Description Quantity - Replace Damaged Light Bar.  1.50 15050R ID BAR RED MOD						Parts	
- Repair Rr Marker Light Wiring Shop Supplies  Parts Charge: 2.00 Labor Charge: 270.00  Norkorder: 1311618  Problem: Repair lights  Meter Reading: 0 In Date: 11/19/2013  Close Date: 12/03/2013  Hours  Description  Quantity - Replace Damaged Light Bar.  1.50  15050R ID BAR RED MOD		Close Date: 07/18	/2013		Description		Quantity
Workorder: 1311618 Problem: Repair lights  Meter Reading: 0 Labor Parts  In Date: 11/19/2013 Close Date: 12/03/2013 Hours Description Quantity  - Replace Damaged Light Bar. 1.50 15050R ID BAR RED MOD	- Repair Rr Marker Light V	Viring.		<b>4.50</b> SHO			1.00
Meter Reading: 0         Labor         Parts           In Date: 11/19/2013         Close Date: 12/03/2013         Hours         Description         Quantity           - Replace Damaged Light Bar.         1.50         15050R ID BAR RED MOD         15050		Parts Charge:	2.00	Labor Charge:	270.00		
In Date: 11/19/2013 Close Date: 12/03/2013 Hours Description Quantity - Replace Damaged Light Bar. 1.50 15050R ID BAR RED MOD	Workorder: 1311618	Problem:	Repair lig	phts			
- Replace Damaged Light Bar. 1.50 15050R ID BAR RED MOD				Labor		Parts	
	In Date: 11/19/2013	Close Date: 12/03	/2013	Hours	Description		Quantity
- Only Supplied	<ul><li>Replace Damaged Light</li><li>Shop Supplies</li></ul>	Bar.		1000	OR ID BAR RED MOD P SUPPLIES		1.00 1.00

90.00

### Asset: 10175062 2009 IMPERIAL TI717TT Trailer, 17 Ft. Tilt, Dual Axle

Labor

Workorder: 1312247 Problem: Locking rod bent.

	In Date: 12/09/2013	Close Date: 12/12/2013	Hours	Description	Quantity
-	Repair And Reinforce Ben	it Locking Rod.	4.50	SHOP SUPPLIES	1.00
-	Replace Damaged Tag Ki	ght. Fabricate Guard To Prevent		LICENSE LAMP	1.00

Further Damage. Shop Supplies

Meter Reading: 0

Parts Charge: 5.99 Labor Charge: 270.00

Workorder: 1403936 Problem: Break away cable.

Meter Reading: 0 Labor Parts

In Date: 04/23/2014 Close Date: 04/24/2014 Hours Description Quantity

- Repair Cable For Break Away Switch. **0.50** 

Parts Charge: 0.00 Labor Charge: 30.00

Workorder: 1407166 Problem: Pm service.

	Meter Reading: 0		Labor		Parts
	In Date: 07/21/2014	Close Date: 08/13/2014	Hours	Description	Quantity
-	Pm Service.		15.00	NAPA BEARING CONE	4.00
-	Replace All Brakes, Bearin	gs And Wheel Seals.		12V5AMP/HOUR BATTERY	1.00
-	Install Battery Box Replace	e Dead Brake Battery.		CUP	4.00
_	Replace Broken Grease F	ittings As Needed.		BRAKE CLEANER	4.00
_	Replace Tag Light, Repair	Wire Harness To Rear Marker		BACKING PLATE ASSM	2.00
	Lights.			SEAL 2.250X3.371X.375	4.00
_	Shop Supplies			CONE	4.00
	Chief Capphice			TRANSF CASE SHAFT BRG	4.00
				BACKING PLATE ASSM	2.00
				SHOP SUPPLIES	1.00

Parts Charge: 696.24 Labor Charge: 900.00

**Parts** 

### Asset: 10175062 2009 IMPERIAL TI717TT Trailer, 17 Ft. Tilt, Dual Axle

Norkorder: 1501920	Problem:	Pm service	Э.			
Meter Reading: 0			Labor		Parts	
In Date: 02/24/2015	Close Date: 03/09	/2015	Hours	Description		Quantity
<ul> <li>Trailer Bed Not Locking.</li> </ul>	Adjust Bed Lock And We	ld	3.50	SHOP SUPPLIES		1.00
Safety Pin To Bed.				LOCK PIN		1.00
<ul> <li>Shop Supplies</li> </ul>				L SPRING LATCH 1/2"		1.00
	Parts Charge:	11.27	Labor Charge:	210.00		
Norkorder: 1507998	Problem:	Pm service	€.			
Meter Reading: 0			Labor		Parts	
In Date: 08/10/2015	Close Date: 08/13	/2015	Hours	Description		Quantity
- Pm Service.			5.00	ST235/80R16 LR-E MTHN		2.00
<ul> <li>Replace Rear Tires.</li> </ul>			;	SHOP SUPPLIES		1.00
<ul> <li>Shop Supplies</li> </ul>			•	TIRE DISPOSAL FEE		2.00
	Parts Charge:	428.08	Labor Charge:	300.00		
<b>Norkorder:</b> 1608001	Problem:	Pm service	e			
Meter Reading: 0			Labor		Parts	
In Date: 08/04/2016	Close Date: 08/08	/2016	Hours	Description		Quantity
- Pm Service.			6.50	SHOP SUPPLIES		1.00
<ul> <li>Replace Brake Battery.</li> </ul>				12V5AMP/HOUR BATTERY		1.00
<ul> <li>Replace Broken Brake S</li> </ul>	Switch.			BREAKAWAY SWITCH		1.00
_	Locking Pin Per Request.					
<ul> <li>Shop Supplies</li> </ul>						
	Parts Charge:	36.63	Labor Charge:	390.00		
Norkorder: 1704851	Problem:	Transition	Prep Charge			
Meter Reading: 0			Labor		Parts	
	Close Date: 05/16	/2017	Hours	Description		Quantity
In Date: 05/16/2017						
In Date: 05/16/2017 - Transition Prep Charge			2.00			

Total Parts Charges: 2,664.86 Total Labor Charges: 5,760.00 Total Comm. Charges: 1,829.77