

6/29/2017
11:02:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10130845 2000 GMC WORKHORSE Van, Stepvan

Workorder: 141611

Problem: PM SERVICE

Meter Reading: 6365	Labor	Parts	
In Date: 06/18/2001	Hours	Description	Quantity
- Pm Service	4.00	L/F AF917-FRM CA3914 WIX 46144 AIR FILTER	1.00
- Shop Supplies		L/F G481 WIX 33481 FUEL FILTER	1.00
		NB-18 WIPER BLADES 18" ANCO 31-18	2.00
		ATFD TRANS FLUID MERCON V	1.00
		SHOP SUPPLIES	1.00
		1401 BRAKE FLUID BRAKE FLUID	1.00
		15/40 OIL	6.00
		L/F#PH51A OIL FILTER WIX 51036 FRAM PH3980	1.00
Parts Charge:	37.57	Labor Charge:	180.00

Workorder: 141686

Problem: ELPEX

Meter Reading: 6370	Labor	Parts	
In Date: 06/19/2001	Hours	Description	Quantity
- Transport To Elpex And Back To Shop	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	90.00

Workorder: 141978

Problem: TIRESOLES OF BROWARD INC T040148/54/50

Meter Reading: 0	Labor	Parts	
In Date: 06/19/2001	Hours	Description	Quantity
- Tiresoles Of Broward Inc T040148/54/50			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	370.78

6/29/2017
11:02:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10130845 2000 GMC WORKHORSE Van, Stepvan

Workorder: 142561

Problem: STALL OUT

Meter Reading: 6458		Labor		Parts	
In Date: 07/03/2001	Close Date: 07/11/2001	Hours	Description	Quantity	
-	R&R Fuel Filtler	5.00	L/F G481 WIX 33481 FUEL FILTER	1.00	
-	R&R Wiper		NB-18 WIPER BLADES 18" ANCO 31-18	1.00	
-	Hook Up Scan Tool.Ck For Codes None Present.Ck Connections At Fuel Pump.Checked Voltages.		SHOP SUPPLIES	1.00	
-	Took To Gmc.Brought Back From Gmc.				
-	Shop Supplies				
Parts Charge:		10.61	Labor Charge:	225.00	

Workorder: 142704

Problem: STEVE'S TOWING INC. 106474

Meter Reading: 0		Labor		Parts	
In Date: 07/03/2001	Close Date: 07/06/2001	Hours	Description	Quantity	
-	Steve'S Towing Inc. 106474 Tow From Congress Ave Just N Of Belvedere - Tow To Heavy Eqpt Shop				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 74.40

Workorder: 248383

Problem: PM SERVICE AND TRANS. SLIPS

Meter Reading: 11499		Labor		Parts	
In Date: 09/24/2002	Close Date: 09/26/2002	Hours	Description	Quantity	
-	Pm	9.50	ATFD TRANS FLUID MERCON V	8.00	
-	Trans Service Slipping? Npf.		SHOP SUPPLIES	1.00	
-	Repair Lights.		L/F G481 WIX 33481 FUEL FILTER	1.00	
-	Reattach W/Washer Reservoir.		L/F AF917-FRM CA3914 WIX 46144 AIR FILTER	1.00	
-	Road Test Transmission.		15/40 OIL	6.00	
-	Shop Supplies		FT1203 TRANS FILTER LBF T709 WIX 58608	1.00	
			L/F#PH51A OIL FILTER WIX 51036 FRAM PH3980	1.00	
Parts Charge:		56.56	Labor Charge:	475.00	

6/29/2017
11:02:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10130845 2000 GMC WORKHORSE Van, Stepvan

Workorder: 336594

Problem: PM SERVICE

Meter Reading: 13501	Labor	Parts	Quantity
In Date: 03/18/2003	Hours	Description	Quantity
- Pm Service	5.50	L/F AF917-FRM CA3914 WIX 46144 AIR FILTER	1.00
- Clean And Adjusted Parking Brake.		31-20 WIPER BLADES 20" BLADE	2.00
- Shop Supplies		L/F#PH51A OIL FILTER WIX 51036 FRAM PH3980	1.00
		15/40 OIL	6.00
		L/F G481 WIX 33481 FUEL FILTER	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	35.87	Labor Charge:	275.00

Workorder: 347200

Problem: PM SERVICE

Meter Reading: 15253	Labor	Parts	Quantity
In Date: 09/03/2003	Hours	Description	Quantity
- Pm Service	21.50	1066 WHITE LITHIUM (CRC 05037)	1.00
- Repair Antilock,Pull Dtc'S Replace Speed Sensors For Rear Break Clear Dtc Codes.		D329A IGN CAP (ACD)	1.00
- Pull Dtc'S.Repair Engine Misfire,Repl Plugs,Wires Ign Rotor And Cap,Pcu Perform Injector And Manifold Cleaning,Rescan & Clear Codes.		FT1203 TRANS FILTER LBF T709 WIX 58608	1.00
- Replace Eng Belt.		K060960 SERP BELT	1.00
- Pm Trans		NB-18 WIPER BLADES 18" ANCO 31-18	2.00
- Check Ac, Charge With F-134, Top Off.		R134A REFRIGERANT	1.00
- Test Brakes. Retest Brakes And Engine.		41-993 SPARKPLUG	8.00
- Shop Supplies		L/F#PH51A OIL FILTER WIX 51036 FRAM PH3980	1.00
		SHOP SUPPLIES	1.00
		ATFD TRANS FLUID MERCON V	8.00
		L17301A ENGINE FOG KIT HARD CARBON (SMART BLEND)	1.00
		D465 IGNITION ROTOR (ACD)	1.00
		15/40 OIL	6.00
		PCV 6847532	1.00
		SPD SNSR 24203876	2.00
		WIRE SET 12192364	1.00
		SEAL 22514722	10.00
		L/F G481 WIX 33481 FUEL FILTER	1.00
		31-20 WIPER BLADES 20" BLADE	-2.00
		31-20 WIPER BLADES 20" BLADE	2.00
Parts Charge:	430.90	Labor Charge:	1,075.00

6/29/2017
11:02:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10130845 2000 GMC WORKHORSE Van, Stepvan

Workorder: 456788

Problem: WILL NOT RUN

Meter Reading: 17859	Labor	Parts	
In Date: 09/17/2004	Hours	Description	Quantity
- No Power To Fuel Pump Relay Or Injectors. Control Module Not Programmed	4.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 200.00		

Workorder: 545801

Problem: PM SERVICE

Meter Reading: 21886	Labor	Parts	
In Date: 05/25/2005	Hours	Description	Quantity
- Pm Service	6.00	15/40 OIL	6.00
- Repair Open Circuit To Backup Lite.		1036 OIL FILTER FRM PH3980 WIX 51036	1.00
- Adjusted Gear Box		3481 FUEL FILTER FRM G3727 WIX 33481	1.00
- Shop Supplies		09997 BRAKE CLEAN	1.00
		CA3914 AIR FILTER LBF AF917 WIX 46144	1.00
		SHOP SUPPLIES	1.00
		798 FLARE KITS TRIANGLE REFLECTOR KITS	1.00
		NB-18 WIPER BLADES 18" ANCO 31-18	2.00
Parts Charge: 59.69	Labor Charge: 300.00		

Workorder: 546323

Problem: TIRESOLES OF BROWARD INC T079740/T079723

Meter Reading: 0	Labor	Parts	
In Date: 05/26/2005	Hours	Description	Quantity
- Tiresoles Of Broward Inc T079740/T079723			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 609.94	

6/29/2017
11:02:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10130845 2000 GMC WORKHORSE Van, Stepvan

Workorder: 549169

Problem: WILL NOT START AND CHECK AC

Meter Reading: 22051	Labor	Parts	
In Date: 06/30/2005	Hours	Description	
Close Date: 07/06/2005		Quantity	
- Replace Battery.Ck Charging Sk And Repair Draw.	9.50	SHOP SUPPLIES	1.00
- Check Ac Repair Leak At "O" Ring Evac And Recharge.		R134A REFRIGERANT	4.00
- Replace Fuel Pump Relay.		RELAY 12193601	1.00
- Check Engine Light.Scan And Reset.		78-72 BATTERY GROUP 78	1.00
- Shop Supplies			
Parts Charge:	130.12	Labor Charge:	475.00

Workorder: 550173

Problem: AC

Meter Reading: 22114	Labor	Parts	
In Date: 07/13/2005	Hours	Description	
Close Date: 07/18/2005		Quantity	
- Check Ac.	1.50	SHOP SUPPLIES	1.00
- Shop Supplies		R134A REFRIGERANT	1.00
Parts Charge:	12.13	Labor Charge:	75.00

6/29/2017
11:02:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10130845 2000 GMC WORKHORSE Van, Stepvan

Workorder: 556906

Problem: PM SERVICE AND ABS LIGHT IS ON CHECK SPEEDO

Meter Reading: 22928		Labor	Parts	
In Date: 10/17/2005	Close Date: 11/29/2005	Hours	Description	Quantity
- Pm		19.00	3481 FUEL FILTER FRM G3727 WIX 33481	1.00
- Replace Sway Bar Bushings.			15005612 INSULATOR	2.00
- Ck Abs Light Scantest Ck Speedo.No Problem Found @ This Time			25162556 SPARK PLUGS	8.00
- Replace Cat Converter Replace O2 Sensors.			BIG G DEGREASER STOCK# 485180002	4.00
- Wash			10452457 ROTOR	1.00
- Ignition Sys.Replace Dist Cap Rotor,Igniton Wires Spark Plug			25312191 SENSOR UP STREAM	2.00
- Fuel Pressure Regulator R&R Intake.			1036 OIL FILTER FRM PH3980 WIX 51036	1.00
- Shop Supplies			15/40 OIL	-6.00
			31-20 WIPER BLADES 20" BLADE	2.00
			W8803039 INSULATOR	2.00
			12192364 WIRE KIT IGNITION	1.00
			17113274 METER-TBI	1.00
			89017453 FUEL REGUL.	1.00
			10452459 CAP/IGN.	1.00
			17113205 SEAL INTC	1.00
			CA3914 AIR FILTER LBF AF917 WIX 46144	1.00
			89017465 GASKET INTAKE	1.00
			15/40 OIL	6.00
			W0001972 CONVERTER	1.00
			17113206 SEAL KIT	1.00
			25312201 SENSOR DOWN STREAM	2.00
			10W30 MOTOR OIL	6.00
			USED FIREX REFURBED FIRE EXTINGSHERS	1.00
			6487532 PCV VALVE	1.00
			SHOP SUPPLIES	1.00
	Parts Charge:	3,022.38	Labor Charge:	950.00

Workorder: 559695

Problem: ENGINE CUTS OUT AND SPEEDO READS FAST

Meter Reading: 22962		Labor	Parts	
In Date: 12/14/2005	Close Date: 12/22/2005	Hours	Description	Quantity
- Replace Speed Sensor Dr Transmission.		2.50	SHOP SUPPLIES	1.00
- Shop Supplies			SPD SNSR 24203876	1.00
	Parts Charge:	24.91	Labor Charge:	125.00

6/29/2017
11:02:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10130845 2000 GMC WORKHORSE Van, Stepvan

Workorder: 737595

Problem: PM SERVICE AND ENGINE STALLS

Meter Reading: 24632	Labor	Parts			
In Date: 04/24/2007	Hours	Description	Quantity		
- Pm Service	7.50	3481 FUEL FILTER FRM G3727 WIX 33481	1.00		
- Repair Running Light		31-20 WIPER BLADES 20" BLADE	2.00		
- Installed Nitrogen		USED FIREX REFURBED FIRE EXTINGSHERS	1.00		
- Hooked Up Scanner No Codes Present.		1036 OIL FILTER FRM PH3980 WIX 51036	1.00		
- Rd Tested No Problem Found.		SHOP SUPPLIES	1.00		
- Shop Supplies		10W30 MOTOR OIL	6.00		
		CA3914 AIR FILTER LBF AF917 WIX 46144	1.00		
Parts Charge:	64.03	Labor Charge:	27.50		
Total Parts Charges:	3,888.77	Total Labor Charges:	4,472.50	Total Comm. Charges:	1,055.12