

10/17/2017  
9:27:47AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166684 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

**Workorder:** 736266

**Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	
In Date: 03/27/2007	Hours	Description	Quantity
- Pre-Delivery Inspection	2.00		
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 110.00		

**Workorder:** 745508

**Problem:** P.M SERVICE

Meter Reading: 3599	Labor	Parts	
In Date: 10/11/2007	Hours	Description	Quantity
- Pm Service	4.00	31-24 WIPER BLADES 24" BLADE	1.00
- Balance All 4 Tires And Nitro Fill		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
- Clean And Readjust Rear Brakes And Drums		NB-18 WIPER BLADES 18" ANCO 31-18	1.00
- Shop Supplies		05046 BATTERY PROTECTOR (CRC)	1.00
		SHOP SUPPLIES	1.00
		5W30 OIL	4.00
		10020 INJECTOR CLEANER DON'T REORDER	1.00
<b>Parts Charge:</b> 40.53	<b>Labor Charge:</b> 60.00		

**Workorder:** 837090

**Problem:** P.M. SERVICE.

Meter Reading: 6143	Labor	Parts	
In Date: 04/16/2008	Hours	Description	Quantity
- Pm Service	4.00	CA10159 AIR FILTER WIX 49116 PRIUS 04-UP	1.00
- High Speed Balance, Nitro Fill 4 Tires		NB-18 WIPER BLADES 18" ANCO 31-18	1.00
- Serviced Rear Brakes		31-24 WIPER BLADES 24" BLADE	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
		5W30 OIL	4.00
<b>Parts Charge:</b> 31.72	<b>Labor Charge:</b> 60.00		

10/17/2017  
9:27:47AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166684 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

**Workorder:** 845856

**Problem:** P.M SERVICE,RUNS ROUGH

<b>Meter Reading:</b> 9197		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 10/17/2008	<b>Close Date:</b> 10/24/2008	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm Service		<b>4.00</b>	5W30 OIL		4.00
- Complaint:Runs Rough.Service Light On.Test			PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
Drive-Ok.Scan For Codes,No Codes.Reset Mainteneace			31-24 WIPER BLADES 24" BLADE		1.00
Light. No Problems At This Time.			31-20 WIPER BLADES 20" BLADE		1.00
- Service Rear Brakes.			SHOP SUPPLIES		1.00
- Shop Supplies			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
<b>Parts Charge:</b> 40.31		<b>Labor Charge:</b> 60.00			

**Workorder:** 937901

**Problem:** P.M SERVICE

<b>Meter Reading:</b> 14093		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 05/18/2009	<b>Close Date:</b> 05/20/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm Service		<b>4.00</b>	NB-18 WIPER BLADES 18" ANCO 31-18		1.00
- Service Rear Brakes.			SHOP SUPPLIES		1.00
- Rotate & High Speed Balance All 4 Tires.Nitro Fill To Specs.			31-24 WIPER BLADES 24" BLADE		1.00
			5W30 OIL		4.00
- Shop Supplies			PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
<b>Parts Charge:</b> 26.32		<b>Labor Charge:</b> 240.00			

**Workorder:** 946676

**Problem:** P.M service, low tire light on.

<b>Meter Reading:</b> 18267		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 12/04/2009	<b>Close Date:</b> 12/14/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- P.M Service.		<b>7.50</b>	TIRE DISPOSAL FEE		2.00
- Mount Two New Tires, Rotate & Balance All Four Tires.			SHOP SUPPLIES		1.00
- Alignment.			PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
- Service Rear Drum Brakes.			CA10159 AIR FILTER WIX 49116 PRIUS 04-UP		1.00
- Shop Supplies			738001571 185/65R15 ASSURANCE(DISCONTINUED)		2.00
			5W30 OIL		4.00
<b>Parts Charge:</b> 184.97		<b>Labor Charge:</b> 900.00			

10/17/2017  
9:27:47AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166684 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

**Workorder:** 1007388

**Problem:** Pm service.

Meter Reading: 23283	Labor	Parts	Quantity
In Date: 07/13/2010	Hours	Description	Quantity
- Perform Pm Service.	5.00	PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
- Install Two New Tires To The Fronts And Balance All Four.		NB-18 WIPER BLADES 18" ANCO 31-18	1.00
- Perform Rear Drum Brakes Service And Adjust Brake Shoes.		31-24 WIPER BLADES 24" BLADE	1.00
- Shop Supplies		5W30 OIL	4.00
		8524247010 BLADE REAR WIPER (TOYOTA)	1.00
		738001571 185/65R15 ASSURANCE(DISCONTINUED)	2.00
		TIRE DISPOSAL FEE	2.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	207.10	<b>Labor Charge:</b>	300.00

**Workorder:** 1009126

**Problem:** damage to rear bumper & lft taol lgt

Meter Reading: 24030	Labor	Parts	Quantity
In Date: 08/10/2010	Hours	Description	Quantity
- Damage To Rear Bumper & Lft Taol Lgt			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00
		<b>Commercial Charge:</b>	216.00

**Workorder:** 1009291

**Problem:** Dead battery

Meter Reading: 24040	Labor	Parts	Quantity
In Date: 08/26/2010	Hours	Description	Quantity
- Recharge Battery. Test Battery And Charging System Ad Check For Draws.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	60.00

**Workorder:** 1010534

**Problem:** replace rear hatch latch

Meter Reading: 24422	Labor	Parts	Quantity
In Date: 09/24/2010	Hours	Description	Quantity
- Remove Panels And Old Door Switch, Install New Switch Test And Reinstall Panels-Ok	1.00	HATCH SWITCH ASSY	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	66.05	<b>Labor Charge:</b>	60.00

10/17/2017  
9:27:47AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166684 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

**Workorder:** 1011305                      **Problem:** damage to rgt frt fender

**Meter Reading:** 24422                      **Labor**                      **Parts**

**In Date:** 09/24/2010                      **Close Date:** 10/14/2010                      **Hours**                      **Description**                      **Quantity**

---

- Damage To Rgt Frt Fender

**Parts Charge:**                      0.00                      **Labor Charge:**                      0.00                      **Commercial Charge:**                      382.80

**Workorder:** 1100410                      **Problem:** Pm service

**Meter Reading:** 25938                      **Labor**                      **Parts**

**In Date:** 01/11/2011                      **Close Date:** 01/13/2011                      **Hours**                      **Description**                      **Quantity**

---

- Perform Pm Service.                      **4.00**                      5W30 OIL                      4.00

- Perform Rear Drum Brakes Service And Adjust Brake Shoes.                      PH4967 OIL FILTER LBF PH2840 WIX 51394                      1.00

- Rotate And Balance All Four Tires.                      CF9846A CAB FILTER WIX 24875                      1.00

- Shop Supplies                      USED FIREX REFURBED FIRE EXTINGSHERS                      1.00

**Parts Charge:**                      40.08                      **Labor Charge:**                      240.00

**Workorder:** 1107960                      **Problem:** P.M. service and water pump recall.

**Meter Reading:** 30063                      **Labor**                      **Parts**

**In Date:** 07/29/2011                      **Close Date:** 08/15/2011                      **Hours**                      **Description**                      **Quantity**

---

- Perform Pm Service.                      **6.00**                      NB-18 WIPER BLADES 18" ANCO 31-18                      1.00

- Rotate And Balance All Four Tires.                      31-24 WIPER BLADES 24" BLADE                      1.00

- Perform Rear Drum Brakes Service And Adjust Brake Shoes.                      5W30 OIL                      4.00

- Transport Vehicle To And From Dealer For Hybrid Water Pump And Accelerator Pedal Recalls.Installing New Hybrid Water Pump And Modify Accelerator Pedal To Floor Surface.                      CA10159 AIR FILTER WIX 49116 PRIUS 04-UP                      1.00

- Shop Supplies                      SHOP SUPPLIES                      1.00

**Parts Charge:**                      47.59                      **Labor Charge:**                      360.00

10/17/2017  
9:27:47AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166684 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

**Workorder:** 1112745                      **Problem:** jump start at vista garage

<b>Meter Reading:</b> 32063	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 12/01/2011	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Jump Start At Vista Garage Deliver To Lv Shop	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 120.00	

**Workorder:** 1112756                      **Problem:** No start,battery drained,dome light on.

<b>Meter Reading:</b> 32079	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 12/01/2011	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Test Starting And Charging System.Fully Recharge And Load Test Battery,Ok.Perform Parasitic Draw Test,Ok.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 60.00	

**Workorder:** 1112946                      **Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

<b>Meter Reading:</b> 32063	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 12/07/2011	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- 1 - Detail Vehicle Wash Ticket(S) Issued			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00 <b>Commercial Charge:</b> 91.80	

**Workorder:** 1113522                      **Problem:** No Start at Vista

<b>Meter Reading:</b> 32491	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 12/28/2011	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Road Call To Vista Ctr. And Back To Shop	2.00	SHOP SUPPLIES	1.00
- Jump Start Vehicle			
- Shop Supplies			
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 120.00	

10/17/2017  
9:27:47AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166684 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

**Workorder:** 1113566

**Problem:** Has to jump start

Meter Reading: 32491	Labor	Parts	
In Date: 12/29/2011	Hours	Description	Quantity
- Test Starting And Charging System.Battery Failed Load	1.00	00544-21171-325 BATTERY (TOYOTA)	1.00
- Test After Recharge.Replace Failed Battery With New.		SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 220.70		<b>Labor Charge:</b> 60.00	

**Workorder:** 1201913

**Problem:** P.M. service.

Meter Reading: 33268	Labor	Parts	
In Date: 02/27/2012	Hours	Description	Quantity
- P.M. Service.	4.00	5W30 OIL	4.00
- Service And Adjust Rear Brakes.		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
- Rotate And Balance All Four Tires.		NB-18 WIPER BLADES 18" ANCO 31-18	1.00
- Shop Supplies		31-24 WIPER BLADES 24" BLADE	1.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b> 27.21		<b>Labor Charge:</b> 240.00	

**Workorder:** 1209668

**Problem:** P.M. service.

Meter Reading: 37235	Labor	Parts	
In Date: 10/10/2012	Hours	Description	Quantity
- P.M. Service.	7.50	SHOP SUPPLIES	1.00
- Pressure Test And Inspect Cooling System.Replace		WATER PUMP	1.00
- Leaking Water Pump .Flush And Refill System.		ANTIFREEZE EXT-LIFE	1.00
- Service And Adjust Rear Brakes.		8524247010 BLADE REAR	1.00
- Rotate And Balance All Tires.		NAPA QUART 5W30	4.00
- Shop Supplies		31-24 WIPER BLADES 2	1.00
		31-18 WIPER BLADES 18	1.00
		PH4967 OIL FILTER LBF	1.00
<b>Parts Charge:</b> 121.29		<b>Labor Charge:</b> 450.00	

10/17/2017  
9:27:47AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166684 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

**Workorder:** 1210238                      **Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 37037	Labor	Parts
In Date: 10/24/2012	Hours	Description
Close Date: 10/24/2012		Quantity
- 1 - Detail Vehicle Wash Ticket(S) Issued		
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 91.80

**Workorder:** 1301351                      **Problem:** Right rear tire damage not repairable.

Meter Reading: 39539	Labor	Parts
In Date: 02/06/2013	Hours	Description
Close Date:		Quantity
-		
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 0.00	

**Workorder:** 1304398                      **Problem:** Pm service.Steering shaft and accelerator pedal recalls.

Meter Reading: 42865	Labor	Parts
In Date: 05/02/2013	Hours	Description
Close Date: 05/16/2013		Quantity
- Perform Pm Service.	<b>9.50</b>	SHOP SUPPLIES 1.00
- Pressure Test And Inspect Cooling System.Replace		NAPAGOLD OIL FILTER 1.00
Failed Water Pump With New.Reverse Flush And Renew		EXACT FIT BLADE 1.00
Engine Coolant.		NAPA QUART 5W30 4.00
- Perform Rear Drum Brake Service And Adjust Brake		cabin air filter cf9846a 1.00
Shoes.		COOLANT 1.00
- Rotate And Balance All Four Tires.		90916-02570 BELT 1.00
- Transport Vehicle To And From Dealer For Performing		WATER PUM 1.00
Steering Shaft Recall Complete.		WIPER BLADE 1.00
- Shop Supplies		
<b>Parts Charge:</b> 201.29	<b>Labor Charge:</b> 570.00	

**Workorder:** 1310117                      **Problem:** Towed in no start.

Meter Reading: 45513	Labor	Parts
In Date: 10/07/2013	Hours	Description
Close Date: 10/17/2013		Quantity
- Recharge Battery.Test Battery And Charging	<b>0.50</b>	
System,Okay.		
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 30.00	

10/17/2017  
9:27:47AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166684 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

**Workorder:** 1310125

**Problem:** NO Start

Meter Reading: 45272	Labor	Parts			
In Date: 10/07/2013	Hours	Description	Quantity		
- Tow From: 2300 Vista Garage					
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b>	104.15

**Workorder:** 1311763

**Problem:** Pm service and check engine light on.

Meter Reading: 46563	Labor	Parts			
In Date: 11/21/2013	Hours	Description	Quantity		
- P.M. Service.					
- Diagnose Check Engine Light,P1121.Perform Repairs Per					
Tsb-0231-2.Replace Defective Coolant Control Valve.Flush					
And Refill Cooling System.Clear Codes.					
- Replace Twotires,Rotate And Balance All Four.					
- Service And Adjust Rear Brakes.					
- Complete Wheel Alignment.Test Drive.					
- Shop Supplies					
<b>Parts Charge:</b>	400.45	<b>Labor Charge:</b>	690.00		

**Workorder:** 1402754

**Problem:** Maintainance light on.

Meter Reading: 47850	Labor	Parts			
In Date: 03/21/2014	Hours	Description	Quantity		
- Reset Maintenance Reminder Light Manually.					
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	18.00		



10/17/2017  
9:27:47AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166684 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

**Workorder:** 1407024

**Problem:** Pm service

<b>Meter Reading:</b> 49959	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 07/16/2014	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- P.M. Service.	<b>4.00</b>	NAPA QUART 5W30	4.00
- Service And Adjust Rear Brakes.		WIPER BLADE	1.00
- Rotate And Balance All Tires.		REAR BLADE TOYOTA	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		NAPAGOLD OIL FILTER	1.00
		31-24 WIPER BLADES 2	1.00
<b>Parts Charge:</b>	50.57	<b>Labor Charge:</b>	240.00

**Workorder:** 1408264

**Problem:** Towed in for no start.

<b>Meter Reading:</b> 50540	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 08/20/2014	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Recharge And Test Battery And Charging System.Replace Defective Battery.	<b>1.00</b>	AGM BATTERY	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	221.00	<b>Labor Charge:</b>	60.00

**Workorder:** 1408383

**Problem:** No start

<b>Meter Reading:</b> 50259	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 08/19/2014	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Tow From: Vista Garage 5Th Floor Spot B-19 To: Lv Shop			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00
		<b>Commercial Charge:</b>	104.15

10/17/2017  
9:27:47AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166684 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

**Workorder:** 1500455

**Problem:** Pm service.

Meter Reading: 53936	Labor	Parts	
In Date: 01/13/2015	Hours	Description	Quantity
- P.M. Service.	7.50	TIRE DISPOSAL FEE	2.00
- Servicer And Adjust Trear Brakes.		SHOP SUPPLIES	1.00
- Replace Two Tires,Roate And Balance All Four.		WIPER BLADE	1.00
- Complete Wheel Alignment.Test Drive.		738523571 P185-65R15	2.00
- Shop Supplies		NAPAGOLD OIL FILTER	1.00
		NAPA QUART 5W30	4.00
		NAPAGOLD AIR FILTER	1.00
		31-24 WIPER BLADES 2	1.00
<b>Parts Charge:</b>	284.34	<b>Labor Charge:</b>	450.00

**Workorder:** 1507390

**Problem:** Pm service.

Meter Reading: 56551	Labor	Parts	
In Date: 07/23/2015	Hours	Description	Quantity
- P.M. Service.	4.00	31-24 WIPER BLADES 2	1.00
- Rotate And Balance All Tires.		MAC WITE LITHIUM GRES	1.00
- Service And Adjust Rear Brakes.		REAR BLADE TOYOTA	1.00
- Shop Supplies		WIPER BLADE	1.00
		WASHER FLUID CONCENTR	1.00
		NAPAGOLD OIL FILTER	1.00
		5W20 ENGINE OIL	4.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	61.72	<b>Labor Charge:</b>	240.00

**Workorder:** 1600695

**Problem:** P.M. Service.Low tire light opn.

Meter Reading: 59064	Labor	Parts	
In Date: 01/21/2016	Hours	Description	Quantity
- Pm Service.	4.50	SHOP SUPPLIES	1.00
- Perform Rear Brake Service.		NAPA QUART 5W30	4.00
- Rotate And Balance All Four Tires.		NAPAGOLD OIL FILTER	1.00
- Fabricate And Replace Front And Rear Asset Numbers.		18" wiper blades	1.00
- Shop Supplies		NAPA CABIN AIR FILTER	1.00
		WIPER BLADES 24"	1.00
<b>Parts Charge:</b>	34.83	<b>Labor Charge:</b>	270.00



10/17/2017  
9:27:47AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166684 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

**Workorder:** 1701721

**Problem:** P.M. Service.

Meter Reading: 63235	Labor	Parts
In Date: 02/16/2017	Hours	Description
Close Date: 02/28/2017		Quantity
- P.M. Service.	<b>4.00</b>	NAPAGOLD OIL FILTER
- Service And Adjust Rear Brakes.		WIPER BLADES 24"
- Rotate And Balance Tires.		NAPA QUART 5W30
- Shop Supplies		SHOP SUPPLIES
		18" wiper blades
		Wiper Blade - AccuFit - Rear - OE Style
<b>Parts Charge:</b>	39.11	<b>Labor Charge:</b> 240.00

**Workorder:** 1703149

**Problem:** Unable to shut off,display black out.

Meter Reading: 63359	Labor	Parts
In Date: 03/29/2017	Hours	Description
Close Date: 07/31/2017		Quantity
- Diagnose Display Black Out.Transport To Dealer For	<b>2.00</b>	SHOP SUPPLIES
Combination Meter Replacement And Program.		COMBO METER + INSTALL
- Shop Supplies		
<b>Parts Charge:</b>	1,160.96	<b>Labor Charge:</b> 120.00

**Workorder:** 1705426

**Problem:** 10 - Wash ticket(s) issued

Meter Reading: 63235	Labor	Parts
In Date: 05/31/2017	Hours	Description
Close Date: 05/31/2017		Quantity
- 10 - Wash Ticket(S) Issued		
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b> 0.00
		<b>Commercial Charge:</b> 85.08

**Workorder:** 1708522

**Problem:** Transition Prep Charge

Meter Reading: 63484	Labor	Parts
In Date: 08/29/2017	Hours	Description
Close Date: 08/29/2017		Quantity
- Transition Prep Charge	<b>2.00</b>	
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b> 0.00

Total Parts Charges:	<b>3,921.91</b>	Total Labor Charges:	<b>6,848.00</b>	Total Comm. Charges:	<b>1,171.78</b>
----------------------	-----------------	----------------------	-----------------	----------------------	-----------------