

10/11/2016  
4:23:42PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K11815 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 836306

**Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	
In Date: 04/01/2008	Hours	Description	Quantity
- Pre-Delivery Inspection	4.00		
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 240.00		

**Workorder:** 836336

**Problem:** INSTALL STROBE LIGHT

Meter Reading: 15	Labor	Parts	
In Date: 04/01/2008	Hours	Description	Quantity
- Fabricate & Install Strobe Light And Lighted Switch Wire	2.50	80865 FUSEHOLDER IMPERIAL 80865	1.00
In Test.Install "Height Clearance"Label O Dash		SHOP SUPPLIES	1.00
- Shop Supplies		84863 ROCKER SWITCH (MOTORMITE)	1.00
<b>Parts Charge:</b> 13.38	<b>Labor Charge:</b> 30.00		

**Workorder:** 844947

**Problem:** P.M SERVICE

Meter Reading: 5955	Labor	Parts	
In Date: 10/01/2008	Hours	Description	Quantity
- Pm Service	5.75	CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
- Rotate And High Speed Balance All 4 Tires.		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
- Nitrogen Service On All 4 Tires		5W20 ENGINE OIL	7.00
- Service Winch.		SHOP SUPPLIES	1.00
- Shop Supplies		5LB FIREX ABC STOCK# 340280001	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
<b>Parts Charge:</b> 117.04	<b>Labor Charge:</b> 60.00		

**Workorder:** 935035

**Problem:** P.M./ SERVICE.

Meter Reading: 11095	Labor	Parts	
In Date: 03/12/2009	Hours	Description	Quantity
- Pm Service	5.50	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Service Winch		SHOP SUPPLIES	1.00
- Repair L/R Tire,Hi Speed Balance & Nitro Fill		31-20 WIPER BLADES 20" BLADE	2.00
- Rotate & Hi Speed Balance 3 Tires,Nitro Fill Tires.		5W20 ENGINE OIL	7.00
- Shop Supplies			
<b>Parts Charge:</b> 32.64	<b>Labor Charge:</b> 330.00		

10/11/2016  
4:23:42PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K11815 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 941764

**Problem:** P.M service, check tires

<b>Meter Reading:</b> 17227	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 08/06/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- P.M Service.	<b>9.75</b>	5W20 ENGINE OIL	7.00
- Mount, Balance & Nitro Fill Four New Tires.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Replace Broken Trailer Plug Socket, Repair Damaged		5404 FEMALE CONNECTOR	1.00
Wiring, Fabricate New Ground For Tag Lamp.		CUSTOM5LB BRACKET FIREX STOCK #340060300	1.00
- Alignment.		SHOP SUPPLIES	1.00
- Inspect & Service Winch.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Shop Supplies		179535492 LT265/70R17 WRANGLER SR-A E	4.00
		TIRE DISPOSAL FEE	4.00
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
		TR416 VALVE STEM	4.00
<b>Parts Charge:</b>	830.40	<b>Labor Charge:</b>	585.00

**Workorder:** 946600

**Problem:** R/R tire flat.

<b>Meter Reading:</b> 20770	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 12/02/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Repair R/R Tire.	<b>1.00</b>	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	120.00

**Workorder:** 947384

**Problem:** right rear tire flat

<b>Meter Reading:</b> 22235	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 12/30/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Repair And Balance Right Rear Tire.	<b>1.00</b>	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	120.00

10/11/2016  
4:23:42PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K11815 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1001826

**Problem:** P.M service.

Meter Reading: 24180	Labor	Parts	
In Date: 02/22/2010	Hours	Description	Quantity
- P.M Service.	7.75	31-20 WIPER BLADES 20" BLADE	2.00
- Rotate & Balance All Four Tires.		FRONT FLOOR MATS	1.00
- Inspect & Service Winch.		SHOP SUPPLIES	1.00
- To/From Dealer For Replacement Floor Mat.		5W20 ENGINE OIL	7.00
- Remove/Reinstall Radios Fire Extingusher & Misc Cab		1372 OIL FILTER FRM PH2 WIX 51372	1.00
Items For Dealer To Warrenty Floor Mat.		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
- Shop Supplies			
<b>Parts Charge:</b>	91.56	<b>Labor Charge:</b>	405.00

**Workorder:** 1007269

**Problem:** P.M. Service

Meter Reading: 30149	Labor	Parts	
In Date: 07/12/2010	Hours	Description	Quantity
- P.M. Service.	11.55	179535492 LT265/70R17 WRANGLER SR-A E	4.00
- Replace And Balance Four Tires.		5W20 ENGINE OIL	7.00
- Replace Left Rear Brake Light.		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
- Test Battery And Charging System.Charge And Retest		31-20 WIPER BLADES 20" BLADE	2.00
Battery,Fail Load Test.Replace Bad Battery.		GROUP 65 BATTERY (MTC BXT-65-850)	1.00
- Inspect And Service Winch.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Complete Front End Alignment.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Scan Vehicle For Codes.Transport To Dealer For Defective		SHOP SUPPLIES	1.00
R.C.M.		TIRE DISPOSAL FEE	4.00
- Shop Supplies		44202R TAIL LIGHT 4" RED 42 LED	1.00
<b>Parts Charge:</b>	1,000.13	<b>Labor Charge:</b>	693.00

10/11/2016  
4:23:42PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K11815 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1012972

**Problem:** Right rear tire flat.

<b>Meter Reading:</b> 35640	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 11/22/2010	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Install One New Tire.Replace One Failed Tire Pressure Sensor With New.Rotate And Balance All Four Tires.	<b>5.75</b>	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Perform Pm Service.		31-20 WIPER BLADES 20" BLADE	2.00
- Inspect And Service Power Winch.		SENSOR MOUNTING KIT	1.00
- Shop Supplies		5W20 ENGINE OIL	7.00
		SHOP SUPPLIES	1.00
		TIRE PRESSURE SENSOR	1.00
		TIRE DISPOSAL FEE	1.00
		179535492 LT265/70R17 WRANGLER SR-A E	1.00
<b>Parts Charge:</b> 372.98	<b>Labor Charge:</b> 345.00		

**Workorder:** 1013946

**Problem:** Right rear tire has nail in it.

<b>Meter Reading:</b> 36460	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 12/20/2010	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Repair Flat Right Rear Tire And Balance Same.	<b>1.00</b>	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 2.00	<b>Labor Charge:</b> 60.00		

10/11/2016  
4:23:42PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K11815 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1106912

**Problem:** Pm service

Meter Reading: 44255 In Date: 06/29/2011	Close Date: 07/18/2011	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		<b>13.25</b>	SYN/ATF TRANS FLUID SYNTHETIC		16.00
- Inspect And Service Transmission.Flush And Renew Transmission Fluid.			179535492 LT265/70R17 WRANGLER SR-A E		4.00
- Install Four New Tires.Nitrogen Fill And Balance All Four.			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
- Fabricate And Install Three Over Head Work Lights And Two Switches.Make Up And Install New Wiring Harness For Power And Ground Circuits.Had To Remove Interior Trims For Access.			TIRE DISPOSAL FEE		4.00
- Perform Power Winch Service.			SHOP SUPPLIES		1.00
- Perform Wheel Alignment Complete.			D3TZ2457B BRAKE PEDAL PAD		1.00
- Shop Supplies			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			80865 FUSEHOLDER IMPERIAL 80865		2.00
			84863 ROCKER SWITCH (MOTORMITE)		2.00
			5W20 ENGINE OIL		7.00
			31-20 WIPER BLADES 20" BLADE		2.00
			18410 PINTLE PIN		1.00
<b>Parts Charge:</b>	931.50	<b>Labor Charge:</b>	795.00		

**Workorder:** 1112746

**Problem:** Pm service.Install computer stand and inverter.

Meter Reading: 50390 In Date: 12/01/2011	Close Date: 12/15/2011	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		<b>10.75</b>	CS4RV RED CABLE #4		4.00
- Install Customer Supplied Computer Stand And Inverter Assembly. Fabricate,Make Up And Install New Wiring Harness With Circuit Breaker For Inverter Power And Ground Circuits.			SHOP SUPPLIES		1.00
- Inspect And Service Power Winch.			CS4L CABLE #4		4.00
- Rotate And Balance All Four Tires.			82-2178 CIRCUIT BREAKER 100AMP		1.00
- Shop Supplies			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			5W20 ENGINE OIL		7.00
			CA10262 AIR FILTER MTC FA1883 WIX 49883		1.00
<b>Parts Charge:</b>	100.91	<b>Labor Charge:</b>	645.00		

10/11/2016  
4:23:42PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K11815 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1204755

**Problem:** P.M. Service.

Meter Reading: 56474		Labor		Parts	
In Date: 05/21/2012	Close Date: 05/31/2012	Hours	Description	Quantity	
-	P.M. Service.	<b>9.00</b>	1372 OIL FILTER FRM PH2 WIX 51372	1.00	
-	Replace And Balance Four Tires.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00	
-	Test And Replace Defective Blower Resistor.		31-20 WIPER BLADES 20" BLADE	2.00	
-	Inspect And Service Winch.		5W20 ENGINE OIL	7.00	
-	Complete Wheel Alignment.		TIRE DISPOSAL FEE	4.00	
-	Shop Supplies		18410 PINTLE PIN	1.00	
			179535492 LT265/70R17 WRANGLER SR-A E	4.00	
			YH1715 A/C BLOWER RESISTOR (MOTORCRAFT)	1.00	
			SHOP SUPPLIES	1.00	
<b>Parts Charge:</b>		841.40	<b>Labor Charge:</b>	540.00	

**Workorder:** 1302559

**Problem:** P.M. service and right rear tire going flat and check for squeek.

Meter Reading: 68712		Labor		Parts	
In Date: 03/14/2013	Close Date: 03/21/2013	Hours	Description	Quantity	
-	P.M. Service.	<b>12.75</b>	5W20 ENGINE OIL	7.00	
-	Replace And Balance Four New Tires.		1372 OIL FILTER	1.00	
-	R&R Driveshaft And Replace 'U' Joints.		NAPAGOLD FUEL FILTER	1.00	
-	Test Battery And Charging System.Replace Bad Battery.Replace Missing Hitch Pintle Pin.		NAPAGOLD AIR FILTER	1.00	
-	Inspect And Service Winch.		31-20 WIPER BLADES 20	2.00	
-	Install Camber/Caster Adjustment Bushings.Perform Complete Alignment.Test Drive.		179535492 LT265-70R17	4.00	
-	Shop Supplies		TR416 VALVE STEM	4.00	
			USED FIREX REFURBED F	1.00	
			CASTER-CAMBER BUSHING	2.00	
			18410 PINTLE PIN	1.00	
			TIRE DISPOSAL FEE	4.00	
			U JOINT	2.00	
			BATTERY 65	1.00	
			SHOP SUPPLIES	1.00	
<b>Parts Charge:</b>		1,425.32	<b>Labor Charge:</b>	765.00	

10/11/2016  
4:23:42PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K11815 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1305087                      **Problem:** Towed in for no start.

<b>Meter Reading:</b> 70478	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 05/22/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Replace Failed Starter.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies		STARTER	1.00
<b>Parts Charge:</b> 367.54		<b>Labor Charge:</b> 60.00	

**Workorder:** 1305174                      **Problem:** No start or run

<b>Meter Reading:</b> 70478	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 05/22/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Tow From: On Airfield Pbia To: Lv Shop			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 104.15

**Workorder:** 1306770                      **Problem:** Runs rough and almost stalls.

<b>Meter Reading:</b> 71926	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 07/08/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Clean Throttle Body And Induction System System.Flush Injectors.	8.50	COIL ASSEMBLY	4.00
		HALOGEN LAMP	2.00
- Diagnose Rough Idle Complain.Replace All Eight Spark Plugs.Replace Defective Coils #1,2,3 And #5.Clear Codes.		SPARK PLUG	8.00
		SHOP SUPPLIES	1.00
- Replace Both Headlamps,Had Water.		408 FUEL INJECTION CL	1.00
- Shop Supplies		KA8A THROTTLE BODY- U	1.00
<b>Parts Charge:</b> 528.14		<b>Labor Charge:</b> 510.00	

**Workorder:** 1308013                      **Problem:** damage to rgt door

<b>Meter Reading:</b> 72113	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 07/15/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Damage To Rgt Door			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 300.00

10/11/2016  
4:23:42PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K11815 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1308512

**Problem:** Both front tires flat.

Meter Reading: 72796	Labor	Parts	
In Date: 08/22/2013	Hours	Description	Quantity
- Repair Flat Both Left And Right Front Tires.Nitrogen Fill And Balance Both.	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	120.00

**Workorder:** 1400646

**Problem:** Pm service.

Meter Reading: 77915	Labor	Parts	
In Date: 01/21/2014	Hours	Description	Quantity
- P.M. Service.	12.25	179535492 LT265-70R17	2.00
- Resurface Front Brake Rotors,Replace Front Pads And Calipers.Service And Lube Slides,Flush And Bleed System And Test Drive.		SHOP SUPPLIES	1.00
		BRAKE CLEANER	1.00
		CALIPER	1.00
- Replace Two Tires,Rotate And Balance All Four.		BRCF120 BRAKE CALIPER	1.00
- Inspect And Service Winch.		CALIPER	1.00
		WIPER BLADE	2.00
- Diagnose Inop Passenger Door Light Switch.Remove Door Panel And Repair Wiring To Switch.Diagnose And Repair Left Work Lamp Ground Circuit.		NAPAGOLD FUEL FILTER	1.00
		BRCF119 BRAKE CALIPER	1.00
- Shop Supplies		5W20 ENGINE OIL	7.00
		1401 BRAKE FLUID BRA	1.00
		NAPAGOLD AIR FILTER	1.00
		CALIPER WASHER	4.00
		TIRE DISPOSAL FEE	2.00
		BRAKE PADS FRONT	1.00
		NAPAGOLD OIL FILTER	1.00
<b>Parts Charge:</b>	974.83	<b>Labor Charge:</b>	735.00



## Palm Beach County Fleet Management Asset Maintenance History

Asset: K11815 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1410028

**Problem:** Pm service.Low tire pressure warning light on.

Meter Reading: 84969 In Date: 10/06/2014	Close Date: 10/30/2014	Labor Hours	Description	Parts	Quantity
- Pm Service.		<b>24.45</b>	5W20 ENGINE OIL		7.00
- Replace Rear Brake Pads And Both Rear Brake Calipers.Resurface Rear Brake Rotors.Flush And Bleed Brake System.			TIRE DISPOSAL FEE		4.00
			NAPAGOLD OIL FILTER		1.00
			WIPER BLADE		2.00
- Inspect And Replace Leaking Rear Pinnion Seal.Also Perform Rear Differential Service.			REAR PADS		1.00
			Caliper w/ Hardware - Left Rear (Eclipse		1.00
- Replace And Balance All Four Tires.			Caliper w/ Hardware - Right Rear (Eclips		1.00
			BRAKE FLUID QT		1.00
- Diagnose For Engine Oil Leak.Remove Left Engine Mount To Access And Replace Leaking Oil Filter Adapter Gasket.Flush And Renew Engine Coolant.			BRAKE CLEANER		2.00
			SEAL		1.00
			75W140 FORD AXLE LUBE		3.00
- Remove Both Door Trims To Acess And Replace Two Broken Door Check Straps.			GASKET		1.00
			FRICTION MODIFIER		1.00
- Perform Complete Wheel Alignment.Test Drive.			left door check asy		2.00
			PTEX ULTRA GREY 3OZ		1.00
- Inspect And Service Winch.			TR416 VALVE STEM		4.00
			PEAK GLOBAL		2.00
- Shop Supplies			179535492 LT265-70R17		4.00
			SHOP SUPPLIES		1.00
<b>Parts Charge:</b>		1,701.01	<b>Labor Charge:</b>		1,467.00

**Workorder:** 1410900

**Problem:** damage to lft rear of body & bumper

Meter Reading: 84969 In Date: 10/17/2014	Close Date: 10/31/2014	Labor Hours	Description	Parts	Quantity
- Damage To Lft Rear Of Body & Bumper					
<b>Parts Charge:</b>		0.00	<b>Labor Charge:</b>		0.00
			<b>Commercial Charge:</b>		840.00

**Workorder:** 1502053

**Problem:** Left rear tire flat.

Meter Reading: 89055 In Date: 02/26/2015	Close Date: 02/28/2015	Labor Hours	Description	Parts	Quantity
- Repair And Balance One Flat Tire.		<b>1.00</b>	SHOP SUPPLIES		1.00
- Shop Supplies					
<b>Parts Charge:</b>		2.00	<b>Labor Charge:</b>		60.00

10/11/2016  
4:23:42PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K11815 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1507437

**Problem:** P.M. Service.

Meter Reading: 94251		Labor		Parts	
In Date: 07/27/2015	Close Date: 08/11/2015	Hours	Description		Quantity
-	P.M. Service.	17.25	STG WHEEL COV - FORD		1.00
-	Replace Two Tires,Repair Both Rear Tires.Rotate And Balance All Four.		5W20 ENGINE OIL		7.00
-	Replace Both Laeking Front Shocks.Replace Left Side Upper And Lower Ball Joints.Replace Both Sides Front Axle Seals.		NAPAGOLD OIL FILTER		1.00
-	Replace Both Worn Out Front Cab Mounts.		NAPAGOLD FUEL FILTER		1.00
-	Complete Wheel Alignment.Test Drive.		SHOP SUPPLIES		1.00
-	Inspect And Service Winch.		WASHER FLUID CONCENTR		1.00
-	Shop Supplies		Ball Joint - Upper - Front Sus		1.00
			GAS GRANDE SHOCK		2.00
			WIPER BLADE		2.00
			LEFT AXLE OUT SEAL		1.00
			Ball Joint - Lower - Front Sus		1.00
			USED FIRE X REFURBISHED		1.00
			179535492 LT265-70R17		2.00
			LEFT AXLE SEAL		1.00
			TIRE DISPOSAL FEE		2.00
			BODY MOUNT KIT		2.00
	<b>Parts Charge:</b> 1,076.99	<b>Labor Charge:</b> 1,035.00			

**Workorder:** 1508463

**Problem:** Right headlight inop.

Meter Reading: 94678		Labor		Parts	
In Date: 08/24/2015	Close Date: 08/25/2015	Hours	Description		Quantity
-	Test And Replace Defective Right Headlamp Bulb.	0.50	HALOGEN LAMP		1.00
	<b>Parts Charge:</b> 12.41	<b>Labor Charge:</b> 30.00			

**Workorder:** 1509903

**Problem:** Left headlamp inop.

Meter Reading: 95878		Labor		Parts	
In Date: 09/30/2015	Close Date: 10/01/2015	Hours	Description		Quantity
-	Replace Left Head Lamp Bulb.	0.50	HALOGEN LAMP		1.00
	<b>Parts Charge:</b> 12.41	<b>Labor Charge:</b> 30.00			

## Palm Beach County Fleet Management Asset Maintenance History

### Asset: K11815 2008 FORD F250 Utility Body, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1512817

**Problem:** Check engine light on and engine was noisy.

Meter Reading: 98267	Labor	Parts	
In Date: 12/18/2015	Hours	Description	Quantity
- Transport Vehicle To And From Dealer For Replacing Defective Catalytic Converters.	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	120.00

**Workorder:** 1602394

**Problem:** Right rear tire flat.

Meter Reading: 100753	Labor	Parts	
In Date: 03/07/2016	Hours	Description	Quantity
- Replace And Balance Two Tires.	1.00	TIRE DISPOSAL FEE	2.00
- Shop Supplies		179535492 LT265-70R17 SHOP SUPPLIES	2.00 1.00
<b>Parts Charge:</b>	538.84	<b>Labor Charge:</b>	60.00

**Workorder:** 1602501

**Problem:** Pm service.

Meter Reading: 100876	Labor	Parts	
In Date: 03/09/2016	Hours	Description	Quantity
- Pm Service.	7.25	NAPAGOLD AIR FILTER	1.00
- Battery Failed Loadtest After Recharge. Test Electrical System. Replace Battery.		BULB	1.00
- Diagnose Blower Speeds Inop. Test And Replace Defective Blower Resistor.		20" WIPER BLADE	2.00
- Replace Failed Left Rear Marker Lamp On Utility Box. Fabricate Wiring As Needed.		M C BASE MOUNT KIT	1.00
- Rotate And Balance All Four Tires.		MACS BATTERY CLEANER	1.00
- Inspect And Service Winch.		NAPAGOLD OIL FILTER	1.00
- Shop Supplies		BLOWER RESISTOR	1.00
		5W20 ENGINE OIL	7.00
		BATTERY	1.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	206.62	<b>Labor Charge:</b>	435.00

Total Parts Charges:	<b>11,188.05</b>	Total Labor Charges:	<b>10,395.00</b>	Total Comm. Charges:	<b>1,244.15</b>
----------------------	------------------	----------------------	------------------	----------------------	-----------------