

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166683 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 736019 **Problem:** WASH VEHICLE

Meter Reading: 0	Labor	Parts	
In Date: 03/22/2007	Hours	Description	Quantity
- Wash Vehicle	2.50		
- Pre-Delivery Inspection			
Parts Charge: 0.00	Labor Charge: 110.00		

Workorder: 736256 **Problem:** 001 WASH TICKET ISSUED OUT 03/21/07

Meter Reading: 0	Labor	Parts	
In Date: 03/21/2007	Hours	Description	Quantity
- 001 Wash Ticket Issued Out 03/21/07			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 7.14	

Workorder: 745497 **Problem:** P.M SERVICE

Meter Reading: 3509	Labor	Parts	
In Date: 10/11/2007	Hours	Description	Quantity
- Pm Service	4.00	SHOP SUPPLIES	1.00
- Nitro Service 5 Tires		5W30 OIL	5.00
- Service Rear Brakes Clean And Adjust.		ANTISEIZE 405540005	1.00
- Shop Supplies		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
		10020 INJECTOR CLEANER DON'T REORDER	1.00
Parts Charge: 41.97	Labor Charge: 60.00		

Workorder: 834352 **Problem:** DEAD BATTERY

Meter Reading: 4831	Labor	Parts	
In Date: 02/19/2008	Hours	Description	Quantity
- Complaint Dead Battery.Test Starting,Charging Sys & Battery Send To Dealer For Warranty	2.40	SHOP SUPPLIES	1.00
- Transport Vehicle To And From Toyota Dealer To Replace Batt Under Factory Warranty.			
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 84.00		

12/28/2017
3:08:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166683 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 834353

Problem: VEHICLE DEAD AT VISTA

Meter Reading: 4831	Labor	Parts	Quantity
In Date: 02/19/2008	Hours	Description	Quantity
- Jump Start 10166683 At Vista And Bring To Lv Shop	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	30.00

Workorder: 837089

Problem: P.M. SERVICE.

Meter Reading: 5633	Labor	Parts	Quantity
In Date: 04/16/2008	Hours	Description	Quantity
- Pm Service	4.00	SHOP SUPPLIES	1.00
- High Speed Balance 4 Tires		CA10159 AIR FILTER WIX 49116 PRIUS 04-UP	1.00
- Clean And Adjust The Rear Brake Shoes		5W30 OIL	4.00
- Shop Supplies		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
Parts Charge:	21.31	Labor Charge:	60.00

Workorder: 839597

Problem: F/F TIRE FLAT TOP FLOOR OF VISTA GARAGE

Meter Reading: 6715	Labor	Parts	Quantity
In Date: 06/06/2008	Hours	Description	Quantity
- Field Service Call-Vista Garage Top Floor Spot#B15	1.50	SHOP SUPPLIES	1.00
- Air Tire Transport To Lv			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	30.00

Workorder: 839605

Problem: L/F TIRE FLAT

Meter Reading: 6715	Labor	Parts	Quantity
In Date: 06/06/2008	Hours	Description	Quantity
- Mount And Balance 1 New Tire On L.Front	1.00	TIRE DISPOSAL FEE	1.00
- Shop Supplies		402032477 185/65R15 INTEGRITY DON'T REORDER	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	63.67	Labor Charge:	60.00

12/28/2017
3:08:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166683 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 839827

Problem: FLAT TIRE,VOID VOID VOID WRONG ASSET #

Meter Reading: 6715	Labor	Parts	
In Date: 06/10/2008	Hours	Description	Quantity
-		402032477 185/65R15 INTEGRITY DON'T REORDER	1.00
		TIRE DISPOSAL FEE	-1.00
		402032477 185/65R15 INTEGRITY DON'T REORDER	-1.00
		TIRE DISPOSAL FEE	1.00
Parts Charge:	0.00	Labor Charge:	0.00

Workorder: 845869

Problem: P.M SERVICE

Meter Reading: 9829	Labor	Parts	
In Date: 10/17/2008	Hours	Description	Quantity
- Pm Service	4.00	PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
- Service Rear Brake.Clean,Inspect,And Adjust Rear Brakes.		SHOP SUPPLIES	1.00
- Rotate & High Speed Balance All 4 Tires.		8524247010 BLADE REAR WIPER (TOYOTA)	1.00
- Shop Supplies		31-24 WIPER BLADES 24" BLADE	1.00
		5W30 OIL	4.00
		NB-18 WIPER BLADES 18" ANCO 31-18	1.00
Parts Charge:	42.66	Labor Charge:	60.00

Workorder: 937897

Problem: P.M SERVICE

Meter Reading: 14947	Labor	Parts	
In Date: 05/18/2009	Hours	Description	Quantity
- Pm Service	4.00	PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
- Service Rear Brakes.		NB-18 WIPER BLADES 18" ANCO 31-18	1.00
- Rotate & Hi Speed Balance All 4 Tires.Nitro Fill Tires To Specs.		SHOP SUPPLIES	1.00
- Shop Supplies		31-24 WIPER BLADES 24" BLADE	1.00
		5W30 OIL	4.00
Parts Charge:	26.32	Labor Charge:	240.00

12/28/2017
3:08:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166683 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 946683

Problem: P.M service.

Meter Reading: 20008		Labor	Parts	
In Date: 12/04/2009	Close Date: 12/16/2009	Hours	Description	Quantity
-	P.M Service.	7.50	PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
-	Mount Two New Tires, Rotate & Balance All Four Tires.		NB-18 WIPER BLADES 18" ANCO 31-18	1.00
-	Service Rear Drum Brakes.		8524247010 BLADE REAR WIPER (TOYOTA)	1.00
-	Alignment.		TIRE DISPOSAL FEE	2.00
-	Shop Supplies		738001571 185/65R15 ASSURANCE(DISCONTINUED)	2.00
			SHOP SUPPLIES	1.00
			5W30 OIL	4.00
			31-24 WIPER BLADES 24" BLADE	1.00
Parts Charge: 207.12		Labor Charge: 900.00		

Workorder: 1006380

Problem: Pm service.

Meter Reading: 23817		Labor	Parts	
In Date: 06/16/2010	Close Date: 06/25/2010	Hours	Description	Quantity
-	Perform Pm Service.	3.00	PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
-	Perform Rear Drum Brakes Service And Adjust Brake Shoes.		5W30 OIL	4.00
-	Shop Supplies		CA10159 AIR FILTER WIX 49116 PRIUS 04-UP	1.00
			BRAKE PEDAL PAD	1.00
			SHOP SUPPLIES	1.00
Parts Charge: 30.94		Labor Charge: 180.00		

Workorder: 1013923

Problem: P.M. service.

Meter Reading: 27461		Labor	Parts	
In Date: 12/17/2010	Close Date: 12/27/2010	Hours	Description	Quantity
-	Perform Pm Service.	4.50	5W30 OIL	4.00
-	Install One New Tire To The Right Front.Nitrogen Fill And Balance All Four.		NB-18 WIPER BLADES 18" ANCO 31-18	1.00
-	Perform Rear Drum Brakes Service And Adjust Brake Shoes.		738523571 P185/65R15 ASSURANCE FUEL MAX 88H	1.00
-	Shop Supplies		TIRE DISPOSAL FEE	1.00
			SHOP SUPPLIES	1.00
			PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
			31-24 WIPER BLADES 24" BLADE	1.00
Parts Charge: 118.04		Labor Charge: 270.00		

12/28/2017
3:08:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166683 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1106640

Problem: P.M. Service.Water pump recall.

Meter Reading: 31828	Labor	Parts	
In Date: 06/23/2011	Hours	Description	Quantity
- Perform Pm Service.	8.25	SHOP SUPPLIES	1.00
- Remove Tailgate Trim To Acss And Replace Failed Trunk Lock Switch/Handle With New.		5W30 OIL	4.00
		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
- Install One New Tire To The Right Front Wheel.Notrogen Fill And Balance All Four.		CF9846A CAB FILTER WIX 24875	1.00
		8524247010 BLADE REAR WIPER (TOYOTA)	1.00
- Perform Rear Drum Brake Service And Adjust Brake Shoes.		738523571 P185/65R15 ASSURANCE FUEL MAX 88H	1.00
		TIRE DISPOSAL FEE	1.00
- Transport Vehicle To And From Dealer For Performing Hybrid Water Pump And Accelerator Pedal Recalls.Replacing Hybrid Water Pump With New And Modify Accelerator Pedal To Floor Surface.		TRUNK RELEASE SWITCH	1.00
		CA10159 AIR FILTER WIX 49116 PRIUS 04-UP	1.00
- Shop Supplies			
Parts Charge:	205.35	Labor Charge:	495.00

Workorder: 1107932

Problem: Left tail lamp lens broken.

Meter Reading: 32643	Labor	Parts	
In Date: 07/28/2011	Hours	Description	Quantity
- Replace Left Tail Light Assemble.	0.50	LEFT TAIL LIGHT ASSY	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	243.85	Labor Charge:	30.00

Workorder: 1111320

Problem: Pm service

Meter Reading: 33903	Labor	Parts	
In Date: 10/26/2011	Hours	Description	Quantity
- P.M. Service.	4.00	PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
- Service And Adjust Rear Brakes.		SHOP SUPPLIES	1.00
- Rotate And Balance All Tires.		31-24 WIPER BLADES 24" BLADE	1.00
- Shop Supplies		5W30 OIL	4.00
		NB-18 WIPER BLADES 18" ANCO 31-18	1.00
Parts Charge:	27.21	Labor Charge:	240.00

12/28/2017
3:08:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166683 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1203322

Problem: P.M. Service.

Meter Reading: 38504		Labor	Parts	
In Date: 04/09/2012	Close Date: 04/18/2012	Hours	Description	Quantity
-	P.M. Service.	4.00	PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
-	Service And Adjust Rear Brakes.		SHOP SUPPLIES	1.00
-	Rotate And Balance All Tires.		NB-18 WIPER BLADES 18" ANCO 31-18	1.00
-	Shop Supplies		31-24 WIPER BLADES 24" BLADE	1.00
			5W30 OIL	4.00
			8524247010 BLADE REAR WIPER (TOYOTA)	1.00
Parts Charge: 43.16		Labor Charge: 240.00		

Workorder: 1209684

Problem: P.M. service.

Meter Reading: 42312		Labor	Parts	
In Date: 10/10/2012	Close Date: 10/25/2012	Hours	Description	Quantity
-	P.M. Service.	7.50	PH4967 OIL FILTER LBF	1.00
-	Replace Two Tires,Rotate And Balance All Four.		SHOP SUPPLIES	1.00
-	Complete Wheel Alignment.Test Drive.		738523571 P185-65R15	2.00
-	Service And Adjust Rear Brakes.		5W30 OIL	4.00
-	Shop Supplies			
Parts Charge: 249.76		Labor Charge: 450.00		

Workorder: 1303510

Problem: Pm service and steering shaft recall.

Meter Reading: 45179		Labor	Parts	
In Date: 04/10/2013	Close Date: 04/22/2013	Hours	Description	Quantity
-	Perform Pm Service.	7.00	NAPA QUART 5W30	4.00
-	Test Starting And Charging System.Battery Failed		NAPAGOLD OIL FILTER	1.00
-	Loadtest After Recharge.Replace Failed Battery With New.		31-24 WIPER BLADES 2	1.00
-	Perform Rear Drum Brake Service And Adjust Brake Shoes.		WIPER BLADE	1.00
-	Rotate And Balance All Four Tires.		8524247010 BLADE REAR	1.00
-	Transport Vehicle To And From Dealer For Performing Steering Shaft Recall Complete.		00544-21171-325 BATT	1.00
-	Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge: 347.03		Labor Charge: 420.00		

12/28/2017
3:08:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166683 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1310296

Problem: P.M. service.

Meter Reading: 48192	Labor	Parts
In Date: 10/10/2013	Hours	Quantity
Close Date: 10/30/2013	Description	
- P.M. Service.	5.00	NAPA QUART 5W30 4.00
- Replace Two Tires,Rotate And Balance All Four.		31-24 WIPER BLADES 2 1.00
- Service And Adjust Rear Brakes.		WIPER BLADE 1.00
- Shop Supplies		738523571 P185-65R15 2.00
		SHOP SUPPLIES 1.00
		TIRE DISPOSAL FEE 2.00
		NAPAGOLD OIL FILTER 1.00
Parts Charge: 275.33	Labor Charge: 300.00	

Workorder: 1403749

Problem: Pm service

Meter Reading: 50877	Labor	Parts
In Date: 04/16/2014	Hours	Quantity
Close Date: 04/24/2014	Description	
- Perform Pm Service.	4.00	NAPAGOLD OIL FILTER 1.00
- Rotate And Balance All Four Tires.		NAPA CABIN AIR FILTER 1.00
- Perform Rear Drum Brake Service And Adjust Brake Shoes.		SHOP SUPPLIES 1.00
- Shop Supplies		NAPAGOLD AIR FILTER 1.00
		NAPA QUART 5W30 4.00
Parts Charge: 35.74	Labor Charge: 240.00	

Workorder: 1410427

Problem: Pm service

Meter Reading: 53458	Labor	Parts
In Date: 10/17/2014	Hours	Quantity
Close Date: 10/30/2014	Description	
- Pm Service.	7.50	TIRE DISPOSAL FEE 2.00
- Replace Two Tires.Rotate And Balance All Four.		SHOP SUPPLIES 1.00
- Complete Front End Alignment And Test Drive.		NAPA QUART 5W30 4.00
- Inspect And Service Rear Drum Brakes.		NAPAGOLD OIL FILTER 1.00
- Shop Supplies		31-24 WIPER BLADES 2 1.00
		WIPER BLADE 1.00
		738523571 P185-65R15 2.00
Parts Charge: 277.65	Labor Charge: 450.00	

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166683 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1410948

Problem: Check engine light on and check tire pressure warning light on and fff.

Meter Reading: 53554	Labor	Parts
In Date: 10/31/2014	Hours	Description
Close Date: 11/12/2014	Quantity	
- Computer Diagnose For Low Tire Pressure Warning Light Flashing.Code C2177.Replace Defective Right Front Tire Pressure Sensor And Register With Scan Tool.	4.00	SHOP SUPPLIES TPMS SENSOR NAPAGOLD AIR FILTER
- Computyer Diagnose For Ckeck Engine Light On.Code P0171.Replace Defective Air Filter With Gasket .Clear Code And Retest.		
- Shop Supplies		
Parts Charge:	104.03	Labor Charge: 240.00

Workorder: 1500210

Problem: Check ac performance.

Meter Reading: 53959	Labor	Parts
In Date: 01/07/2015	Hours	Description
Close Date: 01/22/2015	Quantity	
- A/C Performance Test.Unable To Duplicate Drivedrs Complain At This Time.	0.50	
Parts Charge:	0.00	Labor Charge: 30.00

Workorder: 1504033

Problem: Pm service.

Meter Reading: 55431	Labor	Parts
In Date: 04/17/2015	Hours	Description
Close Date: 04/30/2015	Quantity	
- Pm Service.	4.00	NAPA QUART 5W30
- Inspect And Service Rear Drum Brakes.		WIPER BLADE
- Rotate And Balance All Four Tires.		BRAKE CLEANER
- Shop Supplies		NAPAGOLD OIL FILTER
		31-24 WIPER BLADES 2
		SHOP SUPPLIES
Parts Charge:	33.78	Labor Charge: 240.00

12/28/2017
3:08:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166683 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1510382

Problem: Pm service.

Meter Reading: 56279	Labor	Parts	
In Date: 10/14/2015	Hours	Description	Quantity
- Pm Service.	4.00	SHOP SUPPLIES	1.00
- Rotate And Balance All Four Wheels.		NAPA QUART 5W30	4.00
- Inspect And Service Rear Brakes.		NAPAGOLD OIL FILTER	1.00
- Shop Supplies		WIPER BLADE	1.00
		WIPER BLADE	1.00
		ACCUFIT REAR	1.00
		WASHER FLUID CONCENTR	1.00
Parts Charge:	41.42	Labor Charge:	240.00

Workorder: 1603884

Problem: P.M/ Service

Meter Reading: 57164	Labor	Parts	
In Date: 04/13/2016	Hours	Description	Quantity
- P.M. Service.	5.50	TIRE DISPOSAL FEE	2.00
- Replace Two Tires,Roatae And Balance All Four.		SHOP SUPPLIES	1.00
- Fabricate And Install New Asset #S		ACCUFIT REAR	1.00
- Service And Adjust Rear Brakes.		NAPA CABIN AIR FILTER	1.00
- Shop Supplies		738523571 P185-65R15	2.00
		NAPAGOLD OIL FILTER	1.00
		18" wiper blades	1.00
		WIPER BLADES 24"	1.00
		NAPA QUART 5W30	4.00
Parts Charge:	301.46	Labor Charge:	330.00

Workorder: 1606328

Problem: Tire pressure light on.

Meter Reading: 57981	Labor	Parts	
In Date: 06/21/2016	Hours	Description	Quantity
- Repair And Balance Left Rear Tire.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

12/28/2017
3:08:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166683 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1611616

Problem: P.M. service.

Meter Reading: 61760	Labor	Parts	
In Date: 11/10/2016	Hours	Description	Quantity
- P.M. Service.	4.00	SHOP SUPPLIES	1.00
- Service And Adjust Rear Brakes.		NAPA QUART 5W30	4.00
- Rotate And Balance Tires.		WD40 SPR	1.00
- Shop Supplies		NAPAGOLD OIL FILTER	1.00
		WASHER FLUID CONCENTR	1.00
Parts Charge:	29.81	Labor Charge:	240.00

Workorder: 1701318

Problem: Towed in left front tire flat.

Meter Reading: 63122	Labor	Parts	
In Date: 02/08/2017	Hours	Description	Quantity
- Replace And Balance Damaged Left Front Tire.	0.50	738523571 P185-65R15	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		TIRE DISPOSAL FEE	1.00
Parts Charge:	112.62	Labor Charge:	30.00

Workorder: 1701451

Problem: left front flat tire/ key front seat

Meter Reading: 63122	Labor	Parts	
In Date: 02/08/2017	Hours	Description	Quantity
- Tow From: 2300 Jog Road 5Th Floor Parking Garage To: 2601 Vista			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	96.00

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166683 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1706099

Problem: P.M. Service

Meter Reading: 65206		Labor		Parts	
In Date: 06/20/2017	Close Date: 06/30/2017	Hours	Description		Quantity
-	P.M. Service.	4.00	WIPER BLADES 24"		1.00
-	Rotate And Balance Tires.		SHOP SUPPLIES		1.00
-	Service And Adjust Rear Brakes.		WASHER FLUID CONCENTR		1.00
-	Shop Supplies		NAPA QUART 5W30		4.00
			18" wiper blades		1.00
			ACCUFIT REAR		1.00
			NAPAGOLD OIL FILTER		1.00
	Parts Charge: 37.63	Labor Charge:	240.00		

Workorder: 1708177

Problem: Left rear tire flat ,spare on vehicle.

Meter Reading: 65916		Labor		Parts	
In Date: 08/18/2017	Close Date: 08/22/2017	Hours	Description		Quantity
-	Repair Left Rear Tire And Balance.Nitrogen Fill Tires.	1.00	SHOP SUPPLIES		1.00
-	Shop Supplies				
	Parts Charge: 2.00	Labor Charge:	60.00		

Workorder: 1710836

Problem: Transition Prep Charge

Meter Reading: 66729		Labor		Parts	
In Date: 11/01/2017	Close Date: 11/01/2017	Hours	Description		Quantity
-	Transition Prep Charge	2.00			
	Parts Charge: 0.00	Labor Charge:	0.00		

Total Parts Charges:	2,927.86	Total Labor Charges:	6,659.00	Total Comm. Charges:	103.14
----------------------	-----------------	----------------------	-----------------	----------------------	---------------