

12/28/2017
3:43:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178871 2009 FORD RANGER Pickup, Compact, W/Toolbox

| | | | | |
|----------------------------|-------------------------------|---|--------------------|-----------------|
| Workorder: 935997 | | Problem: PRE-DELIVERY INSPECTION | | |
| Meter Reading: 0 | | Labor | Parts | |
| In Date: 04/02/2009 | Close Date: 04/02/2009 | Hours | Description | Quantity |
| - Pre-Delivery Inspection | | 2.00 | | |
| Parts Charge: | 0.00 | Labor Charge: | 120.00 | |

| | | | | |
|----------------------------|-------------------------------|---------------------------------------|--|-----------------|
| Workorder: 936436 | | Problem: CUT & PROGRAM NEW KEY | | |
| Meter Reading: 124 | | Labor | Parts | |
| In Date: 04/13/2009 | Close Date: 04/17/2009 | Hours | Description | Quantity |
| - Cut Key And Program | | 1.00 | 164-R0475 IGN KEY 2010-EARLIER (DON'T REORDER) | 1.00 |
| - Shop Supplies | | | SHOP SUPPLIES | 1.00 |
| Parts Charge: | 23.45 | Labor Charge: | 60.00 | |

| | | | | |
|----------------------------------|-------------------------------|----------------------------|-------------------------------------|-----------------|
| Workorder: 944760 | | Problem: PM SERVICE | | |
| Meter Reading: 3386 | | Labor | Parts | |
| In Date: 10/20/2009 | Close Date: 10/23/2009 | Hours | Description | Quantity |
| - P.M.Service | | 3.00 | SHOP SUPPLIES | 1.00 |
| - Service Rear Brakes,Test Drive | | | 1516 OIL FILTERFRM PH3600 WIX 51516 | 1.00 |
| - Shop Supplies | | | 5W20 ENGINE OIL | 5.00 |
| | | | NB-18 WIPER BLADES 18" ANCO 31-18 | 2.00 |
| | | | 09997 BRAKE CLEAN | 1.00 |
| Parts Charge: | 41.12 | Labor Charge: | 180.00 | |

12/28/2017
3:43:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178871 2009 FORD RANGER Pickup, Compact, W/Toolbox

Workorder: 1003929

Problem: P. M., & see work request

| Meter Reading: 6416 | Labor | Parts | |
|---|-------|---|----------|
| In Date: 04/15/2010 | Hours | Description | Quantity |
| - P. M. | 6.25 | 1516 OIL FILTERFRM PH3600 WIX 51516 | 1.00 |
| - Rear Brake Drum Service, Adjust Shoes. | | L/REAR TAIL LIGHT ASSY. | 1.00 |
| - Verify. Two Tires Need Replacement. R&R 2 Tires. Mount, | | TIRE DISPOSAL FEE | 2.00 |
| Balance, Add 30 Psi Of Nitrogen. Repair One Tire, | | 183482418 P225/70R15 WRANGLER SR-A 100S | 2.00 |
| Dismount, Patch, Mount, Balance. | | 5W20 ENGINE OIL | 5.00 |
| - Verify, Tail Light Damaged. R&R Tail Light Assy. | | 09997 BRAKE CLEAN | 1.00 |
| - C/C: Trim Damaged Tool Box Will Not Open/Close | | SHOP SUPPLIES | 1.00 |
| Properly, Repair Trim, Found No Problems With Tool Box. | | | |
| - Shop Supplies | | | |
| Parts Charge: 331.58 | | Labor Charge: 375.00 | |

Workorder: 1011412

Problem: P.M., Leak in tire (see dash symbol), tool box does not close or lock properly.

| Meter Reading: 9634 | Labor | Parts | |
|---|-------|---|----------|
| In Date: 10/15/2010 | Hours | Description | Quantity |
| - P. M. Service. | 9.00 | 183482418 P225/70R15 WRANGLER SR-A 100S | 2.00 |
| - Rear Brake Drum Service. | | 09997 BRAKE CLEAN | 1.00 |
| - Verify Needs Two Rear Tires. Dismount, Mount Two | | 1516 OIL FILTERFRM PH3600 WIX 51516 | 1.00 |
| P225/70R15 Tires, Add Nitrogen, Rotate To Front. | | SHOP SUPPLIES | 1.00 |
| - C/C: Tool Box Does Not Close Or Lock Properly, | | NB-18 WIPER BLADES 18" ANCO 31-18 | 2.00 |
| Disassemble Damaged Latch Assys, Lubricate, Adjust, | | 5W20 ENGINE OIL | 5.00 |
| Repair, Reinstall. Install Bumper Sticker. | | CA8243 AIR FILTER LBF AF1658 WIX 46253 | 1.00 |
| - Verify, Nail In F/R Tire, Patch, Rotate To Right Rear. | | TIRE DISPOSAL FEE | 2.00 |
| - Transport & Pick Up Vehicle At Dealer. (Defective Shifter | | | |
| Tube & Indicator). | | | |
| - Dealer To Replace Defective Trans Shifter Bushing & | | | |
| Indicator. | | | |
| - Shop Supplies | | | |
| Parts Charge: 284.37 | | Labor Charge: 480.00 | |

12/28/2017
3:43:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178871 2009 FORD RANGER Pickup, Compact, W/Toolbox

Workorder: 1011965

Problem: flash canceiver

| Meter Reading: 9862 | Labor | Parts | |
|----------------------|-------|----------------------|----------|
| In Date: 10/26/2010 | Hours | Description | Quantity |
| - Flash Canceiver | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: | 2.00 | Labor Charge: | 60.00 |

Workorder: 1104452

Problem: P. M., Tire light is lit on dash, shifter needle stuck all the way to the right, ck interior light

| Meter Reading: 13418 | Labor | Parts | |
|--|-------|-------------------------------------|----------|
| In Date: 04/26/2011 | Hours | Description | Quantity |
| - P. M. Service. | 6.50 | 3424 FUEL FILTER FRM 3424 WIX 33424 | 1.00 |
| - Service Rear Brake Drums. Send To Dealer To Replace Springs On Drums. | | 1516 OIL FILTERFRM PH3600 WIX 51516 | 1.00 |
| | | 5W20 ENGINE OIL | 5.00 |
| - C/C: Tire Light On. Verify, Tpms Light On, Nail In F/L Tire. Dismount, Patch, Mount, Balance, & Add N2. | | NB-18 WIPER BLADES 18" ANCO 31-18 | 2.00 |
| | | SHOP SUPPLIES | 1.00 |
| - C/C: Interior Light Out. Replace Bulb. Replace Cargo Thrid Brake Light Bulb. | | | |
| - Transport & Pick Up Vehicle At Dealer For Defective Trans Shifter Indicator & Rear Brake Shoes Return Springs. | | | |
| - Dealer To Replace Defective Trans Shifter Indicator Under Warranty. | | | |
| - Dealer To Replace Defective Rear Brake Shoes Return Springs Under Warranty. | | | |
| - Shop Supplies | | | |
| Parts Charge: | 31.92 | Labor Charge: | 390.00 |

Workorder: 1110036

Problem: mileage error

| Meter Reading: 16222 | Labor | Parts | |
|---|-------|----------------------|----------|
| In Date: 09/20/2011 | Hours | Description | Quantity |
| - Repair Canceiver Connector Install Updated Screws | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: | 2.00 | Labor Charge: | 60.00 |

12/28/2017
3:43:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178871 2009 FORD RANGER Pickup, Compact, W/Toolbox

Workorder: 1111156

Problem: P. M., & passenger front tire still leaking, (maybe rear passenger tire too).

| Meter Reading: 16915 | Labor | Parts | | |
|--|--------------|-----------------------------|-------------------------------------|-----------------|
| In Date: 10/20/2011 | Hours | | Description | Quantity |
| - P. M. Service. | 8.00 | | 1516 OIL FILTERFRM PH3600 WIX 51516 | 1.00 |
| - Verify, Needs Front Pads. Turn Rotors, Service Calipers. | | | 5W20 ENGINE OIL | 5.00 |
| - Install New Brake Pads & Test Drive. | | | SHOP SUPPLIES | 1.00 |
| - Service Rear Brake Drums, Adjust Shoes. | | | FRONT BRAKE PADS | 1.00 |
| - Cc: Passenger Tires Flat. Verify, Nail In F/R And R/R Tires. Dismount Both, Patch, Mount, Balance, Add N2. Correct All Psi Levels. | | | | |
| - Shop Supplies | | | | |
| Parts Charge: 74.36 | | Labor Charge: 480.00 | | |

Workorder: 1200074

Problem: Front right tire low

| Meter Reading: 17978 | Labor | Parts | | |
|---|--------------|----------------------------|--------------------|-----------------|
| In Date: 01/03/2012 | Hours | | Description | Quantity |
| - C/C: Front Right Tire Low. Verify, Nail In F/R. Dismount, Patch, Mount, Balance, Add N2, & Clear Tpms. | 1.00 | | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | | |
| Parts Charge: 2.00 | | Labor Charge: 60.00 | | |

Workorder: 1200680

Problem: Heater not working

| Meter Reading: 18157 | Labor | Parts | | |
|---|--------------|-----------------------------|--------------------|-----------------|
| In Date: 01/20/2012 | Hours | | Description | Quantity |
| - C/S: Heater Inop. Verified Concern. Found Defective A/C Heater Control Motor Assy. | 2.50 | | SHOP SUPPLIES | 1.00 |
| - Transport & Pick Up Vehicle At Dealer. (Defective A/C Controller & Door Actuator Motor). | | | | |
| - Shop Supplies | | | | |
| Parts Charge: 2.00 | | Labor Charge: 150.00 | | |

12/28/2017
3:43:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178871 2009 FORD RANGER Pickup, Compact, W/Toolbox

Workorder: 1200808

Problem: DEAD BATTERY

| Meter Reading: 18172 | Labor | Parts | Quantity |
|---|-------|----------------------|----------|
| In Date: 01/26/2012 | Hours | Description | Quantity |
| - Recharge Battery & Check Charging System. Found Defective Battery. | 2.50 | SHOP SUPPLIES | 1.00 |
| - Transport & Pick Up Vehicle At Dealer. (Dealer To Replace Defective Battery). | | | |
| - Shop Supplies | | | |
| Parts Charge: | 2.00 | Labor Charge: | 150.00 |

Workorder: 1202921

Problem: drivers side rear tire has a screw in it

| Meter Reading: 19236 | Labor | Parts | Quantity |
|-------------------------|-------|----------------------|----------|
| In Date: 03/27/2012 | Hours | Description | Quantity |
| - Repair Left Rear Tire | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: | 2.00 | Labor Charge: | 60.00 |

Workorder: 1204861

Problem: P. M. SERVICE

| Meter Reading: 20376 | Labor | Parts | Quantity |
|---|--------|---|----------|
| In Date: 05/24/2012 | Hours | Description | Quantity |
| - Pm | 7.25 | SHOP SUPPLIES | 1.00 |
| - Rear Brake Drum Service | | TRANS. GEAR SHIFT INDICATOR | 1.00 |
| - Verify Needds Fofur Tires Dismount Mount Balance 4 P225 70R15 Tires | | 3424 FUEL FILTER FRM 3424 WIX 33424 | 1.00 |
| - Add 30 Psi Of Nitrogen | | 1516 OIL FILTERFRM PH3600 WIX 51516 | 1.00 |
| - Verify Shift Indicator Brolen Disassemble Dash Remove Steering Column Replace Indicator Assy Test Drive | | NB-18 WIPER BLADES 18" ANCO 31-18 | 2.00 |
| - Shop Supplies | | 183482418 P225/70R15 WRANGLER SR-A 100S | 4.00 |
| | | 5W20 ENGINE OIL | 5.00 |
| | | TIRE DISPOSAL FEE | 4.00 |
| Parts Charge: | 572.39 | Labor Charge: | 435.00 |

12/28/2017
3:43:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178871 2009 FORD RANGER Pickup, Compact, W/Toolbox

Workorder: 1206842 **Problem:** screw in tire passenger side rear

| Meter Reading: 21337 | Labor | Parts | |
|-----------------------------|--------------|----------------------|-----------------|
| In Date: 07/23/2012 | Hours | Description | Quantity |
| - Repair Right Rear Tire | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: | 2.00 | Labor Charge: | 60.00 |

Workorder: 1300297 **Problem:** pm

| Meter Reading: 22808 | Labor | Parts | |
|-----------------------------|--------------|-----------------------|-----------------|
| In Date: 01/08/2013 | Hours | Description | Quantity |
| - Pm | 3.00 | SHOP SUPPLIES | 1.00 |
| - Rear Brake Drum Svc | | PH3600 OIL FILTER LBF | 1.00 |
| - Shop Supplies | | NAPA QUART 5W20 | 5.00 |
| Parts Charge: | 27.43 | Labor Charge: | 180.00 |

Workorder: 1308963 **Problem:** P.M.SERVICE,

| Meter Reading: 30717 | Labor | Parts | |
|--|--------------|----------------------|-----------------|
| In Date: 09/04/2013 | Hours | Description | Quantity |
| - Pm | 5.00 | WIPER BLADE | 2.00 |
| - Rear Brake Drum Svc | | NAPAGOLD AIR FILTER | 1.00 |
| - Verify Nail In Side Wall Replace Right Rear Tire Mount | | TIRE DISPOSAL FEE | 1.00 |
| - Balance Add N2 | | SHOP SUPPLIES | 1.00 |
| - Nail In FI Tire Dismount Paatch Mount Balance Add N2 | | NAPAGOLD FUEL FILTER | 1.00 |
| - Shop Supplies | | NAPAGOLD OIL FILTER | 1.00 |
| | | NAPA QUART 5W20 | 5.00 |
| | | 183482418 P225-70R15 | 1.00 |
| Parts Charge: | 205.26 | Labor Charge: | 300.00 |

12/28/2017
3:43:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178871 2009 FORD RANGER Pickup, Compact, W/Toolbox

Workorder: 1311078

Problem: BRAKES ARE GRINDING

| Meter Reading: 32632 | Labor | Parts | |
|---|-----------------------------|----------------------|-----------------|
| In Date: 10/31/2013 | Hours | Description | Quantity |
| - Ck Brakes Noisy Verify Front Brakes Need Replaced | 3.50 | SHOP SUPPLIES | 1.00 |
| Replace Front Pads And Rotors Test Drive | | DISC BRAKE PADS | 1.00 |
| - Shop Supplies | | DISC BRAKE ROTOR HUB | 2.00 |
| Parts Charge: 256.03 | Labor Charge: 210.00 | | |

Workorder: 1403329

Problem: pm

| Meter Reading: 36889 | Labor | Parts | |
|---|-----------------------------|----------------------|-----------------|
| In Date: 04/04/2014 | Hours | Description | Quantity |
| - Pm | 5.50 | TIRE DISPOSAL FEE | 3.00 |
| - Svc And Adj Rear Drum Brakes | | SHOP SUPPLIES | 1.00 |
| - Replace Right Rear Tail Light Assm | | NAPA QUART 5W20 | 5.00 |
| - Verify Needs 3 Tires Mount Balance Add N2 | | NAPAGOLD OIL FILTER | 1.00 |
| - Shop Supplies | | NAPAGOLD FUEL FILTER | 1.00 |
| | | NAPAGOLD AIR FILTER | 1.00 |
| | | WIPER BLADE | 2.00 |
| | | BRAKE CLEANER | 1.00 |
| | | LAMP ASSEMBLY | 1.00 |
| | | 183482418 P225-70R15 | 3.00 |
| Parts Charge: 619.82 | Labor Charge: 330.00 | | |

12/28/2017
3:43:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178871 2009 FORD RANGER Pickup, Compact, W/Toolbox

Workorder: 1410549

Problem: PM, BATTERY LOW, CK RIGHT TURN SIGNAL,

| Meter Reading: 41797 | Labor | Parts | |
|---|--------|----------------------|----------|
| In Date: 10/22/2014 | Hours | Description | Quantity |
| - Pm | 11.25 | GROUP 59 BATTERY MC | 1.00 |
| - Resurface Rear Drums Replace And Adj Shoes | | NAPA QUART 5W20 | 5.00 |
| - Repair Rear Turn Signal | | NAPAGOLD OIL FILTER | 1.00 |
| - Replace Left And Right Front Lower Ball Joint | | WASHER FL | 1.00 |
| - Replace Bad Battery And Ck Charging Sys | | WIPER BLADE | 2.00 |
| - Shop Supplies | | REMAN BRAKE SHOES | 1.00 |
| | | BULB | 1.00 |
| | | LOWER BALL JOINT | 2.00 |
| | | BRAKE CLEANER | 1.00 |
| | | SHOP SUPPLIES | 1.00 |
| Parts Charge: | 307.12 | Labor Charge: | 675.00 |

Workorder: 1411294

Problem: needs spare key

| Meter Reading: 42191 | Labor | Parts | |
|--------------------------------|-------|-------------------------|----------|
| In Date: 11/12/2014 | Hours | Description | Quantity |
| - Make And Program 1 Extra Key | 1.00 | FORD IGNITION KEY BLANK | 1.00 |
| - Shop Supplies | | SHOP SUPPLIES | 1.00 |
| Parts Charge: | 28.61 | Labor Charge: | 60.00 |

12/28/2017
3:43:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178871 2009 FORD RANGER Pickup, Compact, W/Toolbox

Workorder: 1501224

Problem: PM

| Meter Reading: 47687 | Labor | Parts | Quantity |
|--|-------------|----------------------|----------|
| In Date: 02/03/2015 | Hours | Description | Quantity |
| - Pm | 8.00 | NAPA QUART 5W20 | 5.00 |
| - Clean And Adj Rear Brakes Resurface Front Rotors Svc | | NAPAGOLD OIL FILTER | 1.00 |
| Calipers And Replace Front Pads | | NAPAGOLD FUEL FILTER | 1.00 |
| - Replace Both Rear Tires Fill All Tires With Nitrogen And | | NAPAGOLD AIR FILTER | 1.00 |
| Retate New Tires To The Front | | DISC BRAKE PADS | 1.00 |
| - Shop Supplies | | BRAKE CLEANER | 1.00 |
| | | TIRE DISPOSAL FEE | 2.00 |
| | | 183482418 P225-70R15 | 2.00 |
| | | WIPER BLADE | 2.00 |
| | | B FLUID DOT 3-32OZ | 1.00 |
| | | SHOP SUPPLIES | 1.00 |
| Parts Charge: | 452.90 | Labor Charge: | 480.00 |

Workorder: 1504857

Problem: Pm service.Tpms.warning light on.Check transmission concern.

| Meter Reading: 53409 | Labor | Parts | Quantity |
|---|--------------|-----------------------|----------|
| In Date: 05/13/2015 | Hours | Description | Quantity |
| - Pm Service. | 16.00 | SHOP SUPPLIES | 1.00 |
| - Ac Blower Inop.Replace Defective Blower Resistor.Clean | | F3TZ7L278A BUSHING SH | 2.00 |
| Debris And Leaf From Ac Duct. | | DAMPER ASSY | 1.00 |
| - Replace Two Tires.Rotate And Balance Four. | | LEVER | 1.00 |
| - Flush And Replace Transmission Fluid And Filter.Replace | | SEAT R AND R | 1.00 |
| Selector Shaft Bushings And Handle Damper.Reprogram | | 5W20 ENGINE OIL | 5.00 |
| Tcm With Scan Tool. | | NAPAGOLD OIL FILTER | 1.00 |
| - Replace Broken Sway Bar Links. | | PEDAL PAD | 1.00 |
| - R&R Left Front Seat For Repairs. | | BLOWER MOTOR RESISTOR | 1.00 |
| - Complete Front End Alignment. | | 183482418 P225-70R15 | 2.00 |
| - Inspect And Service Rear Brakes. | | SYN-ATF TRANS FLUID S | 14.00 |
| - Shop Supplies | | SWAY BAR REPAIR KIT | 1.00 |
| | | FIL KIT | 1.00 |
| | | TIRE DISPOSAL FEE | 2.00 |
| Parts Charge: | 839.98 | Labor Charge: | 960.00 |

12/28/2017
3:43:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178871 2009 FORD RANGER Pickup, Compact, W/Toolbox

Workorder: 1507618

Problem: Check A/C not cooling at times.

| Meter Reading: 57660 | Labor | Parts | |
|---|-----------------------------|---|--|
| In Date: 07/30/2015 | Hours | Description | Quantity |
| - Check A/C System.Replace Fan Clutch.Replace A/C Accumulator,Orifice And High Side Schrader Valve.Vacuum And Recharge System To Specs. | 4.00 | HIGH SIDE SCHRADER VALVE PRESSURE SWITCH ORIFICE TUBE FILTER R134A LV SHOP 2 E8 A/C OIL UNIV W DYE FAN CLUTCH ASSY ACCUMULATOR SHOP SUPPLIES | 1.00 1.00 1.00 2.00 1.00 1.00 1.00 1.00 |
| - Shop Supplies | | | |
| Parts Charge: 340.88 | Labor Charge: 240.00 | | |

Workorder: 1508037

Problem: Ac inop.

| Meter Reading: 57733 | Labor | Parts | |
|--|-----------------------------|--|------------------------------|
| In Date: 08/11/2015 | Hours | Description | Quantity |
| - Diagnose Blower Inop.Replace Defective Blower Motor.Resistor And Connector With Harness. | 2.00 | BLOWER MOTOR BLOWER RESISTOR WIRE ASY SHOP SUPPLIES | 1.00 1.00 1.00 1.00 |
| - Shop Supplies | | | |
| Parts Charge: 176.66 | Labor Charge: 120.00 | | |

Workorder: 1508344

Problem: Transmission light blinking and bucks during acceleration.

| Meter Reading: 57812 | Labor | Parts | |
|---|-----------------------------|---|--|
| In Date: 08/19/2015 | Hours | Description | Quantity |
| - Computer Diagnose For Check Engine Light.Code P0301 And P0316 Perform Test And Replace Defective Ignition Coil Pack.Perform Tune Up.Replace Four Spark Plugs And Ignition Wire Set.Clear Codes. | 6.50 | IGNITION COIL SPARK PLUG WIRE SET SPARK PLUG INTAKE CLEANER KIT INJECTOR CLEANER SHOP SUPPLIES | 1.00 1.00 4.00 1.00 1.00 1.00 |
| - Perform Air Intake Decarb. And Clean Throttle Body.Perform Injectors Flush. | | | |
| - Shop Supplies | | | |
| Parts Charge: 199.44 | Labor Charge: 390.00 | | |

12/28/2017
3:43:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178871 2009 FORD RANGER Pickup, Compact, W/Toolbox

Workorder: 1509074

Problem: Pm service.

| Meter Reading: 59286 | Labor | Parts |
|--|-----------------------------|----------------------------|
| In Date: 09/10/2015 | Hours | Description |
| Close Date: 09/28/2015 | | Quantity |
| - Pm Service. | 10.25 | molding plate 1.00 |
| - Pressure Test Cooling System.Flush And Renew Coolant. | | SHOP SUPPLIES 1.00 |
| - Replace Cracked Left Tail Lamp Assembly.Replace Broken Sil Plate. | | 5W20 ENGINE OIL 5.00 |
| - Diagnose Looseness In Shifter.Replace Defective Shifter Tube Bushings And Damper.Had To Lower And Dismantle Steering Colum To Access And Readjust Shifter Cable. | | NAPAGOLD OIL FILTER 1.00 |
| - Repair Right Front Tire.Rotate And Balance All Four. | | WIPER BLADE 2.00 |
| - Perform Rear Brakes Service. | | PEAK GLOBAL 1.00 |
| - Shop Supplies | | F3TZ7L278A BUSHING SH 2.00 |
| | | lamp assy 1.00 |
| | | DAMPER ASSY 1.00 |
| | | WASHER FLUID CONCENTR 1.00 |
| Parts Charge: 144.13 | Labor Charge: 615.00 | |

Workorder: 1510285

Problem: Check turnsignals intermittent and brakes squeaky.

| Meter Reading: 60134 | Labor | Parts |
|---|-----------------------------|---------------------------|
| In Date: 10/09/2015 | Hours | Description |
| Close Date: 10/20/2015 | | Quantity |
| - Inspect And Service Rear Brakes.Replace Both Front Brake Rotors.Front Brake Pads,Two Front Calipers And Two Grease Seals.Repack Wheel Bearings.Flush And Bleed Brake System.Test Drive. | 4.75 | SHOP SUPPLIES 1.00 |
| - Diagnose Turnsignal Light Inop.Replace Defective Flasher Unit And Retest. | | DISC BRAKE ROTOR HUB 2.00 |
| - Shop Supplies | | NAPA OIL SEAL 2.00 |
| | | REMAN BRAKE CALIPER 1.00 |
| | | CERAMIC BRAKE LUBE 1.00 |
| | | REMAN BRAKE CALIPER 1.00 |
| | | FLASHER RELAY 1.00 |
| | | BRAKE CLEANER 1.00 |
| Parts Charge: 488.79 | Labor Charge: 285.00 | |

12/28/2017
3:43:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178871 2009 FORD RANGER Pickup, Compact, W/Toolbox

Workorder: 1512547

Problem: Pm service.Check brakes.Flat tire.Check engine warning light was on.

| Meter Reading: 63610 In Date: 12/11/2015 | Close Date: 12/30/2015 | Labor Hours | Description | Parts | Quantity |
|--|------------------------|----------------|----------------------------|-------|----------|
| - Pm Service. | | 12.50 | TIRE /P225/70/15 / HANKOOK | | 2.00 |
| - Computer Diagnose For Check Engine Light On.Code P0442.Evapt.Test And Replace Defective Fuel Cap.Clear Code Wit Scan Tool And Retest Ok. | | | CONTROL ARM ASSEMBLY | | 1.00 |
| - Replace Two Tires.Rotate And Balance All Four. | | | TIRE DISPOSAL FEE | | 2.00 |
| - Right Front Upper Control Arm Bushing Failed.Replace Defective Right Front Upper Control Arm. | | | 5W20 ENGINE OIL | | 5.00 |
| - Complete Front End Alignment. | | | NAPAGOLD OIL FILTER | | 1.00 |
| - Left Front And Right Front Brakes Squealing.R&R Calipers.Service Slides And Pads.Also Service Rear Brakes. | | | NAPAGOLD FUEL FILTER | | 1.00 |
| - Shop Supplies | | | 18" wiper blades | | 2.00 |
| | | | GAS CAP | | 1.00 |
| | | | SHOP SUPPLIES | | 1.00 |
| Parts Charge: | | 361.60 | Labor Charge: | | 750.00 |

Workorder: 1601873

Problem: Pm service.Check brake noise.

| Meter Reading: 67367 In Date: 02/23/2016 | Close Date: 03/07/2016 | Labor Hours | Description | Parts | Quantity |
|--|------------------------|----------------|----------------------------|-------|----------|
| - Pm Service. | | 11.00 | BRAKE PADS | | 1.00 |
| - Replace Two Tires.Rotate And Balance All Four. | | | BRAKE CLEANER | | 1.00 |
| - Replace Defective Valve Cover Gasket Due To Oil Leak.Clean Engine With Degreaser. | | | VALVE CVR GASKET SET | | 1.00 |
| - Resurface Front Brake Rotors.Replace Brake Pads.Service Calipers.Bleed Brakes.Adjust Front Wheel Bearings.Service Rear Brakes. | | | TIRE DISPOSAL FEE | | 2.00 |
| - Shop Supplies | | | 5W20 ENGINE OIL | | 5.00 |
| | | | SHOP SUPPLIES | | 1.00 |
| | | | NAPAGOLD OIL FILTER | | 1.00 |
| | | | WASHER FLUID CONCENTR | | 1.00 |
| | | | 18" wiper blades | | 2.00 |
| | | | TIRE /P225/70/15 / HANKOOK | | 2.00 |
| Parts Charge: | | 355.17 | Labor Charge: | | 660.00 |

12/28/2017
3:43:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178871 2009 FORD RANGER Pickup, Compact, W/Toolbox

Workorder: 1605817

Problem: Brake light on.Turn signal inop.

| Meter Reading: 70095 | | Labor | | Parts | |
|-----------------------------|---|-----------------------------|--------------------|--------------|-----------------|
| In Date: 06/06/2016 | Close Date: 06/15/2016 | Hours | Description | | Quantity |
| - | Diagnose Abs/Brake Warning Lamp On.Test | 3.00 | SHOP SUPPLIES | | 1.00 |
| | Circuits,Open 20 Amp Fuse In Od. Selector Switch | | LEVER | | 1.00 |
| | Circuit.Trace And Replace Shorted Od Selector Switch. | | DAMPER ASSY | | 1.00 |
| - | Shop Supplies | | | | |
| Parts Charge: 72.57 | | Labor Charge: 180.00 | | | |

Workorder: 1607961

Problem: Right front tire flat

| Meter Reading: 71905 | | Labor | | Parts | |
|-----------------------------|----------------------------------|----------------------------|--------------------|--------------|-----------------|
| In Date: 08/03/2016 | Close Date: 08/04/2016 | Hours | Description | | Quantity |
| - | Repair And Balance R/Front Tire. | 1.00 | SHOP SUPPLIES | | 1.00 |
| - | Shop Supplies | | | | |
| Parts Charge: 2.00 | | Labor Charge: 60.00 | | | |

Workorder: 1609122

Problem: P.M.SERVICE, CHECK BRAKE

| Meter Reading: 73498 | | Labor | | Parts | |
|-----------------------------|--|-----------------------------|-----------------------|--------------|-----------------|
| In Date: 09/01/2016 | Close Date: 09/16/2016 | Hours | Description | | Quantity |
| - | P.M.Service. | 8.50 | WASHER FLUID CONCENTR | | 1.00 |
| - | R/R Front Wheel Bearings,Rotors,Brake Pads And | | 18" wiper blades | | 2.00 |
| | Service Calipers, R/R Rear Drums And Brake Shoes, Test | | NON-CHLOR BRAKE CLNR | | 1.00 |
| | Drive. | | TAPPERED BEARING SET | | 2.00 |
| - | Repair L/Rear Tire. | | DISC BRAKE PADS | | 1.00 |
| - | Shop Supplies | | SHOP SUPPLIES | | 1.00 |
| | | | TAPPERED BEARING SET | | 2.00 |
| | | | REMAN BRAKE SHOES | | 1.00 |
| | | | NAPAGOLD AIR FILTER | | 1.00 |
| | | | NAPAGOLD FUEL FILTER | | 1.00 |
| | | | B FLUID DOT 3-32OZ | | 1.00 |
| | | | REAL BRAKE DRUMS | | 2.00 |
| | | | NAPAGOLD OIL FILTER | | 1.00 |
| | | | NAPA QUART 5W20 | | 5.00 |
| | | | NAPA OIL SEAL | | 2.00 |
| | | | DISC BRAKE ROTOR HUB | | 2.00 |
| Parts Charge: 510.51 | | Labor Charge: 510.00 | | | |

12/28/2017
3:43:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178871 2009 FORD RANGER Pickup, Compact, W/Toolbox

Workorder: 1612017

Problem: Wont start.

| Meter Reading: 74034 | | Labor | | Parts | |
|-----------------------------|--|--------------|----------------------|-----------------|-------|
| In Date: 11/22/2016 | Close Date: 11/28/2016 | Hours | Description | Quantity | |
| - | Test Starting&Charging System: Battery Failed Load | 0.75 | BATTERY | | 1.00 |
| | Test,Replace Bad Battery. | | SHOP SUPPLIES | | 1.00 |
| - | Shop Supplies | | | | |
| Parts Charge: | | 114.86 | Labor Charge: | | 45.00 |

Workorder: 1702243

Problem: Left rear turn signal light inop.

| Meter Reading: 78296 | | Labor | | Parts | |
|-----------------------------|--|--------------|----------------------|-----------------|-------|
| In Date: 03/06/2017 | Close Date: 03/13/2017 | Hours | Description | Quantity | |
| - | Test And Replace Left Rear Signal Lamp Bulb. | 0.25 | BULB | | 1.00 |
| Parts Charge: | | 0.78 | Labor Charge: | | 15.00 |

Workorder: 1703371

Problem: P.M.SERVICE, A/C INOP.

| Meter Reading: 79558 | | Labor | | Parts | |
|-----------------------------|--|--------------|----------------------------|-----------------|--------|
| In Date: 04/04/2017 | Close Date: 04/17/2017 | Hours | Description | Quantity | |
| - | Pm Service. | 11.00 | SYN ATF BULK SOUTH | | 1.00 |
| - | Replace Third Brake Lamp Bulb. | | 18" wiper blades | | 2.00 |
| - | Replace Washer Pump. | | WASHER FLUID CONCENTR | | 1.00 |
| - | Tighten Transmission Pan Bolts.Clean Residue And Top | | SYN-ATF TRANS FLUID S | | 1.00 |
| | Off Fluid. | | TUBE ASY | | 1.00 |
| - | Mount And Balance Two Tires.Repair And Balance One. | | WASHER PUMP | | 1.00 |
| - | Ac Performance And Leak Test.Replace High Side Ac | | 183482418 P225-70R15 | | 2.00 |
| | Line.Vacume And Recharge System.Had To Remove And | | TIRE DISPOSAL FEE | | 2.00 |
| | Repair Ac Condenser Flange Bolts. | | FREON SR SHOP | | 2.00 |
| - | Shop Supplies | | wheel cover | | 2.00 |
| | | | SHOP SUPPLIES | | 1.00 |
| | | | BULB | | 2.00 |
| | | | NAPA QUART 5W20 | | 5.00 |
| | | | TIRE /P225/70/15 / HANKOOK | | 2.00 |
| | | | NAPAGOLD OIL FILTER | | 1.00 |
| Parts Charge: | | 621.25 | Labor Charge: | | 660.00 |

12/28/2017
3:43:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178871 2009 FORD RANGER Pickup, Compact, W/Toolbox

Workorder: 1707265

Problem: Right rear tire damage Left rear tire warp..

| Meter Reading: 82472 | | Labor | | Parts | |
|-----------------------------|-------------------------------|----------------------------|----------------------|--------------|-----------------|
| In Date: 07/24/2017 | Close Date: 07/27/2017 | Hours | Description | | Quantity |
| - | Replace Both Rear Tires. | 1.50 | TIRE DISPOSAL FEE | | 2.00 |
| - | Shop Supplies | | SHOP SUPPLIES | | 1.00 |
| | | | 183482418 P225-70R15 | | 2.00 |
| Parts Charge: 309.49 | | Labor Charge: 90.00 | | | |

Workorder: 1712194

Problem: Transition Prep Charge

| Meter Reading: 83047 | | Labor | | Parts | |
|-----------------------------|-------------------------------|-----------------------------|--------------------|--------------|-----------------|
| In Date: 12/12/2017 | Close Date: 12/12/2017 | Hours | Description | | Quantity |
| - | Transition Prep Charge | 2.00 | | | |
| Parts Charge: 0.00 | | Labor Charge: 120.00 | | | |

| | | | | | |
|----------------------|-----------------|----------------------|------------------|----------------------|-------------|
| Total Parts Charges: | 7,808.47 | Total Labor Charges: | 11,055.00 | Total Comm. Charges: | 0.00 |
|----------------------|-----------------|----------------------|------------------|----------------------|-------------|