

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179587 2009 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 944288

**Problem:** install canceiver

Meter Reading: 900	Labor	Parts	Quantity
In Date: 10/07/2009	Hours	Description	
- Install Canceiver Program Reflash Used Can Test Drive 1	2.00	J2284LD CANCEIVER	1.00
Atenna		ANT-200 ANTENNA (EJ WARD)	1.00
- Shop Supplies		CBL-J1962-D CABLE (EJ WARD)	1.00
		CBL-CVR-XTS CABLE CONNECTOR (EJ WARD)	1.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	402.42	<b>Labor Charge:</b>	120.00

**Workorder:** 944405

**Problem:** Pre Delivery Inspection

Meter Reading: 0	Labor	Parts	Quantity
In Date: 10/09/2009	Hours	Description	
- Pre Delivery Inspection	2.00		
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	120.00

**Workorder:** 944476

**Problem:** Install customers computer stand

Meter Reading: 918	Labor	Parts	Quantity
In Date: 10/13/2009	Hours	Description	
- Fabricate & Install Customers Computer Stand & Wire Harness.	4.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	240.00

**Workorder:** 944822

**Problem:** INSTALL FUEL TANK AUXILIARY. ALSO, INSTALL 2, THREE INCH SPOT MIRRORS.

Meter Reading: 948	Labor	Parts	Quantity
In Date: 10/20/2009	Hours	Description	
- Install Spot Mirrors	13.25	SHOP SUPPLIES	1.00
- Fabricate&Install Auxilary Fuel Tank;Tool Box.Wire The Fuel Pump Circuit&Protector;Remove Lower Dash To Install Wiring&Switch.		7039D SPOT MIRROR VELVAC 723060	2.00
		8-149 IN-LINE FUSEHOLDER 30 AMP	1.00
		DS-167 TOGGLE SWITCH (STANDARD)	1.00
- Shop Supplies			
<b>Parts Charge:</b>	32.94	<b>Labor Charge:</b>	795.00

12/28/2017  
4:15:57PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179587 2009 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1002055                      **Problem:** cut key & program

<b>Meter Reading:</b> 4162	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 02/26/2010	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Cut Key And Program Electrical Ok	<b>1.00</b>	SHOP SUPPLIES	1.00
- Shop Supplies		164-R0475 IGN KEY 2010-EARLIER (DON'T REORDER)	1.00
<b>Parts Charge:</b>	23.45	<b>Labor Charge:</b>	60.00

**Workorder:** 1002581                      **Problem:** damage to rgt side of bed, cab, door, step & rgt rear hub cab

<b>Meter Reading:</b> 4370	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 02/26/2010	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Damage To Rgt Side Of Bed, Cab, Door, Step & Rgt Rear Hub Cab			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00
		<b>Commercial Charge:</b>	944.58

**Workorder:** 1003751                      **Problem:** P. M., & needs floor mats

<b>Meter Reading:</b> 5104	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 04/12/2010	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- P. M.	<b>4.50</b>	G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
- C/C: Needs Floor Mats. Order Floor Mats, Install In Vehicle.		FLOOR MATS	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Service Auxilary Fuel Tank. Test Nozzle, Tighten/Check All Bolts Fastening Tank To Bed.		SHOP SUPPLIES	1.00
		5W20 ENGINE OIL	8.00
- Shop Supplies			
<b>Parts Charge:</b>	157.96	<b>Labor Charge:</b>	270.00

**Workorder:** 1008007                      **Problem:** damage to rgt door

<b>Meter Reading:</b> 7677	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 07/16/2010	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Damage To Rgt Door			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00
		<b>Commercial Charge:</b>	357.60

12/28/2017  
4:15:57PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179587 2009 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1011782

**Problem:** P. M. SERVICE, & needs a new tire

Meter Reading: 10339 In Date: 10/21/2010	Close Date: 10/28/2010	Labor Hours	Description	Parts	Quantity
- P. M. Service.		7.25	TIRE DISPOSAL FEE		2.00
- Service Aux Fuel Tank, Test Nozzle, Check All Bolts.			SHOP SUPPLIES		1.00
- C/C: New Tire. Verify. One Tire Damaged, Two Others Need Replacing. Dismount Tires, Balance, Add 75 Psi Of Nitrogen. Rotate To Front.			5W20 ENGINE OIL		8.00
			179636492 LT245/75R17 WRANGLER SR-A E		2.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
- Found Nail In Tire. Dismount, Patch, Mount, Balance, Add 80 Psi Of N2.			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Found Front Manual Locking Hubs Sticking. Remove Hubs. Pack With Grease. Lube Knobs, Reassemble. Test Four Wheel Drive.					
- Shop Supplies					
<b>Parts Charge:</b>		429.97	<b>Labor Charge:</b>		435.00

**Workorder:** 1103805

**Problem:** P. M., replace right side license plate light, Install new fuel filter for reserve diesel tank

Meter Reading: 14782 In Date: 04/07/2011	Close Date: 04/20/2011	Labor Hours	Description	Parts	Quantity
- P. M. Service.		8.75	1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
- Fabricate & Install Fuel Filter Housing For Aux Fuel Tank.			SHOP SUPPLIES		1.00
- Service Aux Fuel Tank.			R/SIDE TAG LIGHT ASSY.		1.00
- Replace Both Rear Tires & Rotate To The Front.			5W20 ENGINE OIL		8.00
- Replace Rr Tag Light Lens. Replace 3Rd Brake Light Bulb.			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
- Install "No Smoking & No Idling" Decal.			31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Shop Supplies			CA10262 AIR FILTER MTC FA1883 WIX 49883		1.00
			179636492 LT245/75R17 WRANGLER SR-A E		2.00
			TIRE DISPOSAL FEE		2.00
			1X2 NIPPLE (VARIOUS)		2.00
			50003 FILTER HEAD SINGLE 3/4" (CIM-TEK)		1.00
			3/4 90D ELBOW GALV. (VARIOUS)		2.00
			3/4"X3/4"NIPPLE (VARIOUS)		2.00
<b>Parts Charge:</b>		320.91	<b>Labor Charge:</b>		525.00

12/28/2017  
4:15:57PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179587 2009 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1105289

**Problem:** 1 extra key/ reflash canceiver

<b>Meter Reading:</b> 15967	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 05/18/2011	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Cut And Program 1 Extra Key	<b>2.00</b>	164-R0475 IGN KEY 2010-EARLIER (DON'T REORDER)	1.00
- Reflash Canceiver And Program		SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 23.45		<b>Labor Charge:</b> 120.00	

**Workorder:** 1109170

**Problem:** Nail in left front tire

<b>Meter Reading:</b> 19900	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 08/30/2011	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- C/C: Nail In Front Left Tire. Dismount, Patch, Mount, Balance, Add N2.	<b>1.00</b>	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 60.00	

**Workorder:** 1109493

**Problem:** P. M. SERVICE

<b>Meter Reading:</b> 20205	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 09/02/2011	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- P. M. Service.	<b>3.75</b>	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Service Aux Fuel Tank.		5W20 ENGINE OIL	8.00
- Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b> 60.03		<b>Labor Charge:</b> 225.00	

12/28/2017  
4:15:57PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179587 2009 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1201848

**Problem:** P. M. SERVICE

Meter Reading: 25891	Labor	Parts	
In Date: 02/24/2012	Hours	Description	Quantity
- P. M. Service.	6.75	G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
- Service Auxiliary Fuel Tank. Replace Filter. Test Pump.		TIRE DISPOSAL FEE	2.00
- Verify, Needs Two Tires. Dismount, Mount, Balance, & Add N2.		5W20 ENGINE OIL	8.00
- Cargo Light Out. R&R Bulb.		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Nitro Fill All Tires.		1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00
- Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		SHOP SUPPLIES	1.00
		179636492 LT245/75R17 WRANGLER SR-A E	2.00
<b>Parts Charge:</b>	457.98	<b>Labor Charge:</b>	405.00

**Workorder:** 1206863

**Problem:** pm, brake light problem

Meter Reading: 31397	Labor	Parts	
In Date: 07/24/2012	Hours	Description	Quantity
- Pm	6.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Ck Brake Light Out Replace Both Brake Light Bulbs Lube Sockets And Test		5W20 ENGINE OIL	8.00
- Service Auxiliary Fuel Tank Replace Filter And Test Pump		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Verify Needs Two Rear Tires Dismount Mount Balance Add N2 Rotate To Front		3157 TAIL LIGHT BULBS	2.00
- Shop Supplies		1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00
		179636492 LT245/75R17 WRANGLER SR-A E	2.00
		TIRE DISPOSAL FEE	2.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	472.24	<b>Labor Charge:</b>	405.00

**Workorder:** 1208947

**Problem:** battery problem

Meter Reading: 33897	Labor	Parts	
In Date: 09/19/2012	Hours	Description	Quantity
- Transport And Pick Up Vehicle At Dealer Defective Battery	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	120.00

12/28/2017  
4:15:57PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179587 2009 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1211003

**Problem:** ds flat tire, pm

Meter Reading: 36075		Labor		Parts	
In Date: 11/13/2012	Close Date: 11/16/2012	Hours	Description		Quantity
- Pm		4.75	CA10262 AIR FILTER MT		1.00
- Svc Aux Fuel Tank			NAPA QUART 5W20		8.00
- Repair Left Front Tire			FORD FUEL FILTER		1.00
- Shop Supplies			PH2 OIL FILTER LBF PH		1.00
			31-22 WIPER BLADES 22		2.00
			P1653A HYDR FILTER LB		1.00
			SHOP SUPPLIES		1.00
<b>Parts Charge:</b>		76.75	<b>Labor Charge:</b>	285.00	

**Workorder:** 1302501

**Problem:** NEEDS HITCH PION/CLIP

Meter Reading: 41167		Labor		Parts	
In Date: 03/13/2013	Close Date: 03/22/2013	Hours	Description		Quantity
- Replace Hitch Pin Clip		0.25	2560 HITCH PIN-CLIP		1.00
<b>Parts Charge:</b>		11.43	<b>Labor Charge:</b>	15.00	

**Workorder:** 1305504

**Problem:** P. M. Service

Meter Reading: 43801		Labor		Parts	
In Date: 06/04/2013	Close Date: 06/07/2013	Hours	Description		Quantity
- P. M. Service.		13.75	NAPA TRANS FILTER		1.00
- R&R Cargo Bulb. Repaired Connection At Tail Light Socket.			SHOP SUPPLIES		1.00
			PADS		1.00
- Removed Bezel To Access Bulb. Trace Wire Repaired Open.			BRAKE CLEANER		1.00
			WIPER BLADE		2.00
- R/Rear Tire Repair.			179636492 LT245-75R17		2.00
- R&R Two Tires & Balance.			1401 BRAKE FLUID BRA		2.00
- Front Brakes.			NAPAGOLD AIR FILTER		1.00
- R&R Aux Fuel Tank Filter, & Serviced.			TIRE DISPOSAL FEE		2.00
- Unsiezed & Lubed Vise.			NAPAGOLD OIL FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
- Shop Supplies			USED FIREX REFURBED F		1.00
			NAPA QUART 5W20		8.00
<b>Parts Charge:</b>		659.54	<b>Labor Charge:</b>	825.00	

12/28/2017  
4:15:57PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179587 2009 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1305919

**Problem:** Horn does not work. Flat tire.

<b>Meter Reading:</b> 44398		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 06/14/2013	<b>Close Date:</b> 06/27/2013	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Ck Horn Insp Verify Bad Horn Replace Horn Assy	<b>3.00</b>	SHOP SUPPLIES		1.00
-	Ck Flat Tire Verify Unable To Repair Side Wall Damange		179636492 LT245-75R17		1.00
	Replace Tire Mount Balance Add N2		HORN ASSEMBLY		1.00
-	Install Steering Wheel Cover		TIRE DISPOSAL FEE		1.00
-	Shop Supplies		STG WHEEL COV - FORD		1.00
<b>Parts Charge:</b>		318.13	<b>Labor Charge:</b>	180.00	

**Workorder:** 1307517

**Problem:** repair tire bad vlave stem

<b>Meter Reading:</b> 46395		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 07/29/2013	<b>Close Date:</b> 07/31/2013	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Replace Right Rear Tire And Mount Space Tire Back	<b>1.25</b>	SHOP SUPPLIES		1.00
	Under Vehicle		TIRE DISPOSAL FEE		1.00
-	Shop Supplies		179636492 LT245-75R17		1.00
<b>Parts Charge:</b>		247.03	<b>Labor Charge:</b>	75.00	

**Workorder:** 1308051

**Problem:** no engine power

<b>Meter Reading:</b> 47032		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/12/2013	<b>Close Date:</b> 08/27/2013	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Ck No Power Test Drive And Scan Foiund Code Po159	<b>7.75</b>	SPARK PLUG		8.00
	Po805 Po430 Perform Pinpoint Test Perform Ppt And		COIL		8.00
	Found Bad Spark Plugs Coils And Catalytdic Converter		SHOP SUPPLIES		1.00
	Replace Coils And Plug				
-	Send Vehicle To Dealer To Replace Catalytic Converter				
	Under Warranty				
-	Clearn Codes And Test Drive Vehicle 50 Miles After				
	Repair				
-	Shop Supplies				
<b>Parts Charge:</b>		753.56	<b>Labor Charge:</b>	465.00	

12/28/2017  
4:15:57PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179587 2009 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1308776

**Problem:** ac problem

<b>Meter Reading:</b> 47582		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/29/2013	<b>Close Date:</b> 09/18/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Ck Ac Problem Ck Sys Pressure And Found Low Freon	<b>3.50</b>	SHOP SUPPLIES		1.00
	Ck For Leak And Found Leaking Hight And Low Side		VALVE CORE		2.00
	Schvader Valve Evaporator Replace Schrader Valve		AC VALVE CORE HIGH		1.00
	Recharge And Leak Test And Test Drive		VALVE CORE		1.00
-	Shop Supplies		E8 A-C OIL R134A A-C		1.00
			A/C SERVICE PORT		1.00
			SOUTH REGION R134A		2.00
<b>Parts Charge:</b> 49.22		<b>Labor Charge:</b> 210.00			

**Workorder:** 1312203

**Problem:** pm, possible water in the fuel tank needs cleaning

<b>Meter Reading:</b> 51005		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 12/06/2013	<b>Close Date:</b> 12/26/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Pm	<b>6.25</b>	NAPAGOLD OIL FILTER		1.00
-	Ck Water In Tank Drain Tank Replace Filter		NAPA TRANS FILTER		1.00
-	Verify Turn Signal Out Replace Lr Turn Signal Bulb		NAPA QUART 5W20		8.00
-	Shop Supplies		BULB		1.00
			SHOP SUPPLIES		1.00
<b>Parts Charge:</b> 41.90		<b>Labor Charge:</b> 375.00			

**Workorder:** 1403202

**Problem:** battery

<b>Meter Reading:</b> 55065		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 04/01/2014	<b>Close Date:</b> 04/11/2014	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Ck Charging Sys And Replace Bad Battery	<b>0.75</b>	SHOP SUPPLIES		1.00
-	Shop Supplies		BATTERY		1.00
<b>Parts Charge:</b> 121.61		<b>Labor Charge:</b> 45.00			



12/28/2017  
4:15:57PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179587 2009 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1404374

**Problem:** pm, nail in tire

<b>Meter Reading:</b> 56493		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 05/05/2014	<b>Close Date:</b> 05/19/2014	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm		<b>5.25</b>	NAPA TRANS FILTER		1.00
- Avc Aux Fuel Tank			NAPA QUART 5W20		8.00
- Repair Right Front Tire			NAPAGOLD OIL FILTER		1.00
- Recharge And Ck Battery Battery Is On At This Time			WIPER BLADE		2.00
- Shop Supplies			SHOP SUPPLIES		1.00
			NAPAGOLD FUEL FILTER		1.00
			USED FIRE X REFURBISHED		1.00
<b>Parts Charge:</b>		70.65	<b>Labor Charge:</b>	315.00	

**Workorder:** 1410558

**Problem:** pm, water in fuel tank, battery problems, fire ext base problem,

<b>Meter Reading:</b> 62594		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 10/22/2014	<b>Close Date:</b> 10/31/2014	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm		<b>9.00</b>	NAPAGOLD OIL FILTER		1.00
- Verify Needs 4 Tires Replace 4 Tires Mount Balance Add N2			179636492 LT245-75R17		4.00
			USED FIRE X REFURBISHED		1.00
- Verify Dead Battery Test Battery Bad Replace Battery Under Warranty Battery Provided By Napa N/C			NAPA TRANS FILTER		1.00
			LT245 75R16 MICH LTX MS2		4.00
- Water In Fuel Tank Drain Tank Replace Filter Remove Gauge J B Weld Cracked Tank Install New Fire Ext Bracker			JB WELD		1.00
			NAPA QUART 5W20		8.00
			SHOP SUPPLIES		1.00
- Shop Supplies			TIRE DISPOSAL FEE		4.00
<b>Parts Charge:</b>		1,117.56	<b>Labor Charge:</b>	540.00	

**Workorder:** 1501838

**Problem:** low tire pressure

<b>Meter Reading:</b> 66479		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/20/2015	<b>Close Date:</b> 02/24/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Correct All N2 Levels Inspect Tires Clear Tpms		<b>0.50</b>			
<b>Parts Charge:</b>		0.00	<b>Labor Charge:</b>	30.00	

12/28/2017  
4:15:57PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179587 2009 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1501942

**Problem:** needs trailer hitch pin

<b>Meter Reading:</b> 66479	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 02/24/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Replace Hitch Pin	<b>0.25</b>	PIN W/CLIP 5/8 FOR HITCH	1.00
<b>Parts Charge:</b> 5.05	<b>Labor Charge:</b> 15.00		

**Workorder:** 1502671

**Problem:** PM, NEEDS STEERING WHEEL COVER

<b>Meter Reading:</b> 67108	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 03/13/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Pm	<b>9.25</b>	SHOP SUPPLIES	1.00
- Verify Needs Rear Pads Turn Rotors Replace Pads Svc		NAPA QUART 5W20	8.00
Calipers		NAPAGOLD FUEL FILTER	1.00
- Replace F Front Headlight		REAR PADS	1.00
- Replace L Rear Tail Light Bulb		BULB	1.00
- Ck Steering Wheel Cover Install Steering Wheel Cover		STG WHEEL COV - FORD	1.00
- Shop Supplies		NAPAGOLD OIL FILTER	1.00
		WIPER BLADE	2.00
		HALOGEN LAMP	1.00
<b>Parts Charge:</b> 158.45	<b>Labor Charge:</b> 555.00		

12/28/2017  
4:15:57PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179587 2009 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1508406

**Problem:** pm, broken mirror, ac problem with 1 & 2

<b>Meter Reading: 72250</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 08/21/2015</b>	<b>Close Date: 08/28/2015</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm		<b>9.00</b>	SHOP SUPPLIES		1.00
- Replace Broken Left Front Rear View Mirror And Spot Mirror			TIRE DISPOSAL FEE		1.00
			NAPAGOLD AIR FILTER		1.00
- Ck Ac Problem With 1 & 2 Perform Pinpoint Test And Found Bad Blower Resistor Replace Ac Blower Resistor			WIPER BLADE		2.00
			OEM REPL MIRROR		1.00
- Svc Aux Fuel Tank			NAPAGOLD OIL FILTER		1.00
- Replace Mismatched Left Front Tire			179636492 LT245-75R17		1.00
- Shop Supplies			MIRROR		1.00
			WD40 16OZ		1.00
			NAPA TRANS FILTER		1.00
			BLOWER MOTOR RESISTOR		2.00
			USED FIRE X REFURBISHED		1.00
			NAPA QUART 5W20		8.00
<b>Parts Charge: 518.31</b>		<b>Labor Charge: 540.00</b>			

**Workorder:** 1508601

**Problem:** Driver side front tire flat

<b>Meter Reading: 72053</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 07/07/2015</b>	<b>Close Date: 08/27/2015</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Tire Service 16854 Knights Bridge - Driver Side Front Tire Flat					
<b>Parts Charge: 0.00</b>		<b>Labor Charge: 0.00</b>	<b>Commercial Charge: 46.40</b>		

**Workorder:** 1508602

**Problem:** Replaced a tire

<b>Meter Reading: 72053</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 07/08/2015</b>	<b>Close Date: 08/27/2015</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Tire Service Knights Bridge In Lake Worth - Replaced A Tire					
<b>Parts Charge: 0.00</b>		<b>Labor Charge: 0.00</b>	<b>Commercial Charge: 165.46</b>		

12/28/2017  
4:15:57PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179587 2009 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Workorder: 1601932

Problem: PM

Meter Reading: 78619	Labor	Parts	
In Date: 02/24/2016	Hours	Description	Quantity
- Pm	6.50	SHOP SUPPLIES	1.00
- Replace 3 Tires Mount Add Ne Reset Tpms		TIRE DISPOSAL FEE	3.00
- Svc Aux Fuel Tank		NAPAGOLD FUEL FILTER	1.00
- Replace 3Rd Brake Light Bulb		WASHER FLUID CONCENTR	1.00
- Replace Steering Sheel Cover		179636492 LT245-75R17	3.00
- Shop Supplies		NAPA TRANS FILTER	1.00
		BULB	2.00
		STG WHEEL COV - FORD	1.00
		NAPA QUART 5W20	8.00
		NAPAGOLD OIL FILTER	1.00
<b>Parts Charge:</b>	828.67	<b>Labor Charge:</b>	390.00

Workorder: 1604286

Problem: Install fuel tank in bed of truck.

Meter Reading: 81044	Labor	Parts	
In Date: 04/25/2016	Hours	Description	Quantity
- C/C Replace Auxiliary Fuel Tank.Install Fuel Tank	9.75	ATC-25 FUSE	5.00
Provided By Wud.R&R Tool Box For Installation Switch		NAPA TRANS FILTER	1.00
Over Pump Assm.R&R Filter.		TOGGLE SWITCH	1.00
- Repair Wire Harness Replace 25 Amps Fuse.R& R Toggle Switch.		VINYL ELECTRICAL TAPE	1.00
- Clean Bed For Installation.		SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	18.13	<b>Labor Charge:</b>	585.00

12/28/2017  
4:15:57PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179587 2009 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1606748

**Problem:** Pm service

Meter Reading: 83715	Labor	Parts	Quantity
In Date: 07/01/2016	Hours	Description	Quantity
- Pm Service.	<b>11.50</b>	SHOP SUPPLIES	1.00
- Service Auxiliary Fuel Tank.		NAPA QUART 5W20	8.00
- Replace All Six Cab Mounts.		22" WIPER BLADE	2.00
- Repair Left Headlamp.		NAPA TRANS FILTER	1.00
- Rotate And Balance All Four Tires.		BODY MOUNT KIT	2.00
- Shop Supplies		BODY MOUNT KIT	4.00
		HALOGEN LAMP	1.00
		NAPAGOLD OIL FILTER	1.00
		WASHER FLUID CONCENTR	1.00
<b>Parts Charge:</b>	592.17	<b>Labor Charge:</b>	690.00

**Workorder:** 1612905

**Problem:** PM Service.Flat tire.

Meter Reading: 89344	Labor	Parts	Quantity
In Date: 12/16/2016	Hours	Description	Quantity
- Pm Service	<b>5.75</b>	NAPAGOLD OIL FILTER	1.00
- Replace Two Tires.Rotate And Balance.Correct All N2 Levels.		179636492 LT245-75R17	2.00
- Service Auxiliary Fuel Tank.		NAPA QUART 5W20	8.00
- Shop Supplies		NAPA TRANS FILTER	1.00
		SHOP SUPPLIES	1.00
		TIRE DISPOSAL FEE	2.00
<b>Parts Charge:</b>	547.62	<b>Labor Charge:</b>	345.00

12/28/2017  
4:15:57PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179587 2009 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1704488

**Problem:** PM Service

Meter Reading: 94135 In Date: 05/03/2017	Close Date: 05/15/2017	Labor Hours	Description	Parts	Quantity
- Pm Service.		7.25	NAPAGOLD OIL FILTER		1.00
- Replace Third Brake Lamp Assm.Right And Left			NAPA QUART 5W20		7.00
Brake/Turnsignal Bulbs And Dome Lamp Bulb.			NAPA TRANS FILTER		1.00
- Mount And Balance Two New Tires.Rotate And Balance			BULB		2.00
Two Tires.			LAMP ASSY		1.00
- Replace Brake Pedal Pad.			USED FIRE X REFURBISHED		1.00
- Service Auxiliary Fuel Tank.			BULB		3.00
- Shop Supplies			179636492 LT245-75R17		2.00
			PEDAL PAD		1.00
			NAPA HYDRAULIC FILTER		1.00
			TIRE DISPOSAL FEE		2.00
			SHOP SUPPLIES		1.00
			WASHER FLUID CONCENTR		1.00
			BULB		1.00
			NAPAGOLD AIR FILTER		1.00
			22" WIPER BLADE		2.00
	<b>Parts Charge:</b>	702.97	<b>Labor Charge:</b>	435.00	

**Workorder:** 1709904

**Problem:** Hitch safety pin.

Meter Reading: 98496 In Date: 10/11/2017	Close Date: 10/18/2017	Labor Hours	Description	Parts	Quantity
- Replace Damage Pintle Pin.		0.25	PINTLE PIN W/CLIP		1.00
	<b>Parts Charge:</b>	2.61	<b>Labor Charge:</b>	15.00	

**Workorder:** 1711858

**Problem:** Transition Prep Charge

Meter Reading: 99573 In Date: 12/04/2017	Close Date: 12/04/2017	Labor Hours	Description	Parts	Quantity
- Transition Prep Charge		2.00			
	<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00	

Total Parts Charges:	<b>9,228.71</b>	Total Labor Charges:	<b>10,830.00</b>	Total Comm. Charges:	<b>1,514.04</b>
----------------------	-----------------	----------------------	------------------	----------------------	-----------------