

12/28/2017
4:36:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178878 2009 FORD F350 Pickup, 1 Ton, 4X4, Srw

Workorder: 938735 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 06/08/2009	Hours	Description
Close Date: 06/08/2009	Quantity	
- Pre-Delivery Inspection	2.00	
Parts Charge: 0.00	Labor Charge: 120.00	

Workorder: 938902 **Problem:** INSTALL FIRE PUMP

Meter Reading: 305	Labor	Parts
In Date: 06/11/2009	Hours	Description
Close Date: 06/26/2009	Quantity	
- Fab,Layout & Install Pump Spring Latches,R&R Bed Liner. Modify To Clear Latches, Weld,Grind,Prime & Paint.	12.50	T-235 GRAY PRIMER 1.00 T-4 WHITE PAINT 1.00 66BR CLEAR SILICONE 2.00
- Shop Supplies		LATCH ASSY 4.00 SPRING LATCH 4.00 SHOP SUPPLIES 1.00
Parts Charge: 148.89	Labor Charge: 750.00	

Workorder: 940613 **Problem:** Trailer plug malfunction

Meter Reading: 807	Labor	Parts
In Date: 07/10/2009	Hours	Description
Close Date: 07/13/2009	Quantity	
- Diagnose & Repair Trailer Plug Wiring & Install New Trailer Plug.	1.00	SHOP SUPPLIES 1.00 5404 FEMALE CONNECTOR 1.00
- Shop Supplies		
Parts Charge: 12.10	Labor Charge: 60.00	

Workorder: 944766 **Problem:** R/R tire flat

Meter Reading: 6373	Labor	Parts
In Date: 10/20/2009	Hours	Description
Close Date: 10/21/2009	Quantity	
- Nail In Side Wall. Mount Balane & Nitro Fill One New Tire On R/R.	1.00	SHOP SUPPLIES 1.00 TR416 VALVE STEM 1.00
- Shop Supplies		TIRE DISPOSAL FEE 1.00 LT245/75R17 TIRE 1.00
Parts Charge: 189.88	Labor Charge: 60.00	

12/28/2017
4:36:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178878 2009 FORD F350 Pickup, 1 Ton, 4X4, Srw

Workorder: 944893

Problem: P.M service, check axle seal leak

Meter Reading: 6458	Labor	Parts	
In Date: 10/21/2009	Hours	Description	Quantity
- P.M Service.	8.00	SHOP SUPPLIES	1.00
- Rotate & Balance All Four Tires.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Inspect & Service Winch.		5W20 ENGINE OIL	7.00
- To/From Dealer For R/R Axle Seal.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Shop Supplies			
Parts Charge:	30.95	Labor Charge:	420.00

Workorder: 1001669

Problem: Check engine light on, engine noise & no power.

Meter Reading: 9747	Labor	Parts	
In Date: 02/17/2010	Hours	Description	Quantity
- Diagnose Internal Engine Faliure, Replace Air Filter & Fuel Filter.	3.50	SHOP SUPPLIES	1.00
		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
- To/From Dealer For Engine Short Block Replacement.		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
- Shop Supplies			
Parts Charge:	23.67	Labor Charge:	150.00

Workorder: 1003390

Problem: canceiver problem

Meter Reading: 9987	Labor	Parts	
In Date: 04/01/2010	Hours	Description	Quantity
- Repair & Flash & Reprogram Canceiver	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1003698

Problem: Right front tire flat,side wall damage

Meter Reading: 10479	Labor	Parts	
In Date: 04/09/2010	Hours	Description	Quantity
- Mount, Balance & Nitro Fill One New R/F Tire.	1.50	SHOP SUPPLIES	1.00
- Repair & Resecure Front Lower Bumper Valance.		TIRRE LT 245/75/17	1.00
- Shop Supplies			
Parts Charge:	150.50	Labor Charge:	90.00

12/28/2017
4:36:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178878 2009 FORD F350 Pickup, 1 Ton, 4X4, Srw

Workorder: 1004983 **Problem:** damage to rgt frt fender & running board

Meter Reading: 11568		Labor		Parts	
In Date: 04/30/2010	Close Date: 05/13/2010	Hours	Description		Quantity

- Damage To Rgt Frt Fender & Running Board					
	Parts Charge: 0.00	Labor Charge:	0.00	Commercial Charge:	846.60

Workorder: 1005091 **Problem:** P.M service.

Meter Reading: 11929		Labor		Parts	
In Date: 05/17/2010	Close Date: 05/20/2010	Hours	Description		Quantity

- P.M Service,		5.00	CA10262 AIR FILTER MTC FA1883 WIX 49883		1.00
- Inspect & Service Winch.			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Shop Supplies			31-20 WIPER BLADES 20" BLADE		2.00
			SHOP SUPPLIES		1.00
			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
			5W20 ENGINE OIL		7.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
	Parts Charge: 63.28	Labor Charge:	300.00		

Workorder: 1011751 **Problem:** Pm service also see notes on check engine light and bed liner cap.

Meter Reading: 19047		Labor		Parts	
In Date: 10/20/2010	Close Date: 10/28/2010	Hours	Description		Quantity

- Perform Pm Service.		10.00	179636492 LT245/75R17 WRANGLER SR-A E		4.00
- Replace Failed Tailgate Trim With New.			TR416 VALVE STEM		4.00
- Install Four New Tires,Nitrogen Fill And Balance All.			31-20 WIPER BLADES 20" BLADE		2.00
- Inspect And Service Power Winch.			1372 OIL FILTER FRM PH2 WIX 51372		1.00
- Perform Wheel Alignment Complete.			SHOP SUPPLIES		1.00
- Shop Supplies			WHEEL COVER		1.00
			7090BLK FRT FLOOR MATS (RUBBER QUEEN)		1.00
			TAILGATE TOP COVER		1.00
			TIRE DISPOSAL FEE		4.00
			5W20 ENGINE OIL		7.00
	Parts Charge: 918.74	Labor Charge:	600.00		

12/28/2017
4:36:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178878 2009 FORD F350 Pickup, 1 Ton, 4X4, Srw

Workorder: 1012014

Problem: reflash canceiver spot 223

Meter Reading: 19047	Labor	Parts	Quantity
In Date: 10/26/2010	Hours	Description	Quantity
- Reflash Canceiver And Reprogram	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1102055

Problem: Replace tires with off road tires.

Meter Reading: 23751	Labor	Parts	Quantity
In Date: 02/22/2011	Hours	Description	Quantity
- Install Four New Off Road Tires As Per Request.Nitrogen	4.50	TIRE DISPOSAL FEE	4.00
Fill And Balance All		TR416 VALVE STEM	4.00
- Perform Wheel Alignment Complete.		SHOP SUPPLIES	1.00
- Shop Supplies		WRANGLER MT/R TIRE	4.00
Parts Charge:	1,135.18	Labor Charge:	270.00

Workorder: 1104488

Problem: P.M. Service

Meter Reading: 25645	Labor	Parts	Quantity
In Date: 04/27/2011	Hours	Description	Quantity
- P.M. Service.	4.75	31-20 WIPER BLADES 20" BLADE	2.00
- Rotate And Balance All Tires.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Inspect And Service Winch.		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
- Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
		SHOP SUPPLIES	1.00
		5W20 ENGINE OIL	7.00
Parts Charge:	38.15	Labor Charge:	285.00

12/28/2017
4:36:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178878 2009 FORD F350 Pickup, 1 Ton, 4X4, Srw

Workorder: 1109812

Problem: Pm service.Check winch cable and lights see notes.

Meter Reading: 30931	Labor	Parts	
In Date: 09/14/2011	Hours	Description	Quantity
- P.M. Service.	15.75	LT265/70R17 TIRES	2.00
- Test Battery And Charging System.Charge And Retest		SHOP SUPPLIES	1.00
Battery,Fail Load Test.Replace Defective Battery.		5W20 ENGINE OIL	7.00
- Replace Right Tail Light Bulb.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Replace Extinguisher Bracket.Replace Missing Front		3157 TAIL LIGHT BULBS	1.00
Bumper Valance.		SYN/ATF TRANS FLUID SYNTHETIC	15.00
- Flush And Refill Transmission.		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
- Replace Two Tires,Rotate And Balance All Four.		CUSTOM5LB BRACKET FIREX STOCK #340060300	1.00
- Inspect And Service Winch.Dis-Assemble Winch And		TIRE DISPOSAL FEE	2.00
Clean Water Corrosion.Lube And Reseal Case.		AIR DAM MOULDING	1.00
- Complete Wheel Alignment.		GROUP 65 BATTERY (MTC BXT-65-850)	1.00
- Shop Supplies		31-20 WIPER BLADES 20" BLADE	2.00
Parts Charge: 947.11		Labor Charge: 945.00	

Workorder: 1203300

Problem: Pm service and request for installing new heavy power pigtail for fire pump.

Meter Reading: 36644	Labor	Parts	
In Date: 04/06/2012	Hours	Description	Quantity
- P.M. Service.	8.75	CS4RV RED CABLE #4	20.00
- Install Battery Isolator.Fabricate And Install Wiring And		BATTERY ISOLATOR	1.00
Connector For Pump Unit.		84-9632 CONNECTOR 4-GAUGE (GROTE)	1.00
- Inspect And Service Winch.		5W20 ENGINE OIL	7.00
- Rotate And Balance All Tires.		31-20 WIPER BLADES 20" BLADE	2.00
- Shop Supplies		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		SHOP SUPPLIES	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		82-2178 CIRCUIT BREAKER 100AMP	1.00
		CS4L CABLE #4	20.00
Parts Charge: 341.03		Labor Charge: 525.00	

12/28/2017
4:36:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178878 2009 FORD F350 Pickup, 1 Ton, 4X4, Srw

Workorder: 1207938

Problem: P.M. Service.Install tool box.

Meter Reading: 42387		Labor	Parts	
In Date: 08/21/2012	Close Date: 09/13/2012	Hours	Description	Quantity
- P.M Service		5.75	5W20 ENGINE OIL	7.00
- Install Tool Box In Truck Bed Per Request.			CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
- Inspect And Service Winch.			117 USED TOOL BOX WEATHER GUARD TOOL BOX	1.00
- Rotate And Balance All Tires.			1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Shop Supplies			GAS CHARGED LIFT SUPPORT	2.00
			LIFT SUPPORT KIT	1.00
			SHOP SUPPLIES	1.00
	Parts Charge: 308.90	Labor Charge:	345.00	

Workorder: 1211548

Problem: Left front tire flat.

Meter Reading: 45327		Labor	Parts	
In Date: 11/30/2012	Close Date: 11/30/2012	Hours	Description	Quantity
- Repair Flat Left Front Tire.Nitrogen Fill And Balance Same.		1.00	SHOP SUPPLIES	1.00
- Shop Supplies				
	Parts Charge: 2.00	Labor Charge:	60.00	

12/28/2017
4:36:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178878 2009 FORD F350 Pickup, 1 Ton, 4X4, Srw

Workorder: 1302439

Problem: P.M. service and check lights and pig tail too short and small.

Meter Reading: 48812 In Date: 03/12/2013	Close Date: 03/28/2013	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		10.50	CASTER-CAMBER BUSHING		2.00
- Test And Replace Failed Left Rear Turnsignal Lamp Bulb With New.			WASHER FL		1.00
- Install Four New Tires.Nitrogen Fill And Balance All Four.			31-20 WIPER BLADES 20		2.00
- Fabricate,Make Up And Install Extension Jumper Harness Between Isolator And Pump Connector.			TIRE DISPOSAL FEE		4.00
- Inspect And Service Power Winch.			BULB		1.00
- Perform Wheel Alignment Complete.Fabricate And Install New Cam Bushings On Both Upper Ball Joints To Adjust Caster And Camber.			USED FIREX REFURBED F		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			84-9633 CONNECTOR 2-G		1.00
			CS2L BLACK CABLE 2 GA		4.00
			LT265/70R17 MT/R		4.00
			5W20 ENGINE OIL		7.00
			1372 OIL FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
			CS2RV RED CABLE 2 GAU		4.00
			TR416 VALVE STEM		4.00
	Parts Charge: 1,590.14	Labor Charge: 630.00			

Workorder: 1306614

Problem: Check engine light on.

Meter Reading: 51249 In Date: 07/02/2013	Close Date: 07/17/2013	Labor Hours	Description	Parts	Quantity
- Clean Throttle Body And Perform Induction System Cleaning.Flush Injectors.		7.50	KA8A THROTTLE BODY- U		1.00
- Diagnose Check Engine Light.P0300,P0305,P0310.Rplace All Ten Spark Plugs And #5 & #10 Coils.Replace Air Filter,Clear Codes And Test Drive.			408 FUEL INJECTION CL		1.00
- Shop Supplies			SPARK PLUG		10.00
			NAPAGOLD AIR FILTER		1.00
			5068 PENTRATING OIL		1.00
			COIL		2.00
			SHOP SUPPLIES		1.00
	Parts Charge: 397.92	Labor Charge: 450.00			

12/28/2017
4:36:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178878 2009 FORD F350 Pickup, 1 Ton, 4X4, Srw

Workorder: 1308526

Problem: Pm service.Check engine light on.Idles rough and ac inop

Meter Reading: 51544	Labor	Parts	Quantity
In Date: 08/23/2013	Hours	Description	Quantity
- P.M. Service.	14.00	TUBE FILTER	1.00
- Replace Right Headlamp Bulb.		R134A LV SHOP 1	2.00
- Diagnose Check Engine Light.Replace #2,6,8&9		STG WHEEL COV - FORD	1.00
Coils.Clear Codes And Retest System.		E8 A-C OIL R134A A-C	1.00
- Check Inop A/C.Replace Defective		COMPRESSOR	1.00
Compressor,Accumulator,Orifice And High Side		STEERING WHEEL COVER	1.00
Hose.Vacuum System And Recharge To Specs.		O-RING	3.00
- Inspect And Service Winch.		ACCUMULATOR	1.00
- Shop Supplies		BELT	1.00
		COIL	4.00
		SEAL	1.00
		HALOGEN LAMP	1.00
		NAPAGOLD OIL FILTER	1.00
		31-20 WIPER BLADES 20	2.00
		BIGG DEGREASER	1.00
		SHOP SUPPLIES	1.00
		5W20 ENGINE OIL	7.00
		TUBE ASY	1.00
Parts Charge:	1,131.44	Labor Charge:	840.00

Workorder: 1400461

Problem: Install fire pump

Meter Reading: 55745	Labor	Parts	Quantity
In Date: 01/14/2014	Hours	Description	Quantity
- R&R Skid On New Pump From Old. Weld And Fabricate	27.50	1-1/2X20 ALUM PIPE SCH 80	10.00
Skid To Fit.Install Pump And Rewire.		ELECTRICAL TAPE	1.00
- R&R Step Rail		SHOP SUPPLIES	1.00
- Make Battery Cables, Install On New Pump. Reconfig		1"X24' SQUARE ALUM TUBE WITH RADIUS 1/8 WALL	15.00
Battery Isolator System. Build Quick Disconnect In Bed		STEP ASY	1.00
- Test Ran Pump		CS4L CABLE 4	12.00
- Shop Supplies			
Parts Charge:	519.27	Labor Charge:	1,650.00

12/28/2017
4:36:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178878 2009 FORD F350 Pickup, 1 Ton, 4X4, Srw

Workorder: 1401669

Problem: Pm service.Towed in.Will not move foward or backward and drive train noisy.

Meter Reading: 56478		Labor		Parts	
In Date: 02/20/2014	Close Date: 03/11/2014	Hours	Description	Quantity	
-	P.M. Service.	12.50	SHOP SUPPLIES	1.00	
-	Tranfer Case Broke In Half.Replace Transfer Case Assemble And Broken Driveshaft.		DRIVESHAFT	1.00	
-	Replace Leaking Left Rear Axle Seal.		NAPAGOLD OIL FILTER	1.00	
-	Inspect And Service Winch.		NAPAGOLD AIR FILTER	1.00	
-	Rotate And Balance All Tires.		WD40 16OZ	1.00	
-	Shop Supplies		USED FIRE X REFURBISHED	1.00	
			Wheel Seal - Rear Wheel	1.00	
			GAS CAP NON-LOCKING	1.00	
			CAP	1.00	
			CAP ASY	1.00	
			NAPAGOLD FUEL FILTER	1.00	
			breezway case asy	1.00	
			5W20 ENGINE OIL	7.00	
			BRAKE CLEANER	2.00	
			FORD TRANSFER CASE FLUID	2.00	
			WIPER BLADE	2.00	
Parts Charge:		2,505.71	Labor Charge:	750.00	

Workorder: 1402159

Problem: Vibrating Rough

Meter Reading: 56269		Labor		Parts	
In Date: 02/17/2014	Close Date: 03/05/2014	Hours	Description	Quantity	
-	Tow From: Turnpike Northbound Between Beeline And Pga To: Lv Shop				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 104.15

Workorder: 1408893

Problem: needs clamping hitch

Meter Reading: 61176		Labor		Parts	
In Date: 09/03/2014	Close Date: 09/10/2014	Hours	Description	Quantity	
-	Install Clamping Hitch	0.50	PIN HOOK	1.00	
-	Shop Supplies		PINTLE MOUNT	1.00	
			PIN W/CLIP 5/8 FOR HITCH	1.00	
			SHOP SUPPLIES	1.00	
Parts Charge:		179.78	Labor Charge:	30.00	

12/28/2017
4:36:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178878 2009 FORD F350 Pickup, 1 Ton, 4X4, Srw

Workorder: 1408905

Problem: P.M. service.

Meter Reading: 61183 In Date: 09/04/2014	Close Date: 09/23/2014	Labor Hours	Description	Parts	Quantity
- Pm Service.		20.00	WIPER BLADE		2.00
- Replace Front And Rear Brake Pads.Replace Front And Rear Brake Calipers.Resurface All Four Brake Rotors.Replace Leaking Right Rear Axle Seal And Oil Slinger.Flush And Bleed Brake System.Test Drive.			BRAKE PADS		1.00
			NAPAGOLD AIR FILTER		1.00
			BRAKE PAD		1.00
			BRAKE CLEANER		2.00
- Inspect And Service Winch.Also Replace Damage Winch Cable.			BATTERY		1.00
			HALOGEN LAMP		2.00
- Pressure Test And Inspect Cooling System.Flush And Refill Coolant.			REMAN BRAKE CALIPER		1.00
			SLINGER		1.00
			BRAKE FLUID QT		2.00
- Check Battery And Charging System.Replace Defective Battery.			REMAN BRAKE CALIPER		1.00
			Caliper w/ Hardware - Right Rear (Eclips		1.00
- Replace Both Headlamp Seal Beams Due To Corroded Reflectors			1401 BRAKE FLUID BRA		1.00
			COOLANT FORD GOLD		2.00
- Rotate And Balance All Four Tires.			WASHER (SLINGER)		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			Caliper w/ Hardware - Left Rear (Eclipse		1.00
			NAPAGOLD OIL FILTER		1.00
			WINCH CABLE FABRICATION		1.00
			5W20 ENGINE OIL		7.00
			SEAL		1.00
	Parts Charge: 960.53	Labor Charge:	1,200.00		

12/28/2017
4:36:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178878 2009 FORD F350 Pickup, 1 Ton, 4X4, Srw

Workorder: 1503895

Problem: Pm service.

Meter Reading: 67445	Close Date: 04/29/2015	Labor Hours	Description	Parts	Quantity
- P.M. Service.		8.50	MOULDING		1.00
- Inspect And Service Front Differential.			5W20 ENGINE OIL		7.00
- Replace Damaged/Bent Steering Wheel.Replace And Secure Missing Tgailgate Cap.			NAPAGOLD OIL FILTER		1.00
- Inspect And Service.Winch.			NAPAGOLD AIR FILTER		1.00
- Rotate And Balance All Four Tires.			WIPER BLADE		2.00
- Shop Supplies			NAPA GEAR 80W-90 QT		3.00
			PTEX ULTRA BLACK 30Z		1.00
			BRAKE CLEANER		1.00
			SHOP SUPPLIES		1.00
			USED FIRE X REFURBISHED		1.00
			STEERING WHEEL		1.00
			NAPAGOLD FUEL FILTER		1.00
	Parts Charge: 471.38	Labor Charge: 510.00			

Workorder: 1508456

Problem: Right front tire flat.

Meter Reading: 71535	Close Date: 08/25/2015	Labor Hours	Description	Parts	Quantity
- Replace And Balance All Four Tires.Replace One Band And Tpms Sensor For Right Rear.		5.00	SHOP SUPPLIES		1.00
- Complete Alignment.Test Drive.			LT265/70R17		4.00
- Shop Supplies			TPMS5 SENSOR TIRE PRE		1.00
			TPMS STRAP		1.00
			TIRE DISPOSAL FEE		4.00
	Parts Charge: 1,437.75	Labor Charge: 300.00			

12/28/2017
4:36:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178878 2009 FORD F350 Pickup, 1 Ton, 4X4, Srw

Workorder: 1509296

Problem: Pm service.Tool box lock inop.

Meter Reading: 72147	Labor	Parts	
In Date: 09/15/2015	Hours	Description	
Close Date: 09/30/2015		Quantity	
- Pm Service.	10.50	TOOL LOCK CYLINDER	1.00
- Cooling Fan Broken And Clutch Inop.Replace Broken Fan Blade And Fan Clutch.		SHOP SUPPLIES	1.00
		5W20 ENGINE OIL	7.00
- Tool Box Locks Broken.Replace Both Broken Locks.		NAPAGOLD OIL FILTER	1.00
- Replace Both Broken Front Body Mounts.		NAPAGOLD AIR FILTER	1.00
- Rotate And Balance All Four Tires.		WIPER BLADE	2.00
- Inspect And Service Winch.		BODY MOUNT KIT	2.00
- Shop Supplies		FAN CLUTCH	1.00
		FAN ASSY	1.00
Parts Charge:	761.15	Labor Charge:	630.00

Workorder: 1511922

Problem: Hook on winch cable broken

Meter Reading: 74040	Labor	Parts	
In Date: 11/23/2015	Hours	Description	
Close Date: 12/09/2015		Quantity	
- Replace Broken Cable On Winch And Test Winch Operation.	1.50	SHOP SUPPLIES	1.00
		CABLE MADE	1.00
- Shop Supplies			
Parts Charge:	248.01	Labor Charge:	90.00

12/28/2017
4:36:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178878 2009 FORD F350 Pickup, 1 Ton, 4X4, Srw

Workorder: 1602285

Problem: Pm service.

Meter Reading: 76892	Labor	Parts
In Date: 03/03/2016	Hours	Quantity
Close Date: 03/17/2016	Description	
- Pm Service.	14.00	5W20 ENGINE OIL 7.00
- Replace Broken Hitch Pintle Pin.		NAPAGOLD OIL FILTER 1.00
- Inspect And Service Rear Differential.Replace Both		NAPAGOLD AIR FILTER 1.00
Leaking Rear Axle Seals.		SEAL 2.00
- Replace Defective Parking Brake Shoe Set.		20" WIPER BLADE 2.00
- Rotate And Balance All Four Tires		SHOP SUPPLIES 1.00
- Inspect And Service Winch.		PEDAL PAD 1.00
- Shop Supplies		75W140 FORD AXLE LUBE 4.00
		PINTLE PIN W/CHAIN 1.00
		FRICTION MODIFIER 2.00
		USED FIRE X REFURBISHED 1.00
		REMAN BRAKE SHOES 1.00
		WASHER FLUID CONCENTR 1.00
		NAPAGOLD FUEL FILTER 1.00
Parts Charge: 318.54	Labor Charge: 840.00	

Workorder: 1604423

Problem: Right rear tire going flat.

Meter Reading: 78403	Labor	Parts
In Date: 04/27/2016	Hours	Quantity
Close Date: 04/29/2016	Description	
- Repair And Balance Right Rear Tire.	1.00	SHOP SUPPLIES 1.00
- Shop Supplies		
Parts Charge: 2.00	Labor Charge: 60.00	

12/28/2017
4:36:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178878 2009 FORD F350 Pickup, 1 Ton, 4X4, Srw

Workorder: 1608978

Problem: pm service/ remove fire pump/ repair trailer plug

Meter Reading: 82834		Labor		Parts	
In Date: 08/29/2016	Close Date: 09/20/2016	Hours	Description		Quantity
-	Pm	9.00	NON-CHLOR BRAKE CLNR		2.00
-	Replace Both Brake Light/ T./S Bulbs		MAC WITE LITHIUM GRES		1.00
-	Replace Tralier Plug		CLEVIS SLIP HOOK-BULK		1.00
-	Rotate And Balance Tires		NAPA QUART 5W20		7.00
-	Repalce Wintch Cable And Service		NAPAGOLD OIL FILTER		1.00
-	Shop Supplies		NAPAGOLD AIR FILTER		1.00
			20" WIPER BLADE		2.00
			BULB		2.00
			5441 CLEAR GEL LUBE G		1.00
			SHOP SUPPLIES		1.00
			trailer plug		1.00
			100' WINCH CABLE		1.00
Parts Charge:		313.12	Labor Charge:	540.00	

Workorder: 1610254

Problem: Tire pressure light on.

Meter Reading: 84333		Labor		Parts	
In Date: 09/30/2016	Close Date: 10/12/2016	Hours	Description		Quantity
-	Test And Replace Defective Left Front Tire Sensor.	1.00	SHOP SUPPLIES		1.00
-	Shop Supplies		TPMS5 SENSOR TIRE PRE		1.00
Parts Charge:		128.71	Labor Charge:	60.00	

Workorder: 1613204

Problem: Right rear tail light out.

Meter Reading: 86671		Labor		Parts	
In Date: 12/30/2016	Close Date: 01/11/2017	Hours	Description		Quantity
-	Replace Right Rear Sign Al Light Bulb And Socket.	0.75	3157 TAIL LIGHT BULBS		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
			STP TRN TL LGT SOCKET		1.00
Parts Charge:		10.19	Labor Charge:	45.00	

12/28/2017
4:36:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178878 2009 FORD F350 Pickup, 1 Ton, 4X4, Srw

Workorder: 1701625

Problem: P.M. service.

Meter Reading: 87943 In Date: 02/15/2017	Close Date: 02/23/2017	Labor Hours	Description	Parts	Quantity
- P.M. Service.		13.50	NAPAGOLD FUEL FILTER		1.00
- Est Battery And Charging System.Replace Bad Battery.			BATTERY		1.00
- Replace Four Worn Out Body Mounts.			bumper		2.00
- Replace Front And Rear Bump Stoppers.			BODY MOUNT KIT		4.00
- Replace Tool Box Struts.			REAL SUSPENSION BUMPSTOPS		2.00
- Replace Serpentine Belt.			BELT		1.00
- Inspect And Sdervice Winch.			5W20 ENGINE OIL		7.00
- Rotate And Balance Tires.			20" WIPER BLADE		2.00
- Shop Supplies			SUPPORT		2.00
			USED FIRE X REFURBISHED		1.00
			NAPAGOLD OIL FILTER		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		734.90	Labor Charge:		810.00

Workorder: 1708103

Problem: P.M. service.

Meter Reading: 93660 In Date: 08/17/2017	Close Date: 08/30/2017	Labor Hours	Description	Parts	Quantity
- P.M. Service.		15.50	NAPA GEAR 80W-90 QT		4.00
- Resurface Both Front Brake Rotors And Service Brake Calipers.Replace Front Brake Pads And Flush Brake System.			MAC WITE LITHIUM GRES		1.00
			NAPAGOLD AIR FILTER		1.00
			NON-CHLOR BRAKE CLNR		2.00
- Replace Two Tires.Nitrogen Fill.Rotate And High Speed Balance All Four Tires.			BRAKE PADS		1.00
			TR416 VALVE STEM		2.00
- Inspect And Service Front Differential.Due To Water In Oil.			USED FIRE X REFURBISHED		1.00
- Inspect And Service Winch.			5W20 ENGINE OIL		7.00
- Perform Front End Alignment.			LT265/70R17		2.00
- Shop Supplies			lube		1.00
			TIRE DISPOSAL FEE		2.00
			B FLUID DOT 3-32OZ		1.00
			NAPAGOLD OIL FILTER		1.00
			SHOP SUPPLIES		1.00
			20" WIPER BLADE		2.00
Parts Charge:		858.49	Labor Charge:		930.00

12/28/2017
4:36:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10178878 2009 FORD F350 Pickup, 1 Ton, 4X4, Srw

Workorder: 1710005

Problem: Transition Prep Charge

Meter Reading: 94815

Labor

Parts

In Date: 10/12/2017

Close Date: 10/12/2017

Hours

Description

Quantity

-	Transition Prep Charge		2.00		
	Parts Charge:	0.00	Labor Charge:	120.00	

Total Parts Charges:	16,883.41	Total Labor Charges:	15,585.00	Total Comm. Charges:	950.75
----------------------	------------------	----------------------	------------------	----------------------	---------------