

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 938029 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 05/20/2009	Hours	Description
Close Date: 05/20/2009	Quantity	
- Pre-Delivery Inspection	4.00	
Parts Charge: 0.00	Labor Charge: 240.00	

Workorder: 938266 **Problem:** 003 KEYS ISSUED OUT 05/27/09

Meter Reading: 0	Labor	Parts
In Date: 05/27/2009	Hours	Description
Close Date: 05/27/2009	Quantity	
- 003 Keys Issued Out 05/27/09	0.60	DUPLICATE VEHICLE KEYS
Parts Charge: 9.00	Labor Charge: 36.00	

Workorder: 940610 **Problem:** coolant leak, no power

Meter Reading: 2072	Labor	Parts
In Date: 07/10/2009	Hours	Description
Close Date: 07/16/2009	Quantity	
- To/From Dealer For Warrenty Water Pump.	2.00	SHOP SUPPLIES
- Shop Supplies		
Parts Charge: 2.00	Labor Charge: 60.00	

Workorder: 941222 **Problem:** A/C not working

Meter Reading: 2456	Labor	Parts
In Date: 07/27/2009	Hours	Description
Close Date: 08/04/2009	Quantity	
- A/C Compressor Not Coming On, Trace Circuit, Replace Defective Low Pressure Cut Off Switch & Retest System.	1.00	A/C LOW PRESSURE SWITCH
- Shop Supplies		SHOP SUPPLIES
Parts Charge: 16.51	Labor Charge: 60.00	

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 942688

Problem: coolant smell in cab.

Meter Reading: 3251	Labor	Parts	
In Date: 08/28/2009	Hours	Description	Quantity
- To/From Dealer For Coolant Leak @ W/P Bypass Tube.	7.00	SHOP SUPPLIES	1.00
- Rewire Crane Power To Upfitter Switches. Fabricate & Refit Hyd Line Off Pto Pump Away From Trans Shift Lever, Protect Hyd Hoses @ Outriggers			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	360.00

Workorder: 943607

Problem: damage to rear bumper

Meter Reading: 3251	Labor	Parts	
In Date: 09/11/2009	Hours	Description	Quantity
- Damage To Rear Bumper			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	468.00

Workorder: 944172

Problem: Driver complain of coolant smell in cab.

Meter Reading: 3512	Labor	Parts	
In Date: 10/05/2009	Hours	Description	Quantity
- Pressure Test Cooling System,Leaking At Water Pump.Transport To Dealer For Warranty Repairs.Seal Hole On Firewall.	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	120.00

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 946225

Problem: P.M service, coolant leak, check rear bumper.

Meter Reading: 4481		Labor		Parts	
In Date: 11/19/2009	Close Date: 12/09/2009	Hours	Description	Quantity	
-	P.M Service.	8.50	15/40 OIL		15.00
-	Rotate & Balance All Six Tires.		CA10270 AIR FILTER MTC FA1886 WIX 49886		1.00
-	Inspect & Service Crane.		7312 OIL FILTERFRM CH9549 WIX 57312		1.00
-	To/From Dealer For Warrenty Water Pump. 2Nd Time.		CS10263 FUEL FILTER (USE CS10263A)		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
Parts Charge: 141.17		Labor Charge: 1,020.00			

Workorder: 947125

Problem: damage to rear bumper

Meter Reading: 4481		Labor		Parts	
In Date: 12/09/2009	Close Date: 12/17/2009	Hours	Description	Quantity	
-	Damage To Rear Bumper				
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 300.00	

Workorder: 1004703

Problem: Check tires, light bar, L/F utility door & vice.

Meter Reading: 7931		Labor		Parts	
In Date: 05/06/2010	Close Date: 05/10/2010	Hours	Description	Quantity	
-	Install Four New Tires To Fronts And Right Rear.Nitro Fill And Balance All Six	8.80	179636492 LT245/75R17 WRANGLER SR-A E		4.00
-	Force Entry,Repair Left Front Door Lock.Replace Failed Vice With New.Drill New Mounting Holes.		TIRE DISPOSAL FEE		4.00
-	Diagnose Light Bar Concern.Test For Short Circuit And Replace Failed Fuse.		SHOP SUPPLIES		1.00
-	Perform Wheel Alignment Complete.		66997 COMBO VISE (RIGID F-60)		1.00
-	Shop Supplies				
Parts Charge: 1,166.69		Labor Charge: 528.00			

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1005766

Problem: Light bar stopped working.

Meter Reading: 8451	Labor	Parts	
In Date: 06/02/2010	Hours	Description	Quantity
<hr/>			
- Diagnose, Repair, Insulate And Reposition Lightbar Harness Away From Body Bushing.	1.50	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	90.00

Workorder: 1006362

Problem: P.M. Service.

Meter Reading: 8731	Labor	Parts	
In Date: 06/16/2010	Hours	Description	Quantity
<hr/>			
- P.M. Service.	7.00	31-20 WIPER BLADES 20" BLADE	2.00
- Replace Both Front Tires. Rotate And Balance All Six.		7312 OIL FILTER FRM CH9549 WIX 57312	1.00
- Replace Pintle Pin On Hitch.		USED FIREX REFURBED FIRE EXTINGUISHERS	1.00
- Shop Supplies		179636492 LT245/75R17 WRANGLER SR-A E	2.00
		CS10263 FUEL FILTER (USE CS10263A)	1.00
		18410 PINTLE PIN	1.00
		15/40 OIL	15.00
		TIRE DISPOSAL FEE	2.00
		SHOP SUPPLIES	1.00
Parts Charge:	485.91	Labor Charge:	420.00

Workorder: 1007016

Problem: vehicle shut off (Diesel problem)

Meter Reading: 8900	Labor	Parts	
In Date: 07/02/2010	Hours	Description	Quantity
<hr/>			
- From: Forest Hill And Pine Hurst To: Lv Shop			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	114.00

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1007042

Problem: Vehicle towed in. Run out of fuel.Will not start.

Meter Reading: 9188	Labor	Parts	
In Date: 07/06/2010	Hours	Description	Quantity
- Remove And Clean Both Fuel Filter Housing And Water Seperator.Bleed All Air Pockets From Fuel Lines And Prime System To Start And Run Engine.	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	120.00

Workorder: 1007055

Problem: reflash canceiver/ spot219

Meter Reading: 8900	Labor	Parts	
In Date: 07/06/2010	Hours	Description	Quantity
- Reflash	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1008981

Problem: Check and repair crane inop.

Meter Reading: 10579	Labor	Parts	
In Date: 08/19/2010	Hours	Description	Quantity
- Repair Broken Power Wire To Crane.Replace Fuse.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies		15319477 FUSE 30 AMP GMC	1.00
		06133 3M ELECTRIC TAPE STOCK #832260101	1.00
Parts Charge:	8.46	Labor Charge:	60.00

Workorder: 1009055

Problem: Lower crain

Meter Reading: 10571	Labor	Parts	
In Date: 08/23/2010	Hours	Description	Quantity
- Lower Crane Send To Lv Shop	2.50	SHOP SUPPLIES	1.00
- Fm To C Rock			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	150.00

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1011759

Problem: Hydraulic tank oil cap leaking.

Meter Reading: 12045		Labor		Parts	
In Date: 10/20/2010	Close Date: 10/21/2010	Hours	Description	Quantity	
-	Replace And Secure Failed Filler Cap For Hydraulic Tank.	0.75	BIG G DEGREASER STOCK# 485180002	1.00	
-	Shop Supplies		SHOP SUPPLIES	1.00	
			35610001 CAP/SCREEN HYD TANK BUCKET TRUCK	1.00	
Parts Charge: 103.74		Labor Charge: 45.00			

Workorder: 1013647

Problem: Pm service also see notes on oil leak.

Meter Reading: 13581		Labor		Parts	
In Date: 12/10/2010	Close Date: 12/27/2010	Hours	Description	Quantity	
-	Perform Pm Service.	21.00	FRONT PADS	1.00	
-	Install New Front And Rear Brake Pads And Resurface All Four Brake Rotors.Perform Brake Fluid Flush And Automated Bleed Abs System With Scan Tool.		15/40 OIL	15.00	
-	Install Two New Tires To The Front Wheels.Nitrogen Fill And Balance All Six.		CA10270 AIR FILTER MTC FA1886 WIX 49886	1.00	
-	Test Starting And Charging System.Both Batteries Failed Loadtest After Recharge.Replace Both Failed Batteries With New.		7090BLK FRT FLOOR MATS (RUBBER QUEEN)	1.00	
-	Fabricate And Replace Failed Hydraulic Oil Filter And Housing With New.Bleed And Top Off Fluid.		09997 BRAKE CLEAN	1.00	
-	Fabricate And Replace Failed Hitch Pindel Pin With New.		179636492 LT245/75R17 WRANGLER SR-A E	2.00	
-	Inspect And Service Crane Also Lube Out Rigger.		GROUP 65 BATTERY (MTC BXT-65-850)	2.00	
-	Shop Supplies		50002 FILTER ADAPTER (CIMTEK)	1.00	
			51551 HYDRAULIC FILTER	1.00	
			SHOP SUPPLIES	1.00	
			18410 PINTLE PIN	1.00	
			CS10263 FUEL FILTER (USE CS10263A)	1.00	
			7312 OIL FILTERFRM CH9549 WIX 57312	1.00	
			2232 BRAKE FLUID QUART	2.00	
			TIRE DISPOSAL FEE	2.00	
			USED FIREX REFURBED FIRE EXTINGSHERS	1.00	
			REAR PADS	1.00	
			AW68 HYDRO FLUID HYDRAULIC OIL 68	10.00	
			56521 THREAD SEALANT HI TEMP THREAD SEALANT	1.00	
			31-20 WIPER BLADES 20" BLADE	2.00	
Parts Charge: 1,073.09		Labor Charge: 1,260.00			

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1100662 **Problem:** repair trailer plug wiring

Meter Reading: 14298	Labor	Parts	
In Date: 01/18/2011	Hours		Quantity
- Test Trailer Plug Replace Bad Fuse	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00		Labor Charge: 60.00	

Workorder: 1102301 **Problem:** service

Meter Reading: 15708	Labor	Parts	
In Date: 02/25/2011	Hours		Quantity
- Haverhill And Summit			
Parts Charge: 0.00		Labor Charge: 0.00	Commercial Charge: 66.00

Workorder: 1103887 **Problem:** replace left rear outer tire

Meter Reading: 16909	Labor	Parts	
In Date: 03/29/2011	Hours		Quantity
- 8100 Forest Hill			
Parts Charge: 0.00		Labor Charge: 0.00	Commercial Charge: 147.76

Workorder: 1103889 **Problem:** service

Meter Reading: 16909	Labor	Parts	
In Date: 03/31/2011	Hours		Quantity
- 8100 Foret Hill Blvd			
Parts Charge: 0.00		Labor Charge: 0.00	Commercial Charge: 33.60

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1105098

Problem: Pm service.

Meter Reading: 18774	Labor	Parts	
In Date: 05/12/2011	Hours	Description	Quantity
- P.M. Service.	8.00	15/40 OIL	15.00
- Inspect And Service Crane.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Replace Three Tires,Rotate And Balance All Six.		CS10263 FUEL FILTER (USE CS10263A)	1.00
- Shop Supplies		31-20 WIPER BLADES 20" BLADE	2.00
		TIRE DISPOSAL FEE	3.00
		TR416 VALVE STEM	3.00
		51551 HYDRAULIC FILTER	1.00
		SHOP SUPPLIES	1.00
		179636492 LT245/75R17 WRANGLER SR-A E	3.00
Parts Charge:	676.03	Labor Charge:	480.00

Workorder: 1107502

Problem: Check engine light on.

Meter Reading: 21914	Labor	Parts	
In Date: 07/18/2011	Hours	Description	Quantity
- Diagnose Fuel Leak At Left Frame Rail.Fuel Condition	4.00	SHOP SUPPLIES	1.00
Module Drain Valve Housing Failed,Warp And		3963 FUEL FILTER FRM CS10263A WIX 33963	1.00
Leaking.Replace Failed Fuel Condition Module With New.		8C3Z9A343A SEAL KIT FUEL FILTER (FORD)	1.00
- Transport Vehicle To And From Dealer For Replacing		8C3Z9A343A SEAL KIT FUEL FILTER (FORD)	1.00
Failed High Pressure Fuel Pump With New.Asper Tsb		FUEL PUMP	1.00
11-4-22 Poo88,Also Reprogram Pcm Asper Recall		09997 BRAKE CLEAN	1.00
11B23B			
- Shop Supplies			
Parts Charge:	489.69	Labor Charge:	240.00

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1111371

Problem: P.M. service and crane inop.

Meter Reading: 24075 In Date: 10/26/2011	Close Date: 11/07/2011	Labor Hours	Description	Parts	Quantity
- P.M. Service.		9.25	SHOP SUPPLIES		1.00
- Replace Left Rear Marker Lamp And Center Brake Light Bulb.			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
			3963 FUEL FILTER FRM CS10263A WIX 33963		1.00
- Diagnose Crane Inop.Repl;Ace Defective Pressure Transducer.Inspec T And Service Crane.			8C3Z9A343A SEAL KIT FUEL FILTER (FORD)		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
- Replace Two Tires,Rotate And Balance All Six.			51551 HYDRAULIC FILTER		1.00
			179636492 LT245/75R17 WRANGLER SR-A E		2.00
- Shop Supplies			33167 L/SENSE SWITCH 1032 (LIFTMOORE)		1.00
			TIRE DISPOSAL FEE		2.00
			15/40 OIL		15.00
			CA10270 AIR FILTER MTC FA1886 WIX 49886		1.00
			19006R MARKER LIGHT 4" RECTANGULAR RED LED		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
	Parts Charge:	816.45	Labor Charge:	555.00	

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1204652

Problem: Pm service.Check hydraulic hoses and crane concern,see notes.

Meter Reading: 29367 In Date: 05/16/2012	Close Date: 07/06/2012	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		24.00	15319476 FUSE 20 AMP GMC		1.00
- Test And Replace Failed Left Headlamp Seal Beam Assembly With New.			H6054 SEALED BEAM		1.00
			WD40 SPRAY LUBE STOCK# 405540002		1.00
- Inspect And Service Crane.Replace One Failed High Pressure Hose With New.Test And Replace Failed Rotating Limit Switch And Solenoid Control Valve With New.			SHOP SUPPLIES		1.00
			MKD1333 FRONT PADS		1.00
			CASTER ADJUSTER		1.00
			REAR PADS		1.00
- Install New Front And Rear Brake Pads And Resurface All Four Brake Rotors.Service All Calipers And Perform Brake Fluid Flush.Automated Bleed Hydraulic System With Scan Tool And Road Test.			09997 BRAKE CLEAN		2.00
			SOLENOID VALVE		1.00
			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
			1401 BRAKE FLUID BRAKE FLUID		2.00
- Replace All Six Tires.Nitrogen Fill And Balance All Six.			179636492 LT245/75R17 WRANGLER SR-A E		6.00
			TIRE DISPOSAL FEE		6.00
- Perform Wheel Alignment Complete.Install New Adjustable Cam To Left Side To Compensate For More Camber And Caster Adjustment.			51551 HYDRAULIC FILTER		1.00
			15/40 OIL		15.00
			ROTATION LIMIT SWITCH		1.00
- Shop Supplies			3963 FUEL FILTER FRM CS10263A WIX 33963		1.00
			PM-22-A ADDITIVE DIESEL FUEL (M/CRAFT)		1.00
Parts Charge:	2,255.79	Labor Charge:	1,440.00	Commercial Charge:	55.22

Workorder: 1207703

Problem: Check engine light on and no power.Check over crane operation.

Meter Reading: 30768 In Date: 08/15/2012	Close Date: 08/30/2012	Labor Hours	Description	Parts	Quantity
- Diagnose Check Engine Light..Check And Replace Fuel Filter.		5.00	3963 FUEL FILTER FRM CS10263A WIX 33963		1.00
			SHOP SUPPLIES		1.00
- Check And Repair Power Wire To Crane.					
- Transport Vehicle To Dealer For Defective High Pressure Pumpand Pcm Update.					
- Shop Supplies					
Parts Charge:	47.59	Labor Charge:	300.00	Commercial Charge:	79.72

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1301073

Problem: Pm service.

Meter Reading: 35061 In Date: 01/30/2013	Close Date: 02/11/2013	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		15.00	OIL FILTER		1.00
- Test And Replace Two Rear Strobe Lamp Bulbs With New. Also Replace Failed Left Alley Lamp, Cargo Lamp And Dome Lamp Bulbs With New.			NAPAGOLD FUEL FILTER		1.00
			USED FIREX REFURBED F		1.00
			18410 PINTLE PIN		1.00
- Test Starting And Charging System. Both Batteries Failed Loadtest After Recharge. Replace Both Failed Batteries With New.			17189E BULB MR11-12V		1.00
			BATTERY 65		2.00
			AW68 HYDRO FLUID HYDR		2.00
- Inspect And Service Hydraulic Crane. Diagnose For Oil Leak. Remove Failed P.T.O Hydraulic Hose. Fabricate And Replace With New After Sent Out And Repaired. Retest For Oil Leak Ok.			RADIATOR HOSE		1.00
			lower hose		1.00
			NAPA HYDRAULIC FILTR		1.00
			VC7B COOLANT MOTORCRA		2.00
- Pressure Test And Inspect Cooling System. Replace Failed Upper And Lower Radiator Hoses With New. Reverse Flush And Renew Engine Coolant.			RADIATOR HOSE		1.00
			HYDRAULIC HOSE		1.00
			HYD FITTING		1.00
			HYD FITTING		1.00
- Rotate And Balance All Six Tires.			SHOP SUPPLIES		1.00
- Shop Supplies			brake pedal pad		1.00
			15-40 OIL		15.00
Parts Charge:		714.29	Labor Charge:		900.00

Workorder: 1301523

Problem: 1 - Key(s) issued

Meter Reading: 35061 In Date: 02/12/2013	Close Date: 02/12/2013	Labor Hours	Description	Parts	Quantity
- 1 - Key(S) Issued		0.20	DUPLICATE VEHICLE KEYS		1.00
Parts Charge:		3.00	Labor Charge:		18.00

Workorder: 1302644

Problem: Rear Outside Left flat tire

Meter Reading: 35948 In Date: 03/15/2013	Close Date: 03/18/2013	Labor Hours	Description	Parts	Quantity
- Tire Service 8100 Forest Hill Blvd - Rear Outside Left Flat Tire					
Parts Charge:		0.00	Labor Charge:		0.00
			Commercial Charge:		46.40

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1302645

Problem: tires

Meter Reading: 35948

In Date: 03/15/2013

Close Date: 03/18/2013

Labor

Hours

Description

Parts

Quantity

- Tire Service 810 Forest Hill Blvd - Tires

Parts Charge: 0.00

Labor Charge: 0.00

Commercial Charge: 205.80

Workorder: 1303140

Problem: Power outlets inop.

Meter Reading: 36476

In Date: 04/01/2013

Close Date: 04/03/2013

Labor

Hours

Description

Parts

Quantity

- Diagnose Power Outlets Inop. Test For Short Circuits. Test
And Replace Two Open 20 Amps. Circuit Breakers With
New.

1.00

FUSE
SHOP SUPPLIES

2.00

1.00

- Shop Supplies

Parts Charge: 8.21

Labor Charge: 60.00

Workorder: 1306038

Problem: service

Meter Reading: 39150

In Date: 06/14/2013

Close Date: 06/17/2013

Labor

Hours

Description

Parts

Quantity

- Tire Service 8100 Forest Hill Blvd - Service

Parts Charge: 0.00

Labor Charge: 0.00

Commercial Charge: 19.93

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1306156

Problem: Pm service.Check tires.

Meter Reading: 39501 In Date: 06/19/2013	Close Date: 06/28/2013	Labor Hours	Description	Parts	Quantity
- P.M. Service.		21.25	REMAN BRAKE CALIPER		1.00
- Replace Right Head Lamp.			1401 BRAKE FLUID BRA		1.00
- Replace Five New Tires,Balance All Six.			NAPA HYDRAULIC FILTR		1.00
- Resurface Front And Rear Brake Rotors,Replace Front			REMAN BRAKE CALIPER		1.00
And Rear Calipers And Brake Pads.Lube Calipers			REMAN BRAKE CALIPER		1.00
Slides.Flush And Bleed Brak System.			SHOP SUPPLIES		1.00
- Inspect And Service Crane.			TIRE DISPOSAL FEE		5.00
- Complete Wheel Alignment.Test Drive.			NAPAGOLD FUEL FILTER		1.00
- Shop Supplies			15-40 OIL		15.00
			NAPAGOLD AIR FILTER		1.00
			31-20 WIPER BLADES 20		2.00
			NAPAGOLD OIL FILTER		1.00
			WASHER FL		1.00
			HALOGEN LAMP		1.00
			179636492 LT245-75R17		5.00
			PADS		1.00
			BRAKE PADS D1334		1.00
			REMAN BRAKE CALIPER		1.00
			MAC WITE LITHIUM GRES		1.00
	Parts Charge:	1,866.85	Labor Charge:	1,275.00	

Workorder: 1308504

Problem: R/R tire flat

Meter Reading: 40675 In Date: 08/21/2013	Close Date: 08/22/2013	Labor Hours	Description	Parts	Quantity
- Tire Service Croc-Gas Pumps - R/R Tire Flat					
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 46.40

Workorder: 1308508

Problem: Service

Meter Reading: 40675 In Date: 08/22/2013	Close Date: 08/22/2013	Labor Hours	Description	Parts	Quantity
- Tire Service 8100 Forst Hill Blvd - Service					
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 199.99

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1309389

Problem: Right front tire flat and power outlet inop.

Meter Reading: 41972		Labor		Parts	
In Date: 09/16/2013	Close Date: 09/19/2013	Hours	Description		Quantity
-	Repair Flat Right Front Tire.Nitrogen Fill And Balance Same.	1.50	SHOP SUPPLIES		1.00
-	Test Power Outlet For Short Circuit And Replace Two Open 20 Amps Fusable Link Breakers With New.		FUSE		2.00
-	Shop Supplies				
Parts Charge:		11.30	Labor Charge:	90.00	

Workorder: 1311125

Problem: Towed in for brake concern.

Meter Reading: 44069		Labor		Parts	
In Date: 11/04/2013	Close Date: 12/10/2013	Hours	Description		Quantity
-	Replace Broken Right Rear Caliper Mounting Bracket And Caliper Assemble.Replace Brake Hose And Flush And Bleed System.	17.00	BOLT		4.00
-	Transport Vehicle To Palm Beach Spring To Repair Damaged Right Rear Spring.		NAPA OIL SEAL		1.00
-	P.M. Service.		2232 BRAKE FLUID QUAR		1.00
-	Inspect And Service Crane.		BACKING PLATE		1.00
-	Replace Two Tires,Rotate And Balance All Six.		BRAKE HOSE		1.00
-	Complete Wheel Alignment.		15-40 OIL		15.00
-	Shop Supplies		Caliper w/ Hardware - Right Rear (Eclips		1.00
			FUEL FILTER FORD ONLY		1.00
			USED FIRE X REFURBISHED		1.00
			179636492 LT245-75R17		2.00
			TIRE DISPOSAL FEE		2.00
			NAPAGOLD OIL FILTER		1.00
			WIPER BLADE		2.00
			NAPA HYDRAULIC FILTR		1.00
			SHOP SUPPLIES		1.00
			REAR SPRIN REPAIR		1.00
Parts Charge:		1,732.76	Labor Charge:	1,020.00	

Workorder: 1311196

Problem: No Brakes

Meter Reading: 43663		Labor		Parts	
In Date: 11/01/2013	Close Date: 11/04/2013	Hours	Description		Quantity
-	Tow From: Croc To: Vista				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 134.77

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1401728

Problem: Inter cooler hose leaking.

Meter Reading: 47191	Labor	Parts	
In Date: 02/21/2014	Hours	Description	Quantity
- Diagnose And Replace Failed Intercooler Hose With New.Clear Codes With Scan Tool And Roadtest.	2.00	SHOP SUPPLIES	1.00
- Shop Supplies		TURBO HOSE CLAMP	1.00
		TURBO HOSE CLAMP	1.00
		INTERCOOLER HOSE	1.00
Parts Charge:	107.51	Labor Charge:	120.00

Workorder: 1402298

Problem: Check engine light on.

Meter Reading: 47551	Labor	Parts	
In Date: 03/07/2014	Hours	Description	Quantity
- P.M. Service.	9.25	15-40 OIL	15.00
- Transport Vehicle To Dealer For Defective Exhaust Back Pressure Sensor.		NAPAGOLD OIL FILTER	1.00
- Inspect And Service Crane.		FUEL FILTER FORD ONLY	1.00
- Replace Two Front Tires,Rotate And Balance All Six.		WIPER BLADE	2.00
- Replace Pintle Pin.		NAPA HYDRAULIC FILTR	1.00
- Shop Supplies		179636492 LT245-75R17	2.00
		PINTLE PIN W/CHAIN	1.00
		STG WHEEL COV - FORD	1.00
		TIRE DISPOSAL FEE	2.00
		SHOP SUPPLIES	1.00
Parts Charge:	666.71	Labor Charge:	555.00

Workorder: 1402768

Problem: wont fuel

Meter Reading: 47812	Labor	Parts	
In Date: 03/21/2014	Hours	Description	Quantity
- Test And Remove Canceiver	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1404783

Problem: Flat rear tires.

Meter Reading: 50547		Labor	Parts	
In Date: 05/15/2014	Close Date: 05/20/2014	Hours	Description	Quantity
-	Install Two New Tires Toleft Rear Inner And Outer	1.00	179636492 LT245-75R17	2.00
	Wheels.Nitrogen Fill And Balance Both.		TIRE DISPOSAL FEE	2.00
-	Shop Supplies		SHOP SUPPLIES	1.00
			TR416 VALVE STEM	2.00
	Parts Charge: 500.14	Labor Charge: 60.00		

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1406097

Problem: Pm service and ckeck brakes fluid leak right front wheel.

Meter Reading: 52032 In Date: 06/20/2014	Close Date: 06/30/2014	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		24.50	TIRE DISPOSAL FEE		2.00
- Install New Front And Rear Brake Pads.Install New Front Brake Rotors.Replace All Failed Calipers With New.Resurface Rear Brake Rotors.Flush Brake Fluid And Bleed Hydraulic System.			15-40 OIL		15.00
			WIPER BLADE		2.00
			Wheel Seal - Front Wheel		2.00
			WASHER FL		1.00
- Install Two New Tires To The Front Wheels.Nitrogen Fill And Balance All Six.			REMAN BRAKE CALIPER		1.00
			REMAN BRAKE CALIPER		1.00
- Test Starting And Charging System.Both Batteries Failed Loadtest After Recharge.Replace Both Failed Batteries With New Warranty Parts			LT245/75R17 HANKOOK TIRE		2.00
			BATTERY 65		2.00
			SHOP SUPPLIES		1.00
- Inspect And Service Hydraulic Crane.			NAPAGOLD OIL FILTER		1.00
- Test And Replace Both Failed Led Brake Lamps With New.Install One New Amber Body Marker Lamp Also Replace Three Roof Lamp Bulbs With New.			DISC BRAKE ROTOR-HUB		2.00
			PADS		1.00
			REAR PADS		1.00
- Diagnose For Blower Low Speed Inop.Test And Replace Failed Blower Resistor With New.			BRAKE FLUID QT		2.00
			REMAN BRAKE CALIPER		1.00
- Perform Wheel Alignment Complete.			BULB		3.00
- Shop Supplies			PINTLE PIN W/CHAIN		1.00
			LED M C LAMP		1.00
			BLOWER RESISTOR		1.00
			NAPA HYDRAULIC FILTR		1.00
			BRAKE ROTOR HUB		2.00
			LED SUP MDL 44 42 DIO		2.00
			BOLT KIT		1.00
			FUEL FILTER FORD ONLY		1.00
			REMAN BRAKE CALIPER		1.00
	Parts Charge: 1,694.90	Labor Charge: 1,470.00			

Workorder: 1406103

Problem: Brakes...Leaking Brake fluid

Meter Reading: 51821 In Date: 06/20/2014	Close Date: 06/20/2014	Labor Hours	Description	Parts	Quantity
- Tow From: 8100 Forest Hill Blvd, (Water Plant)					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 104.15		

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1410711 **Problem:** Flat tire on R/P/O

Meter Reading: 56938		Labor		Parts	
In Date: 10/21/2014	Close Date: 10/27/2014	Hours	Description		Quantity
- Tire Service 8100 Forest Hill - Flat Tire On R/P/O					
Parts Charge:		0.00	Labor Charge:		0.00
			Commercial Charge:		46.40

Workorder: 1410712 **Problem:** tires

Meter Reading: 56938		Labor		Parts	
In Date: 10/24/2014	Close Date: 10/27/2014	Hours	Description		Quantity
- Tire Service 8100 Forest Hill Blvd (Water Plant) - Tires					
Parts Charge:		0.00	Labor Charge:		0.00
			Commercial Charge:		215.66

Workorder: 1411122 **Problem:** P.M. Service.Out-rigger creeping down.Check power outlet.

Meter Reading: 57700		Labor		Parts	
In Date: 11/05/2014	Close Date: 11/25/2014	Hours	Description		Quantity
- Perform Pm Service.					
		17.75	15-40 OIL		15.00
- Inspect And Replace Leaking Left Outrigger Hydraulic Cylinder.Inspect And Service Hydraulic Crane.					
			NAPAGOLD OIL FILTER		1.00
- Replace Two Tires.Rotate And Balance All Six.					
			FUEL FILTER FORD ONLY		1.00
- Inspect And Replace Leaking Brake Master Cylinder.Flush Brake Fluid And Bleed Hydraulic System.Roadtest.					
			WIPER BLADE		2.00
- Replace Both Front Control Arm Bump Stops.					
			PINTLE PIN W/CHAIN		1.00
- Inspect And Replace Both Front Upper And Lower Cab To Chasis Mount Cushions					
			TIRE DISPOSAL FEE		2.00
- Perform Complete Front End Alignment.Roadtest.					
			USED FIRE X REFURBISHED		1.00
- Test And Diagnose Electrical Circuit To Accesory Outlet Short To Ground,High Resistance.Repair And Verify Ok					
			OUTRIGGER CYLINDER R&R		1.00
- Shop Supplies					
			bumper		2.00
			INSULATOR		2.00
			INSUALTOR		2.00
			179636492 LT245-75R17		2.00
			B FLUID DOT 3-32OZ		1.00
			STG WHEEL COV - FORD		1.00
			SHOP SUPPLIES		1.00
			MASTER CYLINDER		1.00
			NAPA HYDRAULIC FILTR		1.00
			NAPAGOLD AIR FILTER		1.00
Parts Charge:		1,800.32	Labor Charge:		1,065.00

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1500074

Problem: Check over heating.Power outlet inop.Right outrigger cylinder falling.

Meter Reading: 59308		Labor		Parts	
In Date: 01/05/2015	Close Date: 01/30/2015	Hours	Description	Quantity	
-	Transport Vehicle To Dealer For Coolant Leaking Into Cylinders.	4.00	SHOP SUPPLIES		1.00
-	Replace Leaking Right Side Outrigger Cylinder.Refill Fluid.		OUTRIGGER CYLINDER R&R		1.00
-	Test And Replace Inop Power Outlet.		SOKET PAWER OUTLET		1.00
-	Shop Supplies				
Parts Charge:		483.21	Labor Charge:	240.00	Commercial Charge: 2,642.35

Workorder: 1500591

Problem: transport to 1530 N. Military Trail

Meter Reading: 59152		Labor		Parts	
In Date: 01/15/2015	Close Date: 01/15/2015	Hours	Description	Quantity	
-	Tow From: 2601 Vista To: 1530 N. Military Trail				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 134.77

Workorder: 1503224

Problem: Pm service.

Meter Reading: 61694		Labor		Parts	
In Date: 03/27/2015	Close Date: 04/21/2015	Hours	Description	Quantity	
-	Pm Service.	22.75	15-40 OIL		15.00
-	Inspect And Service Crane.		NAPAGOLD OIL FILTER		1.00
-	Replace Front And Rear Brake Pads.Resurface Front And Rear Brake Rotors.Service Calipers And Bleed Brake System.		FUEL FILTER FORD ONLY		1.00
-	Diagnose For Noise From Front Of Engine.Replace Defective Serpentine Belt And Tensioner.		BULB		1.00
-	Replace Four Tires.Rotate And Balance All Six.		WIPER BLADE		2.00
-	Dismantle Light Bar.Test And Replace Defective Right Alley Lamp.One Clearance Lamp Bulb And One Take Down Led Lamp.		Freight Charge		1.00
-	Shop Supplies		LT245 75R17 M/S2 TIRE		4.00
			SHOP SUPPLIES		1.00
			17189E BULB MR11-12V		1.00
			NAPA HYDRAULIC FILTR		1.00
			PADS		1.00
			TIRE DISPOSAL FEE		4.00
			TENSIONER-HEAVY DUTY		1.00
			TAKEDOWN LIGHT		1.00
			SERPENTINE BELT		1.00
			REAR PADS		1.00
Parts Charge:		1,780.41	Labor Charge:	1,365.00	

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1504105

Problem: Check for oil leak.

Meter Reading: 61986	Labor	Parts	
In Date: 04/21/2015	Hours	Description	Quantity
- Diagnose For Oil Leaks.Replace Defective Pcv Tube From Engine Crank Case To Oil Filler Neck.	2.50	BOLT CRANK VENT HOSE	1.00 1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge: 40.06	Labor Charge: 150.00		

Workorder: 1505938

Problem: Left headlamp inop.

Meter Reading: 64075	Labor	Parts	
In Date: 06/15/2015	Hours	Description	Quantity
- Test And Replace Left Headlight Bulb And Retest.	0.50	HALOGEN LAMP	1.00
Parts Charge: 12.41	Labor Charge: 30.00		

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1508781

Problem: Pm service and noise from engine air intake.

Meter Reading: 67133 In Date: 09/01/2015	Close Date: 10/20/2015	Labor Hours	Description	Parts	Quantity
- Pm Service.		30.50	BATTERY 65		2.00
- Replace Defective Right Headlamp And Two Tail Lamp Assemblies.			USED FIRE X REFURBISHED		1.00
- Inspect And Service Crane.			VALVE GUIDE KIT		4.00
- Replace Defective Radiator Assembly.Flush And Refill Cooling System.			LED SUP MDL 44 42 DIO		2.00
- Replace Two Tires.Rotate And Balance All Six.			VALVE COVER GASKET		1.00
- Check Battery And Charging System.Replace Both Defective Batteries.			HALOGEN LAMP		1.00
- Diagnose For Noise In Air Intake.Replace All Defective Rocker Arms,Bridges,Injector Seals,Harness And Valve Cover Gasket On Right Side Of Engine.			NAPAGOLD OIL FILTER		1.00
- Shop Supplies			TIRE DISPOSAL FEE		2.00
			ROACKER ARM		8.00
			PEAK GLOBAL		3.00
			INJECTOR TUBE		4.00
			NAPA HYDRAULIC FILTR		1.00
			FUEL FILTER FORD ONLY		1.00
			SHOP SUPPLIES		1.00
			RADIATOR		1.00
			INJECTOR HARNESS		1.00
			LT245 75R17 M/S2 TIRE		2.00
			15-40 OIL		15.00
			SWITCH		1.00
			WIPER BLADE		2.00
	Parts Charge:	2,592.39	Labor Charge:	1,830.00	

Workorder: 1510746

Problem: Check for engine noise.

Meter Reading: 67242 In Date: 10/23/2015	Close Date: 11/03/2015	Labor Hours	Description	Parts	Quantity
- Diagnose For Engine Noise.Replace All Rocker Arms,Bridges,Glow Plug Harness And Valve Cover Gasket On Left Side Of Engine.Test Drive.Ok.Replace One Broken Fuel Cap.		14.00	FUEL CAP		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			VALVE COVER GASKET		1.00
			VALVE GUIDE KIT		4.00
			GLOW PLUG HARNESS		1.00
			ROACKER ARM		8.00
	Parts Charge:	474.15	Labor Charge:	840.00	

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1511477

Problem: Washer nozzles.

Meter Reading: 67463	Labor	Parts	
In Date: 11/09/2015	Hours	Description	Quantity
<hr/>			
- Replace Defective Washer Nozzles.	0.50	WASHER NOZZLE	2.00
Parts Charge: 14.64	Labor Charge: 30.00		

Workorder: 1512557

Problem: Right rear tires flat.

Meter Reading: 68997	Labor	Parts	
In Date: 12/11/2015	Hours	Description	Quantity
<hr/>			
- Repair And Balance Right Rear Tire.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 60.00		

Workorder: 1601248

Problem: Trailer plug inop.

Meter Reading: 70604	Labor	Parts	
In Date: 02/04/2016	Hours	Description	Quantity
<hr/>			
- Replace And Rewire Trailer Plug.Replace Blown Fuse.	1.50	SHOP SUPPLIES	1.00
- Shop Supplies		FUEL CAP DIESEL	1.00
		FEMALE CONN SOCKET	1.00
Parts Charge: 40.79	Labor Charge: 90.00		

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1603137

Problem: Pm service.Fluid leak.Towed in.

Meter Reading: 72442 In Date: 03/24/2016	Close Date: 04/20/2016	Labor Hours	Description	Parts	Quantity
- P.M. Service.		34.50	15-40 OIL		15.00
- Diagnose Check Engine Light.P0206.Replace Fuel Supply Tube To Injectors And Electrical Harness On Left Side.Clear Codes And Test Drive.			BULB		1.00
			FUEL FILTER FORD ONLY		1.00
			REMAN BRAKE CALIPER		1.00
- Replace One Cab Clearance Light Bulb.Replace And Rewire Trailer Plug.			SYN-ATF TRANS FLUID S		20.00
			LT245 75R17 M/S2 TIRE		4.00
			ATP FILTER		1.00
- Resurfaced Rear Brake Rotors,Replace Brake Pads.Serrvice And Lube Calipers.Flush And Bleed System.			NAPA HYDRAULIC FILTR		1.00
			TRANS PAN GASKET		1.00
			BUMPER		2.00
- Replace Rear Bounce Stops.			FAN CLUTCH ASSY		1.00
- Service Transmission.Flush And Refill System.			USED FIRE X REFURBISHED		1.00
- Replace Four Tires.Rotate And Balance All Four.			NAPAGOLD AIR FILTER		1.00
- Inspect And Service Crane.			NAPAGOLD OIL FILTER		1.00
- Diagnose P0529.Pinpoint Test And Replace Defective Fan Clutch Assemble.Clear Codes.			trailer plug		1.00
			BRAKE PAD		1.00
- Complete Wheel Alignment.Test Drive.			20" WIPER BLADE		2.00
- Shop Supplies			REMAN BRAKE CALIPER		1.00
			SHOP SUPPLIES		1.00
			TIRE DISPOSAL FEE		4.00
			AW68 HYDRO FLUID HYDR		4.00
			FUEL INJECTOR KIT		1.00
			INJECTOR HARNESS		1.00
			INJECTOR TUBE		4.00
			B FLUID DOT 3-32OZ		2.00
	Parts Charge:	2,726.88	Labor Charge:	2,070.00	

Workorder: 1603143

Problem: Leaking Fluid/PM

Meter Reading: 71954 In Date: 03/24/2016	Close Date: 03/24/2016	Labor Hours	Description	Parts	Quantity
- Tow From: Gunclub And Kirk To: Lv Shop					
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 96.00

12/28/2017
4:45:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175097 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 1708635 **Problem:** Right rear inner tire going flat.

Meter Reading: 86238		Labor		Parts	
In Date: 08/31/2017	Close Date: 08/31/2017	Hours	Description		Quantity

- Repair Right Rear Inner Tire And Balance .Nitrogen Fill Tires.		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:	2.00	Labor Charge:	60.00		

Workorder: 1709258 **Problem:** 2 - Key(s) issued

Meter Reading: 86665		Labor		Parts	
In Date: 09/25/2017	Close Date: 09/25/2017	Hours	Description		Quantity

- 2 - Key(S) Issued		0.60	DUPLICATE VEHICLE KEYS		2.00
Parts Charge:	6.00	Labor Charge:	36.00		

Workorder: 1710388 **Problem:** Flat, while boulevard was at CROC doing 10198306 this truck came along asking them to repair this flat.

Meter Reading: 87523		Labor		Parts	
In Date: 10/19/2017	Close Date: 10/23/2017	Hours	Description		Quantity

- Tire Service Croc - Flat, While Boulevard Was At Croc Doing 10198306 This Truck Came Along Asking Them To Repair This Flat.					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	161.59

Workorder: 1712443 **Problem:** Transition Prep Charge

Meter Reading: 87902		Labor		Parts	
In Date: 12/18/2017	Close Date: 12/18/2017	Hours	Description		Quantity

- Transition Prep Charge		2.00			
Parts Charge:	0.00	Labor Charge:	0.00		

Total Parts Charges:	29,337.45	Total Labor Charges:	24,975.00	Total Comm. Charges:	5,318.51
----------------------	------------------	----------------------	------------------	----------------------	-----------------