

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 838307

Problem: CHECK IN

Meter Reading: 857 In Date: 05/09/2008	Close Date: 05/19/2008	Labor Hours	Description	Parts	Quantity
- Ck In.Codes Spn 2003 Fm 1 9 Oc 18 Sa 23 Spn 928 Fmi 4 Oc2 Sa23		10.00	SHOP SUPPLIES		1.00
- Road Test					
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 60.00			

Workorder: 840701

Problem: CHECK IN RECHECK

Meter Reading: 857 In Date: 06/30/2008	Close Date: 07/02/2008	Labor Hours	Description	Parts	Quantity
- Recheck		1.50	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 90.00			

Workorder: 840710

Problem: MAKE & APPLY DECALS. CHECK FLUIDS, BELTS, AND OPER

Meter Reading: 0 In Date: 06/30/2008	Close Date: 06/30/2008	Labor Hours	Description	Parts	Quantity
- Make & Apply Decals. Check Fluids, Belts, And Operation As Applicable.		1.00			
Parts Charge: 0.00		Labor Charge: 60.00			

1/2/2018
 10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 841169

Problem: LADDER RACK AND LIST

Meter Reading: 1107		Labor	Parts	
In Date: 07/10/2008	Close Date: 07/22/2008	Hours	Description	Quantity
- Fab & Install Items Per List & Pictures Step,Wire		73.50	12CAL ALUM TAIL-GATE HING	1.00
Racks,Wireholder,Shelves Pipe Racknheader,Ladder			1/4X2X20 STEEL FLAT BAR	3.00
Rack,Ext Cord Holders,Vise,Water Jug Ho			3/82X2X20 STEEL ANGLE	4.00
- Install Nitrogen In Tires.			4X726 BEARING PILLOW BLOCK	1.00
- Shop Supplies			1" X 20 ALUM PIPE SCH 80	2.00
			1/8 4X8 SHEET STEEL	1.00
			1/8 4X8 ALUM PLATE	10.00
			1X2 24 BOX TUBING 1/8" WALL	8.00
			3/16X1-1/2X20 ALUM ANGLE ARCHITECTUAL	10.00
			4X726 BEARING PILLOW BLOCK	3.00
			T-1 BLACK PAINT GLOSS	1.00
			SHOP SUPPLIES	1.00
			1/4X1X20 STEEL FLAT BAR	6.00
			1/4"1X20 ALUM FLAT BAR 6063 GAUGE	10.00
			KEG HOLDER WATER COOLERS 450870003	1.00
			3 LB. EXPANDED METAL 4X8	6.00
			UNDER COAT	1.00
			PILLOW BLOCK BEARING	2.00
			66997 COMBO VISE (RIGID F-60)	1.00
			1/4X2X4X20 ALUM ANGLE 6063	4.00
			1/2"X2"X20' ALUM FLAT BAR	10.00
			4"X3"X25' I BEAM STRUCTURAL ALUMINUM	2.00
			1/4X1X1X20 ANGLE	3.00
			1/4X6X12 ALUM FLAT BAR	4.00
			18410 PINTLE PIN	1.00
			BRASS ROD	3.00
Parts Charge:	920.90	Labor Charge:	90.00	

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 847308

Problem: PM SERVICE

Meter Reading: 5466		Labor		Parts	
In Date: 11/20/2008	Close Date: 12/02/2008	Hours	Description	Quantity	
- Pm Service		16.00	15/40 OIL		30.00
- Order One.Replace Same.			1842639C91 OIL FILTER FRM PH9971 WIX 57744		1.00
- Pressure Wash Truck			31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Pm 42' Upper			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
- Test Run			SHOP SUPPLIES		1.00
- Shop Supplies			3994 FUEL FILTER INT 1878042C92		1.00
			AIR FRESHENER		1.00
Parts Charge: 192.74		Labor Charge: 60.00			

Workorder: 848691

Problem: ANNUAL AT ALTEC

Meter Reading: 6236		Labor		Parts	
In Date: 12/31/2008	Close Date: 03/16/2009	Hours	Description	Quantity	
- Annual At Altec		3.20	SHOP SUPPLIES		1.00
- Fm-Altec. Pickup					
- Dielectric By Altec					
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 96.00		Commercial Charge: 660.00	

Workorder: 937924

Problem: PM SERVICE AND RECALL

Meter Reading: 10914		Labor		Parts	
In Date: 05/19/2009	Close Date: 05/22/2009	Hours	Description	Quantity	
- Pm Truck.		14.50	15/40 OIL		30.00
- Pm Upper.			1842639C91 OIL FILTER FRM PH9971 WIX 57744		1.00
- Evaporator Air Filter Clogged Up.Remove Filter & Clean			09997 BRAKE CLEAN		1.00
Out Evaporator Box Of All Debris.Re-Install Filter & Test.			31-22 WIPER BLADES 22" WIPER BLADE		2.00
- To Rechten International & Back To Shop. Wait There For			2506656C1 A/C FILTER		1.00
Recall To Be Completed.			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			3994 FUEL FILTER INT 1878042C92		1.00
Parts Charge: 215.30		Labor Charge: 870.00			

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 938932

Problem: STROBE LIGHT AND HYD. STOP IN BUCKET ARE NOT WORKING

Meter Reading: 12031		Labor		Parts	
In Date: 06/12/2009	Close Date: 06/17/2009	Hours	Description		Quantity
- R&R Rr Strobe Modify Inside Plate To Accept In Stock Bulb.		3.50	SHOP SUPPLIES S30HAC STROBE BULB (USE S30HACP)		1.00 1.00
- R&R Elbow Covers @ Bucket Free Up Emergency Stop					
- Test Run					
- Shop Supplies					
Parts Charge:		44.07	Labor Charge:		210.00

Workorder: 939161

Problem: REPAIR STROBE LIGHT

Meter Reading: 12031		Labor		Parts	
In Date: 06/18/2009	Close Date: 06/23/2009	Hours	Description		Quantity
- Replace New Bulb.		0.50			
Parts Charge:		0.00	Labor Charge:		30.00

Workorder: 944209

Problem: pm service and list

Meter Reading: 16571		Labor		Parts	
In Date: 10/06/2009	Close Date: 11/05/2009	Hours	Description		Quantity
- Pm Service		28.70	SHOP SUPPLIES		1.00
- Replace Strobe Light And Trailer Plug			18410 PINTLE PIN		1.00
- Replace Hitch Safety Pin			OUTLET COVER 2NA15		1.00
- Bucket Pm Service			3994 FUEL FILTER INT 1878042C92		1.00
- Replace 110 Outlet Cover			5404 FEMALE CONNECTOR		1.00
- Replace Bumper Markers Poles			FHEADHAP AMBER STROBE (WHELEN 01-0681978-AHD)		1.00
- Repair Wiring For Left Turn Signal Reseal Winch By Altec			68491001 SIGHT RODS (ALTEC)		1.00
- Scan For Codes With Laptop Send To Dealer			1842639C91 OIL FILTER FRM PH9971 WIX 57744		1.00
- Test Ac System- Ok			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
- Shop To Int Recall			15/40 OIL		30.00
- Shop To Int Recall			CA9346 AIR FILTER LBF LAF9099 WIX 46870		1.00
- Shop To Altec			CLIPS		6.00
- Shop Supplies					
Parts Charge:		480.00	Labor Charge:		1,506.00
			Commercial Charge:		1,635.41

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1000717

Problem: annual at altec

Meter Reading: 19150	Labor	Parts			
In Date: 01/20/2010	Hours	Description	Quantity		
- Annual At Altec	4.70	SHOP SUPPLIES	1.00		
- Dielectric Test At Altec					
- Fm To Altec					
- Replace Iso Grip At Altec					
- Remove Ladder Rack And Seal Holes					
- Shop Supplies					
Parts Charge:	2.00	Labor Charge:	138.00	Commercial Charge:	2,607.16

Workorder: 1002154

Problem: truck stalls

Meter Reading: 20118	Labor	Parts			
In Date: 03/02/2010	Hours	Description	Quantity		
- Check For Codes Replace Coolant Sensor	18.50	15/40 OIL	30.00		
- Pm Service		1842639C91 OIL FILTER FRM PH9971 WIX 57744	1.00		
- Aerial Pm		29526898 TRANS FILTER FRM C9031 WIX 57740XE	1.00		
- Clean Evap.And Box, Replace Cab Filter		3994 FUEL FILTER INT 1878042C92	1.00		
- Service Trans Replace Both Filters		SHOP SUPPLIES	1.00		
- Move Tag To Rear		31-22 WIPER BLADES 22" WIPER BLADE	2.00		
- Test Run		2506656C1 A/C FILTER	1.00		
- Shop Supplies		09997 BRAKE CLEAN	1.00		
		COOLANT LEVEL SENSOR IN RESERVOIR	1.00		
		1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00		
		SYN/ATF TRANS FLUID SYNTHETIC	19.00		
Parts Charge:	337.49	Labor Charge:	1,110.00		

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1006792

Problem: pm service and list

Meter Reading: 24854 In Date: 06/29/2010	Close Date: 07/15/2010	Labor Hours	Description	Parts	Quantity
- Pm Service		19.80	2506656C1 A/C FILTER		1.00
- Aerial Pm Service			WASHER		6.00
- Replace Left Head Light			9007 BULB ASSY		1.00
- Replace Broken Bucket Pivot Covers			PLACARD		1.00
- Alignment Callaghan			PLACARD		1.00
- Fm To Callaghan			CAPSCREW		3.00
- Road Test			PLACARD		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			FREIGHT		1.00
			MACHINE SCREW		3.00
			COVER		1.00
			FREIGHT		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			1842639C91 OIL FILTER FRM PH9971 WIX 57744		1.00
			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
			15/40 OIL		30.00
			3994 FUEL FILTER INT 1878042C92		1.00
			STRAP		1.00
			RETAINER		6.00
			31-22 WIPER BLADES 22" WIPER BLADE		2.00
			NUT		3.00
			FREIGHT		1.00
			COVER		1.00
			STRAP		1.00
Parts Charge:		1,012.98	Labor Charge:	1,044.00	Commercial Charge: 94.80

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1012334

Problem: head light and tires

Meter Reading: 28775		Labor		Parts	
In Date: 11/03/2010	Close Date: 12/10/2010	Hours	Description	Quantity	
- R&R R/R And R/F Tires		9.80	SHOP SUPPLIES	1.00	
- R&R Head Light			11R225RC TIRE RECAPPED	1.00	
- Alignment			9007 BULB ASSY	1.00	
- Fm Callaghan					
- R&R Valve Cover & Icp Sensor					
- Callaghan/ International 2Xs					
- Shop Supplies					
Parts Charge: 166.27		Labor Charge:	252.00	Commercial Charge:	932.40

Workorder: 1014095

Problem: pm service

Meter Reading: 29350		Labor		Parts	
In Date: 12/28/2010	Close Date: 01/04/2011	Hours	Description	Quantity	
- Pm Service		15.50	3994 FUEL FILTER INT 1878042C92	1.00	
- Aerial Pm Service			15/40 OIL	30.00	
- Test Cooling System Tighten Hoses And Fill With Coolant			31-22 WIPER BLADES 22" WIPER BLADE	2.00	
- Adjust Boom Tie Down			2506656C1 A/C FILTER	1.00	
- Test Drive			15/40 OIL	3.00	
- Shop Supplies			CA9346 AIR FILTER LBF LAF9099 WIX 46870	1.00	
			SHOP SUPPLIES	1.00	
			1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00	
			1842639C91 OIL FILTER FRM PH9971 WIX 57744	1.00	
Parts Charge: 217.80		Labor Charge:	930.00		

Workorder: 1101342

Problem: annual at altec

Meter Reading: 30392		Labor		Parts	
In Date: 02/03/2011	Close Date: 02/18/2011	Hours	Description	Quantity	
- Annual At Altec		3.20	SHOP SUPPLIES	1.00	
- Dielectrical Inspection At Altec					
- Fm To Altec					
- Labor For Boom Repair By Altec					
- Shop Supplies					
Parts Charge: 2.00		Labor Charge:	192.00	Commercial Charge:	3,562.49

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1103774

Problem: exhaust light is on

Meter Reading: 32078 In Date: 04/07/2011	Close Date: 04/13/2011	Labor Hours	Description	Parts	Quantity
- Scan For Codes Regen		2.50	SHOP SUPPLIES		1.00
- Clean Evap. And Housing			6984 EVAPOR CLEANER EVAPORATOR CLEANER		1.00
- Shop Supplies			AIR FRESHENER		2.00
Parts Charge:		9.87	Labor Charge:		150.00

Workorder: 1106614

Problem: pm service and ac blows hot in the afternoon

Meter Reading: 34383 In Date: 06/23/2011	Close Date: 06/29/2011	Labor Hours	Description	Parts	Quantity
- Pm Service		18.50	2506656C1 A/C FILTER		1.00
- Check For Leaks Replace Thermsistor Evac And Recharge			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
			1842639C91 OIL FILTER FRM PH9971 WIX 57744		1.00
- Replace Fan Clutch			2606229C91 THERMSISTORS (INTERNATIONAL)		2.00
- Aerial Pm Service			FAN CLUTCH		1.00
- Test Drive			SHOP SUPPLIES		1.00
- Shop Supplies			E8 A/C OIL R134A A/C OIL (TSI)		1.00
			R134A REFRIGERANT		3.00
			31-22 WIPER BLADES 22" WIPER BLADE		2.00
			15/40 OIL		30.00
			3994 FUEL FILTER INT 1878042C92		1.00
Parts Charge:		968.34	Labor Charge:		1,110.00

Workorder: 1107471

Problem: Battery

Meter Reading: 35034 In Date: 07/18/2011	Close Date: 07/20/2011	Labor Hours	Description	Parts	Quantity
- Try To Jump Replace Batteries And Check Charging System		2.50	GROUP 31 STUD BATTERY (ACD 31-900CT)		2.00
- Test Run			SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		277.22	Labor Charge:		150.00

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1110802

Problem: oil / water lights on, head light , bumper marker and LF tire

Meter Reading: 38550		Labor		Parts	
In Date: 10/11/2011	Close Date: 10/18/2011	Hours	Description	Quantity	
-	Replace Bumper Markers	3.00	SHOP SUPPLIES	1.00	
-	Replace Headlight		9007 BULB ASSY	1.00	
-	Test Cooling System Add Coolant		H/DUTY A/FREEZE EXT/LIFE (CAT 238-8648)	1.00	
-	Test Drive		68491001 SIGHT RODS (ALTEC)	1.00	
-	Replace Lf Tire Boulevard				
-	Shop Supplies				
Parts Charge:		81.07	Labor Charge:	180.00	Commercial Charge: 439.38

Workorder: 1111383

Problem: Coolent buzzer

Meter Reading: 38907		Labor		Parts	
In Date: 10/27/2011	Close Date: 11/03/2011	Hours	Description	Quantity	
-	Pm Service	15.00	15/40 OIL	30.00	
-	Aerial Pm		3994 FUEL FILTER INT 1878042C92	1.00	
-	Test Cooling System Repair Leak At Hoses		31-22 WIPER BLADES 22" WIPER BLADE	2.00	
-	Replace 4 Rear Recaps Boulevard		H/DUTY A/FREEZE EXT/LIFE (CAT 238-8648)	1.00	
-	Top Off Rear End		SHOP SUPPLIES	1.00	
-	Test Drive		1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00	
-	Shop Supplies		1842639C91 OIL FILTER FRM PH9971 WIX 57744	1.00	
			CA9346 AIR FILTER LBF LAF9099 WIX 46870	1.00	
			11R225RC TIRE RECAPPED	4.00	
			2506656C1 A/C FILTER	1.00	
			75W140 GEAR LUBE SYNTHETIC (MC XY75W140QL)	1.00	
Parts Charge:		988.09	Labor Charge:	900.00	Commercial Charge: 180.00

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1111962

Problem: low coolant light is on

Meter Reading: 39045		Labor		Parts	
In Date: 11/07/2011	Close Date: 11/30/2011	Hours	Description	Quantity	
-	Replace Two Egr Coolers And Egr Valve	29.50	L/SIDE EGR COOLER	1.00	
-	Pressure Test ,Service Cooling System		"O" RING	1.00	
-	Test Run Before And After Repairs		H/DUTY A/FREEZE EXT/LIFE (CAT 238-8648)	6.00	
-	R&R Floor Covering ,Dog House ,Brake Controller And Trans Tower		R/SIDE EGR COOLER	1.00	
-	Drill Out Broken Exhaust Bolt		GASKET	3.00	
-	Shop Supplies		SHOP SUPPLIES	1.00	
			EGR VALVE	1.00	
Parts Charge: 1,835.90		Labor Charge: 1,770.00			

Workorder: 1201110

Problem: annual at altec

Meter Reading: 41260		Labor		Parts	
In Date: 02/02/2012	Close Date: 02/16/2012	Hours	Description	Quantity	
-	Annual At Altec	3.20	SHOP SUPPLIES	1.00	
-	Dielectrical By Altec				
-	Fm To Altec				
-	Parts				
-	Shop Supplies				
Parts Charge: 2.00		Labor Charge: 192.00		Commercial Charge: 997.06	

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1203858

Problem: pm service

Meter Reading: 43685		Labor		Parts	
In Date: 04/24/2012	Close Date: 05/08/2012	Hours	Description	Quantity	
- Pm Service		16.50	CA9346 AIR FILTER LBF LAF9099 WIX 46870	1.00	
- Aerial Pm			60261 CLEAR LIGHT (GROTE)	1.00	
- Replace Ac Filter And Clean Ac Air Box			31-22 WIPER BLADES 22" WIPER BLADE	2.00	
- Replace Bulbs In Clearance And Tag Lights			1842639C91 OIL FILTER FRM PH9971 WIX 57744	1.00	
- Test Drive			GREASE NLGI 2	1.00	
- Shop Supplies			6984 EVAPOR CLEANER EVAPORATOR CLEANER	1.00	
			15/40 OIL	30.00	
			USED FIREX REFURBED FIRE EXTINGSHERS	1.00	
			3994 FUEL FILTER INT 1878042C92	1.00	
			2506656C1 A/C FILTER	1.00	
			1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00	
			SHOP SUPPLIES	1.00	
Parts Charge:		308.75	Labor Charge:	990.00	

Workorder: 1206319

Problem: towed in warning light / buzzer on

Meter Reading: 45698		Labor		Parts	
In Date: 07/05/2012	Close Date: 07/11/2012	Hours	Description	Quantity	
- Scan And Clear Codes Manually Regen		5.00	KEG HOLDER WATER COOLERS 450870003	1.00	
- Replace Acuator Door Vent Motor			SHOP SUPPLIES	1.00	
- Replace Keg Holder			3542606C1 ACUATOR DOOR VENT	2.00	
- Shop Supplies					
Parts Charge:		161.41	Labor Charge:	300.00	

Workorder: 1206361

Problem: Warning lights on

Meter Reading: 45603		Labor		Parts	
In Date: 07/05/2012	Close Date: 07/06/2012	Hours	Description	Quantity	
- Tow From: Sr 80 West Of Hwy 15 To: He Shop					
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 220.54

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1207739

Problem: no headlights, exhaust light is on and safety hitch pin broke

Meter Reading: 46972	Labor	Parts	
In Date: 08/15/2012	Hours	Description	Quantity
- Replace Both Headlights	4.50	SHOP SUPPLIES	1.00
- Replace Hitch Safety Pin		9007 BULB ASSY	2.00
- Scan For Codes And Regen Dpf		18410 PINTLE PIN	1.00
- Test Run			
- Shop Supplies			
Parts Charge:	16.55	Labor Charge:	270.00

Workorder: 1210252

Problem: pm service and def filter light is on

Meter Reading: 48985	Labor	Parts	
In Date: 10/25/2012	Hours	Description	Quantity
- Pm Service	19.50	3M TM HEADLIGHT LENS	2.00
- Aerial Pm		LED LICENSE KIT	1.00
- Refinish Headlights		BRACKET	1.00
- Replace Tag Light Assy.		CA9346 AIR FILTER LBF	1.00
- Service Power Steering And Change Filter		CABIN AIR FILTER	1.00
- Road Test		15-40 OIL	30.00
- Service Winch		31-22 WIPER BLADES 22	2.00
- Shop Supplies		P1653A HYDR FILTER LB	1.00
		DIELECTRIC OIL BUCKET	8.00
		05088 BRAKE CLEAN	2.00
		1842639C91 OIL FILTER	1.00
		AIR FRESHENER	2.00
		61A P-STEERING FLUID	2.00
		2503221C1 P-STEERING	1.00
		USED FIREX REFURBED F	1.00
		SHOP SUPPLIES	1.00
		1878042C92 FUEL FILTE	1.00
Parts Charge:	558.54	Labor Charge:	1,170.00

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1212308 **Problem:** spot mirror

Meter Reading: 50562	Labor	Parts	
In Date: 12/26/2012	Hours	Description	
Close Date: 12/27/2012		Quantity	
- Replace Driver Side Mirror	1.00	MIRROR GLASS	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge: 70.51	Labor Charge: 60.00		

Workorder: 1300903 **Problem:** annual at altec

Meter Reading: 51532	Labor	Parts	
In Date: 01/25/2013	Hours	Description	
Close Date: 02/21/2013		Quantity	
- Annual At Altec			
- Dielectric Test			
- R/R Covers Boom Tip, Upper Control Linkage, Stop Valve, Dust Cap, Safety Placards, Hyd Cap			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 1,947.31	

Workorder: 1301967 **Problem:** replace rri tire

Meter Reading: 51930	Labor	Parts	
In Date: 02/26/2013	Hours	Description	
Close Date: 03/04/2013		Quantity	
- Replace Rri Cap		11R225RC TIRE RECAPPED	1.00
- Shop Supplies		TIRE DISPOSAL FEE	1.00
		SHOP SUPPLIES	1.00
Parts Charge: 181.89	Labor Charge: 0.00	Commercial Charge: 99.80	

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1303814

Problem: pm service

Meter Reading: 53843		Labor	Parts	
In Date: 04/18/2013	Close Date: 05/01/2013	Hours	Description	Quantity
-	Pm Service	23.30	31-22 WIPER BLADES 22	2.00
-	Aerial Pm		WASHER PUMP	1.00
-	Replace Ac Filter Clean Evap. And Drains		TRUCK BED COATING	1.00
-	Transmission Service		18410 PINTLE PIN	1.00
-	Replace Both Front Bumper Markers		2"X21 BLACK PIPE	10.00
-	Replace Hitch Safety Pin		SHOP SUPPLIES	1.00
-	Replace Wiper Washer Pump		NAPAGOLD OIL FILTER	1.00
-	Replace 110 Outlet Cover		15-40 OIL	30.00
-	Fab/ Weld Cone Holder		ALARM	1.00
-	Replace Back Up Alarm		NAPAGOLD AIR FILTER	1.00
-	Shop Supplies		CABIN AIR FILTER	1.00
			29526898 TRANS FILTER	1.00
			68491001 SIGHT RODS A	1.00
			OUTLET COVER	1.00
			BRAKE CLEANER	2.00
			SYN-ATF TRANS FLUID S	20.00
			NAPAGOLD FUEL FILTER	1.00
			USED FIREX REFURBED F	1.00
			NAPA HYDRAULIC FILTR	1.00
	Parts Charge: 748.49	Labor Charge: 1,398.00		

Workorder: 1304182

Problem: Replace RRI RRO Recapps

Meter Reading: 53692		Labor	Parts	
In Date: 04/26/2013	Close Date: 04/29/2013	Hours	Description	Quantity
-	Boulevard Replace Rri And Outer Caps		11R225RC TIRE RECAPPED	2.00
-	Shop Supplies		TIRE DISPOSAL FEE	2.00
			SHOP SUPPLIES	1.00
	Parts Charge: 356.32	Labor Charge: 0.00	Commercial Charge: 90.00	

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1307212 **Problem:** headlight is out and upper controls cut out

Meter Reading: 55984	Labor	Parts		
In Date: 07/19/2013	Hours	Description	Quantity	
- Replace Headlight	5.20	RETAINER	1.00	
- Test Bucket Controls		HALOGEN CAPSULE	1.00	
- Fm To Altec		SHOP SUPPLIES	1.00	
- Shop Supplies				
Parts Charge:		17.73		
Labor Charge:		312.00		

Workorder: 1307520 **Problem:** Repairs at Altec

Meter Reading: 55887	Labor	Parts		
In Date: 07/29/2013	Hours	Description	Quantity	
- Altec Repairs				
Parts Charge:		0.00		
Labor Charge:		0.00		
		Commercial Charge:	108.00	

Workorder: 1308702 **Problem:** will not run

Meter Reading: 57436	Labor	Parts		
In Date: 08/28/2013	Hours	Description	Quantity	
- Check No Start, Kept Blowing Fues, Had Towed In	13.00	PTO SENSOR	1.00	
- To 25Th And Pinewood		THROTTLE CONTROL BOX	1.00	
- Repair Grounded Wire, Replaced Moduel And Pto Solinode		GROUP 31 STUD DELCO	2.00	
- Replace Batteries		SHOP SUPPLIES	1.00	
- Tested				
- Shop Supplies				
Parts Charge:		1,102.03		
Labor Charge:		780.00		

Workorder: 1308739 **Problem:** Stop Running

Meter Reading: 57288	Labor	Parts		
In Date: 08/28/2013	Hours	Description	Quantity	
- Tow From: Sw Corner Of 25Th Street And Pinewood Ave (Wpb) To: He Shop				
Parts Charge:		0.00		
Labor Charge:		0.00		
		Commercial Charge:	177.66	

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1310940

Problem: pm service, won't start and abs light is on

Meter Reading: 58499		Labor		Parts	
In Date: 10/31/2013	Close Date: 12/02/2013	Hours	Description	Quantity	
-	P.M.	18.00	SHOP SUPPLIES		1.00
-	Jumped Truck Tested Batteries And Charging System		GREASE NLGI 2		4.00
-	R&R Alternator		CLEAN-R-CARB 200Z		1.00
-	P.M. Bucket		NAPAGOLD OIL FILTER		1.00
-	Replaced Pintle Pin		15-40 OIL		30.00
-	Check Abs System		WIPER BLADE		2.00
-	Test Drove		NAPA HYDRAULIC FILTR		1.00
-	Shop Supplies		ALTERNATOR ASSY		1.00
			NAPAGOLD FUEL FILTER		1.00
			PINTLE PIN W/CHAIN		1.00
Parts Charge: 601.17		Labor Charge: 1,080.00			

Workorder: 1311896

Problem: Replace LRO and LF

Meter Reading: 58431		Labor		Parts	
In Date: 11/26/2013	Close Date: 12/09/2013	Hours	Description	Quantity	
-	R&R Lf And Lro Tires		TIRE DISPOSAL FEE		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
			11R225RC TIRE RECAPPED		1.00
Parts Charge: 179.98		Labor Charge: 0.00		Commercial Charge: 575.16	

Workorder: 1400154

Problem: Surpentine belt broke

Meter Reading: 59550		Labor		Parts	
In Date: 01/07/2014	Close Date: 02/12/2014	Hours	Description	Quantity	
-	Install Drive Shaft After Tow	5.20	PINTLE PIN W/CHAIN		3.00
-	Replace Belt And Tensioner		V-RIBBED BELT		1.00
-	To Altec		TENSIONER-HEAVY DUTY		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
Parts Charge: 166.29		Labor Charge: 312.00			

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1400274 **Problem:** Serpentine belt broke
Meter Reading: 59531 **Labor**
In Date: 01/02/2014 **Hours** **Description** **Parts** **Quantity**

- Tow From: Boynton Beach Blvd And El Claire Ranch Rd.
To: He Shop

Parts Charge: 0.00 **Labor Charge:** 0.00 **Commercial Charge:** 177.66

Workorder: 1400368 **Problem:** Annual
Meter Reading: 59531 **Labor**
In Date: 01/13/2014 **Hours** **Description** **Parts** **Quantity**

- Annual
- Dielectric Test
- R/R Safety Decals, Inserts, Boom Strap, Rear Access Step

Parts Charge: 0.00 **Labor Charge:** 0.00 **Commercial Charge:** 1,497.16

Workorder: 1401424 **Problem:** Hyd. Leak
Meter Reading: 60511 **Labor**
In Date: 02/12/2014 **Hours** **Description** **Parts** **Quantity**

- R&R Hydraulic Line Under Truck. Top Off Oil **6.00** HOSE MAKE UP 1.00
- To Mako For Hose DIELECTRIC OIL AW HVI 12.00
- Test Drive SHOP SUPPLIES 1.00
- Replace Cooler Strap WATER COOLER HOLDER 1.00
- Shop Supplies

Parts Charge: 381.74 **Labor Charge:** 360.00

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1404359

Problem: pm/list

Meter Reading: 63287 In Date: 05/05/2014	Close Date: 05/30/2014	Labor Hours	Description	Parts	Quantity
- Pm		19.00	CARTRIDGE AD9		1.00
- Bucket P.M.			WIPER BLADE		2.00
- Test Drive			NAPAGOLD AIR FILTER		1.00
- Service Air Dryer			USED FIRE X REFURBISHED		1.00
- Replace Mud Flap			NAPA HYDRAULIC FILTR		1.00
- Regen			WASHER FL		1.00
- Checked Brakes And Could Not Find Problem			MACS CHAIN CABLE LUBE		1.00
- Shop Supplies			NAPAGOLD OIL FILTER		1.00
			L0152-063 GEAR SHIELD		1.00
			15-40 OIL		33.00
			NAPAGOLD FUEL FILTER		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		282.46	Labor Charge:		1,140.00

Workorder: 1406647

Problem: Flat tire on Outer Rear Passenger

Meter Reading: 64501 In Date: 07/02/2014	Close Date: 07/07/2014	Labor Hours	Description	Parts	Quantity
- Tire Service Sanlefoot Cover Park - Flat Tire On Outer Rear Passenger					
Parts Charge:		0.00	Labor Charge:		0.00
			Commercial Charge:		471.16

Workorder: 1406648

Problem: SERVICE

Meter Reading: 64501 In Date: 07/07/2014	Close Date: 07/07/2014	Labor Hours	Description	Parts	Quantity
- Tire Service Sandlefoot Cover Park And Lyons Rd - Service					
Parts Charge:		0.00	Labor Charge:		0.00
			Commercial Charge:		46.40

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1407847

Problem: list

Meter Reading: 65459		Labor		Parts	
In Date: 08/11/2014	Close Date: 08/21/2014	Hours	Description	Quantity	
-	Replace Headlight, Windshield Wipers, Hitch Pin, And Water Cooler Holder	3.00	SHOP SUPPLIES		1.00
-	Shop Supplies		WIPER BLADE		2.00
			HALOGEN CAPSULE		1.00
			PINTLE PIN W/CHAIN		1.00
			WATER COOLER HOLDER		1.00
Parts Charge: 132.51		Labor Charge: 180.00			

Workorder: 1408866

Problem: air leak

Meter Reading: 65768		Labor		Parts	
In Date: 09/03/2014	Close Date: 09/11/2014	Hours	Description	Quantity	
-	R&R Regulator On Air Tank. Plug Tank To Drive To Shop.	4.50	TUBE-NYLON-BLACK		6.00
-	Replace Airline From Tank		PNEUMATIC VALVE		1.00
-	To Okeehetee Park		SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge: 113.13		Labor Charge: 270.00			

Workorder: 1500708

Problem: Annual

Meter Reading: 70330		Labor		Parts	
In Date: 01/21/2015	Close Date: 02/05/2015	Hours	Description	Quantity	
-	Annual				
-	Dielectric Inspection				
-	R/R Upper& Lower Boom, Start/Stop Secondary Tow, Dust Caps, Quick Disconnects, Lower Boom Rest				
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 3,987.97	

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1500709

Problem: PM / List

Meter Reading: 70411		Labor	Parts	
In Date: 01/21/2015	Close Date: 02/25/2015	Hours	Description	Quantity
- Pm		26.20	SEAT R AND R	1.00
- To Altec 2Xs			NAPAGOLD OIL FILTER	1.00
- Bucket Pm			FUEL FIL	1.00
- Ck. Codes, Replaced Map, And Icp Regulator			WASHER FL	1.00
- Repair Marker Lamps			NAPA HYDRAULIC FILTR	1.00
- Park Brake Mount Replace			LAMP	1.00
- Seat Upolster			CLEARANCE LIGHT	1.00
- Replace Mumper Guards			68491001 SIGHT RODS A	1.00
- Test Drive			INJECTOR PRESSURE REG	1.00
- Shop Supplies			WIPER BLADE	2.00
			PANEL	1.00
			MANIFOLD SENSOR	1.00
			15-40 OIL	33.00
			SHOP SUPPLIES	1.00
	Parts Charge: 1,368.83	Labor Charge: 1,572.00		

Workorder: 1502156

Problem: RF tire

Meter Reading: 70491		Labor	Parts	
In Date: 02/27/2015	Close Date: 03/03/2015	Hours	Description	Quantity
- Rf Tire				
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 494.20	

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1505294

Problem: wont run/AC blows hot

Meter Reading: 72767 In Date: 05/26/2015	Close Date: 08/11/2015	Labor Hours	Description	Parts	Quantity
- Pressure Test Cooling System.. Repair Leaks Add Coolant		83.50	GROUP 31 STUD DELCO		2.00
			LED LICENSE KIT		1.00
- Check Codes. R&R Icp Sensor, Valve Cover, Dog House, High Pressure Oil Manifold And Pump. Test Drive			OIL MANIFOLD		1.00
			PRESSURE PUMP		1.00
- Check Ac. Replace Compressor, Dryer, Transducer, Thermistors, Evac And Charge System			SEAL KIT		1.00
			LOW PRESSURE PUMP		1.00
- Replace Serp Belt			GASKET		1.00
- Test Batteries. R&R Batteries			FORD RED ANTIFREEZE		1.00
- Check Starter/Wiring. Replace Starter			FITTINGS		1.00
- Replace Tag And Light. Marker Light On Cab			WD40 16OZ		1.00
			BRAKE CLEANER		2.00
- Pm			15-40 OIL		30.00
- Pm Upper			CABLE TIE		1.00
- Shop Supplies			NAPAGOLD OIL FILTER		1.00
			ICP SENSOR		1.00
			WIPER BLADE		2.00
			A/C SEAL		2.00
			FUEL FIL		1.00
			3634621 SEAL TABLETS		1.00
			HOSE KIT		1.00
			MEI		2.00
			CLEARANCE LIGHT		1.00
			EXPANSION ALVE		1.00
			SHOP SUPPLIES		1.00
			A/C SEAL		4.00
			V-RIBBED BELT		1.00
			STARTER MOTOR		1.00
			A/C COMPRESSOR		1.00
			WASHER FLUID CONCENTR		1.00
			A/C ACCUMULATOR		1.00
			E8 A/C OIL UNIV W DYE		7.00
			SWITCH		1.00
			NAPA HYDRAULIC FILTR		1.00
			E8 A/C OIL UNIV W DYE		8.00
			NAPA CABIN AIR FILTER		1.00
			R134A FREON		3.00

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Parts Charge: 8,220.09 **Labor Charge:** 5,010.00

Workorder: 1509938

Problem: RR inner flat

Meter Reading: 74490

Labor

Parts

In Date: 09/29/2015

Close Date: 09/30/2015

Hours

Description

Quantity

- Tire Service Us1 & Access Road Across From Fpl - Rr Inner Flat

Parts Charge: 0.00 **Labor Charge:** 0.00 **Commercial Charge:** 46.40

Workorder: 1509939

Problem: mount/dismount

Meter Reading: 74490

Labor

Parts

In Date: 09/30/2015

Close Date: 09/30/2015

Hours

Description

Quantity

- Tire Service Us1 And Access Rd - Mount/Dismount

Parts Charge: 0.00 **Labor Charge:** 0.00 **Commercial Charge:** 53.40

Workorder: 1510101

Problem: Head Light

Meter Reading: 74658

Labor

Parts

In Date: 10/06/2015

Close Date: 10/07/2015

Hours

Description

Quantity

- Wipers **1.00** WIPER BLADE 2.00
- Head Light Bulb HALOGEN CAPSULE 1.00
- Shop Supplies SHOP SUPPLIES 1.00

Parts Charge: 16.01 **Labor Charge:** 60.00

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1600983

Problem: PM - shuts off

Meter Reading: 77541 In Date: 01/28/2016	Close Date: 02/08/2016	Labor Hours	Description	Parts	Quantity
- Pm		23.70	NAPA CABIN AIR FILTER		1.00
- Replace Water Pump And Coolent			CARTRIDGE AD9		1.00
- Replace Dryer			NAPA HYDRAULIC FILTR		1.00
- Bucket Pm			15-40 OIL		30.00
- Pull Codes 3334,2175,2784,2783,2702			5% MOLY REQ'D		1.00
- To Altec 2Xs			BRAKE CLEANER		2.00
- Shop Supplies			NAPAGOLD OIL FILTER		1.00
			NAPAGOLD AIR FILTER		1.00
			Water pump kit		1.00
			FUEL FIL		1.00
			H DUTY ANTI-FREEZE		5.00
			22" WIPER BLADE		2.00
			SHOP SUPPLIES		1.00
	Parts Charge: 669.00	Labor Charge: 1,422.00			

Workorder: 1601277

Problem: LRIO Tires

Meter Reading: 77541 In Date: 02/05/2016	Close Date: 03/10/2016	Labor Hours	Description	Parts	Quantity
- Lrio Tires					
- Dielectric Inspection					
- Annual Inspection					
- R/R Lower Boom Inserts, Hydraulic Stop Valve, Insert Joints					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 2,355.96		

Workorder: 1602276

Problem: Tires

Meter Reading: 78215 In Date: 03/03/2016	Close Date: 03/03/2016	Labor Hours	Description	Parts	Quantity
- Tire Service Boca Raton (Kimberly And Sr 7) - Tires					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 484.31		

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1602277

Problem: Emergency Service

Meter Reading: 78215

Labor

Parts

In Date: 03/03/2016

Close Date: 03/03/2016

Hours

Description

Quantity

- Tire Service Kimberly And Sr 7 - Emergency Service

Parts Charge: 0.00

Labor Charge: 0.00

Commercial Charge: 51.56

Workorder: 1604145

Problem: Spot mirror

Meter Reading: 79936

Labor

Parts

In Date: 04/20/2016

Close Date: 04/22/2016

Hours

Description

Quantity

- Replace Mirror

1.00 SHOP SUPPLIES

1.00

- Shop Supplies

MIRROR GLASS

1.00

Parts Charge: 82.94

Labor Charge: 60.00

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1607029

Problem: PM

Meter Reading: 82454	Labor	Parts	Quantity
In Date: 07/12/2016	Hours	Description	
- Pm	39.00	HERCULNR	1.00
- Pm Upper		15-40 OIL	30.00
- Check Engine Light. 1211-Eop Out Of Range		NAPAGOLD OIL FILTER	1.00
- Replace Oil Temp Sensor		NAPAGOLD AIR FILTER	1.00
- Replace Drier, Expansion Valve, Condenser, Evac And Charge		WASHER FLUID CONCENTR	1.00
- Pintle Pin		PINTLE PIN W/CLIP	1.00
- Retape Upper Boom Rest Area		NAPA CABIN AIR FILTER	1.00
- Fab Cone Holder		a/c condensor	1.00
- Replace Rear Brakes And Axle Seals		NAPA HYDRAULIC FILTR	1.00
- To Rectien 2Xs		A/C DRYER	1.00
- Shop Supplies		FUEL FIL	1.00
		TEMP SENSOR	1.00
		USED FIRE X REFURBISHED	1.00
		BRAKE SHOE KITS- NEW	2.00
		BRAKE DRUM	2.00
		OIL PRESSURE SENSOR	1.00
		AXLE GASKET	2.00
		WIPER BLADE	2.00
		CABIN AIR FILTER	1.00
		LAMP	1.00
		EXPANSION ALVE	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	2,013.65	Labor Charge:	2,340.00

Workorder: 1607891

Problem: Tires

Meter Reading: 82370	Labor	Parts	Quantity
In Date: 08/02/2016	Hours	Description	
- Tires			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	1,021.38

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1608056	Problem: Hard Start			
Meter Reading: 82370		Labor	Parts	
In Date: 08/04/2016	Close Date: 08/08/2016	Hours	Description	Quantity
- Replace Injectors				
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 3,967.90	

Workorder: 1701400	Problem: 1 - Key(s) issued			
Meter Reading: 88361		Labor	Parts	
In Date: 02/09/2017	Close Date: 02/09/2017	Hours	Description	Quantity
- 1 - Key(S) Issued		0.30	DUPLICATE VEHICLE KEYS	1.00
	Parts Charge: 3.00	Labor Charge: 18.00		

Workorder: 1701465	Problem: PM			
Meter Reading: 88427		Labor	Parts	
In Date: 02/13/2017	Close Date: 03/10/2017	Hours	Description	Quantity
- Pm		28.00	15-40 OIL	30.00
- Pm Bucket			USED FIRE X REFURBISHED	1.00
- Ck Engine Light Pulled Codes 2549-8321-12			NON-CHLOR BRAKE CLNR	3.00
- 1 Strobe & 1 Marker Light Repair			STROBE LIGHT	1.00
- Service Ac			SWITCH	1.00
- Replace Turbo And Repaired Wiring Harness			NAPAGOLD AIR FILTER	1.00
- Washer Motor And Washer Switch			FUEL FIL	1.00
- Road Test			WIPER BLADE	2.00
- Shop Supplies			TURBO KIT	1.00
			BULB	1.00
			NAPAGOLD OIL FILTER	1.00
			NAPA CABIN AIR FILTER	1.00
			CABIN AIR FILTER	1.00
			wiper motor	1.00
			WASHER FLUID CONCENTR	1.00
			NAPA HYDRAULIC FILTR	1.00
			WASHER PUMP	1.00
			SHOP SUPPLIES	1.00
	Parts Charge: 5,459.99	Labor Charge: 1,680.00		

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1703087		Problem: Annual			
Meter Reading: 89476		Labor		Parts	
In Date: 03/28/2017	Close Date: 05/10/2017	Hours	Description		Quantity
<ul style="list-style-type: none"> - Annual - Dielectric Test - R/R Running Light, Ladder Rack, Rotation Bearing & Bolts, Rivets/Boom Tip, Placards, Perform Structural Load Test 					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	4,874.62
Workorder: 1704382		Problem: to altec			
Meter Reading: 89476		Labor		Parts	
In Date: 05/01/2017	Close Date: 05/02/2017	Hours	Description		Quantity
<ul style="list-style-type: none"> - To Altec 2Xs - Shop Supplies 					
Parts Charge:	2.00	Labor Charge:	240.00		
Workorder: 1706290		Problem: air leak/ engine noise			
Meter Reading: 91253		Labor		Parts	
In Date: 06/26/2017	Close Date: 07/17/2017	Hours	Description		Quantity
<ul style="list-style-type: none"> - To Altec - To Tangerine Blvd - Stow Boom Jump Dc Pump - Replace Orings At Fittings At Air Tank - Test Run - Shop Supplies 					
Parts Charge:	2.00	Labor Charge:	330.00		
Workorder: 1706465		Problem: boom wont fly			
Meter Reading: 91169		Labor		Parts	
In Date: 06/29/2017	Close Date: 07/24/2017	Hours	Description		Quantity
<ul style="list-style-type: none"> - Repair Altec 					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	529.24

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1707715

Problem: pm/list

Meter Reading: 91761	Labor	Parts	Quantity
In Date: 08/08/2017	Hours	Description	Quantity
- Pm	32.50	NAPA HYDRAULIC FILTR	1.00
- Pm Bucket		PUSH PULL SWITCH	1.00
- Replace Four Strobes And Rewire System For New Light Assy		STROBE LP LED	2.00
		ELECTRICAL TAPE	1.00
- Repair Air Leak At Compressor And Replace Air Dryer		CLR RTV SILCN SEALANT	1.00
- A/C Service And Clean Evaporator Box		NAPAGOLD OIL FILTER	1.00
- Adjust Front Brakes		WIPER BLADE	2.00
- Pto Inop Replace Auto Reset Circuit Braker Fuse,Check Connexion At Control Box Under Driver Seat		caulk gun	1.00
		NON-CHLOR BRAKE CLNR	1.00
- Retape Boom Protector		PINTLE PIN W/CLIP	1.00
- Road Test		FUSE-ATC-LP CB 30A	1.00
- Shop Supplies		CABIN AIR FILTER	1.00
		NAPA CABIN AIR FILTER	1.00
		sealer	1.00
		LED	2.00
		STROBE LIGHT	2.00
		EVAP ODOR ELINITATOR	1.00
		USED FIRE X REFURBISHED	1.00
		SHOP SUPPLIES	1.00
		NAPAGOLD AIR FILTER	1.00
		CARTRIDGE AD9	1.00
		FUEL FIL	1.00
		15-40 OIL	30.00
		WASHER FLUID CONCENTR	1.00
Parts Charge:	1,780.39	Labor Charge:	1,950.00

Workorder: 1708953

Problem: boom inop/list

Meter Reading: 92278	Labor	Parts	Quantity
In Date: 09/18/2017	Hours	Description	Quantity
- Check Strobes Sent To Auction	1.50	SHOP SUPPLIES	1.00
- Check Boom Sent To Auction			
- Check Headlight Sent To Auction			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	90.00

1/2/2018
10:15:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172271 2008 INTERNATIONAL 4300 Bucket Truck, 42 Ft. W/Utility Body

Workorder: 1709703

Problem: altec service

Meter Reading: 92147	Labor	Parts	
In Date: 10/04/2017	Hours		Quantity
- Altec Service			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	235.20

Workorder: 1712116

Problem: Transition Prep Charge

Meter Reading: 92278	Labor	Parts	
In Date: 12/11/2017	Hours		Quantity
- Transition Prep Charge	2.00		
Parts Charge:	0.00	Labor Charge:	0.00

Total Parts Charges:	32,759.44	Total Labor Charges:	34,584.00	Total Comm. Charges:	34,621.69
----------------------	------------------	----------------------	------------------	----------------------	------------------