

1/2/2018
11:57:56AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10151763 2003 TOWMASTER T10T Trailer, Dual Axle, Tilt

| | | | | | |
|---|-------------------------------|---|----------------------------------|--------------|-----------------|
| Workorder: 343025 | | Problem: WEIGH TRAILER | | | |
| Meter Reading: 0 | | Labor | | Parts | |
| In Date: 06/25/2003 | Close Date: 06/30/2003 | Hours | Description | | Quantity |
| <hr/> | | | | | |
| - Travel To Weigh Station | | 1.50 | SHOP SUPPLIES | | 1.00 |
| - Weigh Trailor | | | | | |
| - Shop Supplies | | | | | |
| Parts Charge: | | 2.00 | Labor Charge: | | 75.00 |
| | | | Commercial Charge: | | 6.00 |
| | | | | | |
| Workorder: 344346 | | Problem: PRE-DELIVERY INSPECTION | | | |
| Meter Reading: 0 | | Labor | | Parts | |
| In Date: 07/18/2003 | Close Date: 07/18/2003 | Hours | Description | | Quantity |
| <hr/> | | | | | |
| - Pre-Delivery Inspection | | 2.00 | | | |
| Parts Charge: | | 0.00 | Labor Charge: | | 100.00 |
| | | | | | |
| Workorder: 344426 | | Problem: TRANSPORT TRAILER | | | |
| Meter Reading: 0 | | Labor | | Parts | |
| In Date: 07/21/2003 | Close Date: 07/21/2003 | Hours | Description | | Quantity |
| <hr/> | | | | | |
| - Transport Trailer | | 3.00 | SHOP SUPPLIES | | 1.00 |
| - Fabricate And Install Tie Down Chains | | | | | |
| - Shop Supplies | | | | | |
| Parts Charge: | | 2.00 | Labor Charge: | | 150.00 |
| | | | | | |
| Workorder: 344452 | | Problem: TIE DOWNS | | | |
| Meter Reading: 0 | | Labor | | Parts | |
| In Date: 07/21/2003 | Close Date: 08/28/2003 | Hours | Description | | Quantity |
| <hr/> | | | | | |
| - Replace Coupler Install Tie Downs | | 3.00 | 2845 3/8" CHAIN HOOK | | 3.00 |
| - Welding Supplies | | | 678143 CHAIN 3/8" CHAIN (CERTEX) | | 40.00 |
| | | | | | 1.00 |
| | | | BOLT 1A5405 | | 2.00 |
| | | | 3/8 BINDER 4ZW94 | | 2.00 |
| | | | LUNETTE EYE 18128 | | 1.00 |
| | | | 2863 SHACKLE 3/8 | | 4.00 |
| Parts Charge: | | 322.11 | Labor Charge: | | 150.00 |

1/2/2018
11:57:56AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10151763 2003 TOWMASTER T10T Trailer, Dual Axle, Tilt

Workorder: 344549

Problem: MINOR WELD REPAIR OR MACHINING.

| Meter Reading: 0 | Labor | Parts | |
|-----------------------------------|-------|----------------------|----------|
| In Date: 07/22/2003 | Hours | Description | Quantity |
| - Minor Weld Repair Or Machining. | 1.00 | SHOP SUPPLIES | 1.00 |
| - Welding Supplies | | | |
| Parts Charge: | 2.00 | Labor Charge: | 50.00 |

Workorder: 345875

Problem: LOWER HITCH

| Meter Reading: 0 | Labor | Parts | |
|--|-------|---------------------------------------|----------|
| In Date: 08/13/2003 | Hours | Description | Quantity |
| - Install Towing Coupling | 11.50 | 765-1589 BLACK SILICONE | 2.00 |
| - Fuse Replace And Repair Harness Remove Compete | | 4054 CHARGER | 1.00 |
| - Harness And Replace | | GROUP U1 BATTERY (ACD U1240W) | 1.00 |
| - Battery Replace | | SHOP SUPPLIES | 1.00 |
| - Install New Charger In Trailer | | 8616-100 TRAILER WIRE 6 WIRE 14 GAUGE | 6.00 |
| - Shop Supplies | | MAX30 30AMP MAXI FUSE | 1.00 |
| Parts Charge: | 70.01 | Labor Charge: | 575.00 |

Workorder: 346612

Problem: MINOR WELD REPAIR OR MACHINING.

| Meter Reading: 0 | Labor | Parts | |
|-----------------------------------|-------|----------------------|----------|
| In Date: 08/25/2003 | Hours | Description | Quantity |
| - Minor Weld Repair Or Machining. | 1.00 | SHOP SUPPLIES | 1.00 |
| - Welding Supplies | | | |
| Parts Charge: | 2.00 | Labor Charge: | 50.00 |

Workorder: 352826

Problem: TRAILER BRAKES LOCKING UP

| Meter Reading: 0 | Labor | Parts | |
|---|-------|----------------------|----------|
| In Date: 12/05/2003 | Hours | Description | Quantity |
| - Repair Short In 6-Way Plug Ck Sys For Shorts. | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: | 2.00 | Labor Charge: | 50.00 |

1/2/2018
11:57:56AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10151763 2003 TOWMASTER T10T Trailer, Dual Axle, Tilt

Workorder: 459257 **Problem:** FLAT TIRE

| Meter Reading: 0 | Labor | Parts | |
|---------------------------|-------|----------------------------|----------|
| In Date: 10/18/2004 | Hours | Description | Quantity |
| - Tire Repair | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: 2.00 | | Labor Charge: 50.00 | |

Workorder: 464622 **Problem:** PM SERVICE

| Meter Reading: 0 | Labor | Parts | |
|---------------------------|-------|-----------------------------|----------|
| In Date: 12/15/2004 | Hours | Description | Quantity |
| - Pm Service | 6.50 | 42385 SEAL | 4.00 |
| - Repair Wiring | | SHOP SUPPLIES | 1.00 |
| - Pressure Clean | | | |
| - Shop Supplies | | | |
| Parts Charge: 9.66 | | Labor Charge: 325.00 | |

Workorder: 465260 **Problem:** LIGHTS

| Meter Reading: 0 | Labor | Parts | |
|---|-------|---------------------------------|----------|
| In Date: 12/22/2004 | Hours | Description | Quantity |
| - Repair Rh Lights.Replae Wire Harness Rm.Replace Rear Lamps. | 1.00 | 44202R TAIL LIGHT 4" RED 42 LED | 2.00 |
| | | 94706 ADAPTER 3 PRONG | 2.00 |
| - Shop Supplies | | SHOP SUPPLIES | 1.00 |
| Parts Charge: 85.94 | | Labor Charge: 50.00 | |

Workorder: 648002 **Problem:** R/F TIRE FLAT

| Meter Reading: 0 | Labor | Parts | |
|---------------------------|-------|----------------------------|----------|
| In Date: 10/31/2006 | Hours | Description | Quantity |
| - Repair Tire As Needed | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: 2.00 | | Labor Charge: 55.00 | |

1/2/2018
11:57:56AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10151763 2003 TOWMASTER T10T Trailer, Dual Axle, Tilt

Workorder: 648621

Problem: REPAIR LIGHTS ON TRAILER.

| Meter Reading: 0 | | Labor | | Parts | |
|----------------------------|---|----------------------------|---------------------------------|-------|----------|
| In Date: 11/14/2006 | Close Date: 11/17/2006 | Hours | Description | | Quantity |
| - | Ck And Repair Connection At Trk & Replace Left Tail Light | 1.50 | 44202R TAIL LIGHT 4" RED 42 LED | | -1.00 |
| - | Shop Supplies | | 44202R TAIL LIGHT 4" RED 42 LED | | 1.00 |
| | | | 44202R TAIL LIGHT 4" RED 42 LED | | 1.00 |
| | | | SHOP SUPPLIES | | 1.00 |
| Parts Charge: 43.48 | | Labor Charge: 82.50 | | | |

Workorder: 649356

Problem: FLAT TIRE

| Meter Reading: 0 | | Labor | | Parts | |
|---------------------------|------------------------|----------------------------|---------------|-------|----------|
| In Date: 12/01/2006 | Close Date: 12/01/2006 | Hours | Description | | Quantity |
| - | Repair Tire | 1.00 | SHOP SUPPLIES | | 1.00 |
| - | Shop Supplies | | | | |
| Parts Charge: 2.00 | | Labor Charge: 55.00 | | | |

Workorder: 649581

Problem: PM

| Meter Reading: 0 | | Labor | | Parts | |
|-----------------------------|---|-----------------------------|--------------------------------|-------|----------|
| In Date: 12/06/2006 | Close Date: 12/11/2006 | Hours | Description | | Quantity |
| - | Pm 2 Axle Trailer | 8.00 | 42385 SEAL | | 4.00 |
| - | Replace 4 Tires | | 762173406 225/75R15 MARATHON D | | 4.00 |
| - | Clean Terminals And Charge And Ck Battery-Repair Wiring Replace Battery | | GROUP U1 BATTERY (ACD U1240W) | | 1.00 |
| - | Parts Onlyinals And Charge And Ck Battery-Repair Wiring Replace Battery | | SHOP SUPPLIES | | 1.00 |
| - | Shop Supplies | | 4086 SWITCH CABLE | | 1.00 |
| Parts Charge: 362.56 | | Labor Charge: 110.00 | | | |

Workorder: 737691

Problem: R/R WHEEL OR BEARING LOOSE

| Meter Reading: 0 | | Labor | | Parts | |
|---------------------------|--|----------------------------|---------------|-------|----------|
| In Date: 04/26/2007 | Close Date: 04/27/2007 | Hours | Description | | Quantity |
| - | R/R Rt Rr Hub Inspect Bearing And Seal | 1.00 | SHOP SUPPLIES | | 1.00 |
| - | Shop Supplies | | | | |
| Parts Charge: 2.00 | | Labor Charge: 55.00 | | | |

1/2/2018
11:57:56AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10151763 2003 TOWMASTER T10T Trailer, Dual Axle, Tilt

Workorder: 741433 **Problem:** TIRESOLES OF BROWARD INC

| Meter Reading: 0 | Labor | Parts | Quantity |
|----------------------------|---------------------------|---------------------------------|----------|
| In Date: 07/11/2007 | Hours | Description | |
| - Tiresoles Of Broward Inc | | | |
| Parts Charge: 0.00 | Labor Charge: 0.00 | Commercial Charge: 60.00 | |

Workorder: 743694 **Problem:** TIRESOLES OF BROWARD INC

| Meter Reading: 0 | Labor | Parts | Quantity |
|----------------------------|---------------------------|---------------------------------|----------|
| In Date: 08/02/2007 | Hours | Description | |
| - Tiresoles Of Broward Inc | | | |
| Parts Charge: 0.00 | Labor Charge: 0.00 | Commercial Charge: 83.10 | |

Workorder: 743695 **Problem:** TIRESOLES OF BROWARD INC

| Meter Reading: 0 | Labor | Parts | Quantity |
|----------------------------|---------------------------|---------------------------------|----------|
| In Date: 08/01/2007 | Hours | Description | |
| - Tiresoles Of Broward Inc | | | |
| Parts Charge: 0.00 | Labor Charge: 0.00 | Commercial Charge: 54.00 | |

Workorder: 744266 **Problem:** HOOK MISSING ON CHAIN

| Meter Reading: 0 | Labor | Parts | Quantity |
|--------------------------------|----------------------------|----------------------|----------|
| In Date: 09/18/2007 | Hours | Description | |
| - Replace Hold Down Chain Hook | 0.50 | 2845 3/8" CHAIN HOOK | 1.00 |
| Parts Charge: 6.39 | Labor Charge: 27.50 | | |

Workorder: 744569 **Problem:** LOW TIRE

| Meter Reading: 0 | Labor | Parts | Quantity |
|---------------------------|----------------------------|---------------|----------|
| In Date: 09/24/2007 | Hours | Description | |
| - Repair Tire | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: 2.00 | Labor Charge: 55.00 | | |

1/2/2018
11:57:56AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10151763 2003 TOWMASTER T10T Trailer, Dual Axle, Tilt

Workorder: 747940

Problem: BREAKAWAY CABLE MISSING.

| Meter Reading: 0 | Labor | Parts | Quantity |
|---|-------|-----------------------|----------|
| In Date: 11/30/2007 | Hours | Description | |
| - Replace Breakaway Switch Charge Battery | 1.50 | BREAKAWAY SWITCH 4098 | 1.00 |
| - Test Run | | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: | 13.34 | Labor Charge: | 30.00 |

Workorder: 748505

Problem: REPAIR TIRE

| Meter Reading: 0 | Labor | Parts | Quantity |
|----------------------|-------|----------------------|----------|
| In Date: 12/12/2007 | Hours | Description | |
| - Repair Tire | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: | 2.00 | Labor Charge: | 60.00 |

Workorder: 835503

Problem: FLAT TIRE

| Meter Reading: 0 | Labor | Parts | Quantity |
|----------------------|-------|--------------------------------|----------|
| In Date: 03/13/2008 | Hours | Description | |
| - Replace Tire | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | 762173406 225/75R15 MARATHON D | 1.00 |
| Parts Charge: | 82.69 | Labor Charge: | 60.00 |

Workorder: 835945

Problem: PM TRAILER

| Meter Reading: 0 | Labor | Parts | Quantity |
|---|--------|--------------------------------|----------|
| In Date: 03/24/2008 | Hours | Description | |
| - Pm 2 Axle Trailer | 6.50 | SHOP SUPPLIES | 1.00 |
| - Replace 2 Tires Rt Side | | BRAKE KIT ASSY | 1.00 |
| - Nitro 2 Tires Left Side | | 42385 SEAL | 4.00 |
| - Replace Brake Shoes And Adj. Left Frt | | TR416 VALVE STEM | 2.00 |
| - Shop Supplies | | 762173406 225/75R15 MARATHON D | 2.00 |
| Parts Charge: | 220.06 | Labor Charge: | 120.00 |

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10151763 2003 TOWMASTER T10T Trailer, Dual Axle, Tilt

| | | | | | |
|------------------------------------|-------------------------------|--|--------------------|--------------|-----------------|
| Workorder: 838879 | | Problem: FLAT TIRE | | | |
| Meter Reading: 0 | | Labor | | Parts | |
| In Date: 05/22/2008 | Close Date: 05/27/2008 | Hours | Description | | Quantity |
| <hr/> | | | | | |
| - Repair R/R Tire | | 1.00 | SHOP SUPPLIES | | 1.00 |
| - Shop Supplies | | | | | |
| | Parts Charge: 2.00 | Labor Charge: | 60.00 | | |
| | | | | | |
| Workorder: 842076 | | Problem: CHECK ALL TIRES AND AIR PRESSURE | | | |
| Meter Reading: 0 | | Labor | | Parts | |
| In Date: 07/29/2008 | Close Date: 08/04/2008 | Hours | Description | | Quantity |
| <hr/> | | | | | |
| - Check All Tires For Air Pressure | | 1.00 | SHOP SUPPLIES | | 1.00 |
| - Shop Supplies | | | | | |
| | Parts Charge: 2.00 | Labor Charge: | 60.00 | | |
| | | | | | |
| Workorder: 842662 | | Problem: REPAIR R/R TIRE | | | |
| Meter Reading: 0 | | Labor | | Parts | |
| In Date: 08/12/2008 | Close Date: 08/14/2008 | Hours | Description | | Quantity |
| <hr/> | | | | | |
| - Repair Tir Per K. Bell | | 1.00 | SHOP SUPPLIES | | 1.00 |
| - Shop Supplies | | | | | |
| | Parts Charge: 2.00 | Labor Charge: | 60.00 | | |
| | | | | | |
| Workorder: 844730 | | Problem: FLAT TIRE | | | |
| Meter Reading: 0 | | Labor | | Parts | |
| In Date: 09/25/2008 | Close Date: 09/29/2008 | Hours | Description | | Quantity |
| <hr/> | | | | | |
| - Repair Left Frt Tire | | 1.00 | SHOP SUPPLIES | | 1.00 |
| - Shop Supplies | | | | | |
| | Parts Charge: 2.00 | Labor Charge: | 60.00 | | |

1/2/2018
11:57:56AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10151763 2003 TOWMASTER T10T Trailer, Dual Axle, Tilt

Workorder: 934685

Problem: PM SERVICE, REAR BRAKES LOCK UP

| Meter Reading: 0 | Labor | Parts | |
|--|-------|---|----------|
| In Date: 03/03/2009 | Hours | Description | Quantity |
| - Pm Service | 14.00 | 42385 SEAL | 4.00 |
| - Replace R/Front Marker Light Repair Wiring | | 10205Y MARKER LIGHT 2.5" YELLOW GROTE 45813 | 1.00 |
| - Replaced L/Rear Tire And Renitro | | TIRE DISPOSAL FEE | 1.00 |
| - Replace 4 Deck Boards And Drill New Holes, Resecure Several Other Boards | | SHOP SUPPLIES | 1.00 |
| - Travel Time To Home Depot To Pick Up Lumber | | 2X6-8 PRESSURE WOOD | 4.00 |
| - Shop Supplies | | 762173406 225/75R15 MARATHON D | 1.00 |
| Parts Charge: 124.57 | | Labor Charge: 780.00 | |

Workorder: 936458

Problem: LEFT TIRE FLAT

| Meter Reading: 0 | Labor | Parts | |
|---------------------------|-------|----------------------------|----------|
| In Date: 04/14/2009 | Hours | Description | Quantity |
| - Tire Repair | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: 2.00 | | Labor Charge: 60.00 | |

Workorder: 942599

Problem: LOW TIRE ON L/R

| Meter Reading: 0 | Labor | Parts | |
|---|-------|----------------------------|----------|
| In Date: 08/27/2009 | Hours | Description | Quantity |
| - Repair Tire, Inflate 3 Other Tires To Proper Pressure | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: 2.00 | | Labor Charge: 60.00 | |

1/2/2018
11:57:56AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10151763 2003 TOWMASTER T10T Trailer, Dual Axle, Tilt

Workorder: 1002845 **Problem:** pm/e..brake cable / lights / tires / see request

| Meter Reading: 0 | Labor | Parts | | |
|------------------------------|-------|--------------------------------|----------|--|
| In Date: 03/19/2010 | Hours | Description | Quantity | |
| - Pm Service | 7.00 | 42385 SEAL | 4.00 | |
| - Replace Trailer Plug | | 004098 BREAKAWAY SWITCH | 1.00 | |
| - Replace Brakeaway Switch | | 762173406 225/75R15 MARATHON D | 2.00 | |
| - Replaced 2 Tires And Nitro | | SHOP SUPPLIES | 1.00 | |
| - Shop Supplies | | TIRE DISPOSAL FEE | 2.00 | |
| | | 755-5046 MALE CONNECTOR | 1.00 | |
| Parts Charge: 220.31 | | Labor Charge: 420.00 | | |

Workorder: 1104609 **Problem:** pm service

| Meter Reading: 0 | Labor | Parts | | |
|-------------------------------------|-------|---------------------------------|----------|--|
| In Date: 04/29/2011 | Hours | Description | Quantity | |
| - Pm Trailer Tandem Axle | 15.50 | 2X12-16 WOOD PLANKS | 6.00 | |
| - Re-Deck Trailer | | 5/16-18X3 TORX DECK SCREW | 100.00 | |
| - Replace Rt Rear Tail Lites | | GROUP U1 BATTERY (ACD U1240W) | 1.00 | |
| - Replace Breakaway Battery | | 42385 SEAL | 4.00 | |
| - Travel To Home Depot For Supplies | | SHOP SUPPLIES | 1.00 | |
| - Shop Supplies | | 44202R TAIL LIGHT 4" RED 42 LED | 1.00 | |
| Parts Charge: 262.31 | | Labor Charge: 930.00 | | |

Workorder: 1104926 **Problem:** check tires

| Meter Reading: 0 | Labor | Parts | | |
|---------------------------|-------|----------------------------|----------|--|
| In Date: 05/10/2011 | Hours | Description | Quantity | |
| - Repair Left Rear Tire | 1.00 | SHOP SUPPLIES | 1.00 | |
| - Shop Supplies | | | | |
| Parts Charge: 2.00 | | Labor Charge: 60.00 | | |

Workorder: 1109223 **Problem:** R&R left rear tire

| Meter Reading: 0 | Labor | Parts | | |
|---------------------------|-------|---------------------------|----------------------------------|--|
| In Date: 08/30/2011 | Hours | Description | Quantity | |
| - R&R L/R Tire | | | | |
| Parts Charge: 0.00 | | Labor Charge: 0.00 | Commercial Charge: 181.76 | |

1/2/2018
11:57:56AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10151763 2003 TOWMASTER T10T Trailer, Dual Axle, Tilt

Workorder: 1204240

Problem: PM

| Meter Reading: 0 | | Labor | Parts | |
|--|------------------------|-----------------------------|--------------------------------|----------|
| In Date: 05/03/2012 | Close Date: 05/22/2012 | Hours | Description | Quantity |
| - Pm Service Tandem Axle Trailer | | 8.50 | BRAKE SHOE KIT | 1.00 |
| - Replace 3 Tires | | | SHOP SUPPLIES | 1.00 |
| - Replace 2 Damaged Safety Chain Hooks | | | 42385 SEAL | 4.00 |
| - Replace Brake Shoes On Rear Axle, And Adjust Brakes. | | | TR416 VALVE STEM | 3.00 |
| - Shop Supplies | | | TIRE DISPOSAL FEE | 3.00 |
| | | | 762173406 225/75R15 MARATHON D | 3.00 |
| | | | BRAKE SHOE KIT | 1.00 |
| | | | SAFTEY HOOK WITH LATCH | 2.00 |
| Parts Charge: 497.01 | | Labor Charge: 510.00 | | |

Workorder: 1302346

Problem: turn/ brake light out

| Meter Reading: 0 | | Labor | Parts | |
|--|------------------------|----------------------------|-------------|----------|
| In Date: 03/08/2013 | Close Date: 03/11/2013 | Hours | Description | Quantity |
| - Repair Traielr Ligth Harness At Plug | | 0.50 | | |
| Parts Charge: 0.00 | | Labor Charge: 30.00 | | |

Workorder: 1307747

Problem: PM

| Meter Reading: 0 | | Labor | Parts | |
|--|------------------------|-----------------------------|---------------------|----------|
| In Date: 08/02/2013 | Close Date: 08/30/2013 | Hours | Description | Quantity |
| - Pm | | 8.00 | 42385 SEAL | 4.00 |
| - Replace Trailer Plug | | | SHOP SUPPLIES | 1.00 |
| - Remove Hyd Cyl For Repair Reinstll Hyd Cyl | | | HYD CYLINDER REPAIR | 1.00 |
| - Resecure Loose Deck Board | | | TRAILER CONN PLUG | 1.00 |
| - Shop Supplies | | | | |
| Parts Charge: 502.99 | | Labor Charge: 480.00 | | |

1/2/2018
11:57:56AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10151763 2003 TOWMASTER T10T Trailer, Dual Axle, Tilt

Workorder: 1312446

Problem: bearings squeak with weight on traler

| Meter Reading: 0 | | Labor | | Parts | |
|----------------------|---|--------|------------------------|--------|----------|
| In Date: 12/13/2013 | Close Date: 12/20/2013 | Hours | Description | | Quantity |
| - | Repalce Front And Rear Wheel Bearigns And Races And New Seals, And Dust Caps. Clean Out All Drums | 6.00 | SHOP SUPPLIES | | 1.00 |
| - | Fabricate Rubber Stops For Bed | | CONE | | 4.00 |
| - | Clean And Readjust All Shoes And Backing Plates | | BEARING CUP | | 4.00 |
| - | Shop Supplies | | MUD FLAP - 24 X18 X1 | | 1.00 |
| | | | MARINE ADH SEAL WHITE | | 2.00 |
| | | | GREASE CAP W PLUG 1.77 | | 4.00 |
| | | | SEAL 2.250X3.371X.375 | | 4.00 |
| | | | BEARING | | 4.00 |
| | | | RACE | | 4.00 |
| Parts Charge: | | 268.28 | Labor Charge: | 360.00 | |

Workorder: 1405476

Problem: needs left front tire fixed and other tires check.

| Meter Reading: 0 | | Labor | | Parts | |
|----------------------|-----------------------------------|--------|----------------------|-------|----------|
| In Date: 06/04/2014 | Close Date: 06/17/2014 | Hours | Description | | Quantity |
| - | Replace One Tire, Repair One Tire | 1.50 | TR416 VALVE STEM | | 2.00 |
| - | Shop Supplies | | TIRE DISPOSAL FEE | | 1.00 |
| | | | SHOP SUPPLIES | | 1.00 |
| | | | 762173406 225-75R15 | | 1.00 |
| Parts Charge: | | 165.18 | Labor Charge: | 90.00 | |

Workorder: 1411224

Problem: pm service

| Meter Reading: 0 | | Labor | | Parts | |
|----------------------|-----------------------------------|--------|-----------------------|--------|----------|
| In Date: 11/10/2014 | Close Date: 11/13/2014 | Hours | Description | | Quantity |
| - | Pm | 8.00 | TIRE DISPOSAL FEE | | 2.00 |
| - | Replace Trailer Plug | | TRAILER CONN PLUG | | 1.00 |
| - | Load Test Battery-Replace Battery | | BATTERY | | 1.00 |
| - | Replace 2 Tires | | SEAL 2.250X3.371X.375 | | 4.00 |
| - | Shop Supplies | | 762173406 225-75R15 | | 2.00 |
| | | | SHOP SUPPLIES | | 1.00 |
| Parts Charge: | | 371.88 | Labor Charge: | 480.00 | |

1/2/2018
11:57:56AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10151763 2003 TOWMASTER T10T Trailer, Dual Axle, Tilt

Workorder: 1601408 **Problem:** flat tire set for 2-3-16 am

| Meter Reading: 0 | Labor | Parts |
|---|---------------------------|---------------------------------|
| In Date: 02/02/2016 | Hours | Description |
| Close Date: 02/10/2016 | Quantity | |
| - Tire Service Rolling Green Yard - Flat Tire Set For 2-3-16 Am | | |
| Parts Charge: 0.00 | Labor Charge: 0.00 | Commercial Charge: 70.25 |

Workorder: 1602937 **Problem:** pm service

| Meter Reading: 0 | Labor | Parts |
|---|-----------------------------|-----------------------|
| In Date: 03/18/2016 | Hours | Description |
| Close Date: 03/28/2016 | Quantity | |
| - Pm | 9.00 | BACKING PLATE ASSM |
| - Replace Trailer Plug,, 2 Rear Running Lights And Harness, Wire In New License Plate Light W/Housing | | LICENSE LAMP |
| - Replace Tow Ring | | SHOP SUPPLIES |
| - Replace R/F Brake Shoe Assembly, Clean And Adjust 3 Other Brakes | | SEAL 2.250X3.371X.375 |
| - Shop Supplies | | BRAKE CLEANER |
| | | LED M C LAMP |
| | | TRAILER CONN PLUG |
| | | LED M C ADAPER PLUG |
| | | TOW RING |
| Parts Charge: 186.33 | Labor Charge: 540.00 | |

Workorder: 1603747 **Problem:** jack does not work

| Meter Reading: 0 | Labor | Parts |
|---|-----------------------------|---------------|
| In Date: 04/08/2016 | Hours | Description |
| Close Date: 04/20/2016 | Quantity | |
| - Fab And Weld Brackets, Install New Jack | 3.00 | DROP LEG |
| - Shop Supplies | | JACK HANDLE |
| | | SHOP SUPPLIES |
| Parts Charge: 244.58 | Labor Charge: 180.00 | |

1/2/2018
11:57:56AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10151763 2003 TOWMASTER T10T Trailer, Dual Axle, Tilt

Workorder: 1604408

Problem: rear tires

| Meter Reading: 0 In Date: 04/27/2016 | Close Date: 04/29/2016 | Labor Hours | Description | Parts | Quantity |
|---|------------------------|----------------------------|---------------------|-------|----------|
| - Replace 2 Rear Tires | | 1.50 | TIRE DISPOSAL FEE | | 2.00 |
| - Shop Supplies | | | SHOP SUPPLIES | | 1.00 |
| | | | 762173406 225-75R15 | | 2.00 |
| | | | TR416 VALVE STEM | | 2.00 |
| Parts Charge: 318.64 | | Labor Charge: 90.00 | | | |

Workorder: 1706210

Problem: replace tire

| Meter Reading: 0 In Date: 06/23/2017 | Close Date: 06/29/2017 | Labor Hours | Description | Parts | Quantity |
|---|------------------------|-----------------------------|------------------------|-------|----------|
| - Replace Tire | | 11.00 | M C LAMP | | 3.00 |
| - Pm Trailer | | | SHOP SUPPLIES | | 1.00 |
| - Replace Trailer Connector Plug-Replace Tial/Stop Lights And 3 Side Marker Lights | | | BULB st225/75r15 10 | | 1.00 |
| - Clean And Adj Brakes 3-Replace Trailer Breakaway Sys-Replace Right Rear Brake Assy | | | LED SUP MDL 44 42 DIO | | 2.00 |
| - Shop Supplies | | | BREAK AWAY SYSTEM | | 1.00 |
| | | | SEAL 2.250X3.371X.375 | | 4.00 |
| | | | GREASE CAP W PLUG 1.77 | | 1.00 |
| | | | TIRE DISPOSAL FEE | | 1.00 |
| | | | MALE TRAILER CONNECTOR | | 1.00 |
| | | | NON-CHLOR BRAKE CLNR | | 1.00 |
| | | | BACKING PLATE ASSM | | 1.00 |
| | | | NON-CHLOR BRAKE CLNR | | 1.00 |
| Parts Charge: 497.34 | | Labor Charge: 660.00 | | | |

Workorder: 1710925

Problem: Transition Prep Charge

| Meter Reading: 0 In Date: 11/03/2017 | Close Date: 11/03/2017 | Labor Hours | Description | Parts | Quantity |
|---|------------------------|---------------------------|-------------|-------|----------|
| - Transition Prep Charge | | 2.00 | | | |
| Parts Charge: 0.00 | | Labor Charge: 0.00 | | | |

| | | | | | |
|----------------------|-----------------|----------------------|-----------------|----------------------|---------------|
| Total Parts Charges: | 4,911.66 | Total Labor Charges: | 8,305.00 | Total Comm. Charges: | 455.11 |
|----------------------|-----------------|----------------------|-----------------|----------------------|---------------|