

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1207403	Meter: 20965	In Date: 08/07/2012	Closed: 08/17/2012
Problem: Pm service.			
- P.m. Service.		Parts List	Qty
- Rotate and balance all tires.		Shop Supplies	1.00
- Shop Supplies		Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
		1372 Oil Filter Frm Ph2 Wix 51372	1.00
		1066 White Lithium (crc 05037)	1.00
		5w20 Engine Oil	6.00
		31-22 Wiper Blades 22" Wiper Blade	2.00
Hours 3.00	Labor: 180.00	Parts: 37.24	Total: 217.24
:			

Workorder: 1302812	Meter: 25957	In Date: 03/21/2013	Closed: 03/28/2013
Problem: P.M. Service			
- Perform pm service.		Parts List	Qty
- Install four new tires.nitrogen fill and balance all four.		5w20 Engine Oil	7.00
- Perform wheel alignment complete.		1372 Oil Filter	1.00
- Shop Supplies		31-20 Wiper Blades 20	2.00
		Wd40 Spray Lube Stock	1.00
		Used Firex Refurbed F	1.00
		758537188 235-75r17	4.00
		Shop Supplies	1.00
		Tire Disposal Fee	4.00
Hours 6.50	Labor: 390.00	Parts: 931.39	Total: 1,321.39
:			

Workorder: 1309430	Meter: 31004	In Date: 09/17/2013	Closed: 09/30/2013
Problem: Pm service.			
- P.m. Service.		Parts List	Qty
- Test battery and charging system.recharge and retest battery,fail load test.replace defective battery.		5w20 Engine Oil	7.00
- Replace noise idler pulley and worn serpentine belt.		Napagold Oil Filter	1.00
- Rotate and balance all four tires.		31-20 Wiper Blades 20	2.00
- Shop Supplies		Battery 65	1.00
		Pulley	1.00
		Serpentine Belt	1.00
		Shop Supplies	1.00
Hours 5.25	Labor: 315.00	Parts: 255.71	Total: 570.71
:			

Workorder: 1403771	Meter: 37028	In Date: 04/17/2014	Closed: 04/29/2014
Problem: Pm service and request to detail vehicle.			
- Perform pm service.		Parts List	Qty
- Diagnose blower motor speeds inop.pin point test and replace failed blower resistor with new.		5w20 Engine Oil	7.00
- Rotate and balance all four tires.		Napagold Oil Filter	1.00
- Shop Supplies		Wiper Blade	2.00
		Used Fire X Refurbished	1.00
		Blower Motor Resistor	1.00
		Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 66.25	Total: 306.25
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1404028 **Meter:** 36931 **In Date:** 04/24/2014 **Closed:** 04/24/2014
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1410631 **Meter:** 42044 **In Date:** 10/23/2014 **Closed:** 10/31/2014
Problem: P.M. Service.

- Pm service.

- Rotate and balance all four tires.

- Shop Supplies

Parts List	Qty
5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Brake Cleaner	1.00
Shop Supplies	1.00

Hours 3.00 Labor: 180.00 Parts: 36.50 Total: 216.50
:

Workorder: 1503843 **Meter:** 47128 **In Date:** 04/14/2015 **Closed:** 04/29/2015
Problem: Pm service.Blower motor only runs on high speed.

- P.m. Service.

- Diagnose blower only blows on high.test and replace defective resistor.

- Resurface front brake rotors,replace front pads.service and lube calipers.flush and bleed system.

- Replace and balance four new tires.

- Flush and refill transmission system.

- Complete wheel alignment.test drive.

- Shop Supplies

Parts List	Qty
5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Blower Resistor	1.00
Brake Pads - Front, Ultra Premium - Oe C	1.00
1401 Brake Fluid Bra	2.00
Brake Cleaner	1.00
Hankook P235 75r17 Dp At	4.00
Syn-atf Trans Fluid S	12.00
kit brak	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours 12.50 Labor: 750.00 Parts: 1,197.94 Total: 1,947.94
:

Workorder: 1510275 **Meter:** 52057 **In Date:** 10/09/2015 **Closed:** 10/27/2015
Problem: Pm service.Left rear tire flat.

- Pm service.

- Pressure test and inspect cooling system.flush and refill antifreeze.

- Replace rear brake pads and resurface rear brake rotors.service calipers and test drive.

- Repair left rear tire.rotate and balance all four.

- Shop Supplies

Parts List	Qty
5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Peak Global	2.00
Brake Pad	1.00
Shop Supplies	1.00

Hours 9.50 Labor: 570.00 Parts: 154.55 Total: 724.55
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1604318 **Meter:** 57998 **In Date:** 04/25/2016 **Closed:** 04/29/2016
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Inspect and service rear differential.	5w20 Engine Oil	7.00
- Rotate and balance all tires.	Napagold Oil Filter	1.00
- Shop Supplies	Napagold Air Filter	1.00
	Washer Fluid Concentr	1.00
	20" Wiper Blade	2.00
	75w140 Ford Axle Lube	3.00
	Friction Modifier	1.00
	Stg Wheel Cov - Ford	1.00
	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 142.01
:		Total: 382.01

Workorder: 1610876 **Meter:** 63149 **In Date:** 10/21/2016 **Closed:** 10/31/2016
Problem: P.M. service and detail.

- P.m. Service.	Parts List	Qty
- Rotate and balance all tires.	5w20 Engine Oil	7.00
- Shop Supplies	Napagold Oil Filter	1.00
	Washer Fluid Concentr	1.00
	20" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 44.99
:		Total: 224.99

Workorder: 1611096 **Meter:** 63125 **In Date:** 10/26/2016 **Closed:** 10/26/2016
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1705293 **Meter:** 67783 **In Date:** 05/30/2017 **Closed:** 06/02/2017
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Battery failed load test after recharge.check electrical system.replace battery.	5w20 Engine Oil	7.00
- Rotate and balance four tires.nitro fill.	Napagold Oil Filter	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Battery	1.00
	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 151.09
:		Total: 391.09

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1705717 **Meter:** 67844 **In Date:** 06/08/2017 **Closed:** 06/13/2017

Problem: Check engine light on.

	Parts List	Qty
- Diagnose check engine light on .computer scan, read codes P0130,p0150reprogram Pcm Per Tsb 12-6-16.replace both bank one and bank two sensor ones.clear codes and test drive.	Sensor	2.00
	Shop Supplies	1.00

- Shop Supplies

Hours 3.00 Labor: 180.00 Parts: 353.51 Total: 533.51
:

Workorder: 1710083 **Meter:** 69239 **In Date:** 10/16/2017 **Closed:** 10/16/2017

Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
: